

Travel Advisory Report

JUNE 2017

N1

| | |
|---------------------------------|--|
| National Route | N1 |
| Section | Old Oak Interchange to Rawsonville |
| Distance | 64 km |
| Description | Two-lane dual carriageway with paved shoulders. |
| Expected Travel Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Chris Roux 083 440 7553 |

| | |
|---------------------------------|--|
| National Route | N1 |
| Section | Rawsonville to Laingsburg |
| Distance | 156 km |
| Description | Single carriageway road with passing lanes and with gravel shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | A compulsory stop, manned by the Provincial Traffic Department, is in operation \pm five km south of Touws River. An unmanned compulsory stop for heavy vehicles is also in operation on the south-bound carriageway in Hex River Pass. Motorists should be alert to pedestrians and/or stray animals just north of De Doorns as well as to the informal traders alongside the road. Please note that it is illegal to stop and buy from the sellers. Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Edwin De Wee 073 985 6476 |

| | |
|---------------------------------|---|
| National Route | N1 |
| Section | Laingsburg to Three Sisters |
| Distance | 280 km |
| Description | Single carriageway with paved shoulders. Stopping places are provided at regular intervals. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | December 2016 |
| Contact for Routine Maintenance | Japie Taljaard 082 857 7175 |

| | |
|---------------------------------|--|
| National Route | N1 |
| Section | Three-Sisters to Colesberg |
| Distance | 236 km |
| Description | Single carriageway with paved shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | December 2016 |
| Contact for Routine Maintenance | Martiens du Plessis 083 655 0644 |

| | |
|--------------------------------------|---|
| National Route | N1 |
| Section | Colesberg to Orange River |
| Distance | 36.34 km |
| Description | Single carriageway with surfaced shoulders and 4 passing lane sections. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Martiens du Plessis 083 655 0644 |

| | |
|--------------------------------------|---|
| National Route | N1 |
| Section | Orange River (Provincial Boundary) to Bloemfontein (Sydenham Interchange) |
| Distance | 175 km |
| Description | A two lane single carriageway with wide paved shoulders and passing lanes on sustained grades. |
| Expected Road Condition | Fair to good. |
| Expected Travel Condition | Upgrading of the section between Trompsburg and Fonteintjie is in progress. Traffic is diverted onto deviations with no Stop/Go controls at both ends of the project. |
| Duration of Work | Until June 2017 |
| Contact for Routine Road Maintenance | Riaan Louwrens 074 601 8998 |

| | |
|--------------------------------------|---|
| National Route | N1 |
| Section | Bloemfontein to Kroonstad |
| Distance | 189 km |
| Description | Around Bloemfontein and extending northwards for some 15km, the road is a four-lane dual carriageway with wide paved shoulders. Thereafter it reduces to a four-lane single carriageway for the next 20kms, otherwise it is a two-lane single carriageway with paved shoulders and passing lanes on steep gradients. The last 10 km, known as the Kroonstad Bypass, is a four-lane dual carriageway. |
| Expected Road Condition | Generally good except for the section between Kroonstad and Ventersburg, where the road surfacing is in a fair condition. |
| Expected Travel Condition | <ol style="list-style-type: none"> 1. Upgrading of section between Sydenham Interchange and Glen Lyon is almost complete. No Stop/Go controls in place. 2. A contract for the upgrade between Winburg and Winburg Station commenced 4 January 2016. Full road closures may be experienced during certain blasting operations. 3. A contract for the upgrade between Ventersburg and Holfontein is in progress. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 4. A contract for the upgrade between Holfontein and Kroonstad is in progress. Traffic is free flowing. Motorists are advised to obey the posted traffic signs. |
| Duration of Work | <ol style="list-style-type: none"> 1. Until June 2017 2. Until April 2018 3. Until September 2018 4. Until March 2018 |
| Contact for Routine Road Maintenance | Abel Majorobela 079 896 3377 |

| | |
|--------------------------------------|--|
| National Route | N1 |
| Section | Kroonstad to Vaal River (Free State – Gauteng Provincial Boundary) |
| Distance | 102 km |
| Description | Partly a single carriageway with alternating passing lanes in each direction and wide gravel shoulders, and partly a four-lane single carriageway, except for the 10 km portion beyond the Vaal Toll Plaza, where it becomes a four-lane dual carriageway with wide paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | 1. A rehabilitation contract between Kroonstad South and Westleigh is in progress. Traffic is free flowing with at least one lane open in each direction. Motorists are advised to obey the posted traffic signs. eriodic maintenance contract between Koppies and Vaal Toll Plaza commenced on 13 May 2016. No Stop/Go controls in place. Two way traffic with reduced lane width. Ad hoc repairs will be undertaken. |
| Duration of Work | 1. Until July 2017ntil June 2017. |
| Contact for Routine Road Maintenance | Abel Majorobela 079 896 3377 |

| | |
|--------------------------------------|--|
| National Route | N1 |
| Section | Vaal River (provincial boundary) to Misgund Soweto |
| Distance | 64 km |
| Description | Four-lane dual carriageway freeway with wide paved shoulders. |
| Expected Travel Condition | Good. |
| Expected Road Condition | Motorists should be beware of pedestrian activity along the route. Additional street lighting has been installed at the Ennerdale Interchange. |
| Duration of Work | |
| Contact for Routine Road Maintenance | Unita Fungile 072 793 2825 |

| | |
|--------------------------------------|---|
| National Route | N1 |
| Section | Misgund Soweto to Grand Central / Olifantsfontein Interchange |
| Distance | 57.6 km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Travel Condition | Good |
| Expected Road Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Pierre Coetzer 076 107 7322 |

| | |
|--------------------------------------|--|
| National Route | N1 |
| Section | Grand Central / Olifantsfontein interchange to Proefplaas N4 Interchange |
| Distance | 33.0 km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Bridge repairs along the N1/N4 Proefplaas interchange. Expect lane reductions |
| Expected Road Condition | Good |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Pierre Coetzer 076 107 7322 |

| | |
|--------------------------------------|--|
| National Route | N1 |
| Section | Proefplaas (N4 Interchange) to Bela Bela (Warmbaths) (Platinum Toll highway) |
| Distance | 94 km |
| Description | Six lane dual carriageway freeway from Pretoria (Proefplaas Interchange) to Zambesi Interchange changing into four lane dual carriageway freeway to Bela Bela. |
| Expected Travel Condition | 1. RRM Teams may be encountered 2. Roadworks within various Toll plazas in Tshwane along the N1 |
| Expected Road Condition | RRM teams may be encountered |
| Duration of Work | 2. Until June 2017 |
| Contact for Routine Road Maintenance | Pt Ops 012 804 0044 |

| | |
|--------------------------------------|--|
| National Route | N1 |
| Section | Bela Bela to Polokwane (Great North Toll Road) |
| Distance | 160 km |
| Description | Four-lane dual divided carriageway freeway from the Warmbaths/Settlers interchange to the Kranskop toll plaza. Four-lane single undivided carriageway freeway from the Kranskop Toll Plaza to the N1/R71 interchange at Polokwane (Meropa). There is ad hoc maintenance works and lane upgrades at the Kranskop Plaza for electronic tolling systems as an additional payment method to road users |
| Expected Travel Condition | 1. Routine Road Maintenance teams may be encountered 2. Major roadworks upgrade of the N1/R71 interchange |
| Duration of Work | 2. Until December 2018 |
| Contact for Routine Road Maintenance | NTRV Danie Kotze 082 822 0902 |

| | |
|--------------------------------------|--|
| National Route | N1: R101 |
| Section | Middelfontein to Mookopong Municipal Border (N1/24S: R101) |
| Distance | 4.78 km |
| Description | Two lane single carriageway with paved shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance Teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Gustavus Fouche 082 780 2391 |

| | |
|--------------------------------------|--|
| National Route | N1: R101 |
| Section | Mookopong Municipal Border to Mokopane (N1/25X: (R101) |
| Distance | 67.13 km |
| Description | Two lane single carriageway with paved shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance Teams may be encountered Roadworks with lanes deviations |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Gustavus Fouche 082 780 2391 |

| | |
|--------------------------------------|--|
| National Route | N1: R101 |
| Section | Mookgopong I/C to N1/25X Intersection (N1/25Y: R101) |
| Distance | 2.200 km |
| Description | Two lane single carriageway with paved shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance Teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Gustavus Fouche 082 780 2391 |

| | |
|--------------------------------------|---|
| National Route | N1: R101 |
| Section | Mokopane to Polokwane |
| Distance | 49.7 km |
| Description | Two lane single carriageway with paved shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance Teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Hannelie Swanepoel 082 380 5264Ha |

| | |
|--------------------------------------|---|
| National Route | N1 |
| Section | Polokwane (Meropa Casino) to Doornbult |
| Distance | 22.3 km |
| Description | Two lane single carriageway with paved shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance Teams may be encountered Major Roadworks upgrades from Meropa N1 to R71 interchange |
| Duration of Work | Ongoing Until December 2018 |
| Contact for Routine Road Maintenance | George Brand 083 730 9385 |

| | |
|--------------------------------------|--|
| National Route | N1 |
| Section | Doornbult to Makhado |
| Distance | 98.75 km |
| Description | Two lane single carriageway with paved shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance Teams may be encountered. There is ad hoc maintenance works and lane upgrades at the Capricorn Plaza for electronic tolling systems as an additional payment method to road users. Expect construction between Polokwane and Diep River and within Botlokwa until December 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | George Brand 083 730 9385 |

| | |
|---------------------------------|--|
| National Route | N1 |
| Section | Makhado to Beitbridge |
| Distance | 107 km |
| Description | Two-lane single carriageway with paved shoulders. |
| Expected Road Condition | Fair. There is ad hoc maintenance works and lane upgrades at the Baobab Plaza for electronic tolling systems as an additional payment method to road users |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Johannes Rakwena 082 304 6880 |

N2

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Swartklip Interchange to Somerset-West |
| Distance | 24 km |
| Description | Two-way dual carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Chris Roux 083 440 7553 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Somerset-West to Botriver |
| Distance | 45 km |
| Description | Single carriageway road with paved shoulders and passing lanes. A four lane single undivided carriageway road through Sir Lowry's Pass and Houwhoek Pass. Average speed cameras have been implemented and fully operational both ways on Sir Lowry's Pass. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Chris Roux 083 440 7553 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Botriver to Riversdale |
| Distance | 218 km |
| Description | Single carriageway with paved shoulders and passing lanes. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing. |
| Contact for Routine Road Maintenance | Pierre Terblanche 084 516 7121 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Riversdale to Mossel Bay |
| Distance | 82 km |
| Description | Single carriageway with paved shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Johan Nel 082 612 1980 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Mossel Bay to George |
| Distance | 51 km |
| Description | A four-lane dual carriageway. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Johan Nel 082 612 1980 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | George to Natures Valley (Sout River) |
| Distance | 113 km |
| Description | Single carriageway with narrow paved shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | It is illegal to stop and buy from the informal traders. Motorists should be alert to pedestrians and/or stray animals in the vicinity of the informal settlement in Knysna, as well as in the vicinity of Plettenberg Bay. Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing. |
| Contact for Routine Road Maintenance | Johan Nel 082 612 1980 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Natures Valley to Storms River |
| Distance | 40 km |
| Description | A two-lane single carriageway with surfaced shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | Toll Road |
| Contact for Routine Road Maintenance | Michelle van Rooyen 072 777 7232 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Storms River Town to Elands River |
| Distance | 14 km |
| Description | A two-lane single carriageway with shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | Toll Road |
| Contact for Routine Road Maintenance | Michelle van Rooyen 072 777 7232 |

| | |
|---------------------------|---|
| National Route | N2 |
| Section | Elands River to Gamtoos |
| Distance | 98 km |
| Description | A two-lane single carriageway with shoulders. |
| Expected Travel Condition | Good |
| Contact for Construction | Michelle van Rooyen 072 777 7232 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Gamtoos River to Van Stadens River |
| Distance | 19 km |
| Description | 14,7 km of 2-lane single carriageway and 4.3 km of dual carriageway with surfaced shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | Undulations occur on sections of this road. At Thornhill, pedestrians could be encountered. |
| Duration of Work | |
| Contact for Routine Road Maintenance | Lauren Adams 073 311 1818 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Van Stadens River to Port Elizabeth (Coega IDZ) |
| Distance | 57 km |
| Description | Dual carriageway with 2 lanes per direction. |
| Expected Travel Condition | Good |
| Contact for Routine Road Maintenance | Lauren Adams 073 311 1818 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Port Elizabeth (Coega IDZ) to Colchester |
| Distance | 14Km |
| Description | Dual carriageway with 2 lanes per direction |
| Expected Travel Condition | Good |
| Contact for Routine Road Maintenance | Lauren Adams 073 311 1818 |

| | |
|---------------------------|-------------------------|
| National Route | N2 |
| Section | Colchester to Nanaga |
| Distance | 13Km |
| Description | 13km single carriageway |
| Expected Travel Condition | Good. |

| | |
|--------------------------------------|---|
| National Route | N2 section 12 & 13 |
| Section | Nanaga to Komgha River |
| Distance | 3km |
| Description | 2 - lane single carriageway, narrow road width. |
| Expected Travel Condition | Good, but no paved shoulders in place. Animals at R67 intersection east of Grahamstown. |
| Duration of Work | |
| Contact for Routine Road Maintenance | |

| | |
|--------------------------------------|---|
| National Route | N2 section 13 |
| Section | Komgha River to Grahamstown |
| Distance | 42km |
| Description | 2 - lane single carriageway |
| Expected Travel Condition | Construction started in March 2016 and is now complete. |
| Duration of Work | 12 months (March 2016 to May 2017) |
| Contact for construction | Sarel Bezuidenhout 073 483 6700 Naseef Parker 072 500 9913 |
| Contact for Routine Road Maintenance | Bathandwa Mankayi 072 774 6539 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Grahamstown to Fish River |
| Distance | 47km |
| Description | A 2-lane single carriageway is being upgraded |
| Expected Travel Condition | Construction commenced in April 2015 on phase 1, km 62,0 to km 78,7 and is nearing completion Construction is also in progress at the fish river bridge: km 103. Construction of phase 2 will commence in June 2017, km 78,7 to km 92,6. |
| Expected Travel Condition | Speed restrictions will be in place. Construction traffic will be encountered. Temporary closures due to blasting will take place approximately 30km east of Grahamstown. Stop-Go's in place to reduce traffic speeds. The stop-go's will be removed during the holidays. However, traffic calming and speed restrictions will be in place at the Fish River Bridge. |
| Duration of Work | April 2015 to June 2019 |
| Contact for Routine Road Maintenance | Bathandwa Mankayi 072 774 6539 |
| Contact for Construction project | Steve Beckerling – Engineer's representative on site 083 554 3605 |

| | |
|--------------------------------------|------------------------------------|
| National Route | N2 |
| Section | Fish river to Keiskamma Pass |
| Distance | 27 km |
| Description | A 2-lane single carriageway. |
| Expected Travel Condition | Good |
| Expected Travel Condition | Isolated repairs being undertaken. |
| Duration of Work | |
| Contact for Routine Road Maintenance | Bathandwa Mankayi 072 774 6539 |

| | |
|--------------------------------------|-----------------------------------|
| National Route | N2 |
| Section | Keiskamma River to Green River |
| Distance | 23 km |
| Description | A 2-lane single carriageway |
| Expected Travel Condition | Good |
| Expected Travel Condition | Recently upgraded |
| Duration of Work | |
| Contact for Routine Road Maintenance | Bathandwa Mankayi 072 774 6539 |

| | |
|---------------------------|---|
| National Route | N2 |
| Section | Green River to Breidbach |
| Distance | 13km |
| Description | Upgrading from Green River to Breidbach Interchange. Rehabilitation of section of route through King Williams Town has started as phase 1 – Buffalo River to Zwelitsha. |
| Expected Travel Condition | Rehab in King Williams Town started in May 2016. Detours can be expected. Grey street closed between Buffalo street and Alexandra street. |
| Duration of Work | May 2016 to November 2017 (Phase 1) |
| Contact for construction | Nick Kitsopoulos 082 576 4667 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | King Williams Town to East London (Gonubie) |
| Distance | 60 km |
| Description | A 4-lane dual carriageway |
| Expected Travel Condition | Good |
| Expected Travel Condition | Expect delays between the Hemmingway way 7/0 and NEX due to road works. |
| Duration of Work | Delays at the intersection of N2 and Breidbach intersection during morning and afternoon peaks. |
| Contact for Routine Road Maintenance | Bathandwa Mankayi 072 774 6539 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Gonubie to Kei River |
| Distance | 60 km |
| Description | The first 2km is a 4-lane dual carriageway. Thereafter it becomes a 2-lane single carriageway with wide paved shoulders. Passing lanes are provided on some steep grades. |
| Expected Travel Condition | Between R63 T-junction to the Kei River Bridge motorists to keep to posted speed limits. Construction contract underway from R63 T-Junction to Kei bridge. Stop-go's may be encountered. |
| Contact for Routine Road Maintenance | Mike De Lange (RRM queries only) 082 779 2993 |
| Contact for Construction | Ean Smit 082 552 0889 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Kei River to Dutywa |
| Distance | 68 km |
| Description | Single carriageway road with paved shoulders and passing lanes. |
| Expected Travel Condition | The condition is fair. |
| Expected Travel Condition | Roaming animals in some areas near villages |
| Contact for Routine Road Maintenance | Mike De Lange 082 779 2993 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Dutywa to Mthatha |
| Distance | 85 km |
| Description | Single carriageway road with paved shoulders and passing lanes. |
| Expected Travel Condition | Fair |
| Expected Travel Condition | Roaming animals in some areas near villages |
| Contact for Routine Road Maintenance | Mike De Lange (RRM queries only) 082 779 2993 |

| | |
|----------------------------------|--|
| National Route | N2 |
| Section | Tetyana to Sithebe Komkulu |
| Distance | 17 km |
| Description | Upgrading of N2 from Tetyana (km 24) to Sitebe Komkulu (Km 41.0) |
| Expected Travel Condition | |
| Expected Travel Condition | Mostly 2-way at a maximum speed of 60km/h. Expect stop-go's for a duration not exceeding 2hrs for blasting activities, mostly on Tuesdays and Thursdays. |
| Duration of work | October 2016 – April 2019 |
| Contact for Construction project | Joe van Dyk 083 283 6507 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Mthatha to Mount Ayliff |
| Distance | 130 km |
| Description | A 2 lane single carriageway with passing lanes and paved shoulders. |
| Expected Travel Condition | The Expected Road Condition between km 54 to km 70 is fair however routine maintenance teams may be encountered. |
| Contact for Routine Road Maintenance | Ernest Zellhuber 072 789 5046 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Brookes Nek (provincial boundary) to Port Shepstone |
| Distance | 135 km |
| Description | This first section of the N2 in KZN is a two-lane single carriageway with narrow paved shoulders. Passing lanes are provided on all the severe grades with the exception of a short 6 km section, 26 km north of Kokstad. |
| Expected Road Condition | Good. |
| Expected Travel Condition | A periodic maintenance contract between Brooksnek and Staffords Post is underway. Traffic is accommodated by Stop/Go controls, with expected delays of up to 20 minutes per closure. There are three closures in place. Occasional night closures can be expected. Motorists are advised to adhere to the reduced speeds as signposted. |
| Duration of Work | Until November 2017 |
| Contact for Routine Road Maintenance | Amit Bhoora 082 442 9646 |

| | |
|--------------------------------------|--|
| National Route | N2 |
| Section | Port Shepstone to Durban (N2/N3 Interchange) |
| Distance | 114 km |
| Description | The first 20 km is a single carriageway road with three lanes of traffic and narrow paved shoulders allowing overtaking opportunities. Thereafter the road becomes a four-lane dual carriageway with wide paved shoulders. The last 17 km leading into Durban has 3 lanes in each direction and is heavily trafficked. |
| Expected Road Condition | Good. |
| Expected Travel Condition | No construction |
| Duration of Work | |
| Contact for Routine Road Maintenance | Port Shepstone to Hibberdene: Amit Bhoora 082 442 9646 Hibberdene to Durban: Emeka Mgbemere 083 641 9056 (Route Manager) |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Durban to Empangeni |
| Distance | 162 km |
| Description | For 71 km, up to Stanger, the road is a four-lane dual carriageway. For the next 52 km, up to the Mtunzini Toll Plaza, the road is a four-lane undivided carriageway with paved shoulders. The remaining portion is a single carriageway with alternating passing opportunities. |
| Expected Road Condition | Good. |
| Expected Travel Condition | <ol style="list-style-type: none"> 1. A contract for the periodic maintenance of the N2 from EB Cloete to Mount Edgecombe Interchange is in progress, with construction work taking place at night between 20h00 to 04h00. Lane reductions will be in place 2. A contract for the upgrading of the N2/M41 Mount Edgecombe Interchange to a free-flow systems interchange is in progress. Traffic is being accommodated on temporary deviations, with speed restrictions in place. Traffic travelling on the M41 from Umhlanga towards the N2 North (towards King Shaka Airport) is being temporarily diverted onto a loop ramp. This diversion requires traffic to keep left on the M41 as the right turn movement is closed. Stop/Go controls are in place on the Mt. Edgecombe Drive underpass. 3. A contract for the joint seal replacement and concrete pavement repairs between Umhloti and New Guelderland is in progress. No Stop/Go controls will be in place, but reduced lane widths and speed restrictions will be in place. 4. A contract for localised realignment of the N2 at Umhlali River Bridge and at Umvoti River Bridge is in progress. No Stop/Go controls will be in place, but reduced lane widths and speed restrictions will be in place. 5. A contract for the upgrade of the N2 to a dual carriageway freeway between Mtunzini Toll Plaza and Empangeni T-Junction is in progress. No Stop/Go controls will be in place. 6. A contract for the maintenance of the north coast toll plazas has commenced. There is minimal disruption to traffic except on certain ramp toll plazas. |
| Duration of work | <ol style="list-style-type: none"> 1. Until April 2018. 2. Until November 2017. 3. Until June 2017. 4. Until October 2017. 5. Until April 2019. 6. Until January 2018. |
| Contact for Routine Road Maintenance | Emeka Mgbemere 083 641 9056 (Route Manager – Durban to eMdloti) Stollie van Wyk 072 283 6669 (eMdloti to Empangeni) |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Empangeni to Pongola |
| Distance | 250 km |
| Description | A 2-lane single carriageway with paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | No construction |
| Duration of work | |
| Contact for Routine Road Maintenance | Gonie Govender 084 466 2198 |

| | |
|--------------------------------------|---|
| National Route | N2 |
| Section | Pongola to KwaZulu-Natal / Mpumalanga Border |
| Distance | 38 km |
| Description | A 2-lane single carriageway road with passing lanes on the steeper gradients. |
| Expected Road Condition | Good |
| Expected Travel Condition | No construction |
| Duration of work | |
| Contact for Routine Road Maintenance | Gonie Govender 084 466 2198 |

| | |
|---------------------------------|--|
| National Route | N2 |
| Section | KwaZulu Natal / Mpumalanga border north of Pongola Border to Piet Retief |
| Distance | 57km |
| Description | A Two-lane single carriageway narrow gravel shoulder. |
| Expected Road Condition | Good |
| Expected Travel Condition | Pavement layer repair is on-going on this section |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Faith Mogano 076 7790 346 |

| | |
|---------------------------------|---|
| National Route | N2 |
| Section | Piet Retief to Ermelo |
| Distance | 98.20 km |
| Description | A Two-lane single Carriageway narrow gravel shoulder. First 7km is 4 lane undivided |
| Expected Road Condition | Good |
| Expected Travel Condition | Reseal contract between Camden and Ermelo. Expect Stop 'n Go's. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Faith Mogano 076 7790 346 |

N3

| | |
|--------------------------------------|--|
| National Route | N3 |
| Section | Durban to Cedara (Hilton) |
| Distance | 85 km |
| Description | This entire section is a multi-lane dual carriageway. The first 4km out of Durban carries heavy traffic with up to 5 lanes in each direction. The next 40 km, up to Cato Ridge, has 3 lanes in each direction with wide paved shoulders. The section between Cato Ridge and the end of the Pietermaritzburg Bypass (33 km) has a two-lane plus paved shoulder configuration, except on steep gradients to the east of Pietermaritzburg where passing lanes are provided. The final 14 km to Howick incorporates the steeply graded Town Hill, which has 3 lanes with paved shoulders in each direction. |
| Expected Road Condition | Good. |
| Expected Travel Condition | <ol style="list-style-type: none"> 1. A contract for the upgrade of the Hammarsdale Interchange is ongoing. Periodic blasting will occur for the next month. There will be minimal disruption to traffic on the N3, with the existing three lanes reduced to two lanes in each direction in the vicinity of the interchange, however there will be disruption to local traffic. 2. There is intermittent closure of the slow lane on the southbound carriageway of Town Hill for surface repairs. Motorists are advised to pay attention to the road signs and speed restrictions. |
| Duration of Work | <ol style="list-style-type: none"> 1. Until November 2018. 2. Until October 2017. |
| Contact for Routine Road Maintenance | Emeka Mgbemere 083 641 9056 (Route Manager) |

| | |
|--------------------------------------|---|
| National Route | N3 (The N3 Toll Route operated by N3 Toll Concession (RF) Proprietary Limited) |
| Section | Cedara to Heidelberg |
| Distance | 415 km |
| Description | This section of road is a public private partnership between SANRAL and the N3Toll Concession (Pty) Ltd. This toll route is a four-lane dual carriageway road between Cedara and the Tugela Toll Plaza. From the Tugela Toll Plaza to the Wilge Toll Plaza (Villiers) the road is a four-lane single carriageway with shoulders of varying width. The section between the Tugela Toll Plaza and Warden has at-grade intersections and access roads with reduced speed limits signposted. The remainder of the road between Villiers and Heidelberg is a four-lane dual carriageway with paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | <p>Current planned construction works include:</p> <ol style="list-style-type: none"> 1. Rehabilitation between Cedara and Mooi River. Work commenced in April 2017 and is programmed for completion in February 2019. 2. Rehabilitation between Frere Interchange and the Sand River near the Bergville Interchange. Work commenced in November 2016 and is programmed for completion on 28 February 2018. 3. Rehabilitation between Harrismith and Warden. Work commenced in January 2015 and is programmed for completion by September 2017. 4. Isolated maintenance on Van Reenens Pass during June 2017. 5. Ongoing routine road maintenance, grass cutting and litter collection. <p>Through the construction zones, traffic may be restricted to one lane in each direction under reduced speed. Road users are urged to obey the posted speed limits, maintain safe following distances and to refrain from littering.</p> |
| Duration of Work | Please see above. Maintenance personnel will be on standby to deal with any emergency repairs. |
| Contact for Routine Road Maintenance | N3TC Customer Care Line 0800 634 357 0800 N3 HELP |

| | |
|--------------------------------------|--|
| National Route | N3 |
| Section | Balfour Interchange to Vosloorus (Barry Marais road) |
| Distance | 38.2km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Marthinus Wilken 082 782 1746 |

| | |
|--------------------------------------|--|
| National Route | N3 |
| Section | Vosloorus / Barry Marais Road to Buccleuch Interchange |
| Distance | 43.0km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Road Condition | Routine Road Maintenance teams may be encountered |
| Expected Travel Condition | Good |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Marthinus Wilken 082 782 1746 |

N4

| | |
|--------------------------------------|---|
| National Route | N4 (Platinum Highway) |
| Section | Botswana Border to Zeerust |
| Distance | 60 km |
| Description | Two-lane single carriageway with paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Major roadworks upgrade from Zeerust. Expect Stop n Go's |
| Duration of Work | |
| Contact for Routine Road Maintenance | Pt Ops 012 804 0044 |

| | |
|--------------------------------------|---|
| National Route | N4 (Platinum Toll Highway) |
| Section | Zeerust to Rustenburg |
| Distance | 120 km |
| Description | Two-lane single carriageway with paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Rehabilitation between Zeerust and Swartuggens Plaza. Expect Stop n Go's |
| Duration of Work | |
| Contact for Routine Road Maintenance | Pt Ops 012 804 0044 |

| | |
|--------------------------------------|--|
| National Route | N4 (Platinum Toll Highway) |
| Section | Rustenburg to Brits (R512 Interchange) |
| Distance | 70 km |
| Description | Two-lane single carriageway freeway. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Motorists must be aware and be on the lookout for pedestrians and animals in the Bapong area. Adhere to posted speed limits. Road markings taking place. Expect narrowing of lanes |
| Duration of Work | |
| Contact for Routine Road Maintenance | Pt Ops 012 804 0044 |

| | |
|--|---|
| National Route | N4 – West Magalies |
| Section | Brits (R512 Interchange) to Hartebeesport |
| Distance | 8.8km |
| Description | Single Carriageway with gravel shoulders |
| Expected Road condition Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop 'n Go's between Broederstroom and Pampoennek until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|--------------------------------------|--|
| National Route | N4 (Platinum Toll Highway) |
| Section | Brits (R512 Interchange) to Pretoria (N1) |
| Distance | 52 km |
| Description | Two-lane dual carriageway freeway. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Road markings taking place. Expect narrowing of lanes Roadworks upgrade at the Doornpoort Plaza. |
| Duration of Work | |
| Contact for Routine Road Maintenance | Pt Ops 012 804 0044 |

| | |
|--------------------------------------|--|
| National Route | N4 West Magalies Toll Road |
| Section | Pretoria (Rebecca Street) to Pelindaba |
| Distance | 21 km |
| Description | Mixture of two-lane dual carriageway and two-lane single carriageway freeway. |
| Expected Road Condition | Good. |
| Expected Travel Condition | There are upgrades happening at both Quagga and Pelindaba Toll Plazas until mid-September 2015. Expect delays through these 2 plazas. Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Timothy Masalesa 076 349 4168 |
| National Route | N4 |
| Section | Pretoria to Hans Strydom Interchange |
| Distance | 13.6 km |
| Description | A 6-lane dual carriageway road up to Simon Vermooten Interchange, thereafter a 4-lane dual carriage way. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Be alert of hijackers at Townland offramp. Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|--------------------------------------|---|
| National Route | N4 |
| Section | Hans Strydom Interchange to Mozambique |
| Distance | 304 km |
| Description | Four-lane dual carriageway from Hans Strydom Int. to Van Dyk's Drift. Thereafter, a four-lane undivided road to Wonderfontein, then 2 lanes undivided to the Mozambique border. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Road Rehabilitation between Middelburg and Wonderfontein Cross Roads and Waterval Onder (Expect 15-20 min stop n go). Wilge River I/C and Balmoral / Kusile I/C |
| Duration of Work | |
| Contact for Routine Road Maintenance | Trans African Concessionaires (TRAC) 013 755 3316 |

| | |
|--------------------------------------|---|
| National Route | N4 |
| Section | 3Y Ellen street to Middelburg |
| Distance | 21.09km |
| Description | Single carriageway with gravel shoulders |
| Expected Road Condition | Fair to satisfactory. Poor road markings. Road go through residential area with entrances both sides of the road. Shoulders in bad state both sides of the road Be alert of coal trucks |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|---|---|
| National Route | N4 |
| Section | Nelspruit: Valencia Road to N4 |
| Distance | 8.6km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition Expected Road Condition | Surfacing Fair to Good. |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|---|
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Andrie Van Niekerk 076 481 5276 |

N5

| | |
|--------------------------------------|---|
| National Route | N5 |
| Section | Harrismith to Bethlehem |
| Distance | 88 km |
| Description | A two-lane single carriageway with wide paved shoulders. There are overtaking opportunities where severe grades occur. |
| Expected Road Condition | Good. |
| Expected Travel Condition | A contract for the upgrade of the N5 between Harrismith and Industriqwa, including construction of an interchange at Murray Street, is in progress. No Stop/Go Controls will be in place. |
| Duration of Work | Until January 2018 |
| Contact for Routine Road Maintenance | Gert de Lange 079 162 2981 (Route Manager) |

| | |
|--------------------------------------|---|
| National Route | N5 |
| Section | Bethlehem to Winburg |
| Distance | 120 km |
| Description | A two-lane single carriageway with varying width of either paved or gravel shoulders. There are overtaking opportunities where severe grades occur. |
| Expected Road Condition | Fair to good |
| Expected Travel Condition | Maintenance crews will be active with occasional localised Stop/Go controls for asphalt patching work, between Bethlehem and Winburg. |
| Duration of Work | Maintenance crews are continuously active. |
| Contact for Routine Road Maintenance | Gert de Lange 079 162 2981 (Route Manager) |

N6

| | |
|--------------------------------------|--|
| National Route | N6 |
| Section | East London to Stutterheim |
| Distance | 70 km |
| Description | A two-lane single carriageway with paved shoulders and passing lanes in places |
| Expected Travel Condition | Fair to good |
| Contact for Routine Road Maintenance | Flip Jacobs 082 563 5218 |

| | |
|--------------------------------------|--|
| National Route | N6 |
| Section | Stutterheim to Cathcart |
| Distance | 49 km |
| Description | A two-lane single carriageway with paved shoulders and passing lanes in places. Busy with line markings and cleaning up. |
| Expected Travel Condition | Good. |
| Contact for Routine Road Maintenance | Flip Jacobs 082 563 5218 Christo Muller 082 491 2166 |

| | |
|--------------------------------------|---|
| National Route | N6 |
| Section | Cathcart to Queenstown |
| Distance | 59 km |
| Description | A two-lane single carriageway with paved shoulders and passing lanes in places. |
| Expected Travel Condition | Completed |
| Expected Travel Condition | Fair to Good |
| Contact for Routine Road Maintenance | Flip Jacobs 082 563 5218 |

| | |
|--------------------------------------|---|
| National Route | N6 |
| Section | Queenstown to Jamestown |
| Distance | 107km |
| Description | A two lane single carriage way with paved shoulders |
| Expected Travel Condition | Good |
| Duration of Work | |
| Contact for Routine Road Maintenance | Flip Jacobs 0825635218 |
| Expected Travel Condition | |

| | |
|--------------------------------------|---|
| National Route | N6 |
| Section | Jamestown to Aliwal North |
| Distance | 58 km |
| Description | A two-lane single carriageway with paved shoulders. |
| Expected Travel Condition | Good |
| Contact for Routine Road Maintenance | Flip Jacobs 082 563 5218 |
| Expected Travel Condition | |

| | |
|--------------------------------------|---|
| National Route | N6 |
| Section | Aliwal North to Bloemfontein |
| Distance | 200 km |
| Description | Predominantly, a two- lane single carriageway with only the last 2.36km of National Route 6 having wide paved shoulders. The rest of the route has gravel shoulders of varying widths. |
| Expected Road Condition | The road between Rouxville and Smithfield is in a fair condition with some pavement repair teams working ad hoc. The road between Paryshoogte and Bloemfontein is in a good condition. |
| Expected Travel Condition | 1. There are pavement repair teams working ad hoc between Rouxville and Smithfield. 2. A contract for the periodic maintenance of the N6 between Reddersburg and Rustfontein commenced in November 2016. Traffic will be accommodated by Stop/Go controls. |
| Duration of Work | 1. Teams working ad hoc. 2. Until September 2017. |
| Contact for Routine Road Maintenance | Johnny Rodgers 082 772 9804 |

N7

| | |
|--------------------------------------|---|
| National Route | N7 |
| Section | Melkbos Turn-off to Clanwilliam |
| Distance | 198 km |
| Description | Dual carriageway with paved shoulders |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Jerome Buys 082 328 9422 |
| Construction Works: | <p>Atlantis Turn-off to Abbotsdale The speed limit throughout the construction area has been lowered to 40 - 60km/h and to be adhered to.</p> <p>Motorist can encounter no day & night Stop/Go closures at this stage.</p> <p>Abbotsdale to Voortrekker Road Interchange (Malmesbury) The speed limit throughout the construction area has been lowered to 40 – 60km/h and to be adhered to.</p> <p>Dual Carriageway North of Darling Road Interchange has been closed and traffic on the South Bound carriageway has been diverted onto the North Bound carriageway at a point halfway between the Voortrekker and Darling road interchanges. Two way traffic is currently accommodated on the North Bound carriageway over the full 4km extent of the project.</p> <p>A dedicated lane for heavy vehicles to stop and engage lowest gear has been introduced on the Southbound carriageway just prior to the traffic diversion referred to above. The speed regulation has been lowered from 80km/h to 60km/h and winding curves have been introduced as a traffic calming mechanism.</p> <p>All off ramps remain functional but slightly hidden/obscured and the public are therefore requested to drive slowly and be alert to the directional signage provided at the off ramps. Some confusion exists for traffic approaching from the North, driving toward Cape Town, who tend to overlook the right hand diversion to Cape Town (N7 continuation).</p> <p>Road and Bridge construction activities are taking place extensively in the interchange and are also consistent between the 4km construction limits.</p> <p>Stop/Go control points are an exception (on the N7) and are generally operational only in the event of routine maintenance being carried out on the existing road surface.</p> <p>The public must be aware of slow moving heavy vehicles entering and exiting the roadway.</p> <p>Due to the urban environment many pedestrians can be expected to be crossing the road for which extra caution is necessary.</p> <p>Voortrekker Road Interchange (Malmesbury) to Hopefield Intersection</p> <p>The speed limit throughout the construction area has been lowered to 40 - 60km/h and to be adhered to.</p> <p>Duration of Work: July 2019</p> |

| | |
|--------------------------------------|---|
| National Route | N7 |
| Section | Clanwilliam to Western Cape /Northern Cape Border |
| Distance | 139.075 km |
| Description | Single carriageway with paved and / or gravel shoulders |
| Expected Road Condition | Fair |
| Expected Travel Condition | <p>Trawal - Klawer</p> <p>The speed limit throughout the construction area has been lowered to 40 - 60km/h and to be adhered to.</p> <p>Motorist can encounter day & night Stop/Go closures at the Olifants' River crossing until October 2017.</p> <p>Motorists must also be aware of slow moving heavy vehicles entering and exiting the roadway.</p> <p>Routine Road Maintenance teams may be encountered</p> |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Louis Burger 074 193 2978 |

| | |
|--------------------------------------|--|
| National Route | N7 Section 8 |
| Section | Northern Cape Border to Vioolsdrift |
| Distance | 412km |
| Description | Single carriageway with gravel shoulders and no passing lanes. Rest areas at regular intervals |
| Expected Travel Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Driaan Koegelenberg 071 683 5392 |

N8

| | |
|--------------------------------------|---|
| National Route | N8 |
| Section | Groblershoop to Kimberley |
| Distance | 285 km |
| Description | Single carriageway with paved shoulders. Stopping places are provided at regular intervals. |
| Expected Travel Condition | Fair. |
| Expected Travel Condition | Motorists should be alert to stray animals. The route is prone to Kudu buck in the roadway between dusk and dawn. Routine Road Maintenance Teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Pottie Potgieter 082 566 7301 |

| | |
|--------------------------------------|---|
| National Route | N8 |
| Section | Kimberley to Bloemfontein |
| Distance | 150 km |
| Description | Predominantly, a two-lane single carriageway. The 29 km section between Kimberley and Perdeberg has paved shoulders, while the final eight km immediately adjacent to Bloemfontein is a four – lane dual carriageway with wide paved shoulders. The remainder of the road has gravel shoulders. |
| Expected Road Condition | Fair |
| Expected Travel Condition | A contract for periodic maintenance between De Brug Farm and Petrusburg is in progress. Traffic is accommodated by Stop/Go controls. |
| Duration of Work | Until July 2017 |
| Contact for Routine Road Maintenance | Riaan Louwrens 074 601 8998 |

| | |
|--------------------------------------|--|
| National Route | N8 |
| Section | Bloemfontein to Maseru |
| Distance | 135 Km |
| Description | The first five km section from Bloemfontein is a four-lane dual carriageway with wide paved shoulders. Between Bloemfontein and Thaba Nchu there are alternating passing and passing lanes. Between Thaba Nchu and Ladybrand is a two-lane single carriageway road with shoulders of varying widths. Route 26/N8-13 (km 0.0) to Maseru Border (km 11.75) is in good condition. |
| Expected Road Condition | Good |
| Expected Travel Condition | <ol style="list-style-type: none"> 1. Rehabilitation work is in progress on Section 11 between Bloemspruit (km 7.0) and Sannaspos (km 31.3). Motorists will encounter reduced speed limits with bi-directional traffic accommodation. 2. A contract for the periodic maintenance between Ladybrand and the Maseru Border commenced in January 2017. 3. A contract for the construction of a crawler lane between km 8.2 and km 11.04 towards Maseru adjacent to the N8 commenced in January 2017. |
| Duration of Work | <ol style="list-style-type: none"> 1. Completion date is June 2017. 2. Until end June 2017. 3. Until end October 2017. |
| Contact for Routine Road Maintenance | Johnny Rodgers 082 772 9804 |

N9

| | |
|--------------------------------------|---|
| National Route | N9 |
| Section | Western Cape and Eastern Cape Boundary to Aberdeen |
| Distance | 138 km |
| Description | A two-lane single carriageway with gravel shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. |
| Contact for Routine Road Maintenance | Elandre van Eck 071 679 1349 |

| | |
|--------------------------------------|--|
| National Route | N9 |
| Section | Aberdeen to Graaff Reinet |
| Distance | 54 km |
| Description | A two-lane single carriageway with paved shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Reseal activities taking place on the road. Stop/Go's can be encountered till July 2017. |
| Duration of Work | |
| Contact for Routine Road Maintenance | Elandre van Eck 071 679 1349 |
| Contact for Construction: | Stephen Gerber 082 378 6196 |

| | |
|-------------------------------|--|
| National Route | N9 |
| Section | Graaff-Reinet to Middelburg |
| Distance | 105 km |
| Description | A Two-Lane single carriageway with paved shoulders |
| Expected Travel Condition | Good. |
| Expected Travel Condition | No construction. Routine road maintenance. |
| Contact for construction work | Elandre van Eck 071 679 1349 |

| | |
|--------------------------------------|---|
| National Route | N9 |
| Section | Middelburg to the intersection of the N10 and N9 between Middelburg and Noupoort (Carlton Heights) |
| Distance | 24 km |
| Description | In construction |
| Expected Travel Condition | Busy with construction. |
| Expected Travel Condition | Construction works have commenced and will continue for 1 year. Traffic will be diverted through Middelburg town for first 6km and temporary short terms closures during blasting period. |
| Duration of work | 13 April 2015 to 13 August 2018 |
| Resident Engineer | Sam Renny 083 799 3638 |
| Contact for Routine Road Maintenance | Elandre van Eck 071 679 1349 |

| | |
|--------------------------------------|---|
| National Route | N9 |
| Section | Carlton Heights to Colesburg |
| Distance | 70 km |
| Description | Single carriageway with paved shoulders and passing lanes. Rest areas at regular intervals. |
| Expected Travel Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Martiens du Plessis 083 655 0644 |

N10

| | |
|--------------------------------------|--|
| National Route | N10 |
| Section | Nanaga-Paterson |
| Distance | 24 km |
| Description | Two lane single carriageway road. Some passing lanes |
| Expected Travel Condition | Good |
| Contact for Routine Road Maintenance | Marco du Plessis 079 893 6256 |

| | |
|--------------------------------------|--|
| National Route | N10 |
| Section | Paterson – Olifantskop Pass |
| Distance | 23 km |
| Description | Two lane single carriageway road. Some passing lanes in pass |
| Expected Travel Condition | Good |
| Duration of work | |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Marco du Plessis 079 893 6256 |

| | |
|--------------------------------------|---|
| National Route | N10 |
| Section | Jaskraal to Baviaans River |
| Distance | 43 km |
| Description | Two lane single carriageway road with paved shoulders |
| Duration of work | Complete |
| Expected Travel Condition | Good |
| Contact for Routine Road Maintenance | Marco du Plessis 079 893 6256 |

| | |
|--------------------------------------|--|
| National Route | N10 |
| Section | Olifanskop Pass to Baviaans River north of Cookhouse |
| Distance | 134 km |
| Description | Complete |
| Expected Travel Condition | Good |
| Contact for routine Road Maintenance | Marco Du Plessis 079 893 6256 |

| | |
|--------------------------------------|--|
| National Route | N10 |
| Section | Baviaans River to Riet River |
| Distance | 25 km |
| Description | Two-lane single carriageway. |
| Expected Travel Condition | Good |
| Expected Travel Condition | The upgrade contract for this section of the road is complete. |
| Contact for Routine Road Maintenance | Marco du Plessis 079 893 6256 |

| | |
|--------------------------------------|--|
| National Route | N10 |
| Section | Riet River to Tarka River |
| Distance | 37 km |
| Description | Two-lane single carriageway with narrow paved shoulders. There is 1 stop/go control in place. Expect delays of at least 15 minutes. Deviations in bad condition and narrow, motorists to travel with caution. |
| Expected Travel Condition | Under construction for 2 years. Scheduled for completion in December 2016. |
| Residednt Engineer | Johan Knoetze 0824174778 |
| Contact for Routine Road Maintenance | Marco du Plessis 079 893 6256 |

| | |
|--------------------------------------|--|
| National Route | N10 |
| Section | Cradock to Middelburg |
| Distance | 95 km |
| Description | The first 43 km is a two-lane single carriageway road with wide paved shoulders. The last 30 km is a two-lane single carriageway road with gravel shoulders. |
| Expected Travel Condition | Fair. |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Marco du Plessis 079 893 6256 |

| | |
|--------------------------------------|---|
| National Route | N10 |
| Section | Ludlow (Intersection of the N10 and N9 between Middelburg and Noupoort) to Prieska |
| Distance | 300 km |
| Description | Single carriageway with paved and/ or gravel shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | De Aar to Prieska Construction work is complete, however road-marking is still to take place. No road closures are expected. The public is to adhere to the applicable speed limits Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Milton van Heerden 083 362 9707 |

| | |
|--------------------------------------|---|
| National Route | N10 |
| Section | Prieska to Nakop (at Namibian Border) |
| Distance | 379 km |
| Description | Single carriageway with paved and / or gravel shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | Prieska to Groblershoop Construction work is complete, however road-marking is still to take place. No road closures are expected. The public is to adhere to the rappable speed limits Groblershoop to Upington The speed limit throughout the construction area has been lowered to 40 – 60km and to be adhered to. Construction work consist of widening and improvement of roads and bridges. Road closures are to be expected. Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Mzo Ntebe 079 017 9353 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

N11

| | |
|--------------------------------------|--|
| National Route | N11 |
| Section | N3 Bergville Interchange to Newcastle |
| Distance | 115 km |
| Description | A two-lane single carriageway with narrow shoulders, except for the 16 km portion before Newcastle and for short sections through the Biggarsberg Mountain range, where there are passing lanes. |
| Expected Road Condition | Variable, generally good. |
| Expected Travel Condition | No construction work |
| Duration of Work | |
| Contact for Routine Road Maintenance | Ms Asanda Koti 079 151 2451 |

| | |
|--------------------------------------|--|
| National Route | N11 |
| Section | Newcastle to Volksrust |
| Distance | 54 km |
| Description | Apart from the 9 km that constitute the Newcastle Bypass and the 17 km that make up the Laingsnek (Majuba) Mountain Pass, the road is a single carriageway, with narrow paved shoulders. |
| Expected Road Condition | Fair to good |
| Expected Travel Condition | A contract for the periodic maintenance of the N11 between Kwaggasnek and Volksrust has commenced. Traffic is accommodated by Stop/Go controls. |
| Duration of Work | Until July 2017 |
| Contact for Routine Road Maintenance | Ms Asanda Koti 079 151 2451 |

| | |
|--------------------------------------|---|
| National Route | N11 |
| Section | Volksrust to Amersfoort |
| Distance | 42.58 km |
| Description | Single carriageway road with passing lanes and paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|--|
| National Route | N11 |
| Section | Amersfoort to Msukaligwa Municipal Border / Vaal River |
| Distance | 27.88km |
| Description | Single carriageway road with passing lanes and paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Motorist should also be alert of stray animals North of Amersfoort km 0.8-3.0 Motorist should be alert of the vast quantity of coal trucks from Vaal River to Amersfoort |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|---|
| National Route | N11 |
| Section | Msukaligwa Municipal border / Vaal River to Ermelo |
| Distance | 29.85km |
| Description | Single carriageway road with passing lanes and paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Vaal River to Ermelo |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|---|
| National Route | N11 |
| Section | Ermelo to Hendrina |
| Distance | 51.10km |
| Description | Single carriageway road with passing lanes and paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Hendrina to Ermelo |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|--|
| National Route | N11 |
| Section | Hendrina to Middelburg –N4 Interchange |
| Distance | 41.97km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Road Marking faded at Woestalleen km 26 Motorist should be alert to the vast quantity of coal trucks from Hendrina to Middelburg |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|---|
| National Route | N11 |
| Section | Middelburg to Loskop |
| Distance | 81.030km |
| Description | Single carriageway with gravel shoulders |
| Expected Road Condition | Fair to Good. Damwall poor road marking High accident zone (Kranspoort mountain pass) km 36 Construction at Kranspoort Pass until December 2017 Expect up to 90 minute delays on Monday and Friday, from 09h00 to 16h30. On Tuesday, Wednesday and Thursday the pass will be closed from 11h00 to 15h00. Saturday and Sunday the pass will be open except for the normal stop go delays. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|--------------------------------------|---|
| National Route | N11 |
| Section | Loskop to Mookgopong Municipal Border |
| Distance | 44.3km |
| Description | Single carriageway with gravel shoulders |
| Expected Road Condition | Fair to Good. Poor road marking |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|--------------------------------------|--|
| National Route | N11 |
| Section | Mookgopong Municipal Border to Mokopane Weigh Bridge / N1/25X Intersection |
| Distance | 89.04km |
| Description | Single carriageway |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Wandile Jiyane 076 886 9997 |

| | |
|--------------------------------------|---|
| National Route | N11 |
| Section | Mokopane to Martin's Drift border post (Botswana) |
| Distance | 188km |
| Description | Single carriageway |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Hannelie Swanepoel 082 380 5264 |

N12

| | |
|--------------------------------------|--|
| National Route | N12 |
| Section | Three Sisters to Hopetown |
| Distance | 299 km |
| Description | Single carriageway with paved shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | <p>Orange River to Hopetown The speed limit throughout the construction area has been lowered to 40 – 60km and to be adhered to.</p> <p>Construction work consist of widening and improvement of roads and bridges. Road closures are to be expected.</p> <p>Routine road maintenance teams may be encountered.</p> |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Charl Muishond 072 746 9827 |

| | |
|--------------------------------------|---|
| National Route | N12 |
| Section | Hopetown to Northern Cape Border at Warrenton |
| Distance | 203 km |
| Description | Single carriageway with paved shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | <p>Hopetown to Voetpaddrift The speed limit throughout the construction area has been lowered to 40 – 60 km and to be adhered to.</p> <p>Construction work consist of resurfacing the road. Road closures could still be expected at this stage.</p> <p>Routine Road Maintenance teams may be encountered.</p> |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Zandile Gaba 082 550 9083 |

| | |
|--------------------------------------|--|
| National Route | N12 |
| Section | North West / Northern Cape Border at Warrenton to Christiana |
| Distance | 28.8 km |
| Description | Two-lane single carriageway with paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | N12 |
| Section | Christiana to Bloemhof |
| Distance | 57.9 km |
| Description | Two-lane single carriageway with paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | N12 |
| Section | Bloemhof to Wolmaranstad |
| Distance | 62.2 km |
| Description | Two-lane single carriageway with paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|--|
| National Route | N12 |
| Section | Wolmaransstad to Klerksdorp |
| Distance | 75 km |
| Description | Two-lane single carriageway with wide paved shoulders on most of the section, except closer to Klerksdorp. |
| Expected Road Condition | Good to very good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | N12 |
| Section | Klerksdorp to Potchefstroom |
| Distance | 38.8km |
| Description | Two-lane narrow double carriageway with gravel shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Road closed between Klerksdorp and Stilfontein due to a sink hole within the road reserve. Please follow the detour road signs |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|--|
| National Route | N12 |
| Section | Potchefstroom to Westonoria Municipal Border |
| Distance | 57.4 km |
| Description | Two-lane narrow single carriageway with passing lanes. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | N12 |
| Section | Diepkloof Interchange to Elands Interchange |
| Distance | 17.2km |
| Description | Four-lane dual carriageway freeway. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Pierre Coetzer 076 107 7322 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|---|
| National Route | N12 |
| Section | Gilloolly's Interchange to Mpumalanga / Gauteng Border |
| Distance | 41km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Road Condition | Routine Road Maintenance teams may be encountered |
| Expected Travel Condition | Good. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746 |

N14

| | |
|--------------------------------------|--|
| National Route | N14 |
| Section | Springbok to Keimoes |
| Distance | 335 km |
| Description | Single carriageway with paved / gravel shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Claudia Jannetjies 078 675 8971 |

| | |
|--------------------------------------|--|
| National Route | N14 |
| Section | Keimoes to Western Cape / Northern Cape Border |
| Distance | 303 km |
| Description | Single carriageway with paved shoulders. |
| Expected Travel Condition | Good. |
| Expected Travel Condition | Upington to Kuruman Construction is ongoing at the Olifantsloop River Bridges and Sishen River Bridge Motorist are requested to adhere to the speed limit and cross the bridges at the indicated reduced speeds to ensure the safety of all road users. Olifantshoek bridge closed for abnormal loads. Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Peet van Wyk 082 406 6371 |

| | |
|--------------------------------------|---|
| National Route | N14 |
| Section | Northern Cape / North West Border to Vryburg |
| Distance | 86 km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition: | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Samu Ndlovu 079 563 4564 |

| | |
|--------------------------------------|---|
| National Route | N14 |
| Section | From Junction at R34 & N14 Section 9 to Junction at N18 in Vryburg |
| Distance | 6 km |
| Description | A two-lane carriageway with concrete kerbing through town up to N18 crossing. |
| Expected Road Condition | Poor to Fair. |
| Expected Travel Condition | Constant pothole & pavement layer failure repairs attended to by RRM team |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Samu Ndlovu 079 563 4564 |

| | |
|--------------------------------------|---|
| National Route | N14 |
| Section | Vryburg to Delareyville |
| Distance | 76 km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Willem – Erik Jacobson 076 148 0321 |

| | |
|--------------------------------------|---|
| National Route | N14 |
| Section | Delareyville to Sannieshof |
| Distance | 37.6 km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to poor. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Willem – Erik Jacobson 076 148 0321 |

| | |
|--------------------------------------|---|
| National Route | N14 |
| Section | Sannieshof to Coligny |
| Distance | 61.9 km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Willem – Erik Jacobson 076 148 0321 |

| | |
|--------------------------------------|---|
| National Route | N14 |
| Section | Coligny to Ventersdorp |
| Distance | 68.8 km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Willem – Erik Jacobson 076 148 0321 |

| | |
|--------------------------------------|---|
| National Route | N14 |
| Section | Ventersdorp to North West / Gauteng Border |
| Distance | 49.7km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Willem – Erik Jacobson 076 148 0321 |

N17

| | |
|--------------------------------------|---|
| National Route | N17 |
| Section | Soweto to Nasrec |
| Distance | 6 km |
| Description | Double carriageway road with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Unita Fugile 072 793 2825 |

| | |
|--------------------------------------|--|
| National Route | N17 |
| Section | Wemmerpan to Geldenhuys Interchange |
| Distance | 7.8 km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Unita Fugile 072 793 2825 |

| | |
|--------------------------------------|---|
| National Route | N17 |
| Section | Geldenhuys Interchange to Springs |
| Distance | 38.8Km |
| Description | Multi lane dual carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Unita Fugile 072 793 2825 |

| | |
|--------------------------------------|---|
| National Route | N17 |
| Section | Springs to Leandra Toll |
| Distance | 40.2 km |
| Description | Single carriageway with passing lanes and gravel shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Motorists should be alert to stray animals north of Leandra Toll Plaza |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 072 647 8142 |

| | |
|--------------------------------------|--|
| National Route | N17 |
| Section | Leandra Toll to Bethal |
| Distance | 72.2 km |
| Description | Single carriageway with passing lanes and paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Motorists should be alert to stray animals north of Leandra Toll Plaza. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 072 647 8142 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|--|
| National Route | N17 |
| Section | Bethal to Ermelo |
| Distance | 55.72 km |
| Description | Single carriageway with passing lanes and paved shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 072 647 8142 |

| | |
|--------------------------------------|---|
| National Route | N17 |
| Section | Ermelo to Oshoek Border Post (Swaziland) |
| Distance | 122.64km |
| Description | Two lane single carriageway with gravel shoulders |
| Expected Road Condition | Poor |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 079 882 1193 |

N18

| | |
|--------------------------------------|--|
| National Route | N18 (R49) |
| Section | Warrenton to Hartswater North / North West Border |
| Distance | 52 km |
| Description | Single carriageway with paved shoulders |
| Expected Travel Condition | Good |
| Expected Travel Condition | Routine Road Maintenance Teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Zandile Gaba 082 550 9083 |

| | |
|--------------------------------------|--|
| National Route | N18 |
| Section | Northern Cape / North West Border South of Taung to Pudimore |
| Distance | 27.54km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Beware of stray animals |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Samu Ndlovu 079 563 4564 |

| | |
|--------------------------------------|--|
| National Route | N18 |
| Section | Pudimore to Vryburg |
| Distance | 48.62 km |
| Description | Single carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Beware of stray animals |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Samu Ndlovu 079 563 4564 |

| | |
|--------------------------------------|---|
| National Route | N18 |
| Section | Vryburg to Stella |
| Distance | 47.44 km |
| Description | Single carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Manie Du Preez 083 262 0242 |

| | |
|--------------------------------------|--|
| National Route | N18 |
| Section | Stella to R375 Intersection |
| Distance | 65 km |
| Description | Single carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Manie Du Preez 083 262 0242 |

| | |
|--------------------------------------|---|
| National Route | N18 |
| Section | R375 Intersection to Mahikeng |
| Distance | 65 km |
| Description | Single carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Manie Du Preez 083 262 0242 |

| | |
|--------------------------------------|---|
| National Route | N18 |
| Section | Mahikeng to Ramatlabama Border Post |
| Distance | 17.019km |
| Description | Single carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Manie Du Preez 083 262 0242 |

OTHER NATIONAL ROUTES

| | |
|--------------------------------------|---|
| National Route | D157 |
| Section | Groblersdal to Hlogotlou |
| Distance | 38.882 km |
| Description | Two lane single carriageway with no paved shoulders |
| Expected Road Condition | Fair |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Maxwell Baloyi 078 972 4445 |

| | |
|---------------------------------|--|
| National Route | D797 |
| Section | One Tree Hill to Tonga |
| Distance | 27.508 km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Fair with uneven riding surface. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Johan Van Niekerk 082 882 9819 |

| | |
|---------------------------------|--|
| National Route | D1120 |
| Section | Komatipoort to Crocodile Bridge Gate |
| Distance | 8.942 km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Johan Van Niekerk 082 882 9819 |

| | |
|---------------------------------|--|
| National Route | D2948 |
| Section | D797 Tonga to Emangweni |
| Distance | 10.196 km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Johan Van Niekerk 082 882 9819 |

| | |
|--------------------------------------|---|
| National Route | P154 |
| Section | 7 |
| Distance | 3.84km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Surfacing Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Koos Beukes 072 444 5742 |

| | |
|--------------------------------------|--|
| National Route | P720 |
| Section | N2 to Golela Border Post with Swaziland |
| Distance | 10 km |
| Description | A Single carriageway road between National Route 2 and Golela Border Post. Two lanes and a narrow paved shoulder and wide gravel shoulder in each direction. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of work | |
| Contact for Routine Road Maintenance | Gonie Govender 084 466 2198 |

| | |
|--------------------------------------|---|
| National Route | R21 |
| Section | Northrand Rand to Olifantsfontein Interchange |
| Distance | 26km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746 |

| | |
|--------------------------------------|---|
| National Route | R21 |
| Section | Olifants Interchange to Hans Strydom Intersection |
| Distance | 18km |
| Description | Multi-lane dual carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746 |

| | |
|--------------------------------------|--|
| National Route | R22 |
| Section | Hluhluwe to Farazela (RSA/Mozambique border) |
| Distance | 175 km |
| Description | A 2-lane single carriageway road with narrow paved shoulders throughout. |
| Expected Road Condition | Good |
| Expected Travel Condition | 1. A periodic maintenance contract between Mseleni River and Phelendaba is ongoing. Temporary road surface and temporary line markings in place. 2. Two projects for the construction of walkways adjacent to the R22 between Phelendaba and Mozambique Border are ongoing. There is minimum disruption to traffic. |
| Duration of Work | 1. Until December 2017 2. Until November 2017 |
| Contact for Routine Road Maintenance | Gonie Govender 084 466 2198 |

| | |
|--------------------------------------|---|
| National Route | R23 |
| Section | Volksrust to Standerton |
| Distance | 78.4km |
| Description | Two-lane single carriageway with gravel shoulders |
| Expected Road Condition | Fairly Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Roadworks for the first 30 km. Expect stop and Go's |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Zachrys Joubert 072 123 4455 |

| | |
|--------------------------------------|--|
| National Route | R23 |
| Section | Standerton to Gauteng / Mpumalanga Border |
| Distance | 99.3 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered between km 0 up to km 4 and Km 56 up to km 86.4 during the day. Reconstruction projects are between Km 4 up to km 56 with permanent road closures at some areas. STOP/GO Reseal contract between Balfour and MP/GP border. Expect Stop 'n Go's. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Zachrys Joubert 072 123 4455 |

| | |
|--------------------------------------|---|
| National Route | R24 |
| Section | Rustenburg to Northwest/Gauteng Border |
| Distance | 45km |
| Description | Two lane double carriageway with paved shoulders between Buiten Street and Oorsak Road. The remaining section is a two lane carriageway with passing lanes through Olifantsnek Pass with gravel shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Reconstruction projects are between Buiten Street and Oorsak Road with permanent road closures at some areas |
| Duration of Work | Ends June 2017 |
| Contact for Routine Road Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|--------------------------------------|--|
| National Route | R27 |
| Section | Van Rhynsdorp to Brandvlei |
| Distance | 236 km |
| Description | Single carriageway road with 1 metre surfaced shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Jacques Wentzel 079 514 3496 |

| | |
|--------------------------------------|--|
| National Route | R27 |
| Section | Brandvlei to Keimoes |
| Distance | 221 km |
| Description | Single carriageway road with paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Johannes Rakwena 082 304 6553 |

| | |
|--------------------------------------|---|
| National Route | R30/R730/R34 Toll Road |
| Section | Bloemfontein to Kroonstad via Brandfort/Welkom |
| Distance | 210 km |
| Description | A single carriageway between National Route N1 and Virginia. It accommodates two lanes and has wide paved shoulders and ad hoc passing lanes in each direction. The section between Virginia and Welkom is a double carriageway and the section between Welkom and Kroonstad is a four-lane undivided carriageway with paved shoulders. |
| Expected Road Condition | Good. |
| Expected Travel Condition | No construction |
| Duration of work | |
| Contact for Routine Road Maintenance | Abel Majorobela 079 896 3377 |

| | |
|--------------------------------------|---|
| National Route | R30 |
| Section | Free State / North West Border to Klerksdorp |
| Distance | 14.5 km |
| Description | Two-lane narrow single carriageway with gravelshoulders. |
| Expected Road Condition | Fair to Bad |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | R30 |
| Section | Klerksdorp to Ventersdorp |
| Distance | 68.8 km |
| Description | Two-lane narrow single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Bad |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|---------------------------------|--|
| National Route | R30 |
| Section | Ventersdorp to Olifants Nek |
| Distance | 76.6 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Fair with uneven riding surface. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Short stop/go's may occur from time to time |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Theuns Jooste 076 751 9898 |

| | |
|---------------------------------|---|
| National Route | R33 |
| Section | Kwazulu Natal / Mpumalanga Border to Piet Retief |
| Distance | 48.3 km |
| Description | A Two-lane single Carriageway narrow gravel shoulder. |
| Expected Road Condition | Good |
| Expected Travel Condition | Normal Maintenance on this section |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Faith Mogano 076 7790 346 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|---------------------------------|---|
| National Route | R33 |
| Section | Piet Retief to Amsterdam |
| Distance | 35.9 km |
| Description | A Two-lane single Carriageway narrow gravel shoulder. |
| Expected Road Condition | Good |
| Expected Travel Condition | Normal Maintenance on this section |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Faith Mogano 076 7790 346 |

| | |
|---------------------------------|---|
| National Route | R33 |
| Section | Amsterdam to Warberton |
| Distance | 88.54 km |
| Description | A two-lane single carriageway narrow gravel shoulder. |
| Expected Road Condition | Good |
| Expected Travel Condition | Normal Maintenance on this section |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Faith Mogano 076 7790 346 |

| | |
|--------------------------------------|---|
| National Route | R33 |
| Section | Warburton (from N17/5) to Carolina |
| Distance | 38km |
| Description | Two lane single carriageway with gravel shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 079 882 1193 |

| | |
|--------------------------------------|---|
| National Route | R33 |
| Section | Carolina to Belfast (N4) |
| Distance | 49.2km |
| Description | Two lane single carriageway with gravel shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 079 882 1193 |

| | |
|--------------------------------------|---|
| National Route | R33 |
| Section | N11 – Marble Hall to Modimolle R101 |
| Distance | 88.3 km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair with poor road markings. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gustav Fouche 082 780 2391 |

| | |
|--------------------------------------|---|
| National Route | R33 |
| Section | Vaalwater to Lephalale – R510 |
| Distance | 85.3 km |
| Description | Single carriageway with limited paved shoulders otherwise gravel shoulders. |
| Expected Road Condition | Fair to Good Km 0.0 – 85.3 poor road markings |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gustav fouche 082 780 2391 |

| | |
|--------------------------------------|--|
| National Route | R34 |
| Section | Vryburg to Schweizer Reneke |
| Distance | 64.86 km |
| Description | First 3km a two lane carriageway with paved shoulders 2nd 30 km a two lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles |
| Expected Road Condition | Fair to poor, constant pothole & pavement layer failure repairs attending by RRM Teams, average travel time from 30 minutes to 40 minutes |
| Expected Travel Condition | Roadworks: Rehabilitation contract between Vryburg and Schweizer Reneke. Expect Stop 'n Go's. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Gerrit Mostert 079 492 8691 |

| | |
|--------------------------------------|--|
| National Route | R34 |
| Section | Schweizer Reneke to Bloemhof |
| Distance | 60 km |
| Description | First 34km a two lane carriageway with paved shoulders 2nd 31 km a two lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles |
| Expected Road Condition | Fair to poor |
| Expected Travel Condition | Constant pothole & pavement layer failure repairs attended to by RRM Teams Roadworks: Rehabilitation contract between Schweizer Reneke and Bloemhof. Expect Stop 'n Go's. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Dries Grundlingh 083 269 3029 |

| | |
|--------------------------------------|---|
| National Route | R34 |
| Section | Bloemhof to North West / Free State Border |
| Distance | 6.7 km |
| Description | Two lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles |
| Expected Road Condition | Fair to poor |
| Expected Travel Condition | Constant pothole & pavement layer failure repairs attended to by RRM Teams |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Dries Grundlingh 083 269 3029 |

| | |
|--------------------------------------|---|
| National Route | R35 |
| Section | Ameersfoort to Bethal |
| Distance | 76.57km |
| Description | |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Rehabilitation in progress from Amersfoort to Morgenzon No STOP/GO controls predicted Motorist should be alert to the vast quantity of coal trucks |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|--|
| National Route | R35 |
| Section | Bethal to Middelburg |
| Distance | 71.03km |
| Description | |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks Reseal contract between Komati and Middelburg. Expect Stop 'n Go's. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|---|
| National Route | R36 |
| Section | Mpumalanga Border to Dublin |
| Distance | 102.2km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Stop/Go traffic accommodation on the Abel Erasmus Pass section Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Marius Nel 073 538 5019 |

| | |
|--------------------------------------|---|
| National Route | R36 |
| Section | Dublin to Ofcolaco |
| Distance | 53.7km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Marius Nel 073 538 5019 |

| | |
|--------------------------------------|---|
| National Route | R36 |
| Section | Ofcolaco to Tzaneen |
| Distance | 33.5km |
| Description | Single carriageway y with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal works for 20km (Expect Stop and Go's) |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Marius Nel 073 538 5019 |

| | |
|--------------------------------------|---|
| National Route | R36 |
| Section | Tzaneen to Modjadjiskloof |
| Distance | 17.8km |
| Description | Km 2.3 to km 7.0 double carriageway. Km7 – 19.5 Single carriageway. Mostly paved shoulders. |
| Expected Road Condition | Surfacing Good. Line markings fair. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Stephan Du Plessis 084 491 1165 |

| | |
|--------------------------------------|--|
| National Route | R36 |
| Section | Modjadjiskloof - Soekmekaar |
| Distance | 44.43km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Stephan Du Plessis 084 491 1165 |

| | |
|--------------------------------------|--|
| National Route | R36 |
| Section | Soekmekaar - Bandelierkop |
| Distance | 17.8km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Stephan Du Plessis 084 491 1165 |

| | |
|--------------------------------------|---|
| National Route | R37 |
| Section | Polokwane Burgersfort |
| Distance | 142km |
| Description | Four lane dual carriageway from km 0 to km 12 & thereafter two lane single carriageway with no paved shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Nathanael Pillay 074 309 0937 |

| | |
|--------------------------------------|---|
| National Route | R37 |
| Section | Burgersfort to Lydenburg |
| Distance | 64 km |
| Description | Single carriageway road with paved shoulders. |
| Expected Road Condition | First km 5-48 fair condition. Patching complete Rest fair to good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered as well as STOP/GO on some sections |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Andrie Van Niekerk 076 481 5276 |

| | |
|--------------------------------------|--|
| National Route | R37 |
| Section | Lydenburg to Sabie |
| Distance | 43.94Km |
| Description | Single carriageway road with mostly paved shoulders. |
| Expected Road Condition | Fair to good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Andrie Van Niekerk 076 481 5276 |

| | |
|--------------------------------------|---|
| National Route | R37 |
| Section | Sabie to Nelspruit |
| Distance | 49.20km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Contact for Routine Road Maintenance | Andrie Van Niekerk 076 481 5276 |

| | |
|--------------------------------------|---|
| National Route | R38 |
| Section | Bethal to Hendrina |
| Distance | 43km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Tankiso Makhele 071 615 1503 |

| | |
|--------------------------------------|---|
| National Route | R38 |
| Section | Hendrina to Carolina |
| Distance | 42.9km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 079 882 1193 |

| | |
|--------------------------------------|---|
| National Route | R38 |
| Section | Carolina to Badplaas |
| Distance | 52.8km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 079 882 1193 |

| | |
|--------------------------------------|---|
| National Route | R38 |
| Section | Badplaas to Barberton R40) |
| Distance | 59km |
| Description | Two lane single carriageway with gravel shoulders |
| Expected Road Condition | Good, recently resealed |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Christoph Botha 079 882 1193 |

| | |
|--------------------------------------|---|
| National Route | R40 |
| Section | Barberton to Nelspruit |
| Distance | 32.77km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Andrie Van Niekerk 076 481 5276 |

| | |
|--------------------------------------|--|
| National Route | R40 |
| Section | White River to Hazyview |
| Distance | 48.7 |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Andrie Van Niekerk 076 481 5276 |

| | |
|--------------------------------------|--|
| National Route | R40 |
| Section | Klaserie to Hoedspruit |
| Distance | 26.79km |
| Description | Single carriageway with gravel shoulders |
| Expected Road Condition | Surfacing Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Wild animals may be encountered. |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Wessel Schalkwyk 082 371 3285 |

| | |
|--------------------------------------|---|
| National Route | R40 |
| Section | Hoedspruit to Mica |
| Distance | 32.20km |
| Description | Single carriageway with limited paved shoulders, otherwise gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Wild animals may be encountered. |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Wessel Schalkwyk 082 371 3285 |

| | |
|--------------------------------------|---|
| National Route | R40 |
| Section | Mica to Junction with R71 west of Phalaborwa |
| Distance | 36.8km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Poor. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Wild animals may be encountered. |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Wessel Schalkwyk 082 371 3285 |

| | |
|--------------------------------------|--|
| National Route | R49 |
| Section | Mafikeng to Zeerust |
| Distance | 61 km |
| Description | A two lane single carriageway with paved shoulders |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Roadworks: Reseal contract between Mafikeng and Zeerust. Expect Stop 'n Go's. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Gerrit Mostert 079 492 8691 |

| | |
|--------------------------------------|---|
| National Route | R49 |
| Section | Zeerust to Kopfontein Border Botswana (P87/1) |
| Distance | 98.8km |
| Description | A two-lane single carriageway with gravel shoulders |
| Expected Road Condition | Fair with isolated potholes, base & surface repairs from time to time. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Roadworks: Reseal contract between Zeerust and Kopfontein Border. Expect Stop 'n Go's. |
| Duration of work | Routine Maintenance Ongoing |
| Contact for Routine Road Maintenance | Gerrit Mostert 079 492 8691 |

| | |
|--------------------------------------|---|
| National Route | R52 |
| Section | Biesiesvlei to Lichtenburg |
| Distance | 36.6km |
| Description | Two-lane single carriageway with gravel shoulders |
| Expected Road Condition | Fair with uneven riding surfaces |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Theuns Jooste 076 751 9898 |

| | |
|---------------------------------|--|
| National Route | R52 |
| Section | Koster to Rustenburg |
| Distance | 38.7 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|--------------------------------------|--|
| National Route | R53 |
| Section | Parys to Potchefstroom |
| Distance | 44.7 km |
| Description | Two-lane narrow single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Bad |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Roadworks. Expect stop and Go's |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|--|
| National Route | R53 |
| Section | Potchefstroom to Ventersdorp |
| Distance | 58.5km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Very Poor to extremely Bad |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Roadworks. Expect stop and Go's |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | R54 |
| Section | Potchefstroom to Emfuleni Local Municipality Border |
| Distance | 42.60 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Bad |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | R56 |
| Section | 1, N9 Middleburg to Steynsburg |
| Distance | 85km |
| Description | Two lane single carriage way |
| Expected Road Condition | First 16km is in fair condition. Further, the condition is newly surfaced and good. |
| Expected Travel Condition | |
| Duration of work | |
| Contact for Routine Road Maintenance | Daniela Bosman 082 395 0875 |

| | |
|--------------------------------------|--------------------------------|
| National Route | R56 |
| Section | 2, Steynsburg to Molteno |
| Distance | 57km |
| Description | Two lane single carriage way |
| Expected Road Condition | Poor |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Daniela Bosman 082 395 0875 |

| | |
|--------------------------------------|--------------------------------|
| National Route | R56 |
| Section | 3, Molteno to N6 |
| Distance | 35km |
| Description | Two lane carriage way |
| Expected Road Condition | Fair |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Daniela Bosman 082 935 0875 |

| | |
|--------------------------------------|--------------------------------|
| National Route | R56 |
| Section | 4, N6 to Dordrecht |
| Distance | 35km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Daniela Bosman 082 935 0875 |

| | |
|--------------------------------------|--------------------------------|
| National Route | R56 |
| Section | 5, Dordrecht to Indwe |
| Distance | 38km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Daniela Bosman 082 935 0875 |

| | |
|--------------------------------------|---|
| National Route | R56 |
| Section | 6, Indwe to Elliot |
| Distance | 56km |
| Description | Two lane single carriage way |
| Expected Road Condition | Special maintenance project between Indwe via Elliot to Maclear for a period of 30 months as from February 2016 to August 2018. |
| Expected Travel Condition | Expect Stop/Go conditions with 20 minute delays. |
| Duration of work | 30 months, from Feb 2016 to August 2018. |
| Resident Engineer | Ian Posselt 084 585 5895 |
| Contact for Routine Road Maintenance | Daniela Bosman 082 935 0875 |

| | |
|--------------------------------------|---|
| National Route | R56 |
| Section | 7, Eliot to Maclear |
| Distance | 68km |
| Description | Two lane single carriage way |
| Expected Road Condition | Special maintenance project between Indwe via Elliot to Maclear for a period of 30 months as from February 2016 to August 2018. |
| Expected Travel Condition | Expect Stop/Go conditions with 20 minute delays. |
| Duration of work | 30 months. From Feb 2016 to August 2018. |
| Resident Engineer | Ian Posselt 084 585 5895 |
| Contact for Routine Road Maintenance | Vincent Gouws 082 300 7409 |

| | |
|--------------------------------------|---|
| National Route | R56 |
| Section | 8, Maclear to KZN Border |
| Distance | 168km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair. Construction is ongoing and should be completed by 31 May 2017. |
| Expected Travel Condition | Reseal between Maclear and Mount Fletcher started in January 2016. It is a 14 months contract – March 2017. There are stop/go conditions. |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Gouws 082 300 7409 |

| | |
|--------------------------------------|--------------------------------------|
| National Route | R56 |
| Section | 10, Matatiele to Eastern Cape Border |
| Distance | 37km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair to poor |
| Expected Travel Condition | |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Davis 082 553 4878 |

| | |
|--------------------------------------|---|
| National Route | R58 |
| Section | Section 2 from Km 33 – 58 Venterstad to Burgersdorp |
| Distance | 22km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair |
| Expected Travel Condition | Good. |
| Duration of work | Complete |
| Contact for Routine Road Maintenance | Happy Maduna 083 282 5256 |

| | |
|--------------------------------------|-----------------------------------|
| National Route | R58 |
| Section | 3, Burgersdorp to Aliwal North N6 |
| Distance | 55km |
| Description | Two lane single carriage way |
| Expected Road Condition | Good |
| Expected Travel Condition | |
| Duration of work | |
| Contact for Routine road maintenance | Happy Maduna 083 282 5256 |

| | |
|---------------------------|---------------------------------|
| National Route | R58 |
| Section | 4, Aliwal North N6 to Lady Grey |
| Distance | 49km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair |
| Expected Travel Condition | |
| Duration of work | Ongoing |
| Contact for construction | Happy Maduna 083 282 5256 |

| | |
|---------------------------|------------------------------|
| National Route | R58 |
| Section | 5, Lady Grey to Barkley East |
| Distance | 66km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair |
| Expected Travel Condition | |
| Duration of work | Ongoing |
| Contact for construction | Happy Maduna 083 282 5256 |

| | |
|--------------------------|------------------------------|
| National Route | R58 |
| Section | 6, Barkly East to Elliot |
| Distance | 62km |
| Description | Two lane single carriage way |
| Expected Road Condition | Fair |
| Duration of work | Ongoing |
| Contact for construction | Happy Maduna 083 282 5256 |

| | |
|--------------------------------------|---|
| National Route | R61 |
| Section | 1 (East Cape/West Cape Border to Aberdeen) |
| Distance | 74.5 km |
| Description | Narrow, single carriageway road with 2 lanes |
| Expected Travel Condition | Fair |
| Expected Travel Condition | No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. |
| Contact for Routine Road Maintenance | Elandre van Eck 071 679 1349 |

| | |
|--------------------------------------|--|
| National Route | R61 |
| Section | Bethesda (N9 Intersection) to Cradock (N10 Intersection)(section 2) |
| Distance | 85.8 km |
| Description | A narrow 2-lane single carriageway with gravel shoulders over most of the length. |
| Expected Travel Condition | Fair. Poor in places. |
| Duration of work | Phase 2: Km 43 to Km 85 (N10) commenced in March 2016 (Phase 2 construction period is 34 months) |
| Expected Travel Condition | Construction in place over 43km on the eastern half of this section. Km 43 to Km 85. No lines on this section. Proceed with care. Up to 3 stop/go's in operation. Please be patient and obey the traffic control operations. |
| Contact person for construction | Johan Pistorius 083 329 0060 |
| Contact for Routine Road Maintenance | Charmaine Diedreicks 079 893 7777 |

| | |
|--------------------------------------|---|
| National Route | R61 |
| Section | Cradock (N10 Intersection) to Tarkastad (section 3) |
| Distance | 74.5 km |
| Description | A narrow 2-lane single carriageway with gravel shoulders |
| Expected Travel Condition | 0-24km Fair 24-75km Fair to poor. |
| Expected Travel Condition | Construction over 27km, in the middle of this section, km 24 to 51, is now complete. Motorists to be aware of wild animals in rural areas and pedestrians in urban areas at Cradock and Tarkastad. Temporary closures for blasting can be anticipated. Construction on phase 2 will commence in July 2017, from km 51 to Tarkastad. |
| Duration of work | Construction period for phase 2 is 18 months. |
| Contact for Routine Road Maintenance | Charmaine Diedericks 079 893 7777 |

| | |
|--------------------------------------|---|
| National Route | R61 |
| Section | Tarkastad to Queenstown (section 4) |
| Distance | 63.1km |
| Description | A 2 lane single carriageway with surfaced shoulders. |
| Expected Travel Condition | Fair. Newly opened sections are in very good condition. |
| Contact for Routine Road Maintenance | Charmaine Diedericks 079 893 7777 |
| Contact for Construction Work | |

| | |
|--------------------------------------|--|
| National Route | R61 |
| Section | Queenstown (N6) to Cofimvaba (Section 5) |
| Distance | 60km |
| Description | A 2 Lane single carriageway with paved shoulders. |
| Expected Travel Condition | Motorists to be aware of pedestrians and stray animals. Motorists may encounter occasional short-terms closures on sections in this area due to maintenance repairs. |
| Expected Travel Condition | Route back to RRM for maintenance. |
| Contact for Construction works | |
| Contact for Routine Road Maintenance | Riaan Graaf 082 821 0175 |

| | |
|--------------------------------------|---|
| National Route | R61 |
| Section | Cofimvaba to Engcobo (Section 6) |
| Distance | 92 km |
| Description | Narrow 2 lane single carriageway with limited gravel shoulders. |
| Expected Travel Condition | Fair to good. |
| Expected Travel Condition | Motorists to be aware of pedestrians and stray animals. Construction works are in progress between Cogland to Baziya area. Between km 57 and km 68, and between All Saints and km 86 to Baziya km 12 (section 7) Reduced speeds and localised detours can be expected. Motorists may encounter occasional short term closures on short section in this area. Road may also be closed for short durations due to blasting operation. |
| Duration of Work | Sept 2017 (All Saints) |
| Contact for Routine Road Maintenance | Riaan Graaf (RRM) 082 821 0175 |
| Contact for Construction Work | Ian Cateley 082 921 5634 |

| | |
|--------------------------------------|---|
| National Route | R61 |
| Section | Engcobo to Mthatha (Section 7) |
| Distance | 49 km |
| Description | Narrow 2 lane single carriageway with limited gravel shoulders. |
| Expected Travel Condition | Fair to good |
| Expected Travel Condition | Motorists to be aware of pedestrian and stray animals. Construction works are in progress from the Baziya km12 to Mthatha Airport km39. Reduced speeds and localised detours can be expected. Motorists may encounter occasional short term closures on short section in this area. Road may also be closed for short durations due to blasting operation |
| Contact for Construction works | Adriaan Roets 083 265 2652 |
| Contact for Routine Road Maintenance | Riaan Graaf 082 821 0175 |

| | |
|--------------------------------------|--|
| National Route | R61 |
| Section | R61 Mthatha to Ngqeleni (Section 8) |
| Distance | 5.7km |
| Description | Construction of dual carriageway and bridges from Mthatha to Ngqeleni interchange. |
| Expected Travel Condition | 2 way traffic is being maintained. Completion June 2017. |
| Contact for Construction works | Vohan Swanepoel 082 782 7400 |
| Contact for Routine Road Maintenance | Riaan Graaf 082 821 0175 |

| | |
|--------------------------------------|--|
| National Route | R61 |
| Section | Mthatha to Port St Johns (Section 8) |
| Distance | 74 km |
| Description | A 2-lane single carriageway, with surfaced shoulders. |
| Expected Travel Condition | Fair. |
| Expected Travel Condition | Libode to Mngazi Upgrading of nine intersections. Reduced speed and localised bypasses/detours. Majola Tea to Tombo Construction works in progress between Majola Tea (km51) to Tombo (km66). Reduced speeds and localised detours can be expected. Motorists may encounter occasional short term closures on short sections in this area. The road may be closed for durations due to blasting operations. Stop/Go in operation towards Tombo. |
| Duration of work | |
| Contact for Routine Road Maintenance | Riaan Graaf (Routine road maintenance) 082 821 0175 |
| Contact for Construction works | Ben Swart 082 778 9953 (Ngqeleni Interchange) Thomas van Wyk de Vries 083 299 7231 (Majola Tea) (Libode to Mngazi) |

| | |
|--------------------------------------|---|
| National Route | R61 (Wild Coast) |
| Section | Ntafufu River to Lusikisiki (Section 9) |
| Distance | 18 Km |
| Description | Two-lane Single carriageway with Passing lanes |
| Expected Travel Condition | Good |
| Expected Travel Condition | Motorist to be aware of pedestrians and animals. The road is winding and motorists may encounter occasional short term closures on a short section for routine maintenance. |
| Duration | |
| Contact for Routine Road Maintenance | Riaan Graaf 082 821 0175 |
| Contact for Construction | |

| | |
|--------------------------------------|--|
| National Route | R61 |
| Section | Mtamvuna River (Provincial Boundary) to Port Shepstone |
| Distance | 45 km |
| Description | Two-lane single carriageway with passing lanes. |
| Expected Road Condition | Good. |
| Expected Travel Condition | A contract for the periodic maintenance of the R61 between Mbizana River and Port Shepstone commenced in November 2016. Restricted lane conditions with reduced speeds as signposted will apply. |
| Duration of work | Until November 2017 |
| Contact for Routine Road Maintenance | Amit Bhoora 082 442 9646 |

| | |
|--------------------------------------|---------------------------|
| National Route | R62 |
| Section | East Cape borders to N2 |
| Distance | 117km |
| Description | Single carriage road |
| Expected Travel Condition | Fair but narrow width |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Lauren Adams 073 311 1818 |

| | |
|---------------------------|---|
| National Route | R62/8 |
| Section | Kareedouw to N2 |
| Distance | |
| Description | Reseal project underway for the next 14 months. |
| Expected Travel Condition | Expect Stop/Go activities. |
| Resident Engineer | Mike Miler 083 974 2072 |

| | |
|--------------------------------------|--|
| National Route | R63 |
| Section | East Cape border to Graaff Reinet |
| Distance | 50km |
| Description | Single carriageway with gravel shoulders |
| Expected Travel Condition | Fair but narrow over most of the section. In wet weather, occasionally dislodged rocks can be found in the Oudeberg pass. Please drive with caution. |
| Expected Travel Condition | A section of this route runs through a National Park so watch out for game. |
| Contact for Routine Road Maintenance | Babalwa Mbandazayo 072 327 4045 |

| | |
|--------------------------------------|--|
| National Route | R63 |
| Section | N9 Graaff Reinet to R75 junction (to Pearston) |
| Distance | 23km |
| Description | Single carriageway with paved shoulders |
| Expected Travel Condition | Fair to Good |
| Expected Travel Condition | Contact for reseal is Rodney walters. Reseal project is underway. Road-marking in progress. |
| Contact for Routine Road Maintenance | Rodney Walters 081 713 9280 |

| | |
|--------------------------------------|---|
| National Route | R63 |
| Section | R75 to Pearston , Somerset East to N10 |
| Distance | 123km |
| Description | Two way single carriage way with gravel shoulders |
| Expected Travel Condition | Fair / Good |
| Expected Travel Condition | Good |
| Contact for Routine Road Maintenance | Johannes Nel 083 295 0606 |
| Contact for reseal contract | Dave Venter 079 516 3280 |

| | |
|--------------------------------------|--|
| National Route | R63 |
| Section | Pearston to Bruintjes Hoogte (Section 9 km 43 to Section 10 km 24.7) |
| Distance | |
| Description | Two way single carriage way with gravel shoulders |
| Expected Travel Condition | Fair / Good |
| Expected Travel Condition | |
| Contact for Routine Road Maintenance | Conrad Bezuidehout – 081 264 8063 Johannes Nel – 083 295 0606 |

| | |
|--------------------------------------|--|
| National Route | R63 |
| Section | N10 to Bedford |
| Distance | 78km |
| Description | Two way single carriage way with gravel shoulders. 4km section before Bedford in poor condition, reduce speed at km 16.9 – km 20.9 |
| Expected Travel Condition | Fair Good, except the 4km section before Bedford which is poor. |
| Expected Travel Condition | Fair |
| Contact for Routine Road Maintenance | Conrad Bezuidehout – 081 264 8063 Johannes Nel – 083 295 0606 |

| | |
|--------------------------------------|---|
| National Route | R63 |
| Section | Adelaide to Komga |
| Distance | 189km |
| Expected Travel Condition | Poor condition between Fort Beaufort and Alice and between Bhisho and Komga. |
| Expected Travel Condition | Two way single carriage way. Motorists may encounter occasional short closures by maintenance team. Between Fort Beaufort and Alice, repairs and uneven surfaces will be encountered. |
| Contact for Routine Road Maintenance | Odwa Ndlwana – 071 045 8203 |

| | |
|--------------------------------------|---|
| National Route | R67 |
| Section | Grahamstown to Fort Beaufort |
| Distance | 70.65km |
| Description | Two lane single carriageway with gravel shoulders (Narrow) 6.4m wide |
| Expected Travel Condition | Fair. Construction started on 11 January 2017 and will be in progress until November 2018. 22-month contract. Stop/go's can be encountered. |
| Expected Travel Condition | The road is winding, observe speed limit through ECCA Pass & beware of wild animals after dusk. |
| Contact for Routine Road Maintenance | Michael Coetzee 083 269 9026 |

| | |
|---------------------------|---|
| National Route | R67 |
| Section | Seymour to Whittlesea |
| Distance | 54,45km |
| Description | Two-lane single carriage with passing lane |
| Expected Travel Condition | Fair |
| Expected Travel Condition | Beware of pedestrian and animals observe speed limit though Nico Malan Pass. Stop/go conditions on this section. Currently doing line markings. Project should be completed by June 2017. |
| Contact for construction | Rudolph Pretorius 082 773 5780 |

| | |
|--------------------------------------|---|
| National Route | R67 |
| Section | Swart Kei to Queenstown |
| Distance | 33,36km |
| Description | Two way lane single carriageway with gravel shoulders |
| Expected Travel Condition | Fair to poor |
| Expected Travel Condition | Beware of pedestrian and animal crossing. |
| Contact for Routine Road Maintenance | Pieter Lombard 082 550 3852 |

| | |
|----------------|---|
| National Route | R71 |
| Section | Polokwane to Tzaneen |
| Distance | 86.04km |
| Description | Km 6.1 – 39.0, 88 – 92.14 Double carriageway. Km 35 – 88 Single carriageway Mostly paved shoulders. |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|--|
| Expected Road Condition | Surfacing Fair to Good. Mountain pass high accident zone (km 69 – 75) Dense Fog Area |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Stephan Du Plessis 084 491 1165 |

| | |
|--------------------------------------|---|
| National Route | R71 |
| Section | Tzaneen to Gravelotte |
| Distance | 55.18km |
| Description | Single carriageway with paved shoulders until Letsitele (km 30) from there mainly gravel shoulders. |
| Expected Road Condition | Surfacing Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Marius Nel 073 538 5019 |

| | |
|--------------------------------------|--|
| National Route | R71 |
| Section | Gravelotte to Phalaborwa Gate at Kruger National Park |
| Distance | 59.6km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Beware of stray animals between Selwane intersection and Lulekani |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Wessel Schalkwyk 082 371 3285 |

| | |
|--------------------------------------|---|
| National Route | R72 |
| Section | Nanaga to Alexandria |
| Distance | 50 km |
| Description | Two lane single carriageway with paved shoulders |
| Expected Road Condition | Good |
| Duration of work | |
| Contact for Routine Road Maintenance | Ian Smith 084 415 2002 |
| National Route | R72 |
| Section | Alexandra – Peddie turnoff. New Keiskamma rivers |
| Distance | 117km |
| Description | Two lane single carriageway with grave shoulders |
| Expected Road Condition | Fair but narrow width |
| Expected Travel Condition | Construction has commenced between Port Alfred and Fish River, where reduced speeds will apply. Construction of Bihra River to Open Shaw till 30 April 2020. |
| Contact for Construction | Hendrik Pretorius 082 772 1335 |
| Duration of work | Till August 2018 |
| Contact for Routine Road Maintenance | Ian Smith 084 415 2002 |

| | |
|--------------------------------------|--|
| National Route | R72 |
| Section | Peddie turn off to East London Airport |
| Distance | 62km |
| Description | Two lane single carriageway with paved soulder |
| Expected Road Condition | Good |
| Contact for Routine Road Maintenance | Ian Smith 084 415 2002 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|--|
| National Route | R75 |
| Section | Port Elizabeth to Uitenhage North |
| Distance | 28km |
| Description | Dual carriageway with 2 lanes per direction for the first 14 km. Not a freeway and a lot of level accesses exist, also a lot of pedestrian movements |
| Expected Road Condition | Good |
| Expected Travel Condition | Please take special care for first 14 km and normal RRM work. A resurfacing contract commenced in November 2016 between km 13 and km 28, section 2. Motorists to expect lane closures in this section. |
| Duration of work | |
| Contact for Routine Road Maintenance | Lauren Adams 073 311 1818 |

| | |
|--------------------------------------|--|
| National Route | R75 |
| Section | Uitenhage North to Jansenville |
| Distance | 136km |
| Description | A two-lane narrow, single carriageway with gravel shoulders. |
| Expected Road Condition | Fair |
| Expected Travel Condition | Fair, no construction currently underway, but routine maintenance is ongoing. Look out for warthogs. |
| Duration of work | |
| Contact for Routine Road Maintenance | Babalwa Mbandazayo 072 327 4045 |

| | |
|--------------------------------------|---|
| National Route | R75 |
| Section | Jansenville to R63 junction (Pearston) |
| Distance | 59km |
| Description | A two-lane, narrow single carriageway with gravel shoulders. The last 23km with paved shoulders. |
| Expected Road Condition | Fair |
| Expected Travel Condition | No construction but motorists may encounter occasional short closures for routine maintenance. Very narrow sections from Jansenville for +- 50km. Construction to start in November 2017. |
| Duration of work | |
| Contact for Routine Road Maintenance | Babalwa Mbandazayo 072 327 4045 |

| | |
|--------------------------------------|---|
| National Route | R81 |
| Section | Polokwane to Mooketsi |
| Distance | 73km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Good. Km 60 – 66 poor surface. Line markings in fair condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Stephan Du Plessis 084 491 1165 |

| | |
|--------------------------------------|---|
| National Route | R81 |
| Section | Mooketsi to Giyani |
| Distance | 73.2km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Good. Line markings in fair condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Stephan Du Plessis 084 491 1165 |

| | |
|---------------------------------|--|
| National Route | R101 |
| Section | Bela-Bela to Modimolle |
| Distance | 26.8 km |
| Description | Two-lane single carriageway with paved shoulders. |
| Expected Road Condition | Fair to Good. Poor road markings |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | NJ Du Toit 083 342 6550 |

| | |
|---------------------------------|--|
| National Route | R101 |
| Section | Modimolle to Middelfontein |
| Distance | 16.4 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Until end of January 2016 |
| Contact for Routine Maintenance | Gustavus Fouche 082 780 2391 |

| | |
|---------------------------------|--|
| National Route | R104 |
| Section | Simon Vermooten to West of Bronkhorspruit |
| Distance | 42.40 km |
| Description | Single carriageway with gravel shoulders |
| Expected Road Condition | Good. Road Markings in a poor state |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|---------------------------------|--|
| National Route | R104 |
| Section | East of Bronkhorstspuit to Mpumalanga Border |
| Distance | 21.20 km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|---------------------------------|--|
| National Route | R300 |
| Section | Swartklip Interchange to Stellenberg Interchange |
| Distance | 16.1 km |
| Description | Three-lane dual carriageway with paved shoulders. |
| Expected Travel Condition | Good |
| Expected Travel Condition | R300 Construction work is taking place at night. The speed limit throughout the construction area has been lowered to 40 – 60km and to be adhered to. Road closures are to be expected as early as 5pm. Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Chris Roux 083 440 7553 |

| | |
|--------------------------------------|---|
| National Route | R500 |
| Section | Parys to Carletonville |
| Distance | 55.4 km |
| Description | Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders. |
| Expected Road Condition | Good to Fair |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|--|
| National Route | R501 |
| Section | Free State Border to Potchefstroom |
| Distance | 21.2 km |
| Description | Two-lane narrow single carriageway with gravel shoulders |
| Expected Road Condition | Good to Fair |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|--------------------------------------|---|
| National Route | R501 |
| Section | Potchefstroom to Westonaria Municipal Border |
| Distance | 64.3 km |
| Description | Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders. |
| Expected Road Condition | The two-lane is bad to poor and then the dual is good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Vincent Stewart 076 272 3080 |

| | |
|---------------------------------|---|
| National Route | R503 |
| Section | Klerksdorp to Coligny |
| Distance | 74.56 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Travel Condition | Fair to Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Roadworks. Expect stop and Go's |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Theuns Jooste 076 751 9898 |

| | |
|---------------------------------|--|
| National Route | R503 |
| Section | Coligny to Lichtenburg |
| Distance | 21.9 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Theuns Jooste 076 751 9898 |

| | |
|---------------------------------|--|
| National Route | R504 |
| Section | Wolmaranstad to Leeudoringstad |
| Distance | 28.9 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Fair |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Dries Grundlingh 083 269 3029 |

| | |
|---------------------------------|--|
| National Route | R504 |
| Section | Leeudoringstad to Free State Border |
| Distance | 24 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Road Condition | Fair |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Short stop/go's may occur from time to time |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Dries Grundlingh 083 269 3029 |

| | |
|---------------------------------|---|
| National Route | R505 |
| Section | Wolmaranstad to N14/11 |
| Distance | 91.7 km |
| Description | Two-lane single carriageway with gravel shoulders. |
| Expected Travel Condition | Fair with uneven riding surface. |
| Expected Road Condition | Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Roadworks. Expect stop and Go's |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Theuns Jooste 076 751 9898 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|--|
| National Route | R505 |
| Section | N14/11 to Lichtenburg |
| Distance | 38.6 km |
| Description | Two-lane single carriageway with gravel shoulders |
| Expected Road Condition | Expected Road Condition Fair with uneven riding surface |
| Expected Travel Condition | Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Theuns Jooste 076 751 9898 |

| | |
|--------------------------------------|---|
| National Route | R505 |
| Section | Lichtenburg to Ottoshoop |
| Distance | 49.4 km |
| Description | Two lane single carriageway with gravel shoulders |
| Expected Road Condition | Road is in a poor condition. Potholes have been attended to but due to the poor Expected Road Condition new potholes and base failures are constantly in repair. Stop/Go will occur from time to time |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gerrit Mostert 079 492 8691 |

| | |
|--------------------------------------|--|
| National Route | R510 |
| Section | Rustenburg to north West / Limpopo Border |
| Distance | 87 km |
| Description | Single carriageway |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. BRT construction from Rustenburg (1 st 7km). expect delays |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|--------------------------------------|---|
| National Route | R510 |
| Section | North Wet /Limpopo Border to Northam |
| Distance | 21 km |
| Description | Single carriageway |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Stephan du Plessis – 084 491 1165 Riaan Fuchs – 082 556 7788 |

| | |
|--------------------------------------|---|
| National Route | R510 |
| Section | Northam to Thabazimbi |
| Distance | 37.2km |
| Description | Single carriageway |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | NJ Du Toit 083 342 6550 |
| National Route | R510 |

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|---|
| Section | Thabazimbi to Lephalale |
| Distance | 125.4 km |
| Description | Single carriageway |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Chantel Purchase 083 789 2304 |

| | |
|--------------------------------------|---|
| National Route | R511 |
| Section | Lephalale to Monte Christo |
| Distance | 38.07km |
| Description | Single carriageway. |
| Expected Road Condition | Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Chantel Purchase 083 789 2304 |

| | |
|--------------------------------------|---|
| National Route | R511 |
| Section | Brits to North West/Limpopo |
| Distance | 71km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|--------------------------------------|--|
| National Route | R511 |
| Section | North West / Limpopo border to Thabazimbi |
| Distance | 62km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. Poor road markings on some sections |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Roadworks: Reseal contract between North West / Limpopo border and Thabazimbi. Expect Stop 'n Go's. |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | NJ Du Toit 083 342 6550 |

| | |
|--------------------------------------|---|
| National Route | R511 |
| Section | Gauteng /north West Border to Broedestroom |
| Distance | 7.44km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|----------------|------|
| National Route | R512 |
|----------------|------|

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

| | |
|--------------------------------------|---|
| Section | R104 to Brits |
| Distance | 10.06 km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|--------------------------------------|---|
| National Route | R516 |
| Section | Koedoeskop to Bela Bela – R101 |
| Distance | 82.0km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Until July 2015. Contract extended until January 2016 |
| Contact for Routine Road Maintenance | NJ Du Toit 083 342 6550 |

| | |
|--------------------------------------|---|
| National Route | R518 |
| Section | Lephalale to Marken |
| Distance | 70km |
| Description | Two-lane single carriageway with gravel shoulders. Paved shoulders in the mountain area. Slope in the mountain area full of falling rocks |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Chantel Purchase 083 789 2304 |

| | |
|--------------------------------------|---|
| National Route | R518 |
| Section | Marken to Mahwelereng |
| Distance | 102.2km |
| Description | Two-lane single carriageway with gravel shoulders. Paved shoulders in the mountain area. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Chantel Purchase 083 789 2304 |

| | |
|--------------------------------------|---|
| National Route | R518 |
| Section | Mokopane to Zebediela |
| Distance | 47.281km |
| Description | Two lane single carriageway. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gert Swanepoel 084 516 3330 |

| | |
|--------------------------------------|---|
| National Route | R518 |
| Section | Zebediela to Lebowakgomo |
| Distance | 25.8km |
| Description | Two lane single carriageway. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gert Swanepoel 084 516 3330 |

| | |
|--------------------------------------|---|
| National Route | R520 |
| Section | R510/3 Junction to Vaalwater |
| Distance | 54km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Fair to Good. Km 0.0 – 54.0 poor road markings |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gustav Fouche 082 780 2391 |

| | |
|--------------------------------------|---|
| National Route | R521 |
| Section | Polokwane to Dendron |
| Distance | 62.3 km |
| Description | Two-lane single carriageway. |
| Expected Road Condition | Fair. Gravel shoulders. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | George Brand 082 5558493 |

| | |
|--------------------------------------|--|
| National Route | R521 |
| Section | Dendron to Vivo |
| Distance | 8km |
| Description | Two lane single carriageway with no paved shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Stop/Go at Patching Team for next month as well as shoulder repair team |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | George Brand 083 730 9385 |

| | |
|--------------------------------------|--|
| National Route | R521 |
| Section | Vivo to R23/1 Intersection |
| Distance | 6.5km |
| Description | Two lane single carriageway with no paved shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Stop/Go may occur. Patching and shoulder repairs teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | George Brand 083 730 9385 |

| | |
|--------------------------------------|--|
| National Route | R523 |
| Section | Vivo to Masewkwaspoort |
| Distance | 67km |
| Description | Two lane single carriageway with no paved shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | George Brand 083 730 9385 |

| | |
|--------------------------------------|--|
| National Route | R524 |
| Section | Louis Trichardt to Punda Maria Gate |
| Distance | 130.3km |
| Description | Two lane single carriageway with no paved shoulders and passing lanes on sustained grades. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Johan de Vries 073 308 2356 |

| | |
|--------------------------------------|--|
| National Route | R526 |
| Section | Mica to Gravelotte |
| Distance | 33.03km |
| Description | Single carriageway with gravel shoulders. |
| Expected Road Condition | Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Wessel Schalkwyk 082 371 3285 |

| | |
|--------------------------------------|--|
| National Route | R529 |
| Section | Giyani to Letsitele |
| Distance | 77.6km |
| Description | Two lane single carriageway with no paved shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Marius Nel 073 538 5019 |

| | |
|--------------------------------------|---|
| National Route | R531 |
| Section | Klaserie junction with R40 to Orpen Gate at Kruger National Park |
| Distance | 3km |
| Description | Single carriageway with paved shoulders. Surfacing Fair to Good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Wessel Schalkwyk 082 371 3285 |

| | |
|--------------------------------------|---|
| National Route | R532 |
| Section | Junction with R36 to Mpumalanga border towards Graskop |
| Distance | 11.4km |
| Description | Single carriageway with gravel shoulders. Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Marius Nel 073 538 5019 |

| | |
|--------------------------------------|---|
| National Route | R555 |
| Section | Witbank to Middelburg |
| Distance | 20 km |
| Description | A 2-lane single carriageway road with narrow gravel shoulders |
| Expected Road Condition | Fair |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Timothy Masalesa 076 349 4168 |

| | |
|--------------------------------------|--|
| National Route | R555 |
| Section | Limpopo / Mpumalanga border at Stoffberg to Kokwaneng |
| Distance | 72.86 |
| Description | Single carriageway with gravel and paved shoulders. |
| Expected Road Condition | First 30km in poor condition. Rest is fair to good. Line markings in poor condition. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Nathanael Pillay 074 309 0937 |

| | |
|--------------------------------------|---|
| National Route | R555 |
| Section | Kokwaneng to Burgersfort |
| Distance | 37.705km |
| Description | Single carriageway with gravel and paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. A large portion in Steelpoort area is under construction |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Nathanael Pillay 074 309 0937 |

| | |
|--------------------------------------|--|
| National Route | R556 |
| Section | Tsitsing to Ledig (Sun City) |
| Distance | 29.6km |
| Description | Two lane single carriageway with paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|--------------------------------------|---|
| National Route | R565 |
| Section | Rustenburg to Ledig (Sun City) |
| Distance | 34.9km |
| Description | Two lane single carriageway with paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Kobus Vermeulen 082 850 7361 |

| | |
|--------------------------------------|--|
| National Route | R567 |
| Section | N11/23 to Seshego (Kompane Stret) |
| Distance | 64km |
| Description | Two lane single carriageway with no paved shoulders. |
| Expected Road Condition | Fair to Good. Speed humps between Moletji and Seshego |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Domestic animals from G-Matlala to Moletjie in the road reserve Reseal contract with Stop and Go's until June 2017 |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Maxwell Baloyi 078 972 4445 |

| | |
|---------------------------------|--|
| National Route | R570 |
| Section | N4 Interchange to Malelane Kruger Park Gate |
| Distance | 3.648 km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Hannelie Swanepoel 084 516 3330 |

| | |
|---------------------------------|--|
| National Route | R570 |
| Section | N4 Interchange to Jeppe's Reef Bordr Post |
| Distance | 40.89 km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | Fair |
| Expected Travel Condition | Rehab started February 2015 Stop and go on this section. Expect stop n go's along the road |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Johan Van Niekerk 082 882 9819 |

| | |
|---------------------------------|--|
| National Route | R571 |
| Section | N4 Interchange to Managa Border Post |
| Distance | 60.469 km |
| Description | Single carriageway with paved shoulders. |
| Expected Road Condition | First 30km is good .Rest Fair to Good |
| Expected Travel Condition | Routine road maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Maintenance | Johan Van Niekerk 082 882 9819 |

| | |
|--------------------------------------|---|
| National Route | R572 |
| Section | Monte Christo to Tom Bourke |
| Distance | 47.952 km |
| Description | Two-lane single carriageway. |
| Expected Road Condition | Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Chantel Purchase 083 789 2304 |

| | |
|--------------------------------------|---|
| National Route | R573 |
| Section | Moloto to Moteti |
| Distance | 48.652 km |
| Description | Two-lane single carriageway with paved shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gert Swanepoel 084 516 3330 |

| | |
|--------------------------------------|---|
| National Route | R573 |
| Section | Moteti to Marble Hall |
| Distance | 43.741 km |
| Description | Two-lane single carriageway with gravel shoulders |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gert Swanepoel 084 516 3330 |

| | |
|--------------------------------------|---|
| National Route | R578 |
| Section | Louis Trichardt to Giyani |
| Distance | 90.76 |
| Description | Two lane single carriageway with no paved shoulders and passing lanes on sustained grades. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. Stop/Go and Patching team for next month |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Johan de Vries 073 308 2356 |

| | |
|--------------------------------------|--|
| National Route | R579 |
| Section | Hlogotlou to Phokwane |
| Distance | 26.046km |
| Description | Two-lane single carriageway with no paved shoulders. |
| Expected Road Condition | Fair to Good |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Gert Swanepoel 084 516 3330 |

| | |
|--------------------------------------|---|
| National Route | R579 |
| Section | Phokwane to Chuniespoort |
| Distance | 78.9km |
| Description | Two lane single carriageway with paved shoulders. |
| Expected Road Condition | Fair to Good. |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered |
| Duration of work | Ongoing |
| Contact for Routine Road Maintenance | Gert Swanepoel 084 516 3330 |

| | |
|--------------------------------------|--|
| National Route | S27 |
| Section | Villiers to Mpumalanga / Gauteng Border |
| Distance | 42km |
| Description | Single carriageway with gravel shoulders and short gravel road portion |
| Expected Road Condition | Good (Gravel road in excellent condition). |
| Expected Travel Condition | Routine Road Maintenance teams may be encountered. |
| Duration of Work | Ongoing |
| Contact for Routine Road Maintenance | Heinrich Scheepers 076 292 0853 |

NATIONAL BORDER CONTROL POSTS

Botswana Border

| Border Post | Location | Description | Condition | Opening Times |
|-----------------|--|------------------------------------|-----------|----------------|
| Twee Rivieren | Situated in the Kgalagadi Cross Border National Park | Single carriageway gravelled road. | Fair | 08h00 to 16h30 |
| Gemsbok | Between Upington and Botswana | Single carriageway gravelled road. | Fair | 08h00 to 16h30 |
| Middelputs | Between Van Zylsrus and Botswana | Single carriageway gravelled road. | Fair | 08h30 to 16h30 |
| McCarthy's Rest | Route R380 between Kathu and Thshabon (Botswana) | Single carriageway gravelled road. | Fair | 08h00 to 16h30 |
| Makopong | Route R379 between Bryburg and Botswana | Single carriageway gravelled road. | Fair | 07h30 to 16h00 |
| Bray | Route R378 between Bryburg and Botswana | Single carriageway gravelled road. | Fair | 07h30 to 16h00 |
| Boshoek | Route R375 between Bryburg and Botswana | Single carriageway gravelled road. | Fair | 07h30 to 16h00 |
| Magobistad | Between Mafikeng & Botswana | Single carriageway gravelled road. | Fair | 07h30 to 16h30 |
| Ramatlabama | Between Mafikeng & Botswana | Single carriageway paved road. | Good | 07h00 to 20h00 |
| Skilpadshok | N4 Platinum – Lobatse | Single carriageway paved road. | Good | 07h00 to 19h30 |
| Swartkopfontein | Between Zeerust & Gaborone | Single carriageway paved road. | Good | 07h00 to 19h00 |
| Kopfontein | Between Zeerust & Gaborone | Single carriageway paved road. | Good | 07h00 to 22h00 |
| Derdepoort | Between Rustenburg & Botswana | Single carriageway gravelled road. | Poor | 07h00 to 19h00 |
| Stockpoort | From Ellisras to Botswana | Single carriageway paved road. | Good | 08h00 to 16h00 |
| Groblers Bridge | From Potgietersrus on N11 to Botswana | Single carriageway paved road. | Good | 08h00 to 18h00 |
| Zanzibar | Between Alldys & Selebi-Pikwi | Single carriageway gravelled road. | Fair | 08h00 to 16h00 |
| Platjan | Between Alldys & Selebi-Pikwi | Single carriageway gravelled road. | Fair | 08h00 to 16h00 |
| Pondrift | From Alldys on R521 to Botswana | Single carriageway paved road. | Good | 08h00 to 16h00 |

Namibia Border

| Border Post | Location | Description | Condition | Opening Times |
|---------------|--|--|-----------|----------------|
| Alexander Bay | Between Alexander Bay and Oranjemund (Namibia) | Single carriageway paved road. | Good | 06h00 to 22h00 |
| Violsdrift | Route N7/B1 between Springbok and Keetmanshoop (Namibia) | Single carriageway paved road. | Good | 24 hours |
| Onseepkans | Route R358/C10 between Pofadder and Karasburg | Single gravelled road with single traffic lane bridge over Orange River Bridge | Fair | 08h00 to 16h30 |
| Nakop | Route N10/B3 between Upington and Karasburg (Namibia) | Single carriageway paved road with gravelled shoulders. New Border Control Post situated 1 km from actual border with Namibia. | Good | 24 hours |
| Noenieput | Between Upington and Aroab (Namibia) | Single carriageway gravelled road. | Fair | 08h00 to 16h30 |
| Rietfontein | Route R31/C16 between Askam and Aroab (Namibia) | Single carriageway gravelled road. | Fair | 08h00 to 16h30 |

Zimbabwe Border

| Border Post | Location | Description | Condition | Opening Times |
|-------------|--------------------------------|--------------------------------|-----------|--|
| Beitbridge | On N1 between RSA and Zimbabwe | Single carriageway paved road. | Fair | Passengers: 24hrs Commercial: 24hrs |

Mozambique Border

| Border Post | Location | Description | Condition | Opening Times |
|--------------------|---|--|-----------|----------------|
| Pafuri | In Kruger National Park, nearest route is R525, east/west direction ± 25 km adrift) | Single carriageway paved road under construction. | Fair | 08h00 to 16h00 |
| Lebombo | On N4 between Nelspruit and Maputo | Single carriageway paved road. | Good | 06h00 to 22h00 |
| Kosibay (Farazela) | On R22 between RSA and Mozambique | Single carriageway paved road with narrow paved shoulders. | Good | 06h00 to 1800 |

Swaziland Border

| Border Post | Location | Description | Expected Condition |
|-----------------|---|------------------------------------|--------------------|
| Mananga | On R571 between Komatipoort and Swaziland | Single carriageway paved road. | Fair |
| Jeppe's Reef | On R570 between Malelane and Swaziland | Single carriageway paved road. | Good |
| Josefsdal | On R40 between Barberton and Piggs Peak | Single carriageway gravelled road | Poor |
| Oshoek | On N17 between Ermelo and Manzini | Single carriageway paved road. | Good |
| Waverley | Off R33 between RSA and Swaziland | Single carriageway paved road. | Good |
| Nerston | On R65 between RSA and Swaziland | Single carriageway paved road. | Fair |
| Emhlalatinhi | Between Piet Retief and Swaziland | Single carriageway paved road. | Good |
| Bothashoop | Between Piet Retief and Swaziland | Single carriageway gravelled road. | Fair |
| Mahamba | Between Piet Retief and Swaziland | Single carriageway paved road. | Good |
| Onverwacht | D1936 off N2 (KwaZulu-Natal) | Single carriageway paved road. | Good |
| Golela/Lavumisa | P 720 off N2 (KwaZulu-Natal) | Single carriageway paved road. | Good |

Lesotho Border

| Border Post | Location | Description | Expected Condition |
|-------------------|--|--------------------------------|---|
| Monantsapas | R 57/S1579 (Free State) | Single carriageway paved road | Fair to good |
| Caledonspoort | P 92/1 (Free State) | Single carriageway paved road | Fair to poor |
| Ficksburg Bridge | R 26 / P75/1 (Free State) | Single carriageway paved road | Fair |
| Peka Bridge | S 388 / S 306 (Free State) | Single carriageway gravel road | Poor |
| Maseru Bridge | N8 (Free State) | Single carriageway paved road. | Fair |
| Van Rooyen's Gate | P66/1 (Free State) | Single carriageway paved road | Fair |
| Sepapu's Gate | S4 (Free State) | Single carriageway gravel road | Poor |
| Makhaleng Bridge | S2 (Free State) | Single carriageway gravel road | Very Poor |
| Telle Bridge | R 392 (from Sterkspruit in the Eastern Cape) | Single carriageway paved road. | Good |
| Ongeluksnek | Eastern Cape: Off R 56. Closest towns are Mount Fletcher and Matatiele | Gravel approach road. | Poor to very poor. Only suitable to 4x4 vehicles beyond the border post. |

| | | | |
|------------------|--------------------------------------|-----------------------|--|
| Qacha's Nek | Eastern Cape: Closest town Matatiele | Gravel approach road. | Poor |
| Ramaselitso Gate | Eastern Cape: Closest from Matatiele | Gravel approach road. | Poor |
| Sani Pass | P 318 (KwaZulu-Natal) | Gravel approach road | Fair but often only accessible to 4X4 vehicles beyond the border post. |

THE SOUTH AFRICAN NATIONAL ROADS AGENCY SOC LTD

Contact Details

Head Office

48 Tambotie Avenue
Val de Grace
Pretoria, 0184
Tel. 012 844 8000
Fax 012 362 2117

Northern Region

38 Ida Street
Menlo Park
Pretoria, 0081
Tel. 012 426 6200
Fax 012 348 1680

Eastern Region

58 Van Eck Place
Mkondeni
Pietermaritzburg
Tel. 033 392 8100
Fax 033 386 6284 / 3365

Southern Region

20 Shoreward Drive
Baywest
Port Elizabeth
6025
Tel. 041 398 3200
Fax 041 492 0201

Western Region

1 Havenga Street
Oakdale, Bellville
7530
Tel. 021 957 4600
Fax 021 910 1699

Website: www.sanral.co.za
E-mail: info@nra.co.za
Fraud Hot Line: 0800204558