

Travel Advisory Report

MAY 2017

N1

National Route	N1
Section	Old Oak Interchange to Rawsonville
Distance	64 km
Description	Two-lane dual carriageway with paved shoulders.
Expected Travel Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Chris Roux 083 440 7553

National Route	N1
Section	Rawsonville to Laingsburg
Distance	156 km
Description	Single carriageway road with passing lanes and with gravel shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	A compulsory stop, manned by the Provincial Traffic Department, is in operation \pm five km south of Touws River. An unmanned compulsory stop for heavy vehicles is also in operation on the south-bound carriageway in Hex River Pass. Motorists should be alert to pedestrians and/or stray animals just north of De Doorns as well as to the informal traders alongside the road. Please note that it is illegal to stop and buy from the sellers. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Edwin De Wee 073 985 6476

National Route	N1
Section	Laingsburg to Three Sisters
Distance	280 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	December 2016
Contact for Routine Maintenance	Japie Taljaard 082 857 7175

National Route	N1
Section	Three-Sisters to Colesberg
Distance	236 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	December 2016
Contact for Routine Maintenance	Martiens du Plessis 083 655 0644

National Route	N1
Section	Colesberg to Orange River
Distance	36.34 km
Description	Single carriageway with surfaced shoulders, and 4 passing lane sections.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Martiens du Plessis 083 655 0644

National Route	N1
Section	Orange River (Provincial Boundary) to Bloemfontein (Sydenham Interchange)
Distance	175 km
Description	A two lane single carriageway with wide paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to good.
Expected Travel Condition	Upgrading of the section between Trompsburg and Fonteintjie is in progress. Traffic is diverted onto deviations with no Stop/Go controls at both ends of the project.
Duration of Work	Until June 2017
Contact for Routine Road Maintenance	Riaan Louwrens 074 601 8998

National Route	N1
Section	Bloemfontein to Kroonstad
Distance	189 km
Description	Around Bloemfontein and extending northwards for some 15km, the road is a four-lane dual carriageway with wide paved shoulders. Thereafter it reduces to a four-lane single carriageway for the next 20kms, otherwise it is a two-lane single carriageway with paved shoulders and passing lanes on steep gradients. The last 10 km, known as the Kroonstad Bypass, is a four-lane dual carriageway.
Expected Road Condition	Generally good except for the section between Kroonstad and Ventersburg, where the road surfacing is in a fair condition.
Expected Travel Condition	<ol style="list-style-type: none"> 1. Upgrading of section between Sydenham Interchange and Glen Lyon is in progress. No Stop/Go controls in place. 2. A contract for the upgrade between Winburg and Winburg Station commenced 4 January 2016. Full road closures may be experienced during certain blasting operations. 3. A contract for the upgrade between Ventersburg and Holfontein is in progress. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 4. A contract for the upgrade between Holfontein and Kroonstad is in progress. Traffic is free flowing. Motorists are advised to obey the posted traffic signs.
Duration of Work	<ol style="list-style-type: none"> 1. Until May 2017 2. Until April 2018 3. Until September 2018 4. Until March 2018
Contact for Routine Road Maintenance	Abel Majorobela 079 896 3377

National Route	N1
Section	Kroonstad to Vaal River (Free State – Gauteng Provincial Boundary)
Distance	102 km
Description	Partly a single carriageway with alternating passing lanes in each direction and wide gravel shoulders, and partly a four-lane single carriageway, except for the 10 km portion beyond the Vaal Toll Plaza, where it becomes a four-lane dual carriageway with wide paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A rehabilitation contract between Kroonstad South and Westleigh is in progress. Traffic is free flowing with at least one lane open in each direction. Motorists are advised to obey the posted traffic signs. 2. A periodic maintenance contract between Koppies and Vaal Toll Plaza commenced on 13 May 2016. No Stop/Go controls in place. Two way traffic with reduced lane width. Ad hoc repairs will be undertaken.
Duration of Work	<ol style="list-style-type: none"> 1. Until May 2017 2. Until June 2017.
Contact for Routine Road Maintenance	Abel Majorobela 079 896 3377

National Route	N1
Section	Vaal River (provincial boundary) to Misgund Soweto
Distance	64 km
Description	Four-lane dual carriageway freeway with wide paved shoulders.
Expected Travel Condition	Good.
Expected Road Condition	Motorists should beware of pedestrian activity along the route. Additional street lighting has been installed at the Ennerdale Interchange.
Duration of Work	
Contact for Routine Road Maintenance	Unita Fungile 072 793 2825

National Route	N1
Section	Misgund Soweto to Grand Central / Olifantsfontein Interchange
Distance	57.6 km
Description	Multi-lane dual carriageway with paved shoulders
Expected Travel Condition	Good
Expected Road Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pierre Coetzer 076 107 7322

National Route	N1
Section	Grand Central / Olifantsfontein interchange to Proefplaas N4 Interchange
Distance	33.0 km
Description	Multi-lane dual carriageway with paved shoulders
Expected Travel Condition	Routine Road Maintenance teams may be encountered Bridge repairs along the N1/N4 Proefplaas interchange. Expect lane reductions
Expected Road Condition	Good
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pierre Coetzer 076 107 7322

National Route	N1
Section	Proefplaas (N4 Interchange) to Bela Bela (Warmbaths) (Platinum Toll highway)
Distance	94 km
Description	Six lane dual carriageway freeway from Pretoria (Proefplaas Interchange) to Zambesi Interchange changing into four lane dual carriageway freeway to Bela Bela.
Expected Travel Condition	1. RRM Teams may be encountered 2. Roadworks within various Toll plazas in Tshwane along the N1
Expected Road Condition	RRM teams may be encountered
Duration of Work	2. Until June 2017
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N1
Section	Bela Bela to Polokwane (Great North Toll Road)
Distance	160 km
Description	Four-lane dual divided carriageway freeway from the Warmbaths/Settlers interchange to the Kranskop toll plaza. Four-lane single undivided carriageway freeway from the Kranskop Toll Plaza to the N1/R71 interchange at Polokwane (Meropa). There is ad hoc maintenance works and lane upgrades at the Kranskop Plaza for electronic tolling systems as an additional payment method to road users
Expected Travel Condition	1. Routine Road Maintenance teams may be encountered 2. Major roadworks upgrade of the N1/R71 interchange
Duration of Work	2. Until December 2018
Contact for Routine Road Maintenance	NTRV Danie Kotze 082 822 0902

National Route	N1: R101
Section	Middefontein to Mookopong Municipal Border (N1/24S: R101)
Distance	4.78 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustavus Fouche 082 780 2391

National Route	N1: R101
Section	Mookopong Municipal Border to Mokopane (N1/25X: (R101)
Distance	67.13 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered Roadworks with lanes deviations
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustavus Fouche 082 780 2391

National Route	N1: R101
Section	Mookgopong I/C to N1/25X Intersection (N1/25Y: R101)
Distance	2.200 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustavus Fouche 082 780 2391

National Route	N1: R101
Section	Mokopane to Polokwane
Distance	49.7 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Hannelie Swanepoel 082 380 5264Ha

National Route	N1
Section	Polokwane (Meropa Casino) to Doornbult
Distance	22.3 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered Major Roadworks upgrades from Meropa N1 to R71 interchange
Duration of Work	Ongoing Until December 2018
Contact for Routine Road Maintenance	George Brand 083 730 9385

National Route	N1
Section	Doornbult to Makhado
Distance	98.75 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered. There is ad hoc maintenance works and lane upgrades at the Capricorn Plaza for electronic tolling systems as an additional payment method to road users. Expect construction between Polokwane and Diep River and within Botlokwa until December 2017
Duration of Work	Ongoing
Contact for Routine Road Maintenance	George Brand 083 730 9385

National Route	N1
Section	Makhado to Beitbridge
Distance	107 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Fair. There is ad hoc maintenance works and lane upgrades at the Baobab Plaza for electronic tolling systems as an additional payment method to road users
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johannes Rakwena 082 304 6880

N2

National Route	N2
Section	Swartklip Interchange to Somerset-West
Distance	24 km
Description	Two-way dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chris Roux 083 440 7553

National Route	N2
Section	Somerset-West to Botriver
Distance	45 km
Description	Single carriageway road with paved shoulders and passing lanes. A four lane single undivided carriageway road through Sir Lowry's Pass and Houwhoek Pass. Average speed cameras have been implemented and fully operational both ways on Sir Lowry's Pass.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chris Roux 083 440 7553

National Route	N2
Section	Botriver to Riversdale
Distance	218 km
Description	Single carriageway with paved shoulders and passing lanes.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Riversdale to Mossel Bay
Distance	82 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johan Nel 082 612 1980

National Route	N2
Section	Mossel Bay to George
Distance	51 km
Description	A four-lane dual carriageway.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johan Nel 082 612 1980

National Route	N2
Section	George to Natures Valley (Sout River)
Distance	113 km
Description	Single carriageway with narrow paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	It is illegal to stop and buy from the informal traders. Motorists should be alert to pedestrians and/or stray animals in the vicinity of the informal settlement in Knysna, as well as in the vicinity of Plettenberg Bay. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Johan Nel 082 612 1980

National Route	N2
Section	Natures Valley to Storms River
Distance	40 km
Description	A two-lane single carriageway with surfaced shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Toll Road
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	N2
Section	Storms River Town to Elands River
Distance	14 km
Description	A two-lane single carriageway with shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Toll Road
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	N2
Section	Elands River to Gamtoos
Distance	98 km
Description	A two-lane single carriageway with shoulders.
Expected Travel Condition	Good
Contact for Construction	Michelle van Rooyen 072 777 7232

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	N2
Section	Gamtoos River to Van Stadens River
Distance	19 km
Description	14,7 km of 2-lane single carriageway and 4.3 km of dual carriageway with surfaced shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Undulations occur on sections of this road. At Thornhill, pedestrians could be encountered.
Duration of Work	
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	N2
Section	Van Stadens River to Port Elizabeth (Markman)
Distance	57 km
Description	Dual carriageway with 2 lanes per direction. A new interchange to Baywest Boulevard has been opened.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	N2
Section	Bramlin Interchange to Soutwerke, Port Elizabeth
Distance	28Km
Description	Dual carriageway with 2 lanes per direction
Expected Travel Condition	Special Maintenance
Expected Travel Condition	Good
Duration of Work	Project completed.
Contact for construction project	Gerome Plaatjies Phil Simpson 082 552 5355
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	N2
Section	Port Elizabeth (Coega IDZ) to Colchester
Distance	14Km
Description	Dual carriageway with 2 lanes per direction
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	N2
Section	Colchester to Nanaga
Distance	13Km
Description	13km freeway
Expected Travel Condition	Good.
Duration of Work	
Contact for Routine Road Maintenance	

National Route	N2 section 12 & 13
Section	Nanaga to Grahamstown
Distance	
Description	2 - lane single carriageway
Expected Travel Condition	Good, but no paved shoulders in place. Animals at R67 intersection east of Grahamstown.
Duration of Work	
Contact for Routine Road Maintenance	

National Route	N2 section 13
Section	Komgha to Grahamstown
Distance	42km
Description	2 - lane single carriageway
Expected Travel Condition	Construction started in March 2016. 3 Stop/Go's are in operation.
Duration of Work	12 months (March 2016 to March 2017)
Contact for construction	Sarel Bezuidenhout 073 483 6700 Naseef Parker 072 500 9913
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539

National Route	N2
Section	Grahamstown to Fish River
Distance	47km
Description	A 2-lane single carriageway is being upgraded
Expected Travel Condition	Construction commenced in April 2015 on phase 1, km 62,0 to km 78,7 and is nearing completion. Construction is also in progress at the fish river bridge: km 103. Construction of phase 2 will commence in May 2017.
Expected Travel Condition	Speed restrictions will be in place. Construction traffic will be encountered. Temporary closures due to blasting will take place approximately 20km east of Grahamstown. Blasting will also occur periodically near the Fish River pass. Stop-Go's in place to reduce traffic speeds. The stop-go's will be removed during the holidays. However, traffic calming and speed restrictions will be in place at the Fish River Bridge.
Duration of Work	April 2015 to January 2018
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539
Contact for Construction project	Steve Beckerling – Engineer's representative on site 083 554 3605

National Route	N2
Section	Fish river to Keiskamma Pass
Distance	27 km
Description	A 2-lane single carriageway mostly on bypass roads
Expected Travel Condition	Good
Expected Travel Condition	Recently upgraded. Repair works / lane closure in progress.
Duration of Work	
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539

National Route	N2
Section	Keiskamma River to Green River
Distance	23 km
Description	A 2-lane single carriageway
Expected Travel Condition	Good
Expected Travel Condition	Recently upgraded
Duration of Work	
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539

National Route	N2
Section	Green River to Breidbach
Distance	13km
Description	Upgrading from Green River to Breidbach Interchange. Rehabilitation of section of route through King Williams Town has started as phase 1 – Buffalo River to Zwelitsha.
Expected Travel Condition	Rehab in King Williams Town started in May 2016. Detours can be expected. Grey street closed between Buffalo street and Alexandra street. There are lane restrictions on the N2 between Welkom street (Breidbach) and Hargreaves Avenue (in town).
Duration of Work	May 2016 to November 2017 (Phase 1)
Contact for construction	Nick Kitsopoulos 082 576 4667

National Route	N2
Section	King Williams Town to East London (Gonubie)
Distance	60 km
Description	A 4-lane dual carriageway
Expected Travel Condition	Good
Expected Travel Condition	Expect delays between the Hemmingway way 7/0 and NEX due to road works.
Duration of Work	Delays at the intersection of N2 and Breidbach intersection during morning and afternoon peaks.
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539

National Route	N2
Section	Gonubie to Kei River
Distance	60 km
Description	The first 2km is a 4-lane dual carriageway. Thereafter it becomes a 2-lane single carriageway with wide paved shoulders. Passing lanes are provided on some steep grades.
Expected Travel Condition	Between R63 T-junction to the Kei River Bridge motorists to keep to posted speed limits. Construction contract underway from R63 T-Junction to Kei bridge. Stop-go's will be encountered.
Contact for Routine Road Maintenance	Mike De Lange 082 779 2993

National Route	N2
Section	Kei River to Dutywa
Distance	68 km
Description	Single carriageway road with paved shoulders and passing lanes.
Expected Travel Condition	The condition is fair.
Expected Travel Condition	Roaming animals in some areas near villages
Duration of work	
Contact for Routine Road Maintenance	Mike De Lange 082 779 2993

National Route	N2
Section	Dutywa to Mthatha
Distance	85 km
Description	Single carriageway road with paved shoulders and passing lanes.
Expected Travel Condition	Fair
Expected Travel Condition	Roaming animals in some areas near villages
Contact for Routine Road Maintenance	Mike De Lange 082 779 2993

National Route	N2
Section	Tetyana to Sithebe Komkulu
Distance	17 km
Description	Upgrading of N2 from Tetyana (km 24) to Sitebe Komkulu (Km 41.0)
Expected Travel Condition	
Expected Travel Condition	Mostly 2-way at a maximum speed of 60km/h. Expect stop-go's for short durations.
Duration of work	October 2016 – April 2019
Contact for Routine Road Maintenance	Joe van Dyk 083 283 6507

National Route	N2
Section	Mthatha to Mount Ayliff
Distance	130 km
Description	A 2 lane single carriageway with passing lanes and paved shoulders.
Expected Travel Condition	The Expected Road Condition between km 54 to km 70 is fair however routine maintenance teams may be encountered.
Contact for Routine Road Maintenance	Ernest Zellhuber 072 789 5046

National Route	N2
Section	Brookes Nek (provincial boundary) to Port Shepstone
Distance	135 km
Description	This first section of the N2 in KZN is a two-lane single carriageway with narrow paved shoulders. Passing lanes are provided on all the severe grades with the exception of a short 6 km section, 26 km north of Kokstad.
Expected Road Condition	Good.
Expected Travel Condition	A periodic maintenance contract between Brooksnek and Staffords Post is underway. Traffic is accommodated by Stop/Go controls, with expected delays of up to 20 minutes per closure. There are three closures in place. Occasional night closures can be expected. Motorists are advised to adhere to the reduced speeds as signposted.
Duration of Work	Until November 2017
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	N2
Section	Port Shepstone to Durban (N2/N3 Interchange)
Distance	114 km
Description	The first 20 km is a single carriageway road with three lanes of traffic and narrow paved shoulders allowing overtaking opportunities. Thereafter the road becomes a four-lane dual carriageway with wide paved shoulders. The last 17 km leading into Durban has 3 lanes in each direction and is heavily trafficked.
Expected Road Condition	Good.
Expected Travel Condition	No construction
Duration of Work	
Contact for Routine Road Maintenance	Port Shepstone to Hibberdene: Amit Bhoora 082 442 9646 Hibberdene to Durban: Emeka Mgbemere 083 641 9056 (Route Manager)

National Route	N2
Section	Durban to Empangeni
Distance	162 km
Description	For 71 km, up to Stanger, the road is a four-lane dual carriageway. For the next 52 km, up to the Mtunzini Toll Plaza, the road is a four-lane undivided carriageway with paved shoulders. The remaining portion is a single carriageway with alternating passing opportunities.
Expected Road Condition	Good.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A contract for the periodic maintenance of the N2 from EB Cloete to Mount Edgecombe Interchange has commenced, with construction works to take place at night between 20h00 to 04h00. Lane reductions will be in place 2. A contract for the upgrading of the N2/M41 Mount Edgecombe Interchange to a free-flow systems interchange is in progress. Traffic is being accommodated on temporary deviations, with speed restrictions in place. Traffic travelling on the M41 from Umhlanga towards the N2 North (towards King Shaka Airport) is being temporarily diverted onto a loop ramp. This diversion requires traffic to keep left on the M41 as the right turn movement is closed. Stop/Go controls are in place on the Mt. Edgecombe Drive underpass. 3. A contract for the joint seal replacement and concrete pavement repairs between Umhloti and New Guelderland is in progress. No Stop/Go controls will be in place, but reduced lane widths and speed restrictions will be in place. 4. A contract for localised realignment of the N2 at Umhlali River Bridge and at Umvoti River Bridge is in progress. No Stop/Go controls will be in place, but reduced lane widths and speed restrictions will be in place. 5. A contract for the upgrade of the N2 to a dual carriageway freeway between Mtunzini Toll Plaza and Empangeni T-Junction is in progress. No Stop/Go controls will be in place. 6. A contract for the maintenance of the north coast toll plazas has commenced. There is minimal disruption to traffic except on certain ramp toll plazas.
Duration of work	<ol style="list-style-type: none"> 1. Until April 2018. 2. Until November 2017. 3. Until June 2017. 4. Until October 2017. 5. Until April 2019. 6. Until January 2018.
Contact for Routine Road Maintenance	Emeka Mgbemere 083 641 9056 (Route Manager – Durban to eMdloti) Stollie van Wyk 072 283 6669 (eMdloti to Empangeni)

National Route	N2
Section	Empangeni to Pongola
Distance	250 km
Description	A 2-lane single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	No construction
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	N2
Section	Pongola to KwaZulu-Natal / Mpumalanga Border
Distance	38 km
Description	A 2-lane single carriageway road with passing lanes on the steeper gradients.
Expected Road Condition	Good
Expected Travel Condition	No construction
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	N2
Section	KwaZulu Natal / Mpumalanga border north of Pongola Border to Piet Retief
Distance	57km
Description	A Two-lane single carriageway narrow gravel shoulder.
Expected Road Condition	Good
Expected Travel Condition	Pavement layer repair is on-going on this section
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 076 7790 346

National Route	N2
Section	Piet Retief to Ermelo
Distance	98.20 km
Description	A Two-lane single Carriageway narrow gravel shoulder. First 7km is 4 lane undivided
Expected Road Condition	Good
Expected Travel Condition	Reseal contract between Camden and Ermelo. Expect Stop 'n Go's.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 076 7790 346

N3

National Route	N3
Section	Durban to Cedara (Hilton)
Distance	85 km
Description	This entire section is a multi-lane dual carriageway. The first 4km out of Durban carries heavy traffic with up to 5 lanes in each direction. The next 40 km, up to Cato Ridge, has 3 lanes in each direction with wide paved shoulders. The section between Cato Ridge and the end of the Pietermaritzburg Bypass (33 km) has a two-lane plus paved shoulder configuration, except on steep gradients to the east of Pietermaritzburg where passing lanes are provided. The final 14 km to Howick incorporates the steeply graded Town Hill, which has 3 lanes with paved shoulders in each direction.
Expected Road Condition	Good.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A contract for the upgrade of the Hammarsdale Interchange is ongoing. Periodic blasting will occur for the next six months. There will be minimal disruption to traffic on the N3, with the existing three lanes reduced to two lanes in each direction in the vicinity of the interchange, however there will be disruption to local traffic. 2. There is intermittent closure of the slow lane on the southbound carriageway of Town Hill for surface repairs. Motorists are advised to pay attention to the road signs and speed restrictions.
Duration of Work	<ol style="list-style-type: none"> 1. Until November 2018. 2. Until October 2017.
Contact for Routine Road Maintenance	Emeka Mgbemere 083 641 9056 (Route Manager)

National Route	N3 (The N3 Toll Route operated by N3 Toll Concession (RF) Proprietary Limited)
Section	Cedara to Heidelberg
Distance	415 km
Description	This section of road is a public private partnership between SANRAL and the N3Toll Concession (Pty) Ltd. This toll route is a four-lane dual carriageway road between Cedara and the Tugela Toll Plaza. From the Tugela Toll Plaza to the Wilge Toll Plaza (Villiers) the road is a four-lane single carriageway with shoulders of varying width. The section between the Tugela Toll Plaza and Warden has at-grade intersections and access roads with reduced speed limits signposted. The remainder of the road between Villiers and Heidelberg is a four-lane dual carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	<p>Current planned construction works include:</p> <ol style="list-style-type: none"> 1. Rehabilitation between Cedara and Mooi River. Work commenced in April 2017 and is programmed for completion in February 2019. 2. Rehabilitation between Frere Interchange and the Sand River near the Bergville Interchange. Work commenced in November 2016 and is programmed for completion on 28 February 2018. 3. Rehabilitation between Harrismith and Warden. Work commenced in January 2015 and is programmed for completion by July 2017. 4. Isolated maintenance on Van Reenens Pass during May 2017. 5. Ongoing routine road maintenance, grass cutting and litter collection. <p>Through the construction zones, traffic may be restricted to one lane in each direction under reduced speed.</p> <p>During peak traffic period 27 April to 1 May, there will be 2 lanes open to traffic in both directions. No work is planned for those periods unless an emergency arises.</p> <p>Road users are urged to obey the posted speed limits, maintain safe following distances and to refrain from littering.</p>
Duration of Work	Please see above. Maintenance personnel will be on standby to deal with any emergency repairs.
Contact for Routine Road Maintenance	N3TC Customer Care Line 0800 634 357 0800 N3 HELP

National Route	N3
Section	Balfour Interchange to Vosloorus (Barry Marais road)
Distance	38.2km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marthinus Wilken 082 782 1746

National Route	N3
Section	Vosloorus / Barry Marais Road to Buccleuch Interchange
Distance	43.0km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Routine Road Maintenance teams may be encountered
Expected Travel Condition	Good
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marthinus Wilken 082 782 1746

N4

National Route	N4 (Platinum Highway)
Section	Botswana Border to Zeerust
Distance	60 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Major roadworks upgrade from Zeerust. Expect Stop n Go's
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Zeerust to Rustenburg
Distance	120 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Rehabilitation between Zeerust and Swartruggens Plaza. Expect Stop n Go's
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Rustenburg to Brits (R512 Interchange)
Distance	70 km
Description	Two-lane single carriageway freeway.
Expected Road Condition	Good.
Expected Travel Condition	Motorists must be aware and be on the lookout for pedestrians and animals in the Bapong area. Adhere to posted speed limits. Road markings taking place. Expect narrowing of lanes
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 – West Magalies
Section	Brits (R512 Interchange) to Hartebeesport
Distance	8.8km
Description	Single Carriageway with gravel shoulders
Expected Road condition Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop 'n Go's between Broederstroom and Pampoennek until June 2017
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N4 (Platinum Toll Highway)
Section	Brits (R512 Interchange) to Pretoria (N1)
Distance	52 km
Description	Two-lane dual carriageway freeway.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Road markings taking place. Expect narrowing of lanes Roadworks upgrade at the Doornpoort Plaza.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 West Magalies Toll Road
Section	Pretoria (Rebecca Street) to Pelindaba
Distance	21 km
Description	Mixture of two-lane dual carriageway and two-lane single carriageway freeway.
Expected Road Condition	Good.
Expected Travel Condition	There are upgrades happening at both Quagga and Pelindaba Toll Plazas until mid-September 2015. Expect delays through these 2 plazas. Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168
National Route	N4
Section	Pretoria to Hans Strydom Interchange
Distance	13.6 km
Description	A 6-lane dual carriageway road up to Simon Vermooten Interchange, thereafter a 4-lane dual carriage way.
Expected Road Condition	Good.
Expected Travel Condition	Be alert of hijackers at Townland offramp. Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N4
Section	Hans Strydom Interchange to Mozambique
Distance	304 km
Description	Four-lane dual carriageway from Hans Strydom Int. to Van Dyk's Drift. Thereafter, a four-lane undivided road to Wonderfontein, then 2 lanes undivided to the Mozambique border.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Road Rehabilitation between Middelburg and Wonderfontein Cross Roads and Waterval Onder (Expect 15-20 min stop n go). Wilge River I/C and Balmoral / Kusile I/C
Duration of Work	
Contact for Routine Road Maintenance	Trans African Concessionaires (TRAC) 013 755 3316

National Route	N4
Section	3Y Ellen street to Middelburg
Distance	21.09km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair to satisfactory. Poor road markings. Road go through residential area with entrances both sides of the road. Shoulders in bad state both sides of the road Be alert of coal trucks
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N4
Section	Nelspruit: Valencia Road to N4
Distance	8.6km
Description	Single carriageway with gravel shoulders.
Expected Road Condition Expected Road Condition	Surfacing Fair to Good.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andrie Van Niekerk 076 481 5276

N5

National Route	N5
Section	Harrismith to Bethlehem
Distance	88 km
Description	A two-lane single carriageway with wide paved shoulders. There are overtaking opportunities where severe grades occur.
Expected Road Condition	Good.
Expected Travel Condition	A contract for the upgrade of the N5 between Harrismith and Industriqwa, including construction of an interchange at Murray Street, is in progress. No Stop/Go Controls will be in place.
Duration of Work	Until January 2018
Contact for Routine Road Maintenance	Gert de Lange 079 162 2981 (Route Manager)

National Route	N5
Section	Bethlehem to Winburg
Distance	120 km
Description	A two-lane single carriageway with varying width of either paved or gravel shoulders. There are overtaking opportunities where severe grades occur.
Expected Road Condition	Fair to good
Expected Travel Condition	Maintenance crews will be active with occasional localised Stop/Go controls for asphalt patching work, between Bethlehem and Winburg.
Duration of Work	Maintenance crews are continuously active.
Contact for Routine Road Maintenance	Gert de Lange 079 162 2981 (Route Manager)

N6

National Route	N6
Section	East London to Stutterheim
Distance	70 km
Description	A two-lane single carriageway with paved shoulders and passing lanes in places
Expected Travel Condition	Fair to good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Stutterheim to Cathcart
Distance	49 km
Description	A two-lane single carriageway with paved shoulders and passing lanes in places
Expected Travel Condition	Good.
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Cathcart to Queenstown
Distance	59 km
Description	A two-lane single carriageway with paved shoulders and passing lanes in places.
Expected Travel Condition	Completed
Expected Travel Condition	Fair to Good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Queenstown to Jamestown
Distance	107km
Description	A two lane single carriage way with paved shoulders
Expected Travel Condition	Good
Duration of Work	
Contact for Routine Road Maintenance	Flip Jacobs 0825635218
Expected Travel Condition	

National Route	N6
Section	Jamestown to Aliwal North
Distance	58 km
Description	A two-lane single carriageway with paved shoulders.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218
Expected Travel Condition	

National Route	N6
Section	Aliwal North to Bloemfontein
Distance	200 km
Description	Predominantly, a two- lane single carriageway with only the last 2.36km of National Route 6 having wide paved shoulders. The rest of the route has gravel shoulders of varying widths.
Expected Road Condition	The road between Rouxville and Smithfield is in a fair condition with some pavement repair teams working ad hoc. The road between Paryshoogte and Bloemfontein is in a good condition.
Expected Travel Condition	1. There are pavement repair teams working ad hoc between Rouxville and Smithfield. 2. A contract for the periodic maintenance of the N6 between Reddersburg and Rustfontein commenced in November 2016. Traffic will be accommodated by Stop/Go controls.
Duration of Work	1. Teams working ad hoc. 2. Until September 2017.
Contact for Routine Road Maintenance	Johnny Rodgers 082 772 9804

N7

National Route	N7
Section	Melkbos Turn-off to Clanwilliam
Distance	198 km
Description	Dual carriageway with paved shoulders
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Jerome Buys 082 328 9422
Construction Works:	<p>Atlantis Turn-off to Kalbaskraal The speed limit throughout the construction area has been lowered to 60km/h and to be adhered to.</p> <p>Motorist can encounter no day & night Stop/Go closures at this stage.</p> <p>Abbotsdale to Voortrekker Road Interchange The speed limit throughout the construction area has been lowered to 40 – 60km/h and to be adhered to.</p> <p>Dual Carriageway North of Darling Road Interchange has been closed and traffic on the South Bound carriageway has been diverted onto the North Bound carriageway at a point halfway between the Voortrekker and Darling road interchanges. Two way traffic is currently accommodated on the North Bound carriageway over the full 4km extent of the project.</p> <p>A dedicated lane for heavy vehicles to stop and engage lowest gear has been introduced on the Southbound carriageway just prior to the traffic diversion referred to above. The speed regulation has been lowered from 80km/h to 60km/h and winding curves have been introduced as a traffic calming mechanism.</p> <p>All off ramps remain functional but slightly hidden/obscured and the public are therefore requested to drive slowly and be alert to the directional signage provided at the off ramps. Some confusion exists for traffic approaching from the North, driving toward Cape Town, who tend to overlook the right hand diversion to Cape Town (N7 continuation).</p> <p>Road and Bridge construction activities are taking place extensively in the interchange and are also consistent between the 4km construction limits.</p> <p>Stop/Go control points are an exception (on the N7) and are generally operational only in the event of routine maintenance being carried out on the existing road surface.</p> <p>The public must be aware of slow moving heavy vehicles entering and exiting the roadway.</p> <p>Due to the urban environment many pedestrians can be expected to be crossing the road for which extra caution is necessary.</p> <p>Voortrekker Road to Hopfield Intersection The speed limit throughout the construction area has been lowered to 60km/h and to be adhered to.</p> <p>Duration of Work: July 2019</p>

National Route	N7
Section	Clanwilliam to Western Cape /Northern Cape Border
Distance	139.075 km
Description	Single carriageway with paved and / or gravel shoulders
Expected Road Condition	Fair
Expected Travel Condition	<p>Trawal - Klawer</p> <p>The speed limit throughout the construction area has been lowered to 60km/h and to be adhered to.</p> <p>No permanent stop/go control points are in operation at this stage, but traffic must be aware of slow moving heavy vehicles entering and exiting the roadway at the Melkboom turn-off.</p> <p>Routine Road Maintenance teams may be encountered</p>
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Louis Burger 074 193 2978

National Route	N7 Section 8
Section	Northern Cape Border to Vioolsdrift
Distance	412km
Description	Single carriageway with gravel shoulders and no passing lanes. Rest areas at regular intervals
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Driaan Koegelenberg 071 683 5392

N8

National Route	N8
Section	Groblershoop to Kimberley
Distance	285 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Expected Travel Condition	Fair.
Expected Travel Condition	Motorists should be alert to stray animals. The route is prone to Kudu buck in the roadway between dusk and dawn Routine Road Maintenance Teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pottie Potgieter 082 566 7301

National Route	N8
Section	Kimberley to Bloemfontein
Distance	150 km
Description	Predominantly, a two-lane single carriageway. The 29 km section between Kimberley and Perdeberg has paved shoulders, while the final eight km immediately adjacent to Bloemfontein is a four – lane dual carriageway with wide paved shoulders. The remainder of the road has gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	A contract for periodic maintenance between De Brug Farm and Petrusburg is in progress. Traffic is accommodated by Stop/Go controls.
Duration of Work	Until July 2017
Contact for Routine Road Maintenance	Riaan Louwrens 074 601 8998

National Route	N8
Section	Bloemfontein to Maseru
Distance	135 Km
Description	The first five km section from Bloemfontein is a four-lane dual carriageway with wide paved shoulders. Between Bloemfontein and Thaba Nchu there are alternating passing and passing lanes. Between Thaba Nchu and Ladybrand is a two-lane single carriageway road with shoulders of varying widths. Route 26/N8-13 (km 0.0) to Maseru Border (km 11.75) is in good condition.
Expected Road Condition	Good
Expected Travel Condition	<ol style="list-style-type: none"> 1. Rehabilitation work is in progress on Section 11 between Bloemspruit (km 7.0) and Sannaspos (km 31.3). Motorists will encounter reduced speed limits with bi-directional traffic accommodation. 2. A contract for the periodic maintenance between Ladybrand and the Maseru Border commenced in January 2017. 3. A contract for the construction of a crawler lane between km 8.2 and km 11.04 towards Maseru adjacent to the N8 commenced in January 2017.
Duration of Work	<ol style="list-style-type: none"> 1. Completion date is June 2017. 2. Until end June 2017. 3. Until end October 2017.
Contact for Routine Road Maintenance	Johnny Rodgers 082 772 9804

N9

National Route	N9
Section	Western Cape and Eastern Cape Boundary to Aberdeen
Distance	138 km
Description	A two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Good
Expected Travel Condition	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Elandre van Eck 071 679 1349

National Route	N9
Section	Aberdeen to Graaff Reinet
Distance	54 km
Description	A two-lane single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Elandre van Eck 071 679 1349

National Route	N9
Section	Graaff-Reinet to Middelburg
Distance	105 km
Description	A Two-Lane single carriageway with paved shoulders
Expected Travel Condition	Good.
Expected Travel Condition	No construction. Routine road maintenance.
Contact for construction work	Elandre van Eck 071 679 1349

National Route	N9
Section	Middelburg to the intersection of the N10 and N9 between Middelburg and Noupoort (Carlton Heights)
Distance	24 km
Description	In construction
Expected Travel Condition	Busy with construction.
Expected Travel Condition	Construction works have commenced and will continue for 3 years. Traffic will be diverted through Middelburg town for first 6km and temporary short term closures during blasting period.
Duration of work	13 April 2015 to 13 August 2019
Resident Engineer	Sam Renny 083 799 3638
Contact for Routine Road Maintenance	Elandre van Eck 071 679 1349

National Route	N9
Section	Carlton Heights to Colesburg
Distance	70 km
Description	Single carriageway with paved shoulders and passing lanes. Rest areas at regular intervals.
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Martiens du Plessis 083 655 0644

N10

National Route	N10
Section	Nanaga-Paterson
Distance	24 km
Description	Two lane single carriageway road. Some passing lanes
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Paterson – Olifantskop Pass
Distance	23 km
Description	Two lane single carriageway road. Some passing lanes in pass
Expected Travel Condition	Good
Duration of work	
Expected Travel Condition	
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Jaskraal to Baviaans River
Distance	43 km
Description	Two lane single carriageway road with paved shoulders
Duration of work	Complete
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Olifanskop Pass to Baviaans River north of Cookhouse
Distance	134 km
Description	Complete
Expected Travel Condition	Good
Contact for routine Road Maintenance	Marco Du Plessis 079 893 6256

National Route	N10
Section	Baviaans River to Riet River
Distance	25 km
Description	Two-lane single carriageway.
Expected Travel Condition	Good
Expected Travel Condition	The upgrade contract for this section of the road is complete.
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Riet River to Tarka River
Distance	37 km
Description	Two-lane single carriageway with narrow paved shoulders. There is 1 stop/go control in place. Expect delays of at least 15 minutes. Deviations in bad condition and narrow, motorists to travel with caution.
Expected Travel Condition	Under construction for 2 years. Scheduled for completion in December 2016.
Residednt Engineer	Johan Knoetze 0824174778
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Cradock to Middelburg
Distance	95 km
Description	The first 43 km is a two-lane single carriageway road with wide paved shoulders. The last 30 km is a two-lane single carriageway road with gravel shoulders.
Expected Travel Condition	Fair.
Expected Travel Condition	
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256
Duration	
Contact for Construction	

National Route	N10
Section	Ludlow (Intersection of the N10 and N9 between Middelburg and Noupoort) to Prieska
Distance	300 km
Description	Single carriageway with paved and/ or gravel shoulders.
Expected Travel Condition	Good
Expected Travel Condition	De Aar to Prieska Rejuvenation of N10. No road closures are expected. The public is to adhere to speed limits. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Milton van Heerden 083 362 9707

National Route	N10
Section	Prieska to Nakop (at Namibian Border)
Distance	379 km
Description	Single carriageway with paved and / or gravel shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Prieska to Groblershoop Rejuvenation of N10. No road closures are expected. The public is to adhere to speed limits. Groblershoop to Upington The speed limit throughout the construction area has been lowered and to be adhered to. Construction work consist of widening and improvement of roads and bridges. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Mzo Ntebe 079 017 9353

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

N11

National Route	N11
Section	N3 Bergville Interchange to Newcastle
Distance	115 km
Description	A two-lane single carriageway with narrow shoulders, except for the 16 km portion before Newcastle and for short sections through the Biggarsberg Mountain range, where there are passing lanes.
Expected Road Condition	Variable, generally good.
Expected Travel Condition	No construction work
Duration of Work	
Contact for Routine Road Maintenance	Ms Asanda Koti 079 151 2451

National Route	N11
Section	Newcastle to Volksrust
Distance	54 km
Description	Apart from the 9 km that constitute the Newcastle Bypass and the 17 km that make up the Laingsnek (Majuba) Mountain Pass, the road is a single carriageway, with narrow paved shoulders.
Expected Road Condition	Fair to good
Expected Travel Condition	A contract for the periodic maintenance of the N11 between Kwaggasnek and Volksrust has commenced. Traffic is accommodated by Stop/Go controls.
Duration of Work	Until May 2017
Contact for Routine Road Maintenance	Ms Asanda Koti 079 151 2451

National Route	N11
Section	Volksrust to Amersfoort
Distance	42.58 km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	N11
Section	Amersfoort to Msukaligwa Municipal Border / Vaal River
Distance	27.88km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should also be alert of stray animals North of Amersfoort km 0.8-3.0 Motorist should be alert of the vast quantity of coal trucks from Vaal River to Amersfoort
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	N11
Section	Msukaligwa Municipal border / Vaal River to Ermelo
Distance	29.85km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Vaal River to Ermelo
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	N11
Section	Ermelo to Hendrina
Distance	51.10km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Hendrina to Ermelo
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	N11
Section	Hendrina to Middelburg –N4 Interchange
Distance	41.97km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Road Marking faded at Woestalleen km 26 Motorist should be alert to the vast quantity of coal trucks from Hendrina to Middelburg
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	N11
Section	Middelburg to Loskop
Distance	81.030km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair to Good. Damwall poor road marking High accident zone (Kranspoort mountain pass) km 36 Construction at Kranspoort Pass until December 2017 Expect up to 90 minute delays on Monday and Friday, from 09h00 to 16h30. On Tuesday, Wednesday and Thursday the pass will be closed from 11h00 to 15h00. Saturday and Sunday the pass will be open except for the normal stop go delays.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N11
Section	Loskop to Mookgopong Municipal Border
Distance	44.3km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair to Good. Poor road marking
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N11
Section	Mookgopong Municipal Border to Mokopane Weigh Bridge / N1/25X Intersection
Distance	89.04km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane 076 886 9997

National Route	N11
Section	Mokopane to Martin's Drift border post (Botswana)
Distance	188km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Hannelie Swanepoel 082 380 5264

N12

National Route	N12
Section	Three Sisters to Hopetown
Distance	299 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Orange River to Hopetown The speed limit throughout the construction area has been lowered and to be adhered to. Construction work consist of widening and improvement of roads and bridges. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Charl Muishond 072 746 9827

National Route	N12
Section	Hopetown to Northern Cape Border at Warrenton
Distance	203 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Hopetown to Voetpaddrift The speed limit throughout the construction area has been lowered and to be adhered to. Construction work consist of resurfacing the road. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Zandile Gaba 082 550 9083

National Route	N12
Section	North West / Northern Cape Border at Warrenton to Christiana
Distance	28.8 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	N12
Section	Christiana to Bloemhof
Distance	57.9 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	N12
Section	Bloemhof to Wolmaranstad
Distance	62.2 km
Description	Two-lane single carriageway with paved shoulders.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	N12
Section	Wolmaransstad to Klerksdorp
Distance	75 km
Description	Two-lane single carriageway with wide paved shoulders on most of the section, except closer to Klerksdorp.
Expected Road Condition	Good to very good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	N12
Section	Klerksdorp to Potchefstroom
Distance	38.8km
Description	Two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Road closed between Klerksdorp and Stilfontein due to a sink hole within the road reserve. Please follow the detour road signs
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	N12
Section	Potchefstroom to Westonia Municipal Border
Distance	57.4 km
Description	Two-lane narrow single carriageway with passing lanes.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	N12
Section	Diepkloof Interchange to Elands Interchange
Distance	17.2km
Description	Four-lane dual carriageway freeway.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pierre Coetzer 076 107 7322

National Route	N12
Section	Gilloolly's Interchange to Mpumalanga / Gauteng Border
Distance	41km
Description	Multi-lane dual carriageway with paved shoulders

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Road Condition	Routine Road Maintenance teams may be encountered
Expected Travel Condition	Good.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746

N14

National Route	N14
Section	Springbok to Keimoes
Distance	335 km
Description	Single carriageway with paved / gravel shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Claudia Jannetjies 078 675 8971

National Route	N14
Section	Keimoes to Western Cape / Northern Cape Border
Distance	303 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Upington to Kuruman Construction is ongoing on the Olifantsloop River Bridges and Sishen River Bridge Motorist are requested to adhere to the speed limit and cross the bridges at the indicated reduced speeds to ensure the safety of all road users. Olifantshoek bridge closed for abnormal loads. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Peet van Wyk 082 406 6371

National Route	N14
Section	Northern Cape / North West Border to Vryburg
Distance	86 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition:	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Samu Ndlovu 079 563 4564

National Route	N14
Section	From Junction at R34 & N14 Section 9 to Junction at N18 in Vryburg
Distance	6 km
Description	A two-lane carriageway with concrete kerbing through town up to N18 crossing.
Expected Road Condition	Poor to Fair.
Expected Travel Condition	Constant pothole & pavement layer failure repairs attended to by RRM team
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Samu Ndlovu 079 563 4564

National Route	N14
Section	Vryburg to Delareyville
Distance	76 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Delareyville to Sannieshof
Distance	37.6 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to poor.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Sannieshof to Coligny
Distance	61.9 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Coligny to Ventersdorp
Distance	68.8 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Ventersdorp to North West / Gauteng Border
Distance	49.7km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

N17

National Route	N17
Section	Soweto to Nasrec
Distance	6 km
Description	Double carriageway road with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Unita Fugile 072 793 2825

National Route	N17
Section	Wemmerpan to Geldenhuys Interchange
Distance	7.8 km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Unita Fugile 072 793 2825

National Route	N17
Section	Geldenhuys Interchange to Springs
Distance	38.8Km
Description	Multi lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Unita Fugile 072 793 2825

National Route	N17
Section	Springs to Leandra Toll
Distance	40.2 km
Description	Single carriageway with passing lanes and gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Motorists should be alert to stray animals north of Leandra Toll Plaza
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 072 647 8142

National Route	N17
Section	Leandra Toll to Bethal
Distance	72.2 km
Description	Single carriageway with passing lanes and paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Motorists should be alert to stray animals north of Leandra Toll Plaza.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 072 647 8142

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	N17
Section	Bethal to Ermelo
Distance	55.72 km
Description	Single carriageway with passing lanes and paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 072 647 8142

National Route	N17
Section	Ermelo to Oshoek Border Post (Swaziland)
Distance	122.64km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Poor
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

N18

National Route	N18 (R49)
Section	Warrenton to Hartswater North / North West Border
Distance	52 km
Description	Single carriageway with paved shoulders
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Zandile Gaba 082 550 9083

National Route	N18
Section	Northern Cape / North West Border South of Taung to Pudimore
Distance	27.54km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Beware of stray animals
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Samu Ndlovu 079 563 4564

National Route	N18
Section	Pudimore to Vryburg
Distance	48.62 km
Description	Single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Beware of stray animals
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Samu Ndlovu 079 563 4564

National Route	N18
Section	Vryburg to Stella
Distance	47.44 km
Description	Single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

National Route	N18
Section	Stella to R375 Intersection
Distance	65 km
Description	Single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

National Route	N18
Section	R375 Intersection to Mahikeng
Distance	65 km
Description	Single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

National Route	N18
Section	Mahikeng to Ramatlabama Border Post
Distance	17.019km
Description	Single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

OTHER NATIONAL ROUTES

National Route	D157
Section	Groblersdal to Hlogotlou
Distance	38.882 km
Description	Two lane single carriageway with no paved shoulders
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Maxwell Baloyi 078 972 4445

National Route	D797
Section	One Tree Hill to Tonga
Distance	27.508 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair with uneven riding surface.
Expected Travel Condition	Routine road maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	D1120
Section	Komatipoort to Crocodile Bridge Gate
Distance	8.942 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	D2948
Section	D797 Tonga to Emangweni
Distance	10.196 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	P154
Section	7
Distance	3.84km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Koos Beukes 072 444 5742

National Route	P720
Section	N2 to Golela Border Post with Swaziland
Distance	10 km
Description	A Single carriageway road between National Route 2 and Golela Border Post. Two lanes and a narrow paved shoulder and wide gravel shoulder in each direction.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	R21
Section	Northrand Rand to Olifantsfontein Interchange
Distance	26km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746

National Route	R21
Section	Olifants Interchange to Hans Strydom Intersection
Distance	18km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746

National Route	R22
Section	Hluhluwe to Farazela (RSA/Mozambique border)
Distance	175 km
Description	A 2-lane single carriageway road with narrow paved shoulders throughout.
Expected Road Condition	Good
Expected Travel Condition	1. A periodic maintenance contract between Mseleni River and Phelendaba is ongoing. Temporary road surface and temporary line markings in place. 2. Two projects for the construction of walkways adjacent to the R22 between Phelendaba and Mozambique Border are ongoing. There is minimum disruption to traffic.
Duration of Work	1. Until December 2017 2. Until November 2017
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	R23
Section	Volksrust to Standerton
Distance	78.4km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Fairly Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Roadworks for the first 30 km. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Zachrys Joubert 072 123 4455

National Route	R23
Section	Standerton to Gauteng / Mpumalanga Border
Distance	99.3 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair to good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered between km 0 up to km 4 and Km 56 up to km 86.4 during the day. Reconstruction projects are between Km 4 up to km 56 with permanent road closures at some areas. STOP/GO Reseal contract between Balfour and MP/GP border. Expect Stop 'n Go's.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Zachrys Joubert 072 123 4455

National Route	R24
Section	Rustenburg to Northwest/Gauteng Border
Distance	45km
Description	Two lane double carriageway with paved shoulders between Buiten Street and Oorsak Road. The remaining section is a two lane carriageway with passing lanes through Olifantsnek Pass with gravel shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Reconstruction projects are between Buiten Street and Oorsak Road with permanent road closures at some areas
Duration of Work	Ends June 2017
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R27
Section	Van Rhynsdorp to Brandvlei
Distance	236 km
Description	Single carriageway road with 1 metre surfaced shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Jacques Wentzel 079 514 3496

National Route	R27
Section	Brandvlei to Keimoes
Distance	221 km
Description	Single carriageway road with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6553

National Route	R30/R730/R34 Toll Road
Section	Bloemfontein to Kroonstad via Brandfort/Welkom
Distance	210 km
Description	A single carriageway between National Route N1 and Virginia. It accommodates two lanes and has wide paved shoulders and ad hoc passing lanes in each direction. The section between Virginia and Welkom is a double carriageway and the section between Welkom and Kroonstad is a four-lane undivided carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	No construction
Duration of work	
Contact for Routine Road Maintenance	Abel Majorobela 079 896 3377

National Route	R30
Section	Free State / North West Border to Klerksdorp
Distance	14.5 km
Description	Two-lane narrow single carriageway with gravelshoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R30
Section	Klerksdorp to Ventersdorp
Distance	68.8 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R30
Section	Ventersdorp to Olifants Nek
Distance	76.6 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair with uneven riding surface.
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop/go's may occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Theuns Jooste 076 751 9898

National Route	R33
Section	Kwazulu Natal / Mpumalanga Border to Piet Retief
Distance	48.3 km
Description	A Two-lane single Carriageway narrow gravel shoulder.
Expected Road Condition	Good
Expected Travel Condition	Normal Maintenance on this section
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 076 7790 346

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R33
Section	Piet Retief to Amsterdam
Distance	35.9 km
Description	A Two-lane single Carriageway narrow gravel shoulder.
Expected Road Condition	Good
Expected Travel Condition	Normal Maintenance on this section
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 076 7790 346

National Route	R33
Section	Amsterdam to Warberton
Distance	88.54 km
Description	A two-lane single carriageway narrow gravel shoulder.
Expected Road Condition	Good
Expected Travel Condition	Normal Maintenance on this section
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 076 7790 346

National Route	R33
Section	Warburton (from N17/5) to Carolina
Distance	38km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R33
Section	Carolina to Belfast (N4)
Distance	49.2km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R33
Section	N11 – Marble Hall to Modimolle R101
Distance	88.3 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair with poor road markings.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	R33
Section	Vaalwater to Lephalale – R510
Distance	85.3 km
Description	Single carriageway with limited paved shoulders otherwise gravel shoulders.
Expected Road Condition	Fair to Good Km 0.0 – 85.3 poor road markings
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gustav fouche 082 780 2391

National Route	R34
Section	Vryburg to Schweizer Reneke
Distance	64.86 km
Description	First 3km a two lane carriageway with paved shoulders 2nd 30 km a two lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles
Expected Road Condition	Fair to poor, constant pothole & pavement layer failure repairs attending by RRM Teams, average travel time from 30 minutes to 40 minutes
Expected Travel Condition	Roadworks: Rehabilitation contract between Vryburg and Schweizer Reneke. Expect Stop 'n Go's.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R34
Section	Schweizer Reneke to Bloemhof
Distance	60 km
Description	First 34km a two lane carriageway with paved shoulders 2nd 31 km a two lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles
Expected Road Condition	Fair to poor
Expected Travel Condition	Constant pothole & pavement layer failure repairs attended to by RRM Teams Roadworks: Rehabilitation contract between Schweizer Reneke and Bloemhof. Expect Stop 'n Go's.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R34
Section	Bloemhof to North West / Free State Border
Distance	6.7 km
Description	Two lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles
Expected Road Condition	Fair to poor
Expected Travel Condition	Constant pothole & pavement layer failure repairs attended to by RRM Teams
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R35
Section	Ameersfoort to Bethal
Distance	76.57km
Description	
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Rehabilitation in progress from Amersfoort to Morgenzon No STOP/GO controls predicted Motorist should be alert to the vast quantity of coal trucks
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	R35
Section	Bethal to Middelburg
Distance	71.03km
Description	
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks Reseal contract between Komati and Middelburg. Expect Stop 'n Go's.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	R36
Section	Mpumalanga Border to Dublin
Distance	102.2km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Stop/Go traffic accommodation on the Abel Erasmus Pass section Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R36
Section	Dublin to Ofcolaco
Distance	53.7km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R36
Section	Ofcolaco to Tzaneen
Distance	33.5km
Description	Single carriageway y with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal works for 20km (Expect Stop and Go's)
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R36
Section	Tzaneen to Modjadjiskloof
Distance	17.8km
Description	Km 2.3 to km 7.0 double carriageway. Km7 – 19.5 Single carriageway. Mostly paved shoulders.
Expected Road Condition	Surfacing Good. Line markings fair.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Stephan Du Plessis 084 491 1165

National Route	R36
Section	Modjadjiskloof - Soekmekaar
Distance	44.43km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Stephan Du Plessis 084 491 1165

National Route	R36
Section	Soekmekaar - Bandelierkop
Distance	17.8km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Stephan Du Plessis 084 491 1165

National Route	R37
Section	Polokwane Burgersfort
Distance	142km
Description	Four lane dual carriageway from km 0 to km 12 & thereafter two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Nathanael Pillay 074 309 0937

National Route	R37
Section	Burgersfort to Lydenburg
Distance	64 km
Description	Single carriageway road with paved shoulders.
Expected Road Condition	First km 5-48 fair condition. Patching complete Rest fair to good
Expected Travel Condition	Routine Road Maintenance teams may be encountered as well as STOP/GO on some sections
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Andrie Van Niekerk 076 481 5276

National Route	R37
Section	Lydenburg to Sabie
Distance	43.94Km
Description	Single carriageway road with mostly paved shoulders.
Expected Road Condition	Fair to good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Andrie Van Niekerk 076 481 5276

National Route	R37
Section	Sabie to Nelspruit
Distance	49.20km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Contact for Routine Road Maintenance	Andrie Van Niekerk 076 481 5276

National Route	R38
Section	Bethal to Hendrina
Distance	43km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tankiso Makhele 071 615 1503

National Route	R38
Section	Hendrina to Carolina
Distance	42.9km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R38
Section	Carolina to Badplaas
Distance	52.8km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R38
Section	Badplaas to Barberton R40)
Distance	59km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good, recently resealed
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R40
Section	Barberton to Nelspruit
Distance	32.77km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andrie Van Niekerk 076 481 5276

National Route	R40
Section	White River to Hazyview
Distance	48.7
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andrie Van Niekerk 076 481 5276

National Route	R40
Section	Klaserie to Hoedspruit
Distance	26.79km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Wild animals may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R40
Section	Hoedspruit to Mica
Distance	32.20km
Description	Single carriageway with limited paved shoulders, otherwise gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Wild animals may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R40
Section	Mica to Junction with R71 west of Phalaborwa
Distance	36.8km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Poor. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Wild animals may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R49
Section	Mafikeng to Zeerust
Distance	61 km
Description	A two lane single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks: Reseal contract between Mafikeng and Zeerust. Expect Stop 'n Go's.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R49
Section	Zeerust to Kopfontein Border Botswana (P87/1)
Distance	98.8km
Description	A two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair with isolated potholes, base & surface repairs from time to time.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks: Reseal contract between Zeerust and Kopfontein Border. Expect Stop 'n Go's.
Duration of work	Routine Maintenance Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R52
Section	Biesiesvlei to Lichtenburg
Distance	36.6km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair with uneven riding surfaces
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Theuns Jooste 076 751 9898

National Route	R52
Section	Koster to Rustenburg
Distance	38.7 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Kobus Vermeulen 082 850 7361

National Route	R53
Section	Parys to Potchefstroom
Distance	44.7 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R53
Section	Potchefstroom to Ventersdorp
Distance	58.5km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Very Poor to extremely Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R54
Section	Potchefstroom to Emfuleni Local Municipality Border
Distance	42.60 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R56
Section	1, N9 Middleburg to Steynsburg
Distance	85km
Description	Two lane single carriage way
Expected Road Condition	First 16km is in fair condition. Further, the condition is newly surfaced and good.
Expected Travel Condition	
Duration of work	
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

National Route	R56
Section	2, Steynsburg to Molteno
Distance	57km
Description	Two lane single carriage way
Expected Road Condition	Poor
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

National Route	R56
Section	3, Molteno to N6
Distance	35km
Description	Two lane carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	4, N6 to Dordrecht
Distance	35km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	5, Dordrecht to Indwe
Distance	38km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	6, Indwe to Elliot
Distance	56km
Description	Two lane single carriage way
Expected Road Condition	Special maintenance project between Indwe via Elliot to Maclear for a period of 30 months as from February 2016 to August 2018.
Expected Travel Condition	Expect Stop/Go conditions with 20 minute delays.
Duration of work	30 months, from Feb 2016 to August 2018.
Resident Engineer	Ian Posselt 084 585 5895
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	7, Elliot to Maclear
Distance	68km
Description	Two lane single carriage way
Expected Road Condition	Special maintenance project between Indwe via Elliot to Maclear for a period of 30 months as from February 2016 to August 2018.
Expected Travel Condition	Expect Stop/Go conditions with 20 minute delays.
Duration of work	Ongoing
Resident Engineer	Ian Posselt 084 585 5895
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R56
Section	8, Maclear KZN Border
Distance	168km
Description	Two lane single carriage way
Expected Road Condition	Fair (Construction ongoing)
Expected Travel Condition	Reseal between Maclear and Mount Fletcher started in January 2016. It is a 14 months contract – March 2017. There are stop/go conditions.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R56
Section	9, Mt Fletcher to Matatiele
Distance	66km
Description	Two lane single carriage way
Expected Road Condition	Good
Expected Travel Condition	Reseal between Matatiele and Mount Fletcher. Complete.
Duration of work	Complete
Contact for Routine Road Maintenance	Riaan Davids 082 553 4878
Contact for Construction	

National Route	R56
Section	10, Matatiele to Eastern Cape Border
Distance	37km
Description	Two lane single carriage way
Expected Road Condition	Fair to poor
Expected Travel Condition	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Davis 082 553 4878

National Route	R58
Section	Section 2 from Km 33 - 58
Distance	22km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	Good.
Duration of work	Complete
Contact for Routine Road Maintenance	Happy Maduna 083 282 5256

National Route	R58
Section	3, Burgersdorp to Aliwal North N6
Distance	55km
Description	Two lane single carriage way
Expected Road Condition	Good
Expected Travel Condition	
Duration of work	
Contact for Routine road maintenance	Happy Maduna 083 282 5256

National Route	R58
Section	4, Aliwal North N6 to Lady Grey
Distance	49km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Duration of work	Ongoing
Contact for construction	Happy Maduna 083 282 5256

National Route	R58
Section	Lady Grey to Barkley East
Distance	66km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Duration of work	Ongoing
Contact for construction	Happy Maduna 083 282 5256

National Route	R58
Section	Barkly East to Elliot
Distance	62km
Description	Two lane single carriage way
Expected Road Condition	Fair
Duration of work	Ongoing
Contact for construction	Happy Maduna 083 282 5256

National Route	R61
Section	1 (East Cape/West Cape Border to Aberdeen)
Distance	74.5 km
Description	Narrow, single carriageway road with 2 lanes
Expected Travel Condition	Fair
Expected Travel Condition	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Elandre van Eck 071 679 1349

National Route	R61
Section	Bethesda (N9 Intersection) to Cradock (N10 Intersection)(section 2)
Distance	85.8 km
Description	A narrow 2-lane single carriageway with gravel shoulders over most of the length.
Expected Travel Condition	Fair. Poor in places.
Duration of work	Phase 2: Km 43 to Km 85 (N10) commenced in March 2016 (Phase 2 construction period is 34 months)
Expected Travel Condition	Construction in place over 43km on the eastern half of this section. Km 43 to Km 85. No lines on this section. Proceed with care. Up to 3 stop/go's in operation.
Contact person for construction	Johan Pistorius 083 329 0060
Contact for Routine Road Maintenance	Charmaine Diedreicks 079 893 7777

National Route	R61
Section	Cradock (N10 Intersection) to Tarkastad (section 3)
Distance	74.5 km
Description	A narrow 2-lane single carriageway with gravel shoulders
Expected Travel Condition	0-24km Fair 24-75kmFair to poor.
Expected Travel Condition	Construction over 27km, in the middle of this section, km 24 to 51. Motorists to be aware of wild animals in rural areas and pedestrians in urban areas at Cradock and Tarkastad. Temporary closures for blasting can be anticipated. Construction on phase 2 will commence in May 2017.
Duration of work	Construction period for phase 2 is 18 months.
Contact for Routine Road Maintenance	Charmaine Diedericks 079 893 7777
Contact for construction	Geoffrey Willmore 083 400 7016

National Route	R61
Section	Tarkastad to Queenstown (section 4)
Distance	63.1km
Description	A 2 lane single carriageway with surfaced shoulders.
Expected Travel Condition	Fair. Newly opened sections are in very good condition.
Expected Travel Condition	Construction is now complete. Localised work-sites for drainage and road marking will be encountered. Motorists to be aware of wild animals and livestock in rural areas and pedestrians in urban areas of Tarkastad and Queenstown.
Contact for Routine Road Maintenance	Charmaine Diedericks 079 893 7777
Contact for Construction Work	

National Route	R61
Section	Queenstown (N6) to Cofimvaba (Section 5)
Distance	60km
Description	A 2 Lane single carriageway with paved shoulders.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Motorists may encounter occasional short-terms closures on sections in this area due to maintenance repairs.
Expected Travel Condition	Route back to RRM for maintenance.
Contact for Construction works	
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Cofimvaba to Engcobo (Section 6)
Distance	92 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Expected Travel Condition	Fair to good.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Construction works are in progress between Cogland to Baziya area. Between km 57 and km 68, and between All Saints and km 86 to Baziya km 12 (section 7) Reduced speeds and localised detours can be expected. Motorists may encounter occasional short term closures on short section in this area. Road may also be closed for short durations due to blasting operation.
Duration of Work	Sept 2017 (All Saints)
Contact for Routine Road Maintenance	Riaan Graaf (RRM) 082 821 0175
Contact for Construction Work	Ian Cateley 082 921 5634

National Route	R61
Section	Engcobo to Mthatha (Section 7)
Distance	49 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Expected Travel Condition	Fair to good
Expected Travel Condition	Motorists to be aware of pedestrian and stray animals. Construction works are in progress from the Baziya km12 to Mthatha Airport km39. Reduced speeds and localised detours can be expected. Motorists may encounter occasional short term closures on short section in this area. Road may also be closed for short durations due to blasting operation
Contact for Construction works	Adriaan Roets 083 265 2652
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	R61 Mthatha to Ngqeleni (Section 8)
Distance	5.7km
Description	Construction of dual carriageway and bridges from Mthatha to Ngqeleni interchange.
Expected Travel Condition	2 way traffic is being maintained.
Contact for Construction works	Vohan Swanepoel 082 782 7400
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Mthatha to Port St Johns (Section 8)
Distance	74 km
Description	A 2-lane single carriageway, with surfaced shoulders.
Expected Travel Condition	Fair.
Expected Travel Condition	<p>Libode to Mngazi Upgrading of nine intersections , rebuild speeds and localised bypasses/detours.</p> <p>Majola Tea to Tombo Construction works in progress between Majola Tea (km51) to Tombo (km66). Reduced speeds and localised detours can be expected. Motorists may encounter occasional short term closures on short sections in this area. The road may be closed for durations due to blasting operations. Stop/Go in operation towards Tombo.</p> <p>St Barnabas The project commenced in August 2012 and is expected to be completed in December 2015. The R61 through St Barnabas is currently under construction and hence closed for traffic over a distance of approximately 2km. Traffic is accommodated via a gravel bypass with a speed limit of 40km/hr. Beware of traffic calming measures in the form of shallow trenches. Travellers should add approximate 15minutes to their travel time.</p> <p>Ngqeleni Interchange to Libode East Project completed.</p>
Duration of work	
Contact for Routine Road Maintenance	Riaan Graaf (Routine road maintenance) 082 821 0175
Contact for Construction works	Ben Swart 082 778 9953 (Ngqeleni Interchange) Thomas van Wyk de Vries 083 299 7231 (Majola Tea) (Libode to Mngazi)

National Route	R61 (Wild Coast)
Section	Ntafufu River to Lusikisiki (Section 9)
Distance	18 Km
Description	Two-lane Single carriageway with Passing lanes
Expected Travel Condition	Good
Expected Travel Condition	Motorist to be aware of pedestrians and animals. The road is winding and motorists may encounter occasional short term closures on a short section for routine maintenance.
Duration	
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175
Contact for Construction	

National Route	R61
Section	Mtamvuna River (Provincial Boundary) to Port Shepstone
Distance	45 km
Description	Two-lane single carriageway with passing lanes.
Expected Road Condition	Good.
Expected Travel Condition	A contract for the periodic maintenance of the R61 between Mbizana River and Port Shepstone commenced in November 2016. Restricted lane conditions with reduced speeds as signposted will apply.
Duration of work	Until November 2017
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	R62
Section	East Cape borders to N2
Distance	117km
Description	Single carriage road
Expected Travel Condition	Fair but narrow width
Expected Travel Condition	
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	R63
Section	East Cape border to Graaff Reinet
Distance	50km
Description	Single carriageway with gravel shoulders
Expected Travel Condition	Fair but narrow over most of the section
Expected Travel Condition	A section of this route runs through a National Park so watch out for game. .
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R63
Section	N9 Graaff Reinet to R75 junction (to Pearston)
Distance	23km
Description	Single carriageway with paved shoulders
Expected Travel Condition	Fair to Good
Expected Travel Condition	Contact for reseal is Rodney walters. Reseal commenced in Feb 2016. Expect stop/go closures from Feb 2016 for 15 months.
Contact for Routine Road Maintenance	Rodney Walters 081 713 9280

National Route	R63
Section	R75 to Pearston , Somerset East to N10
Distance	123km
Description	Two way single carriage way with gravel shoulders
Expected Travel Condition	Fair / Good
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Johannes Nel 083 295 0606 Dave Venter 079 516 3280

National Route	R63
Section	Pearston to Bruintjes Hoogte (Section 9 km 43 to Section 10 km 24.7)
Distance	
Description	Two way single carriage way with gravel shoulders
Expected Travel Condition	Fair / Good
Expected Travel Condition	
Contact for Routine Road Maintenance	Conrad Bezuidehout – 081 264 8063 Johannes Nel – 083 295 0606

National Route	R63
Section	N10 to Bedford
Distance	78km
Description	Two way single carriage way with gravel shoulders. 4km section before Bedford in poor condition, reduce speed at km 16.9 – km 20.9
Expected Travel Condition	Fair Good, except the 4km section before Bedford which is poor.
Expected Travel Condition	Fair
Contact for Routine Road Maintenance	Conrad Bezuidehout – 081 264 8063 Johannes Nel – 083 295 0606

National Route	R63
Section	Adelaide to Komga
Distance	189km
Expected Travel Condition	Poor condition between Fort Beaufort and Alice and between Bhisho and Komga.
Expected Travel Condition	Two way single carriage way. Motorists may encounter occasional short closures by maintenance team. Between Fort Beaufort and Alice, repairs and uneven surfaces will be encountered.
Contact for Routine Road Maintenance	Odwa Ndlwana – 071 045 8203

National Route	R67
Section	Grahamstown to Fort Beaufort
Distance	70.65km
Description	Two lane single carriageway with gravel shoulders (Narrow) 6.4m wide
Expected Travel Condition	Fair
Expected Travel Condition	The road is winding, observe speed limit through ECCA Pass & beware of wild animals after dusk.
Contact for Routine Road Maintenance	Michael Coetzee 083 269 9026

National Route	R67
Section	Seymour to Whittlesea
Distance	54,45km
Description	Two-lane single carriage with passing lane
Expected Travel Condition	Fair
Expected Travel Condition	Beware of pedestrian and animals observe speed limit though Nico Malan Pass. Stop/go conditions on this section. Project should be completed by June 2017.
Contact for construction	Rudolph Pretorius 082 773 5780

National Route	R67
Section	Swart Kei to Queenstown
Distance	33,36km
Description	Two way lane single carriageway with gravel shoulders
Expected Travel Condition	Fair to poor
Expected Travel Condition	Beware of pedestrian and animal crossing.
Contact for Routine Road Maintenance	Pieter Lombard 082 550 3852

National Route	R71
Section	Polokwane to Tzaneen
Distance	86.04km
Description	Km 6.1 – 39.0, 88 – 92.14 Double carriageway. Km 35 – 88 Single carriageway Mostly paved shoulders.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Road Condition	Surfacing Fair to Good. Mountain pass high accident zone (km 69 – 75) Dense Fog Area
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Stephan Du Plessis 084 491 1165

National Route	R71
Section	Tzaneen to Gravelotte
Distance	55.18km
Description	Single carriageway with paved shoulders until Letsitele (km 30) from there mainly gravel shoulders.
Expected Road Condition	Surfacing Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R71
Section	Gravelotte to Phalaborwa Gate at Kruger National Park
Distance	59.6km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Beware of stray animals between Selwane intersection and Lulekani
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R72
Section	Nanaga to Alexandria
Distance	50 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	
Duration of work	
Contact for Routine Road Maintenance	Ian Smith 084 415 2002
National Route	R72
Section	Alexandra – Peddie turnoff. New Keiskamma rivers
Distance	117km
Description	Two lane single carriageway with grave shoulders
Expected Road Condition	Fair but narrow width
Expected Travel Condition	Construction has commenced between Port Alfred and Fish River, where reduced speeds will apply.
Contact for Construction	Hendrik Pretorius 082 772 1335
Duration of work	Till August 2018
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R72
Section	Peddie turn off to East London Airport
Distance	62km
Description	Two lane single carriageway with paved soulder
Expected Road Condition	Good

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Contact for Routine Road Maintenance	Ian Smith 084 415 2002
--------------------------------------	---------------------------

National Route	R75
Section	Port Elizabeth to Uitenhage North
Distance	28km
Description	Dual carriageway with 2 lanes per direction for the first 14 km. Not a freeway and a lot of level accesses exist, also a lot of pedestrian movements
Expected Road Condition	Good
Expected Travel Condition	Please take special care for first 14 km and normal RRM work. A resurfacing contract commenced in November 2016 between km 13 and km 28. Motorists to expect lane closures in this section.
Duration of work	
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	R75
Section	Uitenhage North to Jansenville
Distance	136km
Description	A two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair
Expected Travel Condition	Fair, no construction currently underway, but routine maintenance is ongoing. Look out for warthogs.
Duration of work	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R75
Section	Jansenville to R63 junction (Pearston)
Distance	59km
Description	A two-lane single carriageway with gravel shoulders last 23km with paved shoulders
Expected Road Condition	Fair
Expected Travel Condition	No construction but motorists may encounter occasional short closures for routine maintenance. Very narrow sections from Jansenville for +- 50km.
Duration of work	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R81
Section	Polokwane to Mooketsi
Distance	73km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Good. Km 60 – 66 poor surface. Line markings in fair condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Stephan Du Plessis 084 491 1165

National Route	R81
Section	Mooketsi to Giyani
Distance	73.2km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Good. Line markings in fair condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Stephan Du Plessis 084 491 1165

National Route	R101
Section	Bela-Bela to Modimolle
Distance	26.8 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Fair to Good. Poor road markings
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	NJ Du Toit 083 342 6550

National Route	R101
Section	Modimolle to Middelfontein
Distance	16.4 km
Description	Two-lane single carriageway with gravelshoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Until end of January 2016
Contact for Routine Maintenance	Gustavus Fouche 082 780 2391

National Route	R104
Section	Simon Vermooten to West of Bronkhorspruit
Distance	42.40 km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Good. Road Markings in a poor state
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Timothy Masalesa 076 349 4168

National Route	R104
Section	East of Bronkhorstspuit to Mpumalanga Border
Distance	21.20 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Timothy Masalesa 076 349 4168

National Route	R300
Section	Swartklip Interchange to Stellenberg Interchange
Distance	16.1 km
Description	Three-lane dual carriageway with paved shoulders.
Expected Travel Condition	Good
Expected Travel Condition	R300 Construction taking place at night. The speed limit throughout the construction area has been lowered and to be adhered to. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Chris Roux 083 440 7553

National Route	R500
Section	Parys to Carletonville
Distance	55.4 km
Description	Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	Good to Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R501
Section	Free State Border to Potchefstroom
Distance	21.2 km
Description	Two-lane narrow single carriageway with gravel shoulders
Expected Road Condition	Good to Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R501
Section	Potchefstroom to Westonaria Municipal Border
Distance	64.3 km
Description	Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	The two-lane is bad to poor and then the dual is good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R503
Section	Klerksdorp to Coligny
Distance	74.56 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Roadworks. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Maintenance	Theuns Jooste 076 751 9898

National Route	R503
Section	Coligny to Lichtenburg
Distance	21.9 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Maintenance	Theuns Jooste 076 751 9898

National Route	R504
Section	Wolmaranstad to Leeudoringstad
Distance	28.9 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Dries Grundlingh 083 269 3029

National Route	R504
Section	Leeudoringstad to Free State Border
Distance	24 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop/go's may occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Dries Grundlingh 083 269 3029

National Route	R505
Section	Wolmaranstad to N14/11
Distance	91.7 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Fair with uneven riding surface.
Expected Road Condition	Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Roadworks. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Maintenance	Theuns Jooste 076 751 9898

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R505
Section	N14/11 to Lichtenburg
Distance	38.6 km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Expected Road Condition Fair with uneven riding surface
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop and go's may occur from time to time Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Theuns Jooste 076 751 9898

National Route	R505
Section	Lichtenburg to Ottoshoop
Distance	49.4 km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Road is in a poor condition. Potholes have been attended to but due to the poor Expected Road Condition new potholes and base failures are constantly in repair. Stop/Go will occur from time to time
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R510
Section	Rustenburg to north West / Limpopo Border
Distance	87 km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. BRT construction from Rustenburg (1 st 7km). expect delays
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R510
Section	North Wet /Limpopo Border to Northam
Distance	21 km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Stephan du Plessis – 084 491 1165 Riaan Fuchs – 082 556 7788

National Route	R510
Section	Northam to Thabazimbi
Distance	37.2km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	NJ Du Toit 083 342 6550
National Route	R510

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Section	Thabazimbi to Lephalale
Distance	125.4 km
Description	Single carriageway
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Chantel Purchase 083 789 2304

National Route	R511
Section	Lephalale to Monte Christo
Distance	38.07km
Description	Single carriageway.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Chantel Purchase 083 789 2304

National Route	R511
Section	Brits to North West/Limpopo
Distance	71km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R511
Section	North West / Limpopo border to Thabazimbi
Distance	62km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good. Poor road markings on some sections
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks: Reseal contract between North West / Limpopo border and Thabazimbi. Expect Stop 'n Go's.
Duration of work	Ongoing
Contact for Routine Road Maintenance	NJ Du Toit 083 342 6550

National Route	R511
Section	Gauteng /north West Border to Broedestroom
Distance	7.44km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R512
----------------	------

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Section	R104 to Brits
Distance	10.06 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R516
Section	Koedoeskop to Bela Bela – R101
Distance	82.0km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Until July 2015. Contract extended until January 2016
Contact for Routine Road Maintenance	NJ Du Toit 083 342 6550

National Route	R518
Section	Lephalale to Marken
Distance	70km
Description	Two-lane single carriageway with gravel shoulders. Paved shoulders in the mountain area. Slope in the mountain area full of falling rocks
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chantel Purchase 083 789 2304

National Route	R518
Section	Marken to Mahwelereng
Distance	102.2km
Description	Two-lane single carriageway with gravel shoulders. Paved shoulders in the mountain area.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chantel Purchase 083 789 2304

National Route	R518
Section	Mokopane to Zebediela
Distance	47.281km
Description	Two lane single carriageway.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R518
Section	Zebediela to Lebowakgomo
Distance	25.8km
Description	Two lane single carriageway.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R520
Section	R510/3 Junction to Vaalwater
Distance	54km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good. Km 0.0 – 54.0 poor road markings
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	R521
Section	Polokwane to Dendron
Distance	62.3 km
Description	Two-lane single carriageway.
Expected Road Condition	Fair. Gravel shoulders.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	George Brand 082 5558493

National Route	R521
Section	Dendron to Vivo
Distance	8km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Stop/Go at Patching Team for next month as well as shoulder repair team
Duration of work	Ongoing
Contact for Routine Road Maintenance	George Brand 083 730 9385

National Route	R521
Section	Vivo to R23/1 Intersection
Distance	6.5km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Stop/Go may occur. Patching and shoulder repairs teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	George Brand 083 730 9385

National Route	R523
Section	Vivo to Masewkwaspoort
Distance	67km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	George Brand 083 730 9385

National Route	R524
Section	Louis Trichardt to Punda Maria Gate
Distance	130.3km
Description	Two lane single carriageway with no paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Johan de Vries 073 308 2356

National Route	R526
Section	Mica to Gravelotte
Distance	33.03km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R529
Section	Giyani to Letsitele
Distance	77.6km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R531
Section	Klaserie junction with R40 to Orpen Gate at Kruger National Park
Distance	3km
Description	Single carriageway with paved shoulders. Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R532
Section	Junction with R36 to Mpumalanga border towards Graskop
Distance	11.4km
Description	Single carriageway with gravel shoulders. Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R555
Section	Witbank to Middelburg
Distance	20 km
Description	A 2-lane single carriageway road with narrow gravel shoulders
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	R555
Section	Limpopo / Mpumalanga border at Stoffberg to Kokwaneng
Distance	72.86
Description	Single carriageway with gravel and paved shoulders.
Expected Road Condition	First 30km in poor condition. Rest is fair to good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Nathanael Pillay 074 309 0937

National Route	R555
Section	Kokwaneng to Burgersfort
Distance	37.705km
Description	Single carriageway with gravel and paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. A large portion in Steelpoort area is under construction
Duration of work	Ongoing
Contact for Routine Road Maintenance	Nathanael Pillay 074 309 0937

National Route	R556
Section	Tsitsing to Ledig (Sun City)
Distance	29.6km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R565
Section	Rustenburg to Ledig (Sun City)
Distance	34.9km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R567
Section	N11/23 to Seshego (Kompane Stret)
Distance	64km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good. Speed humps between Moletji and Seshego
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Domestic animals from G-Matlala to Moletjie in the road reserve Reseal contract with Stop and Go's until June 2017
Duration of work	Ongoing
Contact for Routine Road Maintenance	Maxwell Baloyi 078 972 4445

National Route	R570
Section	N4 Interchange to Malelane Kruger Park Gate
Distance	3.648 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Hannelie Swanepoel 084 516 3330

National Route	R570
Section	N4 Interchange to Jeppe's Reef Bordr Post
Distance	40.89 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Rehab started February 2015 Stop and go on this section. Expect stop n go's along the road
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	R571
Section	N4 Interchange to Managa Border Post
Distance	60.469 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	First 30km is good .Rest Fair to Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	R572
Section	Monte Christo to Tom Bourke
Distance	47.952 km
Description	Two-lane single carriageway.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Chantel Purchase 083 789 2304

National Route	R573
Section	Moloto to Moteti
Distance	48.652 km
Description	Two-lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R573
Section	Moteti to Marble Hall
Distance	43.741 km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R578
Section	Louis Trichardt to Giyani
Distance	90.76
Description	Two lane single carriageway with no paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Stop/Go and Patching team for next month
Duration of work	Ongoing
Contact for Routine Road Maintenance	Johan de Vries 073 308 2356

National Route	R579
Section	Hlogotlou to Phokwane
Distance	26.046km
Description	Two-lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R579
Section	Phokwane to Chuniespoort
Distance	78.9km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	S27
Section	Villiers to Mpumalanga / Gauteng Border
Distance	42km
Description	Single carriageway with gravel shoulders and short gravel road portion
Expected Road Condition	Good (Gravel road in excellent condition).
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Heinrich Scheepers 076 292 0853

NATIONAL BORDER CONTROL POSTS

Botswana Border

Border Post	Location	Description	Condition	Opening Times
Twee Rivieren	Situated in the Kgalagadi Cross Border National Park	Single carriageway gravelled road.	Fair	08h00 to 16h30
Gemsbok	Between Upington and Botswana	Single carriageway gravelled road.	Fair	08h00 to 16h30
Middelputs	Between Van Zylsrus and Botswana	Single carriageway gravelled road.	Fair	08h30 to 16h30
McCarthy's Rest	Route R380 between Kathu and Thshabon (Botswana)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Makopong	Route R379 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Bray	Route R378 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Boshoek	Route R375 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Magobistad	Between Mafikeng & Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h30
Ramatlabama	Between Mafikeng & Botswana	Single carriageway paved road.	Good	07h00 to 20h00
Skilpadshok	N4 Platinum – Lobatse	Single carriageway paved road.	Good	07h00 to 19h30
Swartkopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 19h00
Kopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 22h00
Derdepoort	Between Rustenburg & Botswana	Single carriageway gravelled road.	Poor	07h00 to 19h00
Stockpoort	From Ellisras to Botswana	Single carriageway paved road.	Good	08h00 to 16h00
Groblers Bridge	From Potgietersrus on N11 to Botswana	Single carriageway paved road.	Good	08h00 to 18h00
Zanzibar	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Platjan	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Pondrift	From Alldys on R521 to Botswana	Single carriageway paved road.	Good	08h00 to 16h00

Namibia Border

Border Post	Location	Description	Condition	Opening Times
Alexander Bay	Between Alexander Bay and Oranjemund (Namibia)	Single carriageway paved road.	Good	06h00 to 22h00
Violsdrift	Route N7/B1 between Springbok and Keetmanshoop (Namibia)	Single carriageway paved road.	Good	24 hours
Onseepkans	Route R358/C10 between Pofadder and Karasburg	Single gravelled road with single traffic lane bridge over Orange River Bridge	Fair	08h00 to 16h30
Nakop	Route N10/B3 between Upington and Karasburg (Namibia)	Single carriageway paved road with gravelled shoulders. New Border Control Post situated 1 km from actual border with Namibia.	Good	24 hours
Noenieput	Between Upington and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Rietfontein	Route R31/C16 between Askam and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30

Zimbabwe Border

Border Post	Location	Description	Condition	Opening Times
Beitbridge	On N1 between RSA and Zimbabwe	Single carriageway paved road.	Fair	Passengers: 24hrs Commercial: 24hrs

Mozambique Border

Border Post	Location	Description	Condition	Opening Times
Pafuri	In Kruger National Park, nearest route is R525, east/west direction ± 25 km adrift)	Single carriageway paved road under construction.	Fair	08h00 to 16h00
Lebombo	On N4 between Nelspruit and Maputo	Single carriageway paved road.	Good	06h00 to 22h00
Kosibay (Farazela)	On R22 between RSA and Mozambique	Single carriageway paved road with narrow paved shoulders.	Good	06h00 to 1800

Swaziland Border

Border Post	Location	Description	Expected Condition
Mananga	On R571 between Komatipoort and Swaziland	Single carriageway paved road.	Fair
Jeppe's Reef	On R570 between Malelane and Swaziland	Single carriageway paved road.	Good
Josefsdal	On R40 between Barberton and Piggs Peak	Single carriageway gravelled road	Poor
Oshoek	On N17 between Ermelo and Manzini	Single carriageway paved road.	Good
Waverley	Off R33 between RSA and Swaziland	Single carriageway paved road.	Good
Nerston	On R65 between RSA and Swaziland	Single carriageway paved road.	Fair
Emhlalatinhi	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Bothashoop	Between Piet Retief and Swaziland	Single carriageway gravelled road.	Fair
Mahamba	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Onverwacht	D1936 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good
Golela/Lavumisa	P 720 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good

Lesotho Border

Border Post	Location	Description	Expected Condition
Monantsapas	R 57/S1579 (Free State)	Single carriageway paved road	Fair to good
Caledonspoort	P 92/1 (Free State)	Single carriageway paved road	Fair to poor
Ficksburg Bridge	R 26 / P75/1 (Free State)	Single carriageway paved road	Fair
Peka Bridge	S 388 / S 306 (Free State)	Single carriageway gravel road	Poor
Maseru Bridge	N8 (Free State)	Single carriageway paved road.	Fair
Van Rooyen's Gate	P66/1 (Free State)	Single carriageway paved road	Fair
Sepapu's Gate	S4 (Free State)	Single carriageway gravel road	Poor
Makhaleng Bridge	S2 (Free State)	Single carriageway gravel road	Very Poor
Telle Bridge	R 392 (from Sterkspruit in the Eastern Cape)	Single carriageway paved road.	Good
Ongeluksnek	Eastern Cape: Off R 56. Closest towns are Mount Fletcher and Matatiele	Gravel approach road.	Poor to very poor. Only suitable to 4x4 vehicles beyond the border post.

Qacha's Nek	Eastern Cape: Closest town Matatiele	Gravel approach road.	Poor
Ramaselitso Gate	Eastern Cape: Closest from Matatiele	Gravel approach road.	Poor
Sani Pass	P 318 (KwaZulu-Natal)	Gravel approach road	Fair but often only accessible to 4X4 vehicles beyond the border post.

THE SOUTH AFRICAN NATIONAL ROADS AGENCY SOC LTD

Contact Details

Head Office

48 Tambotie Avenue
Val de Grace
Pretoria, 0184
Tel. 012 844 8000
Fax 012 362 2117

Northern Region

38 Ida Street
Menlo Park
Pretoria, 0081
Tel. 012 426 6200
Fax 012 348 1680

Eastern Region

58 Van Eck Place
Mkondeni
Pietermaritzburg
Tel. 033 392 8100
Fax 033 386 6284 / 3365

Southern Region

20 Shoreward Drive
Baywest
Port Elizabeth
6025
Tel. 041 398 3200
Fax 041 492 0201

Western Region

1 Havenga Street
Oakdale, Bellville
7530
Tel. 021 957 4600
Fax 021 910 1699

Website: www.sanral.co.za
E-mail: info@nra.co.za
Fraud Hot Line: 0800204558