



Road Conditions

AUGUST 2008

N1

National Route	N1
Section	Old Oak Interchange to Worcester
Distance	82.44 km
Description	Two-lane dual carriageway with paved shoulders.
Condition of Road	Fair to Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Maintenance	Riaan Davids 082 658 9772

National Route	N1
Section	Worcester to Laingsburg
Distance	156 km
Description	Single carriageway with paved shoulders. The road through Hex River Pass is a four-lane dual carriageway (four km) with an arrestor bed in the south-bound direction before the hairpin curve known as "Spookdraai". Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	A compulsory stop, manned by the Provincial Traffic Department, is in operation \pm five km south of Touws River. An unmanned compulsory stop for heavy vehicles is also in operation on the south-bound carriageway in Hex River Pass. Motorists should also be alert to pedestrians and/or stray animals just north of De Doorns. Motorists should also be alert to hawkers selling alongside the road. It is illegal to stop and buy from the sellers.
Duration of Work	
Contact for Routine Maintenance	Stephen McGregor 072 784 4010

National Route	N1
Section	Laingsburg to Leeu-Gamka
Distance	124 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Construction work in progress in the town of Laingsburg with no delays expected. "Kanniedood" safety project is in operation on this section of road. A compulsory stop, manned by the Provincial Traffic Department, is in operation ± 15 km south of Leeu-Gamka. Motorists should be alert to pedestrians and/or stray animals crossing the road in the vicinity of Leeu-Gamka.
Duration of Work	January 2008 to September 2008
Contact for Routine Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Leeu-Gamka to Beaufort-West
Distance	75 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and/or stray animals in Beaufort-West.
Duration of Work	
Contact for Routine Road Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Beaufort-West to Three-Sisters
Distance	97 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Three-Sisters to Colesberg
Distance	236 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Fair to Good.
Comments	Construction works are in progress between Three-Sisters and Colesberg over a 30 km section. Motorists will encounter up to three (3) Stop/Go and traffic-light controls, with waiting periods on average 20 minutes.
Duration of Work	October 2007 to September 2009
Contact for Routine Maintenance	Marco du Plessis 083 383 8174

National Route	N1
Section	Orange River (Provincial Boundary) to Bloemfontein (Sydenham Interchange)
Distance	173 km
Description	175 km
Condition of Road	Predominantly, a two lane single carriageway. The full length of the road has wide paved shoulders.
Comments	Fair to satisfactory. There are ten interchanges between Orange River bridge and Bloemfontein, with the Edenburg Interchange being mostly used as a bypass to the National Route 6. Another bypass can be formed from Smithfield to Bethulie, then to Xhariep – approximately 124km.
Duration of Work	Section 13: between Springfontein and Orange River bridge, is currently under construction with Stop/Go areas at random locations. Traffic through these locations will be accommodated by means of

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

	Stop/Go operations where fifteen to twenty minutes delays should be expected.
Contact for Routine Road Maintenance	Construction/ Rehabilitation activities is scheduled for completion in 31 October 2009.
	Ofan Motlakane 079 879 4720

National Route	N1
Section	Bloemfontein to Kroonstad
Distance	189 km
Description	Around Bloemfontein, the road is a four-lane dual carriageway with wide paved shoulders; otherwise it is a two-lane single carriageway with paved shoulders and passing lanes on steep gradients. The last 10 km, known as the Kroonstad Bypass, is a four-lane dual carriageway.
Condition of Road	Generally good, but potholes may be expected between Bloemfontein and Verkeerdevlei toll plaza
Comments	Construction of a second carriageway has commenced between Bloemfontein and the Verkeerdevlei toll plaza.. While two lanes are open to traffic, restriction of shoulder width is in place in construction zones. A reduced speed limit is in force along the entire construction area and motorists must be aware of construction traffic entering and exiting work zones Motorists should be alert to pedestrian and heavy vehicle activity in Ventersburg, where an urban speed restriction is in place.
Duration of Work	February 2010
Contact for Routine Road Maintenance	Frank Joubert 083 781 3676

National Route	N1
Section	Kroonstad to Vaal River (Free State – Gauteng Provincial Boundary)
Distance	102 km
Description	Partly a single carriageway with alternating passing lanes in each direction and wide gravel shoulders, and partly a four-lane single carriageway, except for the 10 km portion beyond the Vaal Toll Plaza, where it becomes a four-lane dual carriageway with wide paved shoulders.
Condition of Road	Good.
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Frank Joubert 083 781 3676

National Route	N1
Section	Vaal River (provincial boundary) to Johannesburg
Distance	64 km
Description	Four-lane dual carriageway freeway with wide paved shoulders.
Condition of Road	Good.
Comments	Motorists should beware of pedestrian activity along the route. Additional street lighting has been installed at the Ennerdale Interchange. A pedestrian road safety project is underway between Orange Farm and Ennerdale. Various pedestrian facilities are being constructed, amongst others, walkways, a pedestrian bridge over the N1 and various barriers.
Duration of Work	Completion July 2008 for barriers, pedestrian bridge construction to commence in July 2008 with 4 months duration
Contact for Routine Road Maintenance	Frank Joubert (Vaal River to Golden Highway) 083 781 3676

National Route	N1
Section	Johannesburg to Pretoria (N4 Interchange)
Distance	84 km
Description	Four-lane dual carriageway freeway from Soweto to Roodepoort changing into six-lane dual carriageway freeway from Roodepoort to Pretoria.
Condition of Road	Good.
Comments	Construction of additional lanes and other improvements from R21 interchange up to Atterbury Interchange.
Duration of Work	Completion December 2008

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553
--------------------------------------	---------------------------------

National Route	N1 (GFIP)
Section	Misgund (Soweto) to Buccleuch
Distance	38 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Started June 2008
Duration of Work	30 months

National Route	N1 (GFIP)
Section	Buccleuch to Brakfontein Interchange
Distance	23 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Started June 2008
Duration of Work	30 months

National Route	N1 (GFIP)
Section	Brakfontein to N4 Interchange
Distance	10 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Started June 2008
Duration of Work	30 months

National Route	N1
Section	Pretoria (N4 Interchange) to Bela Bela (Warmbaths) (Platinum Toll highway)
Distance	94 km
Description	Six-lane dual carriageway freeway from Pretoria (Proefplaas Interchange) to Zambesi Interchange changing into four-lane dual carriageway freeway to Bela Bela.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N1
Section	Bela Bela to Polokwane (Great North Toll Road)
Distance	160 km
Description	Four-lane dual carriageway freeway from the Warmbaths/Settlers interchange to the Kranskop toll plaza. Four-lane single carriageway freeway from the Kranskop Toll Plaza to the N1/R71 interchange at Polokwane
Comments	Construction started on Zebediela Load Control Centre.
Duration of Work	February 2009 (12 Months)
Contact for Routine Road Maintenance	NTRV Danie Kotze 082 822 0902

National Route	N1
Section	Polokwane (Pietersburg) to Louis Trichardt
Distance	98 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Very good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Intertoll V&V Themba Mosai 082 901 0902 Stephan du Plessis 084 491 1165

National Route	N1
Section	Louis Trichardt to Masekwaspoort
Distance	28 km
Description	Two-lane single carriageway with passing/climbing lanes and no paved shoulders.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

National Route	N1
Section	Masekwaspoort to Musina
Distance	62 km
Description	Two-lane single carriageway with passing lanes, but paved shoulders only on last 20 Km before Musina.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

National Route	N1
Section	Musina to Beit Bridge
Distance	15 km
Description	Two-lane single carriageway with paved shoulders
Condition of Road	Good
Comments	Construction on Beit Bridge Traffic Control Centre started December 2007
Duration of Work	12 months
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

N2

National Route	N2
Section	Somerset-West to Bot River
Distance	45 km
Description	Single carriageway road with narrow paved shoulders and climbing lanes are provided through Sir Lowry's Pass. A four (4)- lane single undivided carriageway road through Sir Lowry's Pass and Houwhoek Pass.
Condition of Road	Fair.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Riaan Davids 082 658 9772

National Route	N2
Section	Caledon to Riviersonderend
Distance	48 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Riviersonderend to Swellendam
Distance	58 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Mossel Bay to George
Distance	51 km
Description	A four-lane dual carriageway.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	John Strydom 083 677 9401

National Route	N2
Section	George to Knysna
Distance	54 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good with the exception of Knysna Lagoon Bridge to Knysna Town. From the Knysna Lagoon Bridge to Knysna town the road is uneven and very narrow with no overtaking opportunities.
Comments	Routine road maintenance teams may be encountered. Motorists should be alert to pedestrians and/or stray animals in the vicinity of Knysna Lagoon. Motorists should also be alert to hawkers selling alongside the road. It is illegal to stop and buy from the sellers.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	John Strydom 083 677 9401

National Route	N2
Section	Knysna to Plettenberg Bay
Distance	39 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and/or stray animals in the vicinity of the informal settlement in Knysna, as well as in the vicinity of Plettenberg Bay.
Duration of Work	
Contact for Routine Road Maintenance	John Strydom 083 677 9401

National Route	N2
Section	Plettenberg Bay to Natures Valley T-Junction (Sout River)
Distance	20 km
Description	Single carriageway with narrow paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and/or stray animals in the vicinity of the Craggs.
Duration of Work	
Contact for Routine Maintenance	John Strydom 083 677 9401

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	N2
Section	Storms River Town to Elands River
Distance	14 km
Description	A two-lane single carriageway with limited gravel shoulders.
Condition of Road	The road is narrow, with limited passing opportunities and sections where speed restrictions will apply.
Comments	Reconstruction of this section has started, with speed restrictions of 60 km/h. Traffic will be deviated onto bypasses during construction, but permanent stop/go's can be experienced. Motorists should be alert to pedestrian activity in the vicinity of Storms River Bridge.
Duration of Work	January 2007-November 2009.
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501
Contact for Rehabilitation Contract	Louis Joubert 0825744315

National Route	N2
Section	Gamtoos River to Van Stadens River
Distance	19 km
Description	14,7km of 2-lane single carriageway and 4.3km of dual carriageway with surfaced shoulders.
Condition of Road	Fair.
Comments	Road works are in progress on this section. On the section east of the Gamtoos River up to the Hankey interchange, two stop-go closures are in operation and motorists can expect up to 15 minutes delays at these closures. For the remainder of the site the road is opened to uninterrupted two-way traffic. Motorists are urged to obey the posted speed limits.
Duration of Work	November 2006-October 2008.
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501
Contact for Project	Harry Millson 072 306 1612

National Route	N2
Section	Van Stadens River to Port Elizabeth (Markman)
Distance	57 km
Description	A 4-lane dual carriageway freeway.
Condition of Road	Good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Port Elizabeth to King Williams Town
Distance	250 km
Description	A 2-lane single carriageway with gravel shoulders over most of the distance.
Condition of Road	Fair, but narrow and uneven in places and prone to failures in the vicinity of Peddie.
Comments	At the Coega River near Port Elizabeth, construction work is being undertaken for the dualling of the road, with 60 and 80km p/h speed restrictions and crossing vehicles. At Grahamstown, a slip in the road cutting has caused the narrowing of part of the grahamstown bypass with local speed reductions.
Duration of Work	Until Nov/Dec 2008
Contact for Routine Road Maintenance	Yogan Naidoo 082 825 0390

National Route	N2
Section	King Williams Town to East London (Gonubie)
Distance	60 km
Description	A 4-lane dual carriageway
Condition of Road	Good.
Comments	Short-term closures for repairs could be encountered.
Duration of Work	
Contact for Routine Road Maintenance	Yogan Naidoo 082 825 0390

National Route	N2
Section	East London (Gonubie) to Kei River
Distance	60 km
Description	The first 2km is a 4-lane dual carriageway. Thereafter it becomes a 2-lane single carriageway with wide paved shoulders. Climbing lanes are provided on some severe grades between kilometre mark (km) 30 and km 50 and between km 70 and km 80.
Condition of Road	The condition is fair to good, except for the section between km 22 and 27 and between km 50 and km 70 where the condition is poor.
Comments	No construction work but motorists may encounter occasional short term closures over short sections for routine maintenance, especially after rains.
Duration of Work	
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946

National Route	N2
Section	Kei River to Dutywa
Distance	68 km
Description	Single carriageway road with paved shoulders and climbing lanes.
Condition of Road	The condition is good to fair.
Comments	Motorists should be aware of pedestrians and animals along the road. Construction works are in progress between Butterworth and Dutywa where reduced speed and delays will be encountered
Duration of Work	Until August 2008.
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946
Contact for Construction Project	Koos Pretorius 047-491 5561 082 773 1464

National Route	N2
Section	Dutywa to Mthatha
Distance	85 km
Description	Single carriageway road with paved shoulders and climbing lanes. Road surface failures / potholes may occur especially after heavy rains between the SitebeKomkhulu intersection and Mthatha.
Condition of Road	Fair but uneven in places
Comments	Construction works have started between Dutywa and Bashe River where reduced speed and delays will be encountered. Between Viedgesville and Mthatha Routine maintenance repairs will be encountered.
Duration of Work	Until August 2008.
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946
Contact for Construction Project	Koos Pretorius 047-491 5561 082 773 1464

National Route	N2
Section	Mthatha to Brooks Nek (provincial boundary)
Distance	170 km
Description	A 2 lane single carriageway with climbing lanes and paved shoulders. (Up to Mt. Frere no passing lanes between Mt. Frere and Brooks Nek) except the last 16km.
Condition of Road	The condition of the road between km 54 to km 70 is fair to poor and regular routine maintenance may be encountered.
Comments	Construction work has started from the Mthatha River up to km 22,0 and motorists can expect delays at stop/go controls on the single lane closures.
Duration of Work	August 2009
Contact for Routine Road Maintenance	Trevor Morgan 082 331 9085
Contact for construction Project	Lukas van der Westhuizen 082 895 6024

National Route	N2
Section	Brookes Nek (provincial boundary) to Port Shepstone
Distance	135 km
Description	This first section of the N2 in KZN is a two-lane single carriageway with narrow paved shoulders. Climbing lanes are provided on all the severe grades with the exception of a short 6 km section 26 km north of Kokstad.
Condition of Road	Good.
Comments	From mid November 2007 to Mid-August 2008 , there will be construction works including rehabilitation, repairs and resealing works between Wilson's cutting and Murchison. Motorists can expect delays as a result of a number of single lane closures controlled by traffic lights or Stop/Go controls. Motorists to be aware of pedestrian activity between Harding and Port Shepstone.
Duration of Work	
Contact for Routine Road Maintenance	Bill Morris 083 655 4228

National Route	N2
Section	Port Shepstone to Durban (N2/N3 Interchange)
Distance	114 km
Description	The first 20 km is a single carriageway road with three lanes of traffic and narrow paved shoulders allowing overtaking opportunities. Thereafter the road becomes a four-lane dual carriageway with wide paved shoulders. The last 17 km leading into Durban has 3 lanes in each direction and is heavily trafficked. A new project will commence in July 2008 for upgrading of the Higginson Highway and Edwin Swales Interchanges in Durban. There will be minimum disruption to traffic on the N2, with only reduction in speed envisaged, while the on-off ramps will be controlled through stop/go.
Condition of Road	Good.
Comments	
Duration of Work	9 months, up to March 2009.
Contact for Routine Road Maintenance	Nico Bossman Denzil Guruvan 082 444 8858 083 778 6197

National Route	N2		
Section	Durban to Empangeni		
Distance	162 km		
Description	For 71 km, up to Stanger, the road is a four-lane dual carriageway. For the next 52 km, up to the Mtunzini Toll Plaza, the road is a four-lane single carriageway with wide paved shoulders. The remaining portion is also a single carriageway with alternating passing opportunities.		
Condition of Road	Good.		
Comments	<p>A new project will commence in September 2008 for upgrading of the Inanda/Umgeni Interchanges in Durban. There will be minimum disruption to traffic on the N2, with only short term closures of the slow lanes and reduction in speed envisaged, while the on-off ramps will be controlled through stop/go.</p> <p>A new project will commence in September 2008 for the construction of the Cornubia interchange, the ramps of which will into the existing Mount Edgecombe Interchange. The will be a reduced clearance limit for construction of the bridge deck over the N2, and possible deviation during placement of the temporary supports. Speed reductions will signposted.</p> <p>A new project will commence in June 2008 for the construction of a new interchange for the King Shaka Int. Airport, north of the Mhloti river. The will be a reduced clearance limit for construction of the bridge deck over the N2, and possible deviation during placement of the temporary supports. Speed reductions will signposted.</p>		
Duration of Work	18 months, up to January 2010.		
Contact for Routine Road Maintenance	Nico Bossman & 082 444 8858	Denzil Guruvan I(Durban to Umdloti) 083 778 6197	Collin Naidoo (Umdloti to Empangeni) 082 443 6509

National Route	N2		
Section	Empangeni to Pongola		
Distance	250km		
Description	A 2-lane single carriageway with paved shoulders.		
Condition of Road	Good.		
Comments	No Construction		
Duration of work			
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198		

National Route	N2		
Section	Pongola to KwaZulu-Natal / Mpumalanga Border		
Distance	38km		
Description	A 2-lane single carriageway road with narrow lanes and gravel shoulders		
Condition of Road	Fair to Poor. Expect potholes after rainy conditions.		
Comments	Construction work is planned to commence in August 2008. There are limited overtaking opportunities because of pedestrian activity. Motorists must adhere to posted speed limits.		
Duration of work	Construction is planned for August 2008 to February 2011.		
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198		

National Route	N2		
Section	Mpumalanga Border north of Pongola to Piet Retief		
Distance	44km		
Description	A two-lane single carriageway with narrow gravel shoulders.		
Condition of Road	Fair to poor and uneven in places.		
Comments	Reseal and strengthening project started in May 2008		
Duration of Work	18 Months		
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089		

National Route	N2
Section	Piet Retief to Ermelo
Distance	117km
Description	A two-lane single carriageway with narrow gravel shoulders.
Condition of Road	Fair to poor and uneven in places.
Comments	Construction (capacity upgrading) to commence in June '08 between Ermelo to Camden, and only partial pavement upgrading commencing in Jan 2009 from Camden towards Piet Retief..
Duration of Work	10 months (Ermelo->> Camden) and 24 months (Camden → Piet Retief)
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

N3

National Route	N3
Section	Durban to Cedara (Hilton)
Distance	85 km
Description	<p>This entire section is a multi-laned dual carriageway. The first four km out of Durban carries heavy traffic with up to 5 lanes in each direction. The next 40 km, up to Cato Ridge, has 3 lanes in each direction with wide paved shoulders. The section between Cato Ridge and the end of the Pietermaritzburg Bypass (33 km) has a two-lane plus paved shoulder configuration, except on steep gradients to the east of Pietermaritzburg where climbing lanes are provided.</p> <p>Upgrading of the Mariannahill Interchange bridge will commenced in April 2008. While majority of the work will be on the cross road, there will be restricted traffic speed limits of 60km/hr as well as restricted height clearance during the bridge construction over the N3. There will be occasions when there will only be two lanes in each direction. Abnormal vehicles are urged to use the ramp.</p> <p>Repairs to the asphalt pavement between Mariannahill Toll Plaza and Key Ridge commenced from August 2007. Traffic will be accommodated in 2-lanes in each direction, with single lanes during night work and on Sundays. Two closures up to 5kms on the northbound carriageway and one closure up to 4kms on the southbound carriageway can be expected. Repairs to the concrete panels and joint sealing have commenced in April 2007 between Key Ridge and Cato Ridge. Traffic will be accommodated in 2 and sometimes 1lane (when working on the middle and fast lane) in each direction. Closures up to 4km can be expected in each direction. Motorists to be aware that reduced speed limits of 60 km/hr are to be imposed at all work sections.</p> <p>Upgrading of the New England Road Interchange on the Pietermaritzburg Bypass now complete. The final 14 km to Howick incorporates the notorious, steeply graded Town Hill, which has 3 lanes with paved shoulders in each direction.</p>
Condition of Road	Good. Misty conditions could be frequently encountered.
Comments	
Duration of Work	Improvements to Mariannahill Interchange : April 2008 – May 2009.Repairs between Mariannahill Toll Plaza (km 26.3) and Key Ridge (km 4.9): August 2007 to September 2008.
Contact for Routine Road Maintenance	Nico Bossman Denzil Guruvan 082 444 8858 083 778 6197

National Route	N3 (N3 Toll Concession Route)
Section	Cedara to Heidelberg
Distance	415 km
Description	This section of road is a public private partnership between SANRAL and the N3Toll Concession (Pty) Ltd. This toll route is a four-lane dual carriageway road between Cedara and the Tugela Toll Plaza. From the Tugela Toll Plaza to Wilge Toll Plaza, the road is a four-lane single carriageway with paved shoulders of varying width. The section between the Tugela Toll Plaza and Warden is an unlimited access road with at-grade intersections. The remainder of the road between Villiers and Heidelberg is a four-lane dual carriageway with wide-paved shoulders.
Condition of Road	Good.
Comments	Current Construction works include: (i) Rehabilitation works and reseal between the De Hoek Toll Plaza and Villiers. September 2008 to December 2008. (ii) Rehabilitation works on the Harrismith Bypass. Expected completion is December 2008. (iii) Rehabilitation work between Nottingham Road and the Mooi River Toll Plaza. Expected completion is August 2008. (iv) Rehabilitation between Estcourt and Frere. August 2008 to March 2009. (v) Concrete repairs between Frere and the Tugela Toll Plaza. August 2008 to December 2009. (vi) Ongoing routine road maintenance. Through the construction zones, traffic may be restricted to one lane in each direction under reduced speed. During certain peak traffic periods, all four lanes will be open to traffic.
Duration of Work	Please see above.
Contact for Routine Road Maintenance	N3TC Customer Care Line 0800 203 950 0800 634 357 0800 N3 HELP

National Route	N3
Section	Heidelberg to Johannesburg
Distance	50 km
Description	Four-lane dual carriage freeway.
Condition of Road	Good.
Comments	Repairs to the road surface and resealing of the road are suspended till further notice. The construction of a new pedestrian bridge close to Spruit View has started.
Duration of Work	
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553

National Route	N3 (GFIP)
Section	Heidelberg Weg Interchange to Geldenhuis Interchange
Distance	12 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Started June 2008
Duration of Work	30 months

National Route	N3 (GFIP)
Section	Geldenhuis Interchange to Buccleuch Interchange
Distance	17,6 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Started June 2008
Duration of Work	30 months

N4

National Route	N4 (Platinum Highway)
Section	Botswana Border to Zeerust
Distance	60 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Zeerust to Rustenburg
Distance	120 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No Construction.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Rustenburg to Brits (R512 Interchange)
Distance	70 km
Description	Two-lane single carriageway freeway.
Condition of Road	Good.
Comments	Motorists must be aware and be on the look out for pedestrians and animals in the Bapong area. Adhere to posted speed limits.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 West Magalies Toll Road
Section	Rebecca Street to Pelindaba
Distance	21 km
Description	Mixture of two-lane dual carriageway and two-lane single carriageway freeway.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Herman du Plessis 082 771 4886

National Route	N4
Section	Pretoria to Hans Strydom Interchange
Distance	13.6 km
Description	A 6-lane dual carriageway road up to Simon Vermooten Interchange, thereafter a 4-lane dual carriage way.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Phillip Fourie 083 410 2601

National Route	N4
Section	Hans Strydom Interchange to Mozambique
Distance	304 km
Description	Four-lane dual carriageway from Hans Strydom Int. to Van Dyk's Drift. Thereafter, a four-lane undivided road to Wonderfontein, then 2 lanes undivided to the Mozambique border.
Condition of Road	Good.
Comments	Rehabilitation and improvement project underway between Wonderfontein and Belfast
Duration of Work	To be completed by August 2009.
Contact for Routine Road Maintenance	Trans African Concessionaires (TRAC) 013 755 3316

N5

National Route	N5
Section	Harrismith to Bethlehem
Distance	88 km
Description	A two-lane single carriageway with wide paved shoulders. There are overtaking opportunities where severe grades occur.
Condition of Road	Fair to good.
Comments	The rehabilitation and upgrading of the Harrismith Southern Bypass section of the N5 commenced in January 2006. The road and bridge structures will be widened. Pedestrian sidewalks will be added, and street lighting and traffic signals will be installed. During these construction activities, delays can be expected at Stop/Go traffic control points, or traffic may be re-routed through the town of Harrismith. The rains have caused noticeable damage, increasing the number of potholes on the left lane. Additional teams have been increased to accommodate additional repairs with minimal disruption...
Duration of Work	Until July 2009.
Contact for Routine Road Maintenance	Dup du Plessis 082 334 6197

National Route	N5
Section	Bethlehem to Winburg
Distance	120 km
Description	A two-lane single carriageway with varying width of either paved or gravel shoulders. There are overtaking opportunities where severe grades occur.
Condition of Road	Fair to good
Comments	Beware of pedestrian movements in the Paul Roux area. A project for the provision of pedestrian safety measures along 1.6km of the N5 passing the town of Paul Roux commenced at the end of 2007. Stop/Go conditions during the day and traffic signals at night together with speed restrictions will be in operation during construction. The rehabilitation of the section between Senekal and Vaalpensspruit (halfway towards Winburg) had commenced in April 2007 with a 23-month contract duration. Stop/Go conditions during the day and traffic signals at night together with speed restrictions will be in operation during this period.
Duration of Work	March 2009.
Contact for Routine Road Maintenance	Dup du Plessis 082 334 6197

N6

National Route	N6
Section	East London to Stutterheim
Distance	73 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places
Condition of Road	Excellent
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Stutterheim to Cathcart
Distance	48 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places
Condition of Road	Good.
Comments	Road in good condition.
Duration of Work	
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Cathcart to Queenstown
Distance	60 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places.
Condition of Road	Good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Queenstown to Jamestown
Distance	107 km
Description	A two-lane single carriageway with paved shoulders. Winding road with climbing lanes through Penhoek Pass.
Condition of Road	Good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Jamestown to Nek
Distance	14 km
Description	A 2-lane single carriageway with paved shoulders under construction.
Condition of Road	Fair.
Comments	Construction work is in progress and motorists will encounter traffic lights and Stop/Go conditions with delays of about 20 minutes. Motorists must also be aware that reduced speed limits of 60 km/h are imposed through all work sections.
Duration of Work	Until October 2008.
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218
Reconstruction Contract	Joe Coetzee 082 883 1183

National Route	N6
Section	Nek to Aliwal North
Distance	43 km
Description	A two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Aliwal North to Bloemfontein
Distance	200 km
Description	Predominantly, a two-lane single carriageway. The first 2.36km from the National Route 1 towards the National Route 6, has paved shoulders. In addition, the section between Reddersburg and Bloemfontein has been rehabilitated for 41.80 km and is still under a good satisfactory condition. Between Aliwal North and Smithfield the road is in good condition, while the rest of the route has gravel shoulders of varying widths.
Condition of Road	The rest of the route is satisfactory- except for Section 7, between Smithfield and Reddersburg is in poor condition, with the pavement experiencing extensive or dangerous rutting on the wheel paths, undulations, cracks and potholes at random sections.
Comments	Request for road – users to adhere to the permanent and temporary road signs erected, when passing through between Smithfield and Reddersburg. Expect some stop/ go areas on this section of route, which will be accompanied by traffic accommodation or closure road-signs –Be patient, as the maintenance teams will be on road for Patching and other Routine Road Maintenance activities.
Duration of Work	Construction is only scheduled to commence in February 2009 for the half portion between Smithfield and Paryshoogte.
Contact for Routine Road Maintenance	Ofan R. Motlhakane 079 879 4720

N7

National Route	N7
Section	Melkbos Turn-off to Clanwilliam
Distance	198 km
Description	A single carriageway road with paved shoulders between Melkbos and Piekenierskloof Pass; thereafter gravel shoulders.
Condition of Road	Fair to Good.
Comments	The gravel shoulders between Piekenierskloof Pass and Clanwilliam are very narrow. Routine road maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	De Wet Lodewijk 082 309 1528

National Route	N7
Section	Clanwilliam to Northern Cape Border
Distance	188 km
Description	A single carriageway road with gravel shoulders.
Condition of Road	Fair to Good.
Comments	Motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	JJ Vermeulen 079 514 3496

National Route	N7
Section	Northern Cape Border to Vioolsdrift
Distance	412 km
Description	A single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered. Motorists should also be alert to pedestrians and/or stray animals in the vicinity of Okiep and Steinkopf.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chris Roux 083 440 7553

N8

National Route	N8
Section	Groblersshoop to Kimberley
Distance	285 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Fair.
Comments	Routine road maintenance teams may be encountered. Motorists should also be alert to stray animals along the route.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Andre Bardenhorst 082 779 7025

National Route	N8
Section	Kimberley to Bloemfontein
Distance	150 km
Description	Predominantly, a two-lane single carriageway. The 29 km section between Kimberly and Perdeberg has paved shoulder, while the final eight km immediately adjacent to Bloemfontein is four – lane dual carriageway with wide paved shoulders. The remainder of the road has gravel shoulders.
Condition of Road	Fair
Comments	Resurfacing of some sections between Kimberly and Bloemfontein has been completed. Traffic through work zones will be accommodated by means of Stop/Go boards, where delays of less than five minutes can be expected
Duration of Work	Rehabilitation is scheduled to commence during January 2009 between Kloofeinde to De Brug.
Contact for Routine Road Maintenance	Ofan R. Motlhakane 079 879 4720

National Route	N8
Section	Bloemfontein to Maseru
Distance	135 Km
Description	The first five km from Bloemfontein is four-lane dual carriageway with wide paved shoulders. Between Bloemfontien and Thaba Nchu there are alternating passing and climbing lanes. Between Thaba Nchu and Ladybrand is a two-lane single carriageway road with shoulders of varying widths.
Condition of Road	Satisfactory – Except for the section between Tweespruit and Ladybrand which is fair
Comments	Patching teams are active on section between Tweespruit and Ladybrand, and will be accommodated by means of Stop/Go boards, where delays of less than five minutes can be expected.
Duration of Work	Rehabilitation is scheduled to commence in June 2009 for the section between Tweespruit and Ladybrand
Contact for Routine Road Maintenance	Ofan R. Motlhakane 079 879 4720

N9

National Route	N9
Section	Western Cape and Eastern Cape Boundary to Willowmore
Distance	22 km
Description	A two-lane single carriageway with wide gravel shoulders.
Condition of Road	Fair to good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Willowmore to Aberdeen
Distance	117 km
Description	A two-lane single carriageway with wide paved shoulders
Condition of Road	Fair to good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Aberdeen to Graaff Reinet
Distance	54 km
Description	A two-lane single carriageway with wide paved shoulders.
Condition of Road	Good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Graaff-Reinet to Middelburg
Distance	105 km
Description	A two-lane single carriageway with wide paved shoulders through the Amandelhoogte, Naudesberg Pass and Lootsberg Pass the shoulder is alternately used for a passing lane on the up slopes.
Condition of Road	Good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance, particularly the first 15km north of Graaff Reinet. Approximately 10km north of Graaf Reinet, uneven road section will be encountered.
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Middelburg to the intersection of the N10 and N9 between Middelburg and Noupoort (Carlton Heights).
Distance	24 km
Description	Single carriageway with short section of paved shoulders.
Condition of Road	Fair to good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N10
Section	Nanacha Interchange to Baviaans River
Distance	114 km
Description	This section is a single carriageway facility with one lane in each direction. Apart from the 13km between Paterson and Olifanskop Pass the road has wide surfaced shoulders and climbing lanes where there are steep grades.
Condition of Road	Fair to Good.
Comments	No construction works are in progress on this section of road. Motorists are however warned to be aware of wild animals that may jump the fence occasionally. In addition motorists should be aware of high pedestrian activity at the Paterson and Cookhouse intersections where reduced speeds apply.
Contact for Routine Road Maintenance	Christo Muller 083 628 0272

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	N10
Section	Baviaans River to Cradock
Distance	63 km
Description	The first 10 km is a two-lane single carriageway with narrow gravel shoulders and climbing lanes on some severe grades. Thereafter it becomes a two-lane single carriageway with narrow paved shoulders.
Condition of Road	Fair/Poor.
Comments	No construction works are in progress on this section of road. Motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of stray animals and high pedestrian activity at Cradock.
Contact for Routine Road Maintenance	Christo Muller 083 628 0272

National Route	N10
Section	Cradock to Middelburg
Distance	95 km
Description	The first 43 km is a two-lane single carriageway road with wide paved shoulders. Thereafter it becomes a two-lane single carriageway road with narrow gravel shoulders. .
Condition of Road	Fair / Poor
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance, particularly South of Witkransnek.
Duration of Work	
Contact for Routine Road Maintenance	Christo Muller 083 628 0272

National Route	N10
Section	Ludlow (Intersection of the N10 and N9 between Middelburg and Noupoort) to Hanover
Distance	62 km
Description	Single carriageway with short section of paved shoulders and thereafter gravel shoulders.
Condition of Road	Fair
Comments	Motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Riaan Malan 082 932 0362

National Route	N10
Section	Hanover to De Aar
Distance	64 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Fair to Good
Comments	Motorists may encounter occasional short-term closures over short sections for routine maintenance
Duration of work	Ongoing.
Contact for Routine Road Maintenance	Riaan Malan 082 932 0362

National Route	N10
Section	De Aar to Britstown
Distance	48 km
Description	Single carriageway with short section of paved shoulders; thereafter gravel shoulders.
Condition of Road	Good
Comments	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Riaan Malan 082 932 0362

National Route	N10
Section	Britstown to Prieska
Distance	127 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good
Comments	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Riaan Malan 082 932 0362

National Route	N10
Section	Prieska to Groblershoop
Distance	149 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good .
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Charles van Wyk 076 281 1433

National Route	N10
Section	Groblershoop to Upington
Distance	116 km
Description	Single carriageway with gravel shoulders. Road widening through winelands of Orange River Valley with sharp curves and steep gradients.
Condition of Road	Fair to good.
Comments	Routine road maintenance teams may be encountered. Motorists should also be alert to pedestrians and/ or stray animals in the road reserve.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Charles van Wyk 076 281 1433

National Route	N10
Section	Upington to Nakop (Namibian Border)
Distance	134 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routie Road Maintenance	Charles van Wyk 076-281-1433

N11

National Route	N11
Section	N3 Bergville Interchange to Newcastle
Distance	115 km
Description	A two-lane single carriageway with narrow shoulders, except for the 16 km portion before Newcastle and for short sections through the Biggarsberg Mountain range, where there are passing lanes.
Condition of Road	Variable, generally fair.
Comments	Patching / pothole repairs may be expected around Fort Mistake.
Duration of Work	Currently in progress
Contact for Routine Road Maintenance	Ronald Dookhie 073 155 4944

National Route	N11
Section	Newcastle to Volksrust
Distance	54 km
Description	Apart from the 9 km that constitute the Newcastle Bypass and the 12 km that make up the Laingsnek (Majuba) Mountain Pass, the road is a single narrow carriageway, with no shoulders.
Condition of Road	Some sections are in a poor condition
Comments	The road is uneven in places. Drivers must exercise extreme caution in wet weather; the spray raised by the tyres of all vehicles restricts visibility. The Laingsnek Pass is steep, winding and dangerous in wet conditions. Motorists are urged to adhere to the speed limit and drive cautiously.
Duration of Work	
Contact for Routine Road Maintenance	Ronald Dookhie 073 155 4944

National Route	N11
Section	Volksrust to Amersfoort
Distance	50 km
Description	A two-lane single carriageway with narrow gravel shoulders. The whole section is heavily trafficked.
Condition of Road	Poor.
Comments	Construction works/bridge repair works are in progress over a 50 km section between Volksrust and Amersfoort. Motorists may encounter manually controlled Stop/Go conditions at up to 5 work sections with possible delays of 20 minutes at each. Motorists must also be aware that reduced speed limits are imposed through all work sections.
Duration of Work	November 2008
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N11
Section	Amersfoort to Ermelo
Distance	51 km
Description	A two-lane single carriageway road with narrow gravel shoulders.
Condition of Road	Poor.
Comments	Construction and road rehabilitation works in progress with Stop/Go at up to 2 work sections with possible delays of 20 minutes each. Road closures due to blasting operations will happen on some Sundays with a maximum delay of 2 hours.
Duration of Work	Completion September 2010.
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N11
Section	Ermelo to Middelburg
Distance	101 km
Description	A two-lane single carriageway with wide gravel shoulders.
Condition of Road	Good. Erosion in places on gravel shoulders
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N11
Section	Middelburg to Groblersdal
Distance	82 km
Description	A two-lane single carriageway with narrow gravel shoulders.
Condition of Road	Fair, but uneven in places.
Comments	Reseal project, with special maintenance on portions, from Loskop Dam to Roedtan, started in February 2008
Duration of Work	Completion April 2009.
Contact for Routine Road Maintenance	Phillip Fourie 083 410 2601

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	N11
Section	Groblersdal via Marblehall to Old Mpumalanga / Limpopo Border
Distance	38km
Description	A two-lane single carriageway road with narrow gravel shoulders.
Condition of Road	Fair to poor, and uneven in places. No surfacing for 1 km after Marble Hall.
Comments	Strengthening (reconstruction) project (part of Loskop dam to Roedtan Project) started in February 2008
Duration of Work	Completion April 2009.
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	N11
Section	Old Mpumalanga Border (North of Marble Hall) – Mokopane (Potgietersrust) – Groblersdrift Border Post
Distance	276 kms
Description	Two-lane single carriageway.
Condition of the road	Fair. Gravel shoulders.
Comments	Reseal project with strengthening (reconstruction) over portions, (part of Loskop dam to Roedtan project) started February 2008.
Duration of work	Completion April 2009.
Contact for Routine Road Maintenance	Wimpie van Rensburg 082 906 0150

N12

National Route	N12
Section	Three Sisters to Victoria-West
Distance	61 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair to Good.
Comments	Motorists may encounter occasional short-term closures over short sections for routine maintenance
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Johan Nel 082-612-1980

National Route	N12
Section	Victoria-West to Britstown
Distance	104 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Johan Nel 082-612-1980

National Route	N12
Section	Britstown to Hopetown
Distance	134 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Johan Nel 082-612-1980

National Route	N12
Section	Hopetown to Kimberley
Distance	118 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Andre Badenhorst 082-779-7025

National Route	N12
Section	Kimberley to Northern Cape Border
Distance	85 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair to Good.
Comments	Construction works are in progress between Kimberley and Warrenton. Motorists will encounter up to three (3) Stop/Go and traffic-light controls, with waiting periods on average 15 minutes.
Duration of Work	May 2008 to June 2009.
Contact for Routine Road Maintenance	Andre Bardenhorst 082-779-7025

National Route	N12
Section	North West / Northern Cape Border at Warrenton to Christiana
Distance	42km
Description	Two-lane single carriageway with unpaved shoulders.
Condition of Road	Fair to poor in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Jo Botha 082-307-1697

National Route	N12
Section	Christiana to Bloemhof
Distance	52km
Description	Two-lane narrow single carriageway with unpaved shoulders.
Condition of Road	Fair to poor and uneven in places.
Comments	Road is being reconstructed and widened on the section between Bloemhof and Beefmaster. 2 Stop/go controls will be encountered with delays of up to 20 minutes. There will be reduced speed limits in place within these areas
Duration of Work	Completion March 2010.
Contact for Routine Road Maintenance	Jo Botha 082-307-1697

National Route	N12
Section	Bloemhof to Wolmaranstad
Distance	64km
Description	Two-lane narrow single carriageway with unpaved shoulders.
Condition of Road	Fair to poor and uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Jo Botha 082-307-1697

National Route	N12
Section	Wolmaransstad to Klerksdorp
Distance	81km
Description	Two-lane single carriageway with wide paved shoulders on most of the section, except closer to Klerksdorp.
Condition of Road	Good to very good.
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Jo Botha 082-307-1697

National Route	N12
Section	Klerksdorp to Potchefstroom
Distance	25km
Description	Two-lane narrow double carriageway with unpaved shoulders.
Condition of Road	Good.
Comments	Reseal with special maintenance underway. Two lanes reduced to one in places.
Duration of Work	Completion December 2008.
Contact for Routine Road Maintenance	Jo Botha 082-307-1697

National Route	N12
Section	Potchefstroom to North West Border at Carltonville
Distance	51km
Description	Two-lane narrow single carriageway with passing lanes.
Condition of Road	Fair.
Comments	Reseal with special maintenance project from Potchefstroom to R54, underway.
Duration of Work	Completion December 2008
Contact for Routine Road Maintenance	Jo Botha 082-307-1697

National Route	N12
Section	Diepkloof Interchange to Gauteng/Mpumalanga Border
Distance	50km
Description	Four-lane dual carriageway freeway.
Condition of Road	Fair to Good.
Comments	Reconstruction project between Gilloolys and R21 will start June 2008
Duration of Work	Expected completion 2011
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553

National Route	N12 (GFIP)
Section	Reading to Elands Interchange
Distance	4 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Started in June 2008
Duration of Work	30 months

	N12
Section	Gauteng / Mpumalanga Border to Middelburg
Distance	115km
Description	Four-lane dual carriageway freeway
Condition of Road	Fair to good
Comments	(a) Reseal contract on tender between Delmas and Ogies (44 km) (b) Concrete repair between Ogies and Witbank (36 km) has started
Duration of Work	Concrete repair completion September 2008
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

N14

National Route	N14
Section	Springbok to Pofadder
Distance	163 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and/or stray animals in Pofadder and ± 8 km west of Kuruman.
Duration of Work	
Contact for Routine Road Maintenance	Louw Mposi 072-325-5886

National Route	N14
Section	Pofadder to Kakamas
Distance	130 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Louw Mposi 072-325-5886

National Route	N14
Section	Kakamas to Keimoes
Distance	41km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Louw Mposi 072-325-5886

National Route	N14
Section	Upington to Olifantshoek
Distance	166 km
Description	Single carriageway with short section of paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Milton van Heerden 083-406-6371

National Route	N14
Section	Olifantshoek to Kuruman
Distance	97 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Milton van Heerden 083-406-6371

National Route	N 14
Section	Kuruman to Vryburg
Distance	132km
Description	Single narrow carriageway with gravel shoulders.
Condition of Road	Good
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

National Route	N 14
Section	Vryburg to Delareyville
Distance	82km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

National Route	N 14
Section	Delareyville to Coligny
Distance	104km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

National Route	N 14
Section	Coligny to Ventersdorp
Distance	53km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

National Route	N 14
Section	Ventersdorp to North West / Gauteng Border
Distance	101km
Description	Single carriageway with gravel shoulders.
Condition of Road	Poor and uneven in places.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

N17

National Route	N 17
Section	Soweto to Nasrec
Distance	6 km
Description	New alignment
Condition of Road	NA
Comments	Construction on new alignment started February 2008
Duration of Work	December 2009
Contact for Routine Road Maintenance	N.A.

National Route	N 17
Section	Johannesburg to Springs
Distance	35 km
Description	A 4-lane dual carriageway.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	N17 Toll Operations (Pty) Ltd. 082 909 0689

National Route	N 17
Section	Springs to Leandra
Distance	53km
Description	Single carriageway with paved shoulders in places.
Condition of Road	Fair.
Comments	Project for widening and an asphalt overlay plus new interchanges started July 2007. Stop/ go control is in place on three sections along the route and motorists can expect delays of up to 15 minutes per stop.
Duration of Work	July 2009
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	N 17
Section	Leandra to Kinross
Distance	15Km
Description	New Alignment
Condition of Road	N.A.
Comments	Construction on new alignment started November 2007
Duration of Work	December 2010
Contact for Routine Road Maintenance	N.A.

National Route	N 17
Section	Kinross via Bethal to Ermelo
Distance	99km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to Poor, uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N 17
Section	Ermelo to Oshoek Border Post
Distance	122.59km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair, but uneven in places
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

N18 (R49)

National Route	N 18 (R49)
Section	Warrenton to Hartswater (Northern Cape Border)
Distance	55 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and / or stray animals.
Duration of Work	
Contact for Routine Road Maintenance	Andre Badenhorst 082-779-7025

National Route	N 18
Section	Northern Cape / North West Border at Taung to Vryburg
Distance	119km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

National Route	N 18
Section	Vryburg to Mafekeng
Distance	156km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

OTHER NATIONAL ROUTES

National Route	R22
Section	Hluhluwe to Farazela (RSA/Mozambique border)
Distance	175 km
Description	A 2-lane single carriageway road with narrow paved shoulders throughout.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	P720
Section	N2 to Golela Border Post with Swaziland
Distance	10 km
Description	A Single carriageway road between National Route 2 and Golela Border Post. Two lanes and a narrow paved shoulder and wide gravel shoulder in each direction.
Condition of Road	Fair to good.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	R23
Section	Heidelberg to Standerton
Distance	93km
Description	Single carriageway road with paved shoulders.
Condition of Road	Variable but generally fair.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Johannes Dlomo 076 685 1388

National Route	R23
Section	Standerton to Volksrust
Distance	80km
Description	Single carriageway road with unpaved shoulders.
Condition of Road	Fair to good
Comments	Minor works to complete the project
Duration of Work	Construction completed
Contact for Routine Road Maintenance	Johannes Dlomo 076 685 1388

National Route	R27
Section	Vanrhyns Pass to Calvinia
Distance	82 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Sandla Tsengiwe 073 368 1666

National Route	R27
Section	Calvinia to Brandvlei
Distance	147 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Sandla Tsengiwe 073 368 1666

National Route	R27
Section	Brandvlei to Kenhardt
Distance	141 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6880

National Route	R27
Section	Kenhardt to Keimoes
Distance	76 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6880

National Route	S27
Section	Villiers to Heidelberg
Distance	62km
Description	Single carriageway with gravel shoulders and short gravel road portion.
Condition of Road	Good (Gravel road fair).
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Johannes Dlomo 076 685 1388

National Route	R30/R34
Section	Bloemfontein to Kroonstad via Brandfort/Welkom
Distance	210 km
Description	A single carriageway between National Route N1 and Virginia. Generally, it accommodates two lanes and a narrow paved shoulder or wide gravel shoulder in each direction. The five km portion bypassing Brandfort has 4 lanes and paved shoulders. The section between Virginia and Welkom is a double carriageway and the section between Welkom and Kroonstad is a four-lane undivided carriageway with paved shoulders.
Condition of Road	Variable, but generally good.
Comments	A contract for the upgrade of the road between Brandfort and the Vet River bridge commenced on 26 June 2008. Construction will take place in half widths with STOP/GO traffic control during the day and traffic signals at night.
Duration of work	Until August 2010
Contact for Routine Road Maintenance	Dup du Plessis 082 334 6197

National Route	R33
Section	From Kwa Zulu Natal border, over Piet Retief up to N17 near Warburton
Distance	139kms
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair but uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	R33
Section	From N17 near Warburton, over Carolina up to N4 near Belfast
Distance	89kms
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair but uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R35
Section	Amersfoort over Bethal up to Middelburg
Distance	156 kms
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair to poor
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R36 – R71 – R526 – R40
Section	Bandelierskop –Soekmekaar –Mooketsi – Modjadjikloof (Duiwelskloof) – Tzaneen – Gravelotte – Mica – Klaserie (New Mpumalanga Border)
Distance	197 kms
Description	Two-lane narrow single carriageway with gravel shoulders in places.
Condition of the road	Fair.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Eben Smith 072 494 1234

National Route	R37
Section	Polokwane (Pietersburg) up to Mpumalanga border north of Burgersfort
Distance	160 kms
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair.
Comments	No construction
Duration of work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R37
Section	Burgersfort to Lydenburg
Distance	57km
Description	Single carriageway road with paved shoulders.
Condition of Road	Variable but generally fair.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R37
Section	Lydenburg over Sabie to Nelspruit
Distance	86Km
Description	Single carriageway road with narrow shoulders.
Condition of Road	Good
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R38
Section	Bethal to Hendrina
Distance	43 kms
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair to poor and uneven in places
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R38
Section	Hendrina over Carolina up to R40 near Barberton
Distance	171kms
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair to poor and uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R40
Section	(New Mpumalanga Border) to North of White River to Klaserie
Distance	116km
Description	Single carriageway with gravel shoulders in places.
Condition of Road	Fair
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R40
Section	Nelspruit to Barberton
Distance	45km
Description	Upgraded single carriageway with climbing lanes in places and paved shoulders. Portion between Hilltop and Barberton still under construction, see2) below
Condition of Road	Very good and completed from Nelspruit to HilltopPass but fair to poor where construction work is still in progress towards Barberton and road surfaces varying from well- kept gravel deviations to temporary all werther surfaces, but with no lane markings.
Comments	The remaining portion of the route from Hilltop Pass to Barberton, is still being reconstructed/realigned/widened until June 2009. Some portions in the Pass have short deviations and STOP/GO traffic control methods involving one way traffic. Expect delays up to 20 minutes , but blasting or bridge works on certain days will cause longer delays. (Watch/listen to the local media for more details on this.) Two way traffic is being maintained towards the Barberton side...
Duration of Work	June 2009.
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	R61
Section	Mtamvuna to Port Shepstone
Distance	45 km
Description	Two-lane single carriageway with passing lanes.
Condition of Road	Good.
Comments	
Contact for Routine Road Maintenance	Bill Morris 083 655 4228

National Route	R61
Section	1 (East Cape/West Cape Border to Aberdeen)
Distance	74.5 km
Description	Single carriageway road
Condition of Road	Fair.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance, particularly near Aberdeen
Duration of Work	Continuous – Routine Road Maintenance.
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	R61
Section	Bethesda (N9 Intersection) to Cradock (N10 Intersection)
Distance	85.8 km
Description	A narrow 2-lane single carriageway with gravel shoulders over most of the length.
Condition of Road	Fair.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of pedestrians and stray animals.
Duration of Work	
Contact for Routine Road Maintenance	Leon van Rensburg 082 320 2869

National Route	R61
Section	Cradock (N10 Intersection) to Tarkastad
Distance	74.5 km
Description	A narrow 2-lane single carriageway with gravel shoulders
Condition of Road	Fair
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of pedestrians and stray animals.
Contact for Routine Road Maintenance	Leon van Rensburg 082 320 2869

National Route	R61
Section	Tarkastad to Queenstown
Distance	63.1km
Description	A narrow 2 lane single carriageway with gravel shoulders.
Condition of Road	Fair.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of pedestrians and stray animals.
Contact for Routine Road Maintenance	Leon van Rensburg 082 320 2869

National Route	R61
Section	Queenstown (N6) to Cofimvaba
Distance	60 km
Description	A 2-lane single carriageway with wide paved shoulders.
Condition of Road	Good.
Comments	Construction works are in progress between the N6 to beyond Cofimvaba. 3 Stop/Go closures in operation and delays of up to 20 minutes may be experienced at each closure.
Duration of Work	Until May 2009.
Contact for Routine Road Maintenance	George Brand 083 304 6553
Contact for rehabilitation contract	Gerard Downing 083 262 7143

National Route	R61
Section	Cofimvaba to Engcobo
Distance	92 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Condition of Road	Fair to good.
Comments	Motorists to be aware of pedestrians and stray animals.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 304 6553

National Route	R61
Section	Engcobo to Mthatha
Distance	49 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Condition of Road	Fair to good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of pedestrians and stray animals.
Contact for Routine Road Maintenance	George Brand 083 304 6553

National Route	R61
Section	Mthatha to Port St Johns
Distance	74 km
Description	A 2-lane single carriageway, with surfaced shoulders.
Condition of Road	Fair.
Comments	Motorists to be aware of pedestrians and stray animals. Motorist must also be aware of reduced speed limits of 60km/h are imposed through sections which require maintenance.
Contact for Routine Road Maintenance	George Brand 083 304 6553

National Route	R71
Section	Polokwane (Pietersburg) – Magoebaskloof – Tzaneen
Distance	89 kms
Description	Two-lane narrow single carriageway with gravel shoulders.
Condition of the road	Fair.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Eben Smith 072 494 1234

National Route	R81
Section	Polokwane (Pietersburg) – Mooketsi – Giyani
Distance	149 kms
Description	Two-lane narrow single carriageway with gravel shoulders.
Condition of the road	Fair.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Eben Smith 072 494 1234

National Route	R101
Section	Middelfontein Interchange (Modimole (Nylstroom)) to Mookgopong (Naboomspruit)
Distance	30km
Description	Two-lane single carriageway with passing lanes.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

National Route	R101
Section	Mookgopong (Naboomspruit) to Mokopane (Potgietersrust)
Distance	68km
Description	Two-lane single carriageway with paved shoulders and passing lanes in places.
Condition of Road	Fair to good
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

National Route	R101
Section	Mokopane (Potgietersrus) to southern outskirts of Polokwane (Pietersburg)
Distance	51km
Description	Two-lane single carriageway with paved shoulders and passing lanes in places.
Condition of Road	Good
Comments	Construction on Load Control Station, near Ultra City, started in February 2008
Duration of Work	Completion December 2008.
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

National Route	R104 (P154-1& P154-2)
Section	Pretoria-Bronkhorstspuit-Mpumalanga Border
Distance	64.28 Kms
Description	2-lane single carriageway with narrow gravel shoulders
Condition of the road	Fair/Poor uneven in places
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	R510
Section	North West Border - Thabazimbi – Lephalala (Ellisras) – Monte Christo
Distance	253 kms
Description	Two-lane single carriageway with gravel shoulders
Condition of the road	Good.
Comments	No construction
Duration of work	
Contact for Routine Road Maintenance	Wimpie van Rensburg 082 906 0150

National Route	R521
Section	Polokwane (Pietersburg) – Dendron -_ Vivo
Distance	103 kms
Description	Two-lane single carriageway.
Condition of the road	Fair. Gravel shoulders.
Comments	No construction
Duration of work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R523
Section	Vivo - Waterpoort – Masekwaspoort
Distance	75 kms
Description	Two-lane single carriageway.
Condition of the road	Fair. Gravel shoulders.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R555
Section	Witbank to Middelburg
Distance	28 km
Description	A 2-lane single carriageway road with narrow gravel shoulders
Condition of Road	Fair to Good
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	R570 (P133/1)
Section	N4 to Malalane Gate
Distance	3 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair, uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R570 (P80/1)
Section	N4 to Jeppes Reef Border Post
Distance	41 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair, but uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R571 (D2683)
Section	N4 to Coopersdal
Distance	21 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair, uneven in places
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R571 (D797)
Section	One Tree Hill (P80/1) to Tonga (D2948)
Distance	27 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor, and uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R571 (D2948)
Section	Tonga (D797) to Mangweni (P179/1)
Distance	10 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair to satisfactory.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R572
Section	Monte Christo – Tom Bourke
Distance	95 kms
Description	Two-lane single carriageway.
Condition of the road	Fair. Gravel shoulders.
Comments	No Construction.
Duration of work	
Contact for Routine Road Maintenance	Wimpie van Rensburg 082 906 0150

NATIONAL BORDER CONTROL POSTS

Botswana Border

Border Post	Location	Description	Condition	Opening Times
Twee Rivieren	Situated in the Kgalagadi Cross Border National Park	Single carriageway gravelled road.	Fair	08h00 to 16h30
Gemsbok	Between Upington and Botswana	Single carriageway gravelled road.	Fair	08h00 to 16h30
Middelputs	Between Van Zylsrus and Botswana	Single carriageway gravelled road.	Fair	08h30 to 16h30
McCarthy's Rest	Route R380 between Kathu and Thshabon (Botswana)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Makopong	Route R379 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Bray	Route R378 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Boshoek	Route R375 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Magobistad	Between Mafikeng & Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h30
Ramatlabama	Between Mafikeng & Botswana	Single carriageway paved road.	Good	07h00 to 20h00
Skilpadshek	N4 Platinum – Lobatse	Single carriageway paved road.	Good	07h00 to 19h30
Swarikopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 19h00
Kopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 22h00
Derdepoort	Between Rustenburg & Botswana	Single carriageway gravelled road.	Poor	07h00 to 19h00
Stockpoort	From Ellisras to Botswana	Single carriageway paved road.	Good	08h00 to 16h00
Groblers Bridge	From Potgietersrus on N11 to Botswana	Single carriageway paved road.	Good	08h00 to 18h00
Zanzibar	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Platjan	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Pondrift	From Alldys on R521 to Botswana	Single carriageway paved road.	Good	08h00 to 16h00

Namibia Border

Border Post	Location	Description	Condition	Opening Times
Alexander Bay	Between Alexander Bay and Oranjemund (Namibia)	Single carriageway paved road.	Good	06h00 to 22h00
Violsdrift	Route N7/B1 between Springbok and Keetmanshoop (Namibia)	Single carriageway paved road.	Good	24 hours
Onseepkans	Route R358/C10 between Pofadder and Karasburg	Single gravelled road with single traffic lane bridge over Orange River Bridge	Fair	08h00 to 16h30
Nakop	Route N10/B3 between Upington and Karasburg (Namibia)	Single carriageway paved road with gravelled shoulders. New Border Control Post situated 1 km from actual border with Namibia.	Good	24 hours
Noenieput	Between Upington and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Rietfontein	Route R31/C16 between Askam and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30

Zimbabwe Border

Border Post	Location	Description	Condition	Opening Times
Beitbridge	On N1 between RSA and Zimbabwe	Single carriageway paved road.	Fair	Passengers: 24hrs Commercial: 24hrs

Mozambique Border

Border Post	Location	Description	Condition	Opening Times
Pafuri	In Kruger National Park, nearest route is R525, east/west direction ±25 km adrift)	Single carriageway paved road under construction.	Fair	08h00 to 16h00
Lebombo	On N4 between Nelspruit and Maputo	Single carriageway paved road.	Good	06h00 to 22h00
Kosibay (Farazela)	On R22 between RSA and Mozambique	Single carriageway paved road with narrow paved shoulders.	Good	06h00 to 1800

Swaziland Border

Border Post	Location	Description	Condition
Mananga	On R571 between Komatipoort and Swaziland	Single carriageway paved road.	Fair
Jeppe's Reef	On R570 between Malelane and Swaziland	Single carriageway paved road.	Good
Josefsdal	On R40 between Barberton and Piggs Peak	Single carriageway gravelled road.	Poor
Oshoek	On N17 between Ermelo and Manzini	Single carriageway paved road.	Good
Waverley	Off R33 between RSA and Swaziland	Single carriageway paved road.	Good
Nerston	On R65 between RSA and Swaziland	Single carriageway paved road.	Fair
Emhlatintini	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Bothashoop	Between Piet Retief and Swaziland	Single carriageway gravelled road.	Fair
Mahamba	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Onverwacht	D1936 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good
Golela/Lavumisa	P 720 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

Lesotho Border

Border Post	Location	Description	Condition
Monantsapas	R 57/S1579 (Free State)	Single carriageway paved road	Fair to good
Caledonspoort	P 92/1 (Free State)	Single carriageway paved road	Fair to poor
Ficksburg Bridge	R 26 / P75/1 (Free State)	Single carriageway paved road	Fair
Peka Bridge	S 388 / S 306 (Free State)	Single carriageway gravel road	Poor
Maseru Bridge	N8 (Free State)	Single carriageway paved road.	Fair
Van Rooyen's Gate	P66/1 (Free State)	Single carriageway paved road	Fair
Sepapu's Gate	S4 (Free State)	Single carriageway gravel road	Poor
Makhaleng Bridge	S2 (Free State)	Single carriageway gravel road	Very Poor
Telle Bridge	R 392 (from Sterkspruit in the Eastern Cape)	Single carriageway paved road.	Good
Ongeluksnek	Eastern Cape: Off R 56. Closest towns are Mount Fletcher and Matatiele	Gravel approach road.	Poor to very poor. Only suitable to 4x4 vehicles beyond the border post.
Qacha's Nek	Eastern Cape: Closest town Matatiele	Gravel approach road.	Poor
Ramaselitso Gate	Eastern Cape: Closest from Matatiele	Gravel approach road.	Poor
Sani Pass	P 318 (KwaZulu-Natal)	Gravel approach road	Fair but often only accessible to 4X4 vehicles beyond the border post.

THE SOUTH AFRICAN NATIONAL ROADS AGENCY LTD

Contact Details

Head Office

Ditsela Place
1204 Park Street
Hatfield 0083
Tel. 012 426 6000
Fax 012 362 2117

Northern Region

38 Ida Street
Menlo Park
Pretoria
Tel. 012 426 6200
Fax 012 348 1680

Eastern Region

58 Van Eck Place
Mkondeni
Pietermaritzburg
Tel. 033 392 8100
Fax 033 386 6284

Southern Region

NRA House
Southern Life Gardens
70 Second Avenue
Newton Park
Port Elizabeth
Tel. 041 398 3200
Fax 041 398 3222

Western Region

Parc du Cap
Building 5
Corner Mispel Street / Willie van Schoor Avenue
Bellville 7530
Tel. 021 957 4600
Fax 021 946 1630

Website: www.nra.co.za

E-mail: info@nra.co.za

Fraud Hot Line: 0800204558