



Travel Advisory Report OCTBER 2019

N1

National Route	N1
Section	Old Oak Interchange to Rawsonville
Distance	64 km
Description	Two-lane dual carriageway with paved shoulders.
Expected Travel Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Chris Roux 083 440 7553

National Route	N1
Section	Rawsonville to Laingsburg
Distance	156 km
Description	Single carriageway road with passing lanes and with gravel shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	<p>A compulsory stop, manned by the Provincial Traffic Department, is in operation ± five km south of Touws River. An unmanned compulsory stop for heavy vehicles is also in operation on the south-bound carriageway in Hex River Pass.</p> <p>Motorists should be alert to pedestrians and/or stray animals just north of De Doorns as well as to the informal traders alongside the road. Please note that it is illegal to stop and buy from the sellers.</p> <p>De Doorns Pedestrian Facility (km 19.7) Construction of sidewalks and pedestrian facilities is taking place.</p> <p>At this stage No STOP/GOs or road closures are expected.</p> <p>Motorists are to be mindful of pedestrians and site personnel.</p> <p>Routine Road Maintenance teams may be encountered.</p>
Duration of Work	Ongoing
Contact for Routine Maintenance	Bernice Cloete 079 696 6628

National Route	N1
Section	Laingsburg to Three Sisters
Distance	280 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Gerhard Coetsee 078 453 6326

National Route	N1
Section	Three-Sisters to Colesberg
Distance	236 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Martiens du Plessis 083 655 0644

National Route	N1
Section	Colesberg to Orange River
Distance	36.34 km
Description	Single carriageway with surfaced shoulders and 4 passing lane sections.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Martiens du Plessis 083 655 0644

National Route	N1
Section	Orange River (Provincial Boundary) to Bloemfontein (Sydenham Interchange)
Distance	175 km
Description	A two-lane single carriageway with wide paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to good.
Expected Travel Condition	No construction.
Duration of Work	RRM until January 2021
Contact for Routine Road Maintenance	Milton van Heerden 078 460 6552

National Route	N1
Section	Bloemfontein to Kroonstad
Distance	189 km
Description	Around Bloemfontein and extending northwards for some 15km, the road is a four-lane dual carriageway with wide paved shoulders. Thereafter it reduces to a four-lane single carriageway for the next 20kms, otherwise it is a two-lane single carriageway with paved shoulders and passing lanes on steep gradients. The last 10 km, known as the Kroonstad Bypass, is a four-lane dual carriageway.
Expected Road Condition	Generally good except for the section between Ventersburg and Kroonstad, where the road surfacing is being rehabilitated.
Expected Travel Condition	1. A contract for the upgrade between Ventersburg and Holfontein is in progress. Traffic is free flowing. Motorists are advised to obey the posted traffic signs,
Duration of Work	1. Until November 2019
Contact for Routine Road Maintenance	Abel Majorobela 079 896 3377

National Route	N1
Section	Kroonstad to Vaal River (Free State – Gauteng Provincial Boundary)
Distance	102 km
Description	Partly a single carriageway with alternating passing lanes in each direction and wide gravel shoulders, and partly a four-lane single carriageway, except for the 10 km portion beyond the Vaal Toll Plaza, where it becomes a four-lane dual carriageway with wide paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Good
Duration of Work	
Contact for Routine Road Maintenance	Abel Majorobela 079 896 3377

National Route	N1
Section	Vaal River (provincial boundary) to Misgund Soweto
Distance	64 km
Description	Four-lane dual carriageway freeway with wide paved shoulders.
Expected Travel Condition	Good.
Expected Road Condition	Motorists should be beware of pedestrian activity along the route. Additional street lighting has been installed at the Ennerdale Interchange.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Brighton Chipanyama 071 923 6155

National Route	N1
Section	20 Misgund Soweto to Grand Central / Olifantsfontein Interchange
Distance	57.6 km
Description	Multi-lane dual carriageway with paved shoulders
Expected Travel Condition	Good
Expected Road Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553 Unita Fugile 072 793 2825

National Route	N1
Section	21 Grand Central / Olifantsfontein interchange to Proefplaas N4 Interchange
Distance	33.0 km
Description	Construction of a Pedestrian bridge at Solomon Mahlangu.
Expected Travel Condition	
Expected Road Condition	Good
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pierre Coetzer 066 248 0005

National Route	N1
Section	Proefplaas (N4 Interchange) to Bela Bela (Warmbaths) (Platinum Toll highway)
Distance	94 km
Description	Six lane dual carriageway freeway from Pretoria (Proefplaas Interchange) to Zambesi Interchange changing into four lane dual carriageway freeway to Bela Bela.
Expected Travel Condition	1. RRM Teams may be encountered
Expected Road Condition	RRM teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N1
Section	Bela Bela to Polokwane (Great North Toll Road)
Distance	160 km
Description	Four-lane dual divided carriageway freeway from the Warmbaths/Settlers interchange to the Kranskop toll plaza. Four-lane single undivided carriageway freeway from the Kranskop Toll Plaza to the N1/R71 interchange at Polokwane (Meropa Casino).
Expected Travel Condition	1. Routine Road Maintenance teams may be encountered 2. Major roadworks upgrade on the N1 from Town Lodge / Shell Ultra City to R71 interchange
Duration of Work	Until December 2018
Contact for Routine Road Maintenance	NTRV Danie Kotze 082 822 0902

National Route	N1: R101
Section	Middelfontein to Mookgopong Municipal Border (N1/24S: R101)
Distance	4.78 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	March 2020
Contact for Routine Road Maintenance	Gustavus Fouche 082 780 2391

National Route	N1: R101
Section	Mookgopong Municipal Border to Mokopane (N1/25X: (R101)
Distance	67.13 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	March 2020
Contact for Routine Road Maintenance	Gustavus Fouche 082 780 2391

National Route	N1: R101
Section	Mookgopong I/C to N1/25X Intersection (N1/25Y: R101)
Distance	2.570 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustavus Fouche 082 780 2391

National Route	N1: R101
Section	26X Mokopane to Polokwane
Distance	49.7 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	Until end of March 2020
Contact for Routine Road Maintenance	Hannelie Swanepoel 082 380 5264

National Route	N1
Section	Polokwane (Meropa Casino) to Doornbult
Distance	22.3 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered Major Roadworks upgrades from Meropa Casino N1 to R71 interchange (work not in progress) Speed limit throughout the construction zone (for the first 15km) has been lowered to 40 – 60km/h and to be adhered to.
Duration of Work	Ongoing Until March 2020
Contact for Routine Road Maintenance	Thabo Malete 073 418 5228

National Route	N1
Section	28X Doornbult to Louis Trichardt
Distance	98.75 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered Roadworks, application of slurry from Km20.00 to Km40.00 between Solomondale Intersection and Bylsteel Intersection is work in progress Speed limit throughout the construction zone (for the first 15km) has been lowered to 40 – 60km/h and to be adhered to Motorists should be alert of stray animals around Matoks area
Duration of Work	Until March 2020
Contact for Routine Road Maintenance	Thabo Malete 073 418 5228

National Route	N1
Section	Makhado to Beitbridge
Distance	107 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Fair. Expect major roadworks upgrade at Musina (Ring Road)
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Contact for Routine Maintenance	Johannes Rakwena 082 304 6880
---------------------------------	----------------------------------

N2

National Route	N2
Section	Swartklip Interchange to Somerset-West
Distance	24 km
Description	Two-way dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chris Roux 083 440 7553

National Route	N2
Section	Somerset-West to Botriver
Distance	45 km
Description	Average speed cameras have been implemented and are fully operational both ways on Sir Lowry's Pass. Sir Lowry's Pass: Construction works are currently taking place. Two (2) Night STOP/GO's are in place. Delays may be expected. Speed has been reduced to 60km/h. Anticipated completion date: October 2019.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chris Roux 083 440 7553

National Route	N2
Section	Botriver to Riversdale
Distance	218 km
Description	Single carriageway with paved shoulders and passing lanes.
Expected Road Condition	Good.
Expected Travel Condition	Caledon to Riviersonderend: The project is 48,3km long and presently the entire 48.3km is under construction on one side of the road only, alternating left or right depending on where widening is required. Where construction is underway, the traffic is moved to the other side of the road away from the construction activities. Delineators, signage and temporary road markings are in place for the deviation of traffic. Two-way traffic is being maintained with daytime STOP/GO facilities where required when construction activities cannot allow for two-way traffic. These are limited as far as possible with a maximum number of four (4) STOP/GO operations at any one time throughout the stretch of road. Anticipated completion is August 2020 Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Riversdale to Mossel Bay
Distance	82 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johan Nel 082 612 1980

National Route	N2
Section	Mossel Bay to George
Distance	51 km
Description	A four-lane dual carriageway.
Expected Travel Condition	Good.
Expected Travel Condition	<p>N2 - DOUBLING OF THE GWAING RIVER BRIDGE</p> <p>Construction works are in progress west of George. No road closures are anticipated. Two lane traffic is open in both directions with shoulder closure on the east bound carriageway. Traffic can use an alternate route via R102</p> <p>Anticipated completion July 2020</p> <p>Routine Road Maintenance teams may be encountered.</p>
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johan Nel 082 612 1980

National Route	N2
Section	George to Natures Valley (Sout River)
Distance	113 km
Description	Single carriageway with narrow paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	<p>It is illegal to stop and buy from the informal traders.</p> <p>Motorists should be alert to pedestrians and/or stray animals in the vicinity of the informal settlement in Knysna, as well as in the vicinity of Plettenberg Bay.</p> <p>Routine Road Maintenance teams may be encountered.</p>
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Johan Nel 082 612 1980

National Route	N2
Section	Natures Valley to Storms River
Distance	40 km
Description	A two-lane single carriageway with surfaced shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Toll Road
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	N2
Section	Storms River Town to Elands River
Distance	14 km
Description	A two-lane single carriageway with shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Toll Road
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	N2
----------------	----

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Section	Elands River to Gamtoos
Distance	98 km
Description	A two-lane single carriageway with shoulders.
Expected Travel Condition	Good
Contact for Construction	Michelle van Rooyen 072 777 7232

National Route	N2
Section	Gamtoos River to Van Stadens River
Distance	19 km
Description	14, 7 km of 2-lane single carriageway and 4.3 km of dual carriageway with surfaced shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Undulations occur on sections of this road. At Thornhill, pedestrians could be encountered.
Duration of Work	
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	N2
Section	Van Stadens River to Port Elizabeth (Coega IDZ)
Distance	57 km
Description	Dual carriageway with 2 lanes per direction.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	N2
Section	Port Elizabeth (Coega IDZ) to Colchester
Distance	14Km
Description	Dual carriageway with 2 lanes per direction
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	N2
Section	Colchester to Nanaga
Distance	13Km
Description	13km single carriageway
Expected Travel Condition	Good.
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2 section 12 & 13
Section	Nanaga to Komgha River
Distance	30km
Description	2 - Lane single carriageway, narrow road width.
Expected Travel Condition	Good, but no paved shoulders in place.
Duration of Work	
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2 section 13
Section	Komgha River to Grahamstown
Distance	42km
Description	2 - lane single carriageway
Expected Travel Condition	Construction is complete and the road conditions are good.
Duration of Work	Project completed
Contact for construction	
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539

National Route	N2
Section	Grahamstown to Fish River
Distance	47km
Description	A 2-lane single carriageway is being upgraded
Expected Travel Condition	Construction commenced in April 2015 on phase 1. 62 km to 78.7 km and is now complete. The Fish river bridge: km 103, is also complete. Construction of phase 2 commenced in June 2017, 78.7 km to 92.6km. Completion is scheduled for April 2019.
Expected Travel Condition	Speed restrictions will be in place. Construction traffic will be encountered. Speed humps have been installed for safety of road users. Stop/Go controls are in place to reduce traffic speed. The stop/go controls will be removed during the holidays. However, traffic calming and speed restrictions will be in place due to work taking place alongside the road. Animals at R67 intersection east of Grahamstown. Livestock in vicinity of R67 intersection.
Duration of Work	April 2015 to June 2019 (Phase 2) Jan 2019 – April 2021 (Phase 3)
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539
Contact for Construction project	Steve Beckerling – Engineer's representative on site 083 554 3605

National Route	N2
Section	Fish river to Keiskamma Pass
Distance	27 km
Description	A 2-lane single carriageway.
Expected Travel Condition	Good
Expected Travel Condition	Isolated repairs being undertaken.
Duration of Work	
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2
Section	Keiskamma River to Green River
Distance	23 km
Description	A 2-lane single carriageway
Expected Travel Condition	Good
Expected Travel Condition	Recently upgraded
Duration of Work	
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2
Section	Green River to Breidbach - Section 14 & 15
Distance	13km
Description	Upgrading from Green River to Breidbach Interchange. Rehabilitation of section of route through King Williams Town from Buffalo River to Zwelitsha has been completed. Work from Green River to Buffalo river and at Breidbach interchange is planned for future implementation.
Expected Travel Condition	Typical traffic signals in King Williams Town.
Duration of Work	Not applicable at this stage.
Contact for construction	Nick Kitsopoulos 082 576 4667

National Route	N2
Section	Gonubie to Kei River
Distance	60 km
Description	The first 2km is a 4-lane dual carriageway. Thereafter it becomes a 2-lane single carriageway with wide paved shoulders. Passing lanes are provided on some steep grades.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Mike De Lange 082 779 2993

National Route	N2
Section	Kei River to Dutywa
Distance	68 km
Description	Single carriageway road with paved shoulders and passing lanes.
Expected Travel Condition	The condition is fair.
Expected Travel Condition	Roaming animals in some areas near villages. N2 Toleni to Ibeka – expect up to 2hr delays due to road works.
Contact for Routine Road Maintenance	Mike De Lange 082 779 2993

National Route	N2
Section	Dutywa to Mthatha
Distance	85 km
Description	Single carriageway road with paved shoulders and passing lanes.
Expected Travel Condition	Fair
Expected Travel Condition	Roaming animals in some areas near villages
Contact for Routine Road Maintenance	Mike De Lange (RRM queries only) 082 779 2993

National Route	N2
Section	Tetyana to Sitebe Komkulu
Distance	17 km
Description	Upgrading of N2 from Tetyana (km 24) to Sitebe Komkulu (Km 41.0)
Expected Travel Condition	Under construction.
Expected Travel Condition	Mostly 2-way at a maximum speed of 60km/h. Expect stop/go controls for short durations. You may contact the Resident Engineer, MR. Joe van Dyk on the number below, to confirm the blasting times.
Duration of work	October 2016 – May 2019
Contact for Construction project	Joe van Dyk 083 283 6507

National Route	N2
Section	Mthatha to Brookes Nek
Distance	168 km
Description	A 2-lane single carriageway with passing lanes and paved shoulders.
Expected Travel Condition	The Expected Road Condition between km 54 to km 70 is fair however routine maintenance teams may be encountered. Animals may be encountered in some areas near villages.
Contact for Routine Road Maintenance	Ernest Zellhuber 072 789 5046

National Route	N2/22 (Previously R61)
Section	Mtamvuna River (Provincial Boundary) to Port Shepstone
Distance	45 km
Description	Two-lane single carriageway with passing lanes.
Expected Road Condition	Good.
Expected Travel Condition	No construction
Duration of work	
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	N2
Section	Brookes Nek (provincial boundary) to Port Shepstone (Sections 21X & 22X)
Distance	135 km
Description	This section of the N2 in KZN is a two-lane single carriageway with narrow paved shoulders. Passing lanes are provided on all the severe grades with the exception of a short 6 km section, 26 km north of Kokstad.
Expected Road Condition	Good.
Expected Travel Condition	
Duration of Work	
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	N2
Section	Port Shepstone to Durban (N2/N3 Interchange)
Distance	114 km
Description	The first 20 km is a single carriageway road with three lanes of traffic and narrow paved shoulders allowing overtaking opportunities. Thereafter the road becomes a four-lane dual carriageway with wide paved shoulders. The last 17 km leading into Durban has 3 lanes in each direction and is heavily trafficked.
Expected Road Condition	Good.
Expected Travel Condition	No construction. However routine road maintenance teams may be encountered, including road marking. Expect short-term reduced lanes. Flood damage repairs to take place on the surfaced roadway.
Duration of Work	
Contact for Routine Road Maintenance	Port Shepstone to Hibberdene: Amit Bhoora 082 442 9646 Hibberdene to Durban: Emeka Mgbemere 083 641 9056 (Route Manager)

National Route	N2
Section	Durban to Empangeni
Distance	162 km
Description	For 71 km, up to Stanger, the road is a four-lane dual carriageway. For the next 52 km, up to the Mtunzini Toll Plaza, the road is a four-lane undivided carriageway with paved shoulders. The remaining portion is a single carriageway with alternating passing opportunities.
Expected Road Condition	Good.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A closure of the N2 at Umhlali River Bridge and at Umvoti River Bridge is in place. No Stop/Go controls will be in place, but a single lane and speed restrictions are in place on the northbound carriageway. 2. A contract for the upgrade of the N2 to a dual carriageway freeway between Mtunzini Toll Plaza and Empangeni T-junction is in progress. No Stop/Go controls will be in place. Cross over to a portion of the new constructed carriageway between Mtunzini and Esikhaweni took place in January 2019.
Duration of work	<ol style="list-style-type: none"> 1. Until July 2020. 2. Until November 2019.
Contact for Routine Road Maintenance	Emeka Mgbemere 083 641 9056 (Route Manager – Durban to eMdloti) Mikhail Ramlukan 074 325 8752 (Assistant Route Manager – Durban to eMdloti) Stollie van Wyk 072 283 6669 (eMdloti to Empangeni)

National Route	N2
Section	Empangeni to Pongola
Distance	250 km
Description	A 2-lane single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance may be encountered.
Duration of work	Until end of August 2018
Contact for Routine Road Maintenance	Gonie Govender (Route Manager) 084 466 2198

National Route	N2
Section	Pongola to KwaZulu-Natal / Mpumalanga Border
Distance	38 km
Description	A 2-lane single carriageway road with passing lanes on the steeper gradients.
Expected Road Condition	Good
Expected Travel Condition	No construction
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	N2
Section	KwaZulu Natal / Mpumalanga border north of Pongola Border to Piet Retief
Distance	57km
Description	A Two-lane single carriageway narrow gravel shoulder.
Expected Road Condition	Bad
Expected Travel Condition	Two compulsory stop and go are in operation. A temporarily speed camera has been implemented at 60 km/h zone near mall. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 071 638 9828

National Route	N2
Section	Piet Retief to Ermelo
Distance	98.20 km
Description	A Two-lane single Carriageway narrow gravel shoulder. First 7km is 4 lanes undivided
Expected Road Condition	Bad
Expected Travel Condition	There are several potholes so road users are encouraged to drive with caution.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 071 638 9828

N3

National Route	N3
Section	Durban to Cedara (Hilton)
Distance	85 km
Description	This entire section is a multi-lane dual carriageway. The first 4km out of Durban carries heavy traffic with up to 5 lanes in each direction. The next 40 km, up to Cato Ridge, has 3 lanes in each direction with wide paved shoulders. The section between Cato Ridge and the end of the Pietermaritzburg Bypass (33 km) has a two-lane plus paved shoulder configuration, except on steep gradients to the east of Pietermaritzburg where passing lanes are provided. The final 14 km to Howick incorporates the steeply graded Town Hill, which has 3 lanes with paved shoulders in each direction.
Expected Road Condition	Good. Damaged concrete truck lane at Townhill. Proceed with caution.
Expected Travel Condition	1. A contract for the upgrade of the Hammarsdale Interchange is ongoing. There is minimal disruption to traffic on the N3, however there will be disruption to local traffic. The posted speed limit through the site is 80km/hr. There will be temporary lane closures in the coming months to complete the aspects of the bridge and short term full closures of the N3 can be expected for blasting. There will be a full road closure in August 2019 for demolition of the existing bridge structure, however details will be made available closer to the time. 2. Routine road maintenance teams may be encountered. Expect reduced lanes.
Duration of Work	1. Until December 2019. 2. Ongoing
Contact for Routine Road Maintenance	Emeka Mgbemere 083 641 9056 (Route Manager) Mikhail Ramlukan 074 325 8752 (Assistant Route Manager)

National Route	N3 (The N3 Toll Route operated by N3 Toll Concession (RF) Proprietary Limited)
Section	Cedara to Heidelberg
Distance	415 km
Description	This section of road is a public private partnership between SANRAL and the N3Toll Concession (Pty) Ltd. This toll route is a four-lane dual carriageway road between Cedara and the Tugela Toll Plaza. From the Tugela Toll Plaza to the Wilge Toll Plaza (Villiers) the road is a four-lane single carriageway with shoulders of varying width. The section between the Tugela Toll Plaza and Warden has at-grade intersections and access roads with reduced speed limits signposted. The remainder of the road between Villiers and Heidelberg is a four-lane dual carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Current planned construction works include: 1. Rehabilitation between Cedara and Mooi River. Work commenced in April 2017 and is programmed for completion in June 2020. 2. Rehabilitation of Van Reenens Pass. Work commenced in November 2018 and is programmed for completion in September 2020. 3. Rehabilitation between Warden and Villiers. Work commenced in September 2019 and is programmed for completion in January 2023. 4. Ongoing routine road maintenance and litter collection. Please be aware that veld fires are common at this time of the year. Please do not light fires adjacent to the road and report veld fires to 0800 634 357. Through the construction zones, traffic may be restricted to one lane in each direction under reduced speed. Road users are urged to obey the posted speed limits, maintain safe following distances and refrain from littering.
Duration of Work	Please see above. Maintenance personnel will be on standby to deal with any emergency repairs.
Contact for Routine Road Maintenance	N3TC Customer Care Line 0800 634 357 Twitter @N3Route

National Route	N3
Section	Balfour Interchange to Vosloorus (Barry Marais road)
Distance	38.2km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered 1. Jacobs Street in Heidelberg-, Truck stopping to give hitch hikers rides. This may result in accidents 2. Beware of pedestrians crossing
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Unita Fungile 072 793 2825

National Route	N3
Section	Vosloorus / Barry Marais Road to Buccleuch Interchange
Distance	43.0km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Routine Road Maintenance teams may be encountered
Expected Travel Condition	Good
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marthinus Wilken 082 782 1746

N4

National Route	N4 (Platinum Highway)
Section	Botswana Border to Zeerust
Distance	60 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Zeerust to Rustenburg
Distance	120 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Rehabilitation between Zeerust and Swartuggens Plaza. Expect Stop n Go's Temporary traffic restrictions at the Groot Marico bridge
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Rustenburg to Brits (R512 Interchange)
Distance	70 km
Description	Two-lane single carriageway freeway.
Expected Road Condition	Good.
Expected Travel Condition	Motorists must be aware and be on the lookout for pedestrians and animals in the Bapong area. Adhere to posted speed limits. Expect roadworks with lane reductions
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 – West Magalies
Section	Brits (R512 Interchange) to Hartebeesport
Distance	8.8km
Description	Single Carriageway with gravel shoulders
Expected Road condition Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Major roadworks at Pampoensnek. Fast lane is closed at this stage
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N4 (Platinum Toll Highway)
Section	Brits (R512 Interchange) to Pretoria (N1)
Distance	52 km
Description	Two-lane dual carriageway freeway.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. New constructions: upgrade to a dual carriageway between Brits (R512 Interchange) and Gauteng / North West border

Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pt Ops 012 804 0044
National Route	N4 West Magalies Toll Road
Section	Pretoria (Rebecca Street) to Pelindaba
Distance	21 km
Description	Mixture of two-lane dual carriageway and two-lane single carriageway freeway.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168
National Route	N4
Section	Pretoria (Hatfield) to Hans Strydom Interchange
Distance	13.6 km
Description	A 6-lane dual carriageway road up to Simon Vermoeten Interchange, thereafter a 4-lane dual carriage way.
Expected Road Condition	Good.
Expected Travel Condition	Be alert of hijackers at Townland offramp. Routine Road Maintenance teams may be encountered. Resurfacing contract taking place. Be aware of deviations.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N4
Section	Hans Strydom Interchange to Mozambique
Distance	304 km
Description	Four-lane dual carriageway from Hans Strydom Int. to Van Dyk's Drift. Thereafter, a four-lane undivided road to Wonderfontein, then 2 lanes undivided to the Mozambique border.
Expected Road Condition	Good.
Expected Travel Condition	<ol style="list-style-type: none"> 1. Routine Road Maintenance teams may be encountered 2. <u>Road Rehabilitation between Kromdraai/ Highveld Steel interchange to OR Tambo interchange (N4/13.8 3 km to N4/3 30.2km) in Witbank</u> <ul style="list-style-type: none"> • Pavement rehabilitation – single lane closures will occur as work proceeds • Chicanes are used to divert 2 lanes traffic Adding additional 3rd lane in the road median 3. <u>O R Tambo interchange to Middelburg Plaza (N4/3 30.2 km to N4/4 2.0km)</u> <ul style="list-style-type: none"> • Crack sealing between eMalahleni and Middelburg Toll Plaza • Concrete road and shoulder repairs between eMalahleni and Middelburg Toll Plaza 4. Between Wonderfontein to Machadodorp these activities are taking place; grass cutting 5. Belfast to Machadodorp Rehabilitation and upgrade of existing road has commenced and will continue until April 2021; R541 has been closed for construction and the R36 road can be used for access to and from Machadodorp 6. <u>Crossroads via Elandsvalley to Malaga (N4/6X 2.7 km– N4/6X 20.3km)</u> <ul style="list-style-type: none"> • Burning of fire breaks 7. <u>Elandsvalley -Malaga Hotel to Montrose Falls T-junction</u> <ul style="list-style-type: none"> • Routine maintenance • Construction of additional climbing lanes and rehabilitation of road underway. • 3 Stop/Gos controls – as follows: 1 during day time and 2 permanent.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

	8. <u>Malalane to Komatipoort</u> <ul style="list-style-type: none"> Beware of stray animals. Lane closures may occur in Hectorspruit region
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Trans African Concessionaires (TRAC) 013 755 3316 / 0800 87 22 64 / +27 82 881 4444

National Route	N4
Section	3Y Ellen street to Middelburg
Distance	21.09km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair to satisfactory. Poor road markings. Road go through residential area with entrances both sides of the road. Be alert of coal trucks
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	N4
Section	Nelspruit: Valencia Road to N4
Distance	8.6km
Description	Single carriageway with gravel shoulders.
Expected Road Condition Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

N5

National Route	N5
Section	Harrismith to Bethlehem
Distance	88 km
Description	A two-lane single carriageway with wide paved shoulders. There are overtaking opportunities where severe grades occur.
Expected Road Condition	Good.
Expected Travel Condition	No Construction.
Duration of Work	
Contact for Routine Road Maintenance	Gert de Lange 079 162 2981 (Route Manager) Moeketsi Moeketsi 083 672 0544 (Assistant Route Manager)

National Route	N5
Section	Bethlehem to Winburg
Distance	120 km
Description	A two-lane single carriageway with varying width of either paved or gravel shoulders. There are overtaking opportunities where severe grades occur.
Expected Road Condition	Fair to good
Expected Travel Condition	1. Maintenance crews will be active with occasional localised Stop/Go controls for asphalt patching work, between Bethlehem and Winburg.
Duration of Work	1. Maintenance crews are continuously active.
Contact for Routine Road Maintenance	Marelize van Zyl 082 775 6839 Moeketsi Moeketsi 083 672 0544 (Route Manager)

N6

National Route	N6
Section	East London to Stutterheim
Distance	70 km
Description	A two-lane single carriageway with paved shoulders and passing lanes in places
Expected Travel Condition	Fair to good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Stutterheim to Cathcart
Distance	49 km
Description	Construction completed, road is open.
Expected Travel Condition	Good.
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

National Route	N6
Section	Cathcart to Queenstown
Distance	59 km
Description	A two-lane single carriageway with paved shoulders and passing lanes in places.
Expected Travel Condition	Completed
Expected Travel Condition	Fair to Good
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

National Route	N6
Section	Queenstown to Jamestown
Distance	107km
Description	A two-lane single carriage way with paved shoulders
Expected Travel Condition	Good
Duration of Work	
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

National Route	N6
Section	Jamestown to Aliwal North
Distance	58 km
Description	A two-lane single carriageway with paved shoulders.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

National Route	N6
Section	Aliwal North to Bloemfontein
Distance	200 km
Description	Predominantly, a two-lane single carriageway with only the last 2.36km of National Route 6 having wide paved shoulders. The rest of the route has gravel shoulders of varying widths.
Expected Road Condition	A rehabilitation contract between Rouxville and Smithfield is in progress. There will be three Stop/Go controls in operation, with approximately 20-minute delay at each stop/go. The road between Paryshoogte and Bloemfontein is in a good condition.
Expected Travel Condition	Ongoing
Duration of Work	Until September 2020.
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

N7

National Route	N7
Section	Melkbos Turn-off to Clanwilliam
Distance	198 km
Description	Dual carriageway with paved shoulders
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Jerome Buys 082 328 9422
Construction Works:	<p>Atlantis Turn-off to Abbotsdale A speed limit of 80km/h will be maintained throughout the project with some sections limited to 60km/h due to construction work. No day & night Stop/Go closures are expected at this stage.</p> <p>Voortrekker Road Interchange (Malmesbury) to Hopefield Intersection</p> <p>Road construction is taking place north of Malmesbury's Voortrekker Road Interchange starting approximately at the Voortrekker Road On- ramp (Northbound) past the Hopefield/Vredendal intersection and ending some 800 meters north of the existing commercial quarry.</p> <p>Work is currently proceeding along sections of the new northbound carriageway of the N7, the re-aligned section of the R45 and the new southbound carriageway, as well as certain of the new local access roads. The works are nearing completion on the agricultural underpass and all 3 bridge decks for the new Hopefield Interchange. Some asphalt re-surfacing is also being carried out at the Voortrekker interchange on occasions.</p> <p>2-way traffic is accommodated along the new N7-2 carriageway sections N and S of the bridges and the R45 to Hopefield, with these being linked via the surfaced western side ramps operating as two-way roadways past the R45 intersection. The various routes available are well sign-posted with care and speed control are required when moving through the site</p> <p>No long-term Stop/Go operations are presently in place, but truck crossings are in place. There are heavy movements of haulage vehicles along the length of the project to this and other construction sites along the N7 from the commercial quarry located within the limits of this contract.</p> <p>There are median cross-overs in place just north of the Voortrekker Road Interchange on-ramp towards Moorreesburg and at the northern end of the project. The Voortrekker Road on-ramp towards Moorreesburg is operating with a Stop control onto the N7, and two lane-two-way traffic operates north of this point.</p> <p>Motorists are warned to observe the signage and lane markings, heed the warnings of flag-persons and obey the posted speed restrictions along the route, for both their own safety and that of the workforce. Please proceed with extreme caution, especially during periods of severe dust or heavy mist.</p> <p>Anticipated completion date: October 2019</p>

National Route	N7
Section	Clanwilliam to Western Cape /Northern Cape Border
Distance	139.075 km
Description	Single carriageway with paved and / or gravel shoulders
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Louis Burger 074 193 2978

National Route	N7 Section 8
Section	Northern Cape Border to Violsdrift
Distance	412km
Description	Single carriageway with gravel shoulders and no passing lanes. Rest areas at regular intervals
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Driaan Koegelenberg 071 683 5392

N8

National Route	N8
Section	Groblershoop to Kimberley
Distance	285 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Expected Travel Condition	Fair.
Expected Travel Condition	Motorists should be alert to stray animals. The route is prone to Kudu buck in the roadway between dusk and dawn. Routine Road Maintenance Teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pottie Potgieter 082 566 7301

National Route	N8
Section	Kimberley to Bloemfontein
Distance	150 km
Description	Predominantly, a two-lane single carriageway. The 29-km section between Kimberley and Perdeberg has paved shoulders, while the final eight km immediately adjacent to Bloemfontein is a four – lane dual carriageway with wide paved shoulders. The remainder of the road has gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Good
Duration of Work	Until January 2021
Contact for Routine Road Maintenance	Milton van Heerden 078 460 6552

National Route	N8
Section	Bloemfontein to Maseru
Distance	135 Km
Description	The first five km section from Bloemfontein is a four-lane dual carriageway with wide paved shoulders. Between Bloemfontein and Thaba Nchu there are alternating passing and passing lanes. Between Thaba Nchu and Ladybrand is a two-lane single carriageway road with shoulders of varying widths. Route 26/N8-13 (km 0.0) to Maseru Border (km 11.75) is in good condition.
Expected Road Condition	Good
Expected Travel Condition	
Duration of Work	Until January 2021
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

N9

National Route	N9
Section	Western Cape and Eastern Cape Boundary to Aberdeen (3+4)
Distance	138 km
Description	A two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Danre Gerber 071 679 1349

National Route	N9
Section	Aberdeen to Graaff Reinet (SECTION 5)
Distance	54 km
Description	A two-lane single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	
Duration of Work	
Contact for Routine Road Maintenance	Danre Gerber 071 679 1349

National Route	N9
Section	Graaff-Reinet to Middelburg (SECTION 6)
Distance	105 km
Description	A Two-Lane single carriageway with paved shoulders
Expected Travel Condition	Good.
Expected Travel Condition	
Contact for construction work	Danre Gerber 071 679 1349

National Route	N9
Section	Middelburg to the intersection of the N10 and N9 between Middelburg and Noupoort (Carlton Heights) (SECTION 7)
Distance	24 km
Description	
Expected Travel Condition	Good.
Expected Travel Condition	Routine road maintenance. Travel condition is good.
Duration of work	
Contact for Routine Road Maintenance	Danre Gerber 071 679 1349

National Route	N9
Section	Carlton Heights to Colesburg
Distance	70 km
Description	Single carriageway with paved shoulders and passing lanes. Rest areas at regular intervals.
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Martiens du Plessis 083 655 0644

N10

National Route	N10
Section	Nanaga-Paterson
Distance	24 km
Description	Two lane single carriageway road. Some passing lanes
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Paterson – Olifantskop Pass
Distance	23 km
Description	Two lane single carriageway road. Some passing lanes in pass
Expected Travel Condition	Good
Duration of work	
Expected Travel Condition	
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Jaskraal to Baviaans River
Distance	43 km
Description	Two lane single carriageway road with paved shoulders
Duration of work	Complete
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Olifanskop Pass to Baviaans River north of Cookhouse
Distance	134 km
Description	Two lane single carriageway.
Expected Travel Condition	Good
Contact for routine Road Maintenance	Marco Du Plessis 079 893 6256

National Route	N10
Section	Baviaans River to Riet River
Distance	25 km
Description	Two-lane single carriageway.
Expected Travel Condition	Good
Expected Travel Condition	
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Riet River to Tarka River
Distance	37 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	
Resident Engineer	
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Cradock to Middelburg
Distance	95 km
Description	The first 43 km is a two-lane single carriageway road with wide paved shoulders. The last 30 km is a two-lane single carriageway road with gravel shoulders.
Expected Travel Condition	Fair.
Expected Travel Condition	
Contact for Routine Road Maintenance	Marco du Plessis 079 893 6256

National Route	N10
Section	Ludlow (Intersection of the N10 and N9 between Middelburg and Noupoort) to Prieska
Distance	300 km
Description	Single carriageway with paved and/ or gravel shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Yusuf James 083 362 9707

National Route	N10
Section	Prieska to Nakop (at Namibian Border)
Distance	379 km
Description	Single carriageway with paved and / or gravel shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Mzo Ntebe 079 017 9353

N11

National Route	N11
Section	N3 Bergville Interchange to Newcastle
Distance	115 km
Description	A two-lane single carriageway with narrow shoulders, except for the 16-km portion before Newcastle and for short sections through the Biggarsberg Mountain range, where there are passing lanes.
Expected Road Condition	Variable, generally good.
Expected Travel Condition	No construction works. There will be general maintenance works with minor traffic disruptions encountered.
Duration of Work	Ongoing (RRM Project)
Contact for Routine Road Maintenance	Ms Asanda Koti 079 151 2451

National Route	N11
Section	Newcastle to Volksrust
Distance	54 km
Description	Apart from the 9 km that constitute the Newcastle Bypass and the 17 km that make up the Laingsnek (Majuba) Mountain Pass, the road is a single carriageway, with narrow paved shoulders.
Expected Road Condition	Fair to good
Expected Travel Condition	Normal patch works. Minor disruption to traffic.
Duration of Work	Ongoing (RRM Project)
Contact for Routine Road Maintenance	Ms Asanda Koti 079 151 2451

National Route	N11
Section	Volksrust to Amersfoort
Distance	42.58 km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Good but some areas still need road markings especially coming from Amersfoort towards Volksrust. From 4.0 KM to 3.5 KM pavement and road marking is new.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Motorist should look out for stray animals from Vaal River to Amersfoort
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N11
Section	Amersfoort to Msukaligwa Municipal Border / Vaal River
Distance	27.88km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Good, but needs road marking near Amersfoort town it is not visible at all.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should also be alert of stray animals North of Amersfoort km 0.8-3.0 Motorist should be alert of the vast quantity of coal trucks from Vaal River to Amersfoort
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N11
Section	Msukaligwa Municipal border / Vaal River to Ermelo
Distance	29.85km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Fair but needs road marking in some areas especially from Ermelo town to 24.0 KM.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Vaal River to Ermelo
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N11
Section	Ermelo to Hendrina
Distance	51.10km
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Hendrina to Ermelo
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N11
Section	Hendrina to Middelburg –N4 Interchange
Distance	41.97km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	From Hendrina town to KM 18.6 pavement and road making are good because it was done recently and from to the end pavement is very poor needs serious attention together with road markings.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Hendrina to Middelburg
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N11
Section	Middelburg to Loskop
Distance	29.24 km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair Good High accident zone (Kranspoort mountain pass) km 36
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane 076 886 9997

National Route	N11
Section	Loskop to Mookgopong Municipal Border
Distance	44.3km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane 076 886 9997

National Route	N11
Section	Mookgopong Municipal Border to Mokopane Weigh Bridge / N1/25X Intersection
Distance	89.04km
Description	Single carriageway
Expected Road Condition	Good to excellent
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane 076 886 9997

National Route	N11
Section	Mokopane to Martin's Drift border post (Botswana)
Distance	188km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing until March 2020
Contact for Routine Road Maintenance	Hannelie Swanepoel 082 380 5264

N12

National Route	N12
Section	Three Sisters to Hopetown
Distance	299 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Routine road maintenance teams may also be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Charl Muishond 072 746 9827

National Route	N12
Section	Hopetown to Northern Cape Border at Warrenton
Distance	203 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may also be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Zandile Gaba 082 550 9083

National Route	N12
Section	North West / Northern Cape Border at Warrenton to Christiana
Distance	28.8 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12
Section	Christiana to Bloemhof
Distance	57.9 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12
Section	Bloemhof to Wolmaranstad
Distance	62.2 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	N12
Section	Wolmaransstad to Klerksdorp
Distance	75 km
Description	Two-lane single carriageway with wide paved shoulders on most of the section, except closer to Klerksdorp.
Expected Road Condition	Good to very good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12
Section	Klerksdorp to Potchefstroom
Distance	38.8km
Description	Two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Road partially closed between Klerksdorp and Stilfontein due to a sink hole within the road reserve. Expect lane reductions.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12
Section	Potchefstroom to Westonia Municipal Border
Distance	57.4 km
Description	Two-lane narrow single carriageway with passing lanes.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12
Section	Diepkloof Interchange to Elands Interchange
Distance	17.2km
Description	Four-lane dual carriageway freeway.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marthinus Wilken 082 782 1746

National Route	N12
Section	Gilloolly's Interchange to Mpumalanga / Gauteng Border
Distance	41km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Routine Road Maintenance teams may be encountered
Expected Travel Condition	Good.
Duration of Work	Ongoing

Contact for Routine Road Maintenance	Marthinus Wilken 082 782 1746
--------------------------------------	----------------------------------

N14

National Route	N14
Section	Springbok to Keimoes
Distance	335 km
Description	Single carriageway with paved / gravel shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Claudia Jannetjies 078 675 8971

National Route	N14
Section	Keimoes to Western Cape / Northern Cape Border
Distance	303 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	<p>Kathu North and Kathu South Intersections: Construction work is in progress. Be mindful of the deviations at the circles. No STOP/GO's or road closures are anticipated. A speed limit of 60km/h to be maintained at the intersections.</p> <p>Olifantshoek T-Junction to Kathu: Construction work is in progress. Be mindful of the deviations at the circle. No STOP/GO's or road closures are anticipated. A speed limit of 60km/h to be maintained at the intersection. Routine road maintenance teams may be encountered.</p>
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Peet van Wyk 082 406 6371

National Route	N14
Section	Northern Cape / North West Border to Vryburg
Distance	86 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition:	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Divhani Netshishivhe 076 331 8812

National Route	N14
Section	From Junction at R34 & N14 Section 9 to Junction at N18 in Vryburg
Distance	6 km
Description	A two-lane carriageway with concrete kerbing through town up to N18 crossing.
Expected Road Condition	Poor to Fair.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Divhani Netshishivhe 076 331 8812

National Route	N14
Section	Vryburg to Delareyville
Distance	76 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Vryburg to Northern Cape Border East of Kuruman
Distance	84.8km
Description	Around Vryburg and extending Westwards towards the Northern Cape Border for some 84.80km, the road is two-lane single carriageway with wide gravel shoulders.
Expected Road Condition	Generally good condition.
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs. 2. Minor maintenance work on this section
Duration of Work	Until August 2019
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 7452

National Route	N14
Section	Delareyville to Sannieshof
Distance	37.6 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Sannieshof to Coligny
Distance	61.9 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Coligny to Ventersdorp
Distance	68.8 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Ventersdorp to North West / Gauteng Border
Distance	49.7km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair. Isolated potholes
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

N17

National Route	N17
Section	Soweto to Nasrec
Distance	6 km
Description	Double carriageway road with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Pierre Coetzer 066 248 0005

National Route	N17
Section	Wemmerpan to Geldenhuys Interchange
Distance	7.8 km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Unita Fugile 072 793 2825

National Route	N17
Section	Geldenhuys Interchange to Springs
Distance	38.8Km
Description	Multi lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Unita Fugile 072 793 2825

National Route	N17
Section	Springs to Leandra Toll
Distance	40.2 km
Description	Single carriageway with passing lanes and gravel shoulders.
Expected Road Condition	Good although some places need the pavement repairs but it not that bad and on KM 60.6 there is burnt surface because of the accident.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Motorists should be alert of stray animals north of Leandra Toll Plaza
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N17
Section	Leandra Toll to Bethal
Distance	72.2 km
Description	Single carriageway with passing lanes and paved shoulders.
Expected Road Condition	Good and in some areas our team did surface repairs, but we still need to do more pavement repairs as the road is damaged because of the car crashes.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Motorists should be alert to stray animals north of Leandra Toll Plaza.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	N17
Section	Bethal to Ermelo
Distance	55.72 km
Description	Single carriageway with passing lanes and paved shoulders.
Expected Road Condition	Good, but in some areas, but there are some surface failure and the road markings are still in a good condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Motorist should be alert to stray animals just after leaving Bethal to Ermelo
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N17
Section	Ermelo to Oshoek Border Post (Swaziland)
Distance	122.64km
Description	Carolina Warburton Intersection to Lochiel- Pavement complications in certain sections, pavement deformation between km 60 – 85.
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

N18

National Route	N18 (R49)
Section	Warrenton to Hartswater North / North West Border
Distance	52 km
Description	Single carriageway with paved shoulders
Expected Travel Condition	Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Zandile Gaba 082 550 9083
National Route	N18
Section	Northern Cape / North West Border South of Taung to Pudimoe
Distance	27.54km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Beware of stray animals
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Divhani Netshishivhe 076 331 8812

National Route	N18
Section	Vryburg to Pudimoe
Distance	49.10km
Description	Around Vryburg and extending Southwards for some 49.10km to Pudimoe, the road is two-lane single carriageway with wide gravel shoulders
Expected Road Condition	Generally good condition
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Minor maintenance work from time to time on this section
Duration of Work	1.Until August 2019
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 7452

National Route	N18
Section	Pudimoe to Northern Cape Border South of Taung
Distance	27.8 km
Description	From Pudimoe Southwards for 19.6km to Taung where a traffic circle is encountered. The road continues Southwards towards the Northern Cape border for 8.2km as two-lane single carriageway with gravel shoulders.
Expected Road Condition	Generally good condition
Expected Travel Condition	1. A contract to upgrade the Taung circle is in progress, traffic is free flowing. Motorists are advised to obey the posted traffic sign. 2. Minor maintenance work from time to time on this section
Duration of Work	1. Until June 2019 2. Until August 2019
Contact for Routine Road Maintenance	Matlou Tumelo 076 659 7452

National Route	N18
Section	Vryburg to Stella
Distance	47km
Description	Extending northwards for some 47km, the road is a two-lane single carriageway with gravel shoulders.
Expected Road Condition	Generally good
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Minor maintenance work from time to time on this section
Duration of Work	1. Until August 2019
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

National Route	N18
Section	Vryburg to Northern Cape Border South of Taung
Distance	76.9km
Description	Around Vryburg and extending Southwards for some 49.10km to Pudimoe (Section 3), the road is two-lane single carriageway with wide gravel shoulders. Thereafter it continues Southwards for 19.6km to Taung where a traffic circle is encountered. The road continues Southwards towards the Northern Cape border for 8.2km as two-lane single carriageway with gravel shoulders.
Expected Road Condition	Generally good.
Expected Travel Condition	1. A contract to upgrade the Taung circle is in progress, traffic is free flowing. Motorists are advised to obey the posted traffic sign.
Duration of Work	1. Until April 2019
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 7452

National Route	N18
Section	Stella to R375 Intersection
Distance	65.70 km
Description	Extending northwards for some 65.7km, the road is a two-lane single carriageway with gravel shoulders.
Expected Road Condition	Generally good condition
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Construction of edge breaks and beams in process at Setlagole between km 39.0 to km 42 until July 2019 2. Minor maintenance work from time to time on this section Shoulder reconstruction at Setlagole
Duration of Work	1. Until end of July 2019 2. Until August 2019
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	N18
Section	R375 Intersection to Mahikeng
Distance	65 km
Description	Single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Construction of edge breaks and beams in process at Setlagole between km 39.0 to 42 3. Minor maintenance work from time to time on this section
Duration of Work	2. Until end of March 2019 3. Until August 2019
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

National Route	N18
Section	Km 65.70 to Mahikeng
Distance	37.50 km
Description	Extending northwards for some 37.50km, the road is a two-lane single carriageway with gravel shoulders. From Km 31.00 fencing is a problem due to theft. Stray animals will be encountered.
Expected Road Condition	Generally good condition
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Construction of edge breaks and beams in process at Setlagole between km 39.0 to 42 Until July 2019 3. Minor maintenance work from time to time on this section Shoulder reconstruction at Setlagole
Duration of Work	2. Until end of July 2019 4. Until August 2019
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

National Route	N18
Section	Mahikeng to Ramatlabama Border Post
Distance	17.019km
Description	Extending northwards for some 37.50km, the road is a two-lane single carriageway with gravel shoulders. From Km 31.00 fencing is a problem due to theft. Stray animals will be encountered.
Expected Road Condition	Good
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Minor maintenance work from time to time on this section
Duration of Work	Until August 2019
Contact for Routine Road Maintenance	Manie Du Preez 083 262 0242

National Route	N18
Section	Mafikeng Km 9.70 to 25.00
Distance	15.30 km
Description	Extending westwards for some 15.30km, the road is a two-lane single carriageway with paved shoulders.
Expected Road Condition	Generally good condition
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Minor maintenance work from time to time on this section
Duration of Work	Until August 2019
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

OTHER NATIONAL ROUTES

National Route	D157
Section	Groblersdal to Hlogotlou
Distance	38.882 km
Description	Two lane single carriageway with no paved shoulders
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Maxwell Baloyi 078 972 4445

National Route	D797
Section	One Tree Hill to Tonga
Distance	27.508 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair with uneven riding surface.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	D1120
Section	Komatipoort to Crocodile Bridge Gate
Distance	8.942 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	D2948
Section	D797 Tonga to Emangweni
Distance	10.196 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	P154
Section	7
Distance	3.84km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Koos Beukes 072 444 5742

National Route	P720
Section	N2 to Golela Border Post with Swaziland
Distance	10 km
Description	A Single carriageway road between National Route 2 and Golela Border Post. Two lanes and a narrow-paved shoulder and wide gravel shoulder in each direction.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	R21
Section	Northrand Rand to Olifantsfontein Interchange
Distance	26km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746

National Route	R21
Section	Olifants Interchange to Hans Strydom Intersection
Distance	18km
Description	Multi-lane dual carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553 Marthinus Wilken 082 782 1746

National Route	R22
Section	Hluhluwe to Farazela (RSA/Mozambique border)
Distance	175 km
Description	A 2-lane single carriageway road with narrow paved shoulders throughout.
Expected Road Condition	Good. Traffic congestion through the Town of Manguzi (ongoing issue) due to traders and high volume of pedestrian activity.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	No Construction
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	R23
Section	Volksrust to Standerton
Distance	78.44km
Description	Two lanes single carriageway with paved shoulders and climbing lanes at some areas from km 78.27 up to km 52, two lane single carriageway with gravel shoulders from km 52 to km 30 and single carriageway with paved shoulders from km 30 to km 2.
Expected Road Condition	Fairly Good
Expected Travel Condition	Motorist may encounter stray animals on the road reserve from Perdekop from km 37, km 21 to km 24 and from km 15 to km 17 towards Volksrust
Duration of Work	Ongoing (contract ends Feb 2020)
Contact for Routine Road Maintenance	Solomon Mathabe 071 159 6123

National Route	R23
Section	Standerton to Gauteng / Mpumalanga Border
Distance	86.4km
Description	Single carriageway with climbing lanes at some areas with paved shoulders from km 4 to km 56 and single carriageway with gravel shoulders from km 56 to km 86.4
Expected Road Condition	Fair to good.
Expected Travel Condition	Motorists are advised to reduce speed at the following locations along the road: 1) The first 4 km stretch of the road from Standerton for pedestrians and stray animals. 2) Along deviations (km 6.6, km 17 to km 19, km 21 and km 53 3) There is a stop/go at km 17 to km 19 whereby the contractor is working on the deviation.
Duration of Work	Ongoing (End Feb 2020)
Contact for Routine Road Maintenance	Solomon Mathabe 071 159 6123

National Route	R24
Section	Rustenburg to Northwest/Gauteng Border
Distance	45km
Description	Two lane double carriageway with paved shoulders between Buiten Street and Oorsak Road. The remaining section is a two-lane carriageway with passing lanes through Olifantsnek Pass with gravel shoulders to the NW/Gauteng border to Magaliesburg and Krugersdorp.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R27
Section	Van Rhynsdorp to Brandvlei
Distance	236 km
Description	Single carriageway road with 1 metre surfaced shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Jacques Wentzel 079 514 3496

National Route	R27
Section	Brandvlei to Keimoes
Distance	221 km
Description	Single carriageway road with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6553

National Route	R30/R730/R34 Toll Road
Section	Bloemfontein to Kroonstad via Brandfort/Welkom
Distance	210 km
Description	A single carriageway between National Route N1 and Virginia. It accommodates two lanes and has wide paved shoulders and ad hoc passing lanes in each direction. The section between Virginia and Welkom is a double carriageway and the section between Welkom and Kroonstad is a four-lane undivided carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	No construction. Possible repairs at Brandfort Toll Plaza on the R30.
Duration of work	Scheduled to be completed in March 2019
Contact for Routine Road Maintenance	Abel Majorobela 079 896 3377 Kgomotso Kalela (Brandfort Toll Plaza Manager) 082 901 4027

National Route	R30
Section	Free State / North West Border to Klerksdorp
Distance	14.5 km
Description	Two-lane narrow single carriageway with gravel-shoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R30
Section	Klerksdorp to Ventersdorp
Distance	68.8 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R30
Section	Ventersdorp to Olifants Nek
Distance	76.6 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair with uneven riding surface.
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop/go's may occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R33
Section	Kwazulu Natal / Mpumalanga Border to Piet Retief
Distance	48.3 km
Description	A Two-lane Single Carriageway narrow gravel shoulder.
Expected Road Condition	Good
Expected Travel Condition	Patches are being repaired on this section.
Duration of Work	Ongoing

Contact for Routine Maintenance	Faith Mogano 076 7790 346
---------------------------------	------------------------------

National Route	R33
Section	Piet Retief to Amsterdam
Distance	35.9 km
Description	A Two-lane Single Carriageway narrow gravel shoulder.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Road markings are on-going.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 076 7790 346

National Route	R33
Section	Amsterdam to Warburton
Distance	88.54 km
Description	A Two-lane single carriageway with narrow gravel shoulders.
Expected Road Condition	Fair.
Expected Travel Condition	Gabions are not in good condition and an -inspection is done. Patches are done on this section. Road markings are on-going.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 076 7790 346

National Route	R33
Section	Warburton (from N17/5) to Carolina
Distance	38km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R33
Section	Carolina to Belfast (N4)
Distance	49.2km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered, construction of Access at km 40.173 Northern Coal Weltevreden Mine
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R33
Section	N11 – Marble Hall to Modimolle R101
Distance	88.3 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	From Km 0.0 to 78.0 Good –and from Km 78.0 –to 86.0 Poor
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane 076 886 9997

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

--	--

National Route	R33
Section	Vaalwater to Lephalale – R510
Distance	85.3 km
Description	Single carriageway with limited paved shoulders otherwise gravel shoulders.
Expected Road Condition	Fair to Good Km 0.0 – 85.3 poor road markings
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	R34
Section	Vryburg to Schweizer Reneke
Distance	64.86 km
Description	First 30km a two-lane carriageway with paved shoulders 2nd 30 km a two-lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles
Expected Road Condition	Fair to poor.
Expected Travel Condition	Roadworks: Rehabilitation contract between Vryburg and Schweizer Reneke. Expect Stop \Go controls.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R34
Section	Schweizer Reneke to Bloemhof
Distance	60 km
Description	First 34km a two-lane carriageway with paved shoulders 2nd 31 km a two-lane carriageway with narrow earth shoulders, widened on both sides to accommodate heavy vehicles
Expected Road Condition	Good
Expected Travel Condition	Roadworks: Rehabilitation contract between Schweizer Reneke and Bloemhof. Expect Stop/ Go controls. Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Andre van der Merwe 071 643 1004

National Route	R34
Section	Bloemhof to North West / Free State Border
Distance	6.7 km
Description	Two lane carriageways with narrow earth shoulders, widened on both sides to accommodate heavy vehicles
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Andre van der Merwe 071 643 1004

National Route	R35
Section	Amersfoort to Bethal
Distance	77.97km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair, our road making needs some attention and there is a surface failure with cracks on KM 45.2-45.4 on the opposite side.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	R35
Section	Bethal to Middelburg
Distance	71.03km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair, but still needs road marking as some are not visible and the surface is destroyed due to heavy vehicles. This is so especially on KM 71.03 to 66 negative side.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	R36
Section	Mpumalanga Border to Dublin
Distance	102.2km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing: Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R36
Section	Dublin to Ofcolaco
Distance	53.7km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing: Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R36
Section	Ofolaco to Tzaneen
Distance	33.5km
Description	Single carriageway y with gravel shoulders.
Expected Road Condition	Surfacing: Fair. Isolated potholes. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R36
Section	Tzaneen to Modjadjiskloof (Section 7)
Distance	17.8km
Description	Km 2.3 to km 7.0 double carriageway. Km7 – 19.5 Single carriageway. Mostly paved shoulders.
Expected Road Condition	Surfacing Good. Line markings fair.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tony Mathebula 083 437 8856

National Route	R36
Section	Modjadjiskloof – Soekmekaar (Section 8)
Distance	44.43km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Good. Line Marking fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tony Mathebula 083 437 8856

National Route	R36
Section	Soekmekaar - Bandelierkop
Distance	17.8km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tony Mathebula 083 437 8856

National Route	R37
Section	Polokwane Burgersfort
Distance	40.80km
Description	Four lane dual carriageway from km 0 to km 12 & thereafter two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good Beware of stray animals
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R37
Section	Burgersfort to Lydenburg
Distance	64 km
Description	Single carriageway road with paved shoulders.
Expected Road Condition	First 5-48 km fair condition. Rest fair to good
Expected Travel Condition	Routine Road Maintenance teams may be encountered as well as STOP/GO controls on some sections Beware of stray animals Rehabilitation (Construction) with control STOP/GO 10 km before Lydenburg
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R37
Section	Lydenburg to Sabie
Distance	43.94Km
Description	Single carriageway road with mostly paved shoulders.
Expected Road Condition	Fair to good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R37
Section	Sabie to Nelspruit
Distance	49.20km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Construction with control STOP/GO, 8km before Nelspruit
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R38
Section	Bethal to Hendrina
Distance	47.04km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair, some areas need pavement repairs and we busy with pothole repair at the moment and from Km 0.0 to 5 there is are number of cracks. There is uneven surface on KM 6.6-6.8 on the positive side
Expected Travel Condition	Routine Road Maintenance teams may be encountered and stray animals Good
Duration of work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	R38
Section	Hendrina to Carolina
Distance	42.9km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R38
Section	Carolina to Badplaas
Distance	52.8km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R38
Section	Badplaas to Barberton R40)
Distance	59km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good, recently resealed
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R40
Section	Barberton to Nelspruit
Distance	32.77km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R40
Section	White River to Hazyview
Distance	48.7
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Shoulder closure 25 km before Hazyview at Swartfontein Beware of the stray animals
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R40
Section	Hazyview to Klaserie
Distance	67
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Beware of stray animals and pedestrians
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R40
Section	Klaserie to Hoedspruit
Distance	26.79km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Wild animals may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R40
Section	Hoedspruit to Mica
Distance	32.20km
Description	Single carriageway with limited paved shoulders, otherwise gravel shoulders.
Expected Road Condition	Surfacing Fair to Good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Wild animals may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R40
Section	Mica to Junction with R71 west of Phalaborwa
Distance	36.8km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Poor. Line markings in poor condition. Roadworks will be encountered with Stop n Go controls
Expected Travel Condition	Routine Road Maintenance teams may be encountered Wild animals may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R49
Section	Mafikeng to Zeerust
Distance	61 km
Description	A two-lane single carriageway with paved shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R49
Section	Zeerust to Kopfontein Border Botswana (P87/1)
Distance	98.8km
Description	A two-lane single carriageway with gravel shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Routine Maintenance Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R52
Section	Biesiesvlei to Lichtenburg
Distance	36.6km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair with uneven riding surfaces
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R52
Section	Koster to Rustenburg
Distance	38.7 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Kobus Vermeulen 082 850 7361

National Route	R53
Section	Parys to Potchefstroom
Distance	44.7 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R53
Section	Potchefstroom to Ventersdorp
Distance	58.5km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Very Poor to extremely Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R54
Section	Potchefstroom to Emfuleni Local Municipality Border
Distance	42.60 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair to Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R56
Section	Middleburg and Elliot
Distance	310km
Description	Two lane single carriage way with gravel shoulders.
Expected Road Condition	Middelburg to Steynsburg is in fair condition. Steynsburg to Molteno is poor. Molteno to N6 is fair. N6 to Dordrecht is very poor. Dordrecht to Indwe is poor. Indwe to Elliot is in a bad state. Routine road maintenance busy installing road signs.
Expected Travel Condition	Routine road-maintenance teams may be encountered. Construction teams and stop-go controls will be encountered from Indwe to Elliot.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R56
Section	1, N9 Middleburg to Steynsburg
Distance	85km
Description	One lane single carriage way
Expected Road Condition	First 16km is in fair condition. Further, the condition is newly surfaced and good.
Expected Travel Condition	
Duration of work	
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

National Route	R56
Section	2, Steynsburg to Molteno
Distance	57km
Description	One lane single carriage way
Expected Road Condition	Fair to good with pavement repairs recently completed.
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

National Route	R56
Section	3, Molteno to N6
Distance	35km
Description	One lane carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	4, N6 to Dordrecht
Distance	35km
Description	One lane single carriage way
Expected Road Condition	Poor.
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	5, Dordrecht to Indwe
Distance	38km
Description	One lane single carriage way
Expected Road Condition	Poor.
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	6, Indwe to Elliot
Distance	56km
Description	Two lane single carriage way
Expected Road Condition	Special maintenance project between Indwe via Elliot to Maclear for a period of 30 months as from February 2016 to October 2018.
Expected Travel Condition	Expect Stop/Go conditions with 20-minute delays.
Duration of work	32 months, from Feb 2016 to October 2018. Not complete.
Resident Engineer	Ian Posset 084 585 5895
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56 Section 7
Section	Eliot to Maclear
Distance	68km
Description	Two lane single carriage way with alternate passing and gravel shoulders
Expected Road Condition	Under construction and up to RRM standards.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A contract for the refurbishment of the road to Maclear has stopped, Routine road maintenance in progress 2. Traffic is being accommodated on the newly-constructed road sections but with speed restrictions in place. 3. Special maintenance project between Indwe via Elliot to Maclear for a period of 32 months as from February 2016 to October 2018. Contract stopped. Routine road maintenance busy with emergency pavement repairs and road signs. 4. Stop/go controls are in place.
Duration of work	32 months, from Feb 2016 to October 2018.
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R56 Section 8
Section	Maclear to KZN Border
Distance	168km
Description	Two lane single carriage way with gravel shoulders
Expected Road Condition	Good and up to RRM standards.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A contract for the reseal of the R56 section 8, from Maclear to Mount Fletcher (km 0.0 – km 64.4) was completed in November 2016. 2. A contract for the refurbishment of the road from Matatiele to KZN border is being planned for 2019. 3. Routine road-maintenance teams may be encountered.
Duration of work	Completed. No road works. In a good condition.
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R56
Section	8, Matatiele to Eastern Cape Border
Distance	37km
Description	Two lane single carriage way
Expected Road Condition	Fair to poor. All potholes fixed on this route.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R58
Section	Section 12 from Km 33 – 58 Venterstad to Burgersdorp
Distance	22km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	Good.
Duration of work	
Contact for Routine Road Maintenance	Happy Maduna 083 282 5256

National Route	R58
Section	3, Burgersdorp to Aliwal North N6
Distance	55km
Description	Two lane single carriage way
Expected Road Condition	Good
Expected Travel Condition	
Duration of work	
Contact for Routine road maintenance	Happy Maduna 083 282 5256

National Route	R58
Section	4, Aliwal North N6 to Lady Grey
Distance	49km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Duration of work	
Contact for construction	Happy Maduna 083 282 5256

National Route	R58
Section	5, Lady Grey to Barkley East
Distance	66km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	Motorists to drive with care due to potential rock falls.
Duration of work	
Contact for construction	Happy Maduna 083 282 5256

National Route	R58
Section	6, Barkly East to Elliot
Distance	62km
Description	Two lane single carriage way
Expected Road Condition	Fair
Duration of work	
Contact for construction	Happy Maduna 083 282 5256

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R58
Section	7, R56 to R410
Distance	4,55km
Description	Two lane single carriage way
Expected Road Condition	Fair
Duration of work	
Contact for construction	Happy Maduna 083 282 5256

National Route	R61
Section	1 (East Cape/West Cape Border to Aberdeen)
Distance	74.5 km
Description	Narrow, single carriageway road with 2 lanes
Expected Travel Condition	Fair
Expected Travel Condition	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Danie Gerber 071 679 1349

National Route	R61
Section	Bethesda (N9 Intersection) to Cradock (N10 Intersection) (section 2)
Distance	85.8 km
Description	A narrow 2-lane single carriageway with gravel shoulders over most of the length.
Expected Travel Condition	Fair but Good where repair work is complete.
Duration of work	Phase 2: Completed
Expected Travel Condition	A reseal project from the N9 to the Wapadsberg Pass (Km 0.0 to Km 14.0) will commence in the latter half of 2019.
Contact for Routine Road Maintenance	Charmaine Diedericks 079 893 7777

National Route	R61
Section	Cradock (N10 Intersection) to Tarkastad (section 3)
Distance	74.5 km
Description	A narrow 2-lane single carriageway with gravel shoulders
Expected Travel Condition	0-24km Fair.
Expected Travel Condition	Construction- over 27km, in the middle of this section, km 24 to 51, is now complete. Km 24-51 in good condition. Km 51-75 in a fair to poor condition. Motorists to be aware of wild animals in rural areas and pedestrians in urban areas at Cradock and Tarkastad.
Duration of work	Construction period for phase 2 is 18 months. Commencement anticipated in March 2019.
Contact for Routine Road Maintenance	Charmaine Diedericks 079 893 7777

National Route	R61
Section	Section 3. Cradock to Tarkastad
Distance	
Description	
Expected Travel Condition	
Expected Travel Condition	Special maintenance project underway from May 2019 for an 18-month period.
Duration of work	
Contact for Resident Engineer	Christo Miller 083 556 5535

National Route	R61
Section	Tarkastad to Queenstown (section 4)
Distance	63.1km
Description	A 2-lane single carriageway with surfaced shoulders.
Expected Travel Condition	Road in good condition. Beware of livestock in places.
Contact for Routine Road Maintenance	Charmaine Diedericks 079 893 7777
Contact for Construction Work	

National Route	R61
Section	Queenstown (N6) to Cofimvaba (Section 5)
Distance	60km
Description	A 2 Lane single carriageway with paved shoulders.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Motorists may encounter occasional short-terms closures on sections in this area due to maintenance repairs.
Expected Travel Condition	Route back to RRM for maintenance.
Contact for Construction works	No construction.
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Cofimvaba to Engcobo (Section 6)
Distance	92 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Expected Travel Condition	Fair to good.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Motorists may encounter occasional short-term closures on short section in this area.
Duration of Work	No construction.
Contact for Routine Road Maintenance	Riaan Graaf (RRM) 082 821 0175

National Route	R61
Section	Engcobo to Mthatha (Section 7)
Distance	49 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Expected Travel Condition	Fair to good
Expected Travel Condition	Motorists to be aware of pedestrian and stray animals. Construction works are in progress from the Baziya km12 to Mthatha Airport km39. Reduced speed as gravel detours can be expected. Motorists may encounter occasional short-term closures on short section in this area. Road may also be closed for short durations.
Contact for Construction works	Jannie Theron 083 456 0661
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	R61 Mthatha to Ngqeleni (Section 8)
Distance	5.7km
Description	A two (2) lane single carriageway with paved shoulders.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Travel condition is good.
-	-
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Mthatha to Port St Johns (Section 8)
Distance	74 km
Description	A 2-lane single carriageway, with surfaced shoulders.
Expected Travel Condition	Fair.
Expected Travel Condition	Libode to Mngazi Upgrading of nine intersections. Reduced speed and localised bypasses/detours.
Duration of work	Libode to Mngazi – completion date July 2019.
Contact for Routine Road Maintenance	Riaan Graaf (Routine road maintenance) 082 821 0175
Contact for Construction works	Nick North-Coombs 082 411 2890 (Libode to Mngazi)

National Route	R61 (Wild Coast)
Section	Ntafufu River to Lusikisiki (Section 9)
Distance	18 Km
Description	Two-lane Single carriageway with Passing lanes
Expected Travel Condition	Good
Expected Travel Condition	Motorist to be aware of pedestrians and animals. The road is winding and motorists may encounter occasional short-term closures on a short section for routine maintenance.
Duration	
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175
Contact for Construction	

National Route	R62
Section	East Cape borders to N2

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Distance	117km
Description	Single carriage road
Expected Travel Condition	Fair but narrow width
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	R63
Section	East Cape border to Graaff Reinet
Distance	50km
Description	Single carriageway with gravel shoulders
Expected Travel Condition	Good but narrow over most of the section. In wet weather, occasionally dislodged rocks can be found in the Oudeberg pass. Please drive with caution.
Expected Travel Condition	A section of this route runs through a National Park so watch out for game. .
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R63
Section	Graaff Reinet to R75 junction (to Pearston)
Distance	23km
Description	Single carriageway with paved shoulders
Expected Travel Condition	Good
Expected Travel Condition	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R63
Section	R75 to Pearston , Somerset East to N10
Distance	123km
Description	Two-way single carriage way with gravel shoulders
Expected Travel Condition	Good but narrow.
Contact for Routine Road Maintenance	Johannes Nel 083 295 0606

National Route	R63
Section	Pearston to Bruintjes Hoogte (Section 9 km 43 to Section 10 km 24.7)
Distance	
Description	Two-way single carriage way with gravel shoulders
Expected Travel Condition	Good, but narrow road.
Contact for Routine Road Maintenance	Conrad Bezuidehout – 081 264 8063 Johannes Nel – 083 295 0606

National Route	R63
Section	N10 to Bedford
Distance	78km
Description	Two-way single carriage way with gravel shoulders. 4km section before Bedford in poor condition, reduce speed at km 16.9 – km 20.9
Expected Travel Condition	Fair Good, except the 4km section before Bedford which is poor.

Expected Travel Condition	Fair
Contact for Routine Road Maintenance	Conrad Bezuidenhout – 081 264 8063 Johannes Nel – 083 295 0606

National Route	R63
Section	Adelaide to Komga
Distance	189km
Expected Travel Condition	Poor condition between Fort Beaufort and Alice and between Bhisho and Komga.
Expected Travel Condition	Two-way single carriage way. Motorists may encounter occasional short closures by maintenance team, between Fort Beaufort and Alice, and between Bhisho and Komga.
Contact for Routine Road Maintenance	Odwa Ndlwana – 071 045 8203

National Route	R67
Section	Grahamstown to Fort Beaufort
Distance	70.65km
Description	Two lane single carriageway with gravel shoulders (Narrow) 6.4m wide, currently being widened in sections.
Expected Travel Condition	Fair. Construction started on 11 January 2017 and will be in progress until May 2019. The contract has been extended by a further 6 months, so it is now a 28-month contract. 3 Stop/go controls can be encountered. Expect delays.
Expected Travel Condition	The road is winding, observe speed limit through ECCA Pass & beware of wild animals after dusk.
Contact for Routine Road Maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849 Contact: Sarel / Neil Mcillroy 071 382 8127

National Route	R67
Section	Fort Beaufort to Seymour
Distance	42km
Description	Two lane carriageway
Expected Travel Condition	Project complete. Road now open.
Contact for routine road maintenance	Gerhard Bester 083 679 1849

National Route	R67
Section	Seymour to Whittlesea
Distance	54,45km
Description	Two-lane single carriage with passing lane
Expected Travel Condition	Fair
Expected Travel Condition	Beware of pedestrian and animals - observe speed limit through to Nico Malan Pass. Stop/go controls in operation on this section. Currently doing line markings. Project should be completed by July 2017.
Contact for Routine road maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849

National Route	R67/5
Section	Whittlesea to Swart Kei
Distance	15,4km
Description	
Expected Travel Condition	Project is in completion stage. Road opened.
Expected Travel Condition	Beware of pedestrians and animals crossing.
Contact for Routine Road Maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849

National Route	R67/5
Section	Swart Kei to Queenstown
Distance	18,3km
Description	Two way lane single carriageway with gravel shoulders
Expected Travel Condition	Fair to poor. Narrow road.
Expected Travel Condition	Fair to poor. Narrow roads.
Contact for Routine Road Maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849

National Route	R71
Section	Polokwane to Tzaneen (Section 1)
Distance	86.04km
Description	Km 7.3 – 39.0, 88 – 92.14 Double carriageway. Km 39.0 – 88- 92.14 Single carriageway Mostly paved shoulders.
Expected Road Condition	Surfacing is Good. Mountain pass high accident zone (km 69 – 75) Dense Fog Area
Expected Travel Condition	Routine Road Maintenance teams may be encountered Beware of pedestrians at Mankweng and Moria from km 21.0 to 40.0
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tony Mathebula 083 437 8856

National Route	R71
Section	Tzaneen to Letsitele
Distance	30.18km
Description	Single carriageway with paved shoulders until Letsitele (km 30)
Expected Road Condition	Surfacing Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Beware of pedestrians in Tzaneen and Letsitele
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R71
Section	Letsitele to Phalaborwa Gate at Kruger National Park
Distance	79.6km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing is Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Beware of stray animals between Selwane intersection and Lulekani Beware of pedestrians at Namakgale
Duration of work	Ongoing

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285
National Route	R72
Section	Nanaga to Alexandria
Distance	50 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Good
Duration of work	
Contact for Routine Road Maintenance	Ian Smith 084 415 2002
National Route	R72
Section	Alexandra – Peddie turnoff. New Keiskamma rivers
Distance	117km
Description	Two lane single carriageway with grave shoulders
Expected Road Condition	Fair but narrow width
Expected Travel Condition	Construction has commenced between Port Alfred and Fish River, where reduced speeds and stop/go controls will apply. Construction of Bihra River to Open Shaw, where reduced speeds and stop/go controls will apply.
Contact for Construction	Hendrik Pretorius 082 772 1335 (Port Alfred to Fish River) Rian Groenewald 082 837 0500 (Bihra to Open Shaw)
Duration of work	Till August 2018
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R72
Section	Peddie turn off to East London Airport
Distance	62km
Description	Two lane single carriageway with paved shoulder
Expected Road Condition	Good
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R75
Section	Port Elizabeth to Uitenhage North
Distance	28km
Description	Dual carriageway with 2 lanes per direction for the first 14 km. Not a freeway and a lot of level accesses exist, also a lot of pedestrian movements
Expected Road Condition	Good
Expected Travel Condition	Please take special care for first 13 km and normal RRM work. Reconstruction from km 1,0 to km 13 has commenced. Expect delays.
Duration of work	To be completed in May 2019.
Contact for construction	Andre Roodt 082 490 0199.
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	R75
Section	Uitenhage North to Jansenville
Distance	136km
Description	A two-lane narrow, single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Fair, no construction currently underway, but routine maintenance is ongoing. Look out for warthogs.
Duration of work	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R75
Section	Jansenville to R63 junction (Pearston)
Distance	59km
Description	A two-lane, narrow single carriageway with gravel shoulders. The last 23km with paved shoulders.
Expected Road Condition	Fair
Expected Travel Condition	No construction but motorists may encounter occasional short closures for routine maintenance. Very narrow sections from Jansenville for +- 50km.
Duration of work	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R81
Section	Polokwane to Mooketsi
Distance	73km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Good. Km 60 – 66 poor surface. Line markings in fair condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tony Mathebula 083 437 8856

National Route	R81
Section	Mooketsi to Giyani
Distance	73.2km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Construction works completed at Maphalle
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tony Mathebula 083 437 8856

National Route	R101
Section	Bela-Bela to Modimolle
Distance	26.8 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R101
Section	Modimolle to Middelfontein
Distance	16.4 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing

Contact for Routine Maintenance	Gustavus Fouche 082 780 2391
---------------------------------	---------------------------------

National Route	R104
Section	Simon Vermoeten to West of Bronkhorspruit
Distance	58.5 km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Good. Road Markings in a poor state
Expected Travel Condition	Routine road maintenance teams may be encountered. Beware of pedestrians at Nellmaphius
Duration of Work	Ongoing
Contact for Routine Maintenance	Timothy Masalesa 076 349 4168

National Route	R104
Section	East of Bronkhorstspuit to Mpumalanga Border
Distance	21 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Timothy Masalesa 076 349 4168

National Route	R300
Section	Swartklip Interchange to Stellenberg Interchange
Distance	16.1 km
Description	Three-lane dual carriageway with paved shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Repairs are anticipated at both the Stellenberg and Swartklip:Bridges. Traffic will be accommodated accordingly. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Chris Roux 083 440 7553

National Route	R390
Section	1 – Cradock to Hofmeyr
Distance	67.9km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good, up to RRM standards.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marco Du Plessis 079 893 6256

National Route	R390
Section	2 - Hofmeyr to R56 Steynsburg
Distance	34.20km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good, recently resealed
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R391
Section	Section 2
Distance	37.49km
Description	Reseal project underway until December 2019. Expect stop/go sections.
Expected Road Condition	
Expected Travel Condition	
Duration of Work	Ongoing
Resident Engineer	Mike Miller 083 974 2072

National Route	R410 Section 1
Section	R392 Intersection to Lady Frere
Distance	Km 0.0 to Km 38.8
Description	Two lane single carriageways with gravel shoulders for 38.8 km, up to Lady Frere.
Expected Road Condition	Poor to fair.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	RRM Ongoing

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409
--------------------------------------	-------------------------------

National Route	R410 Section 2
Section	Lady Frere to Cala
Distance	Km 0.0 to Km 58.0
Description	Two lane single carriageways with alternating passing and gravel shoulders.
Expected Road Condition	Good and Up to RRM Standards
Expected Travel Condition	A contract for the Reseal of the R410 Section 2 was completed July 2017. Routine Road Maintenance teams may be encountered
Duration of Work	RRM Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R410 Section 3
Section	Cala to R58 Intersection
Distance	Km 0.0 to Km 16.8
Description	Two lane single carriageways with alternating passing and gravel shoulders.
Expected Road Condition	Good and Up to RRM Standards
Expected Travel Condition	A contract for the Reseal of the R410 Section 2 was completed July 2017. Routine Road Maintenance teams may be encountered
Duration of Work	RRM Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R500
Section	Parys to Carletonville
Distance	55.4 km
Description	Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	Good to Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R501
Section	Free State Border to Potchefstroom
Distance	21.2 km
Description	Two-lane narrow single carriageway with gravel shoulders
Expected Road Condition	Good to Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080

National Route	R501
Section	Potchefstroom to Westonaria Municipal Border
Distance	64.3 km
Description	Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	The two-lane is bad to poor and then the dual is good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Vincent Stewart 076 272 3080
National Route	R503
Section	Klerksdorp to Coligny
Distance	74.56 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Fair to Good.
Duration of Work	Ongoing
Contact for Routine Maintenance	André Van Der Merwe 071 643 1004

National Route	R503
Section	Coligny to Lichtenburg
Distance	21.9 km
Description	Two-lane single carriageway with gravel shoulders.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop/go controls may occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R504
Section	Wolmaranstad to Leeudoringstad
Distance	28.9 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop/ go controls occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R504
Section	Leeudoringstad to Free State Border
Distance	24 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop/go controls may occur from time to time
Duration of Work	Ongoing
Contact for Routine Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R505
Section	Wolmaranstad to N14/11
Distance	91.7 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Fair with uneven riding surface.
Expected Road Condition	Routine road maintenance teams may be encountered. Short stop/go control may occur from time to time Roadworks. Expect stop and Go's
Duration of Work	Ongoing
Contact for Routine Maintenance	Ronald Nthite 073 126 8587

National Route	R505
Section	N14/11 to Lichtenburg
Distance	38.6 km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Expected Road Condition Fair with uneven riding surface
Expected Travel Condition	Routine road maintenance teams may be encountered. Short stop/go controls may occur from time to time
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R505
Section	Lichtenburg to Ottoshoop
Distance	49.4 km
Description	Two lane single carriageway with gravel shoulders

Expected Road Condition	Road is in a fair condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R510
Section	Rustenburg to north West / Limpopo Border (Thabazimbi via Northam)
Distance	69.48 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R510
Section	North Wet /Limpopo Border to Northam
Distance	21 km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R510
Section	Northam to Thabazimbi
Distance	37.2km
Description	Single carriageway
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R510/3
Section	Hermanusdoring to Lephalale
Distance	56km
Description	Two-lane single carriageway with unpaved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Russell Odendaal – 081 254 5488 Glen Mmako – 082 451 8801

National Route	R510/4
Section	Lephalale to Monte Christo
Distance	36.08km
Description	Two-lane single carriageway with unpaved shoulders.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Russell Odendaal – 081 254 5488 Glen Mmako – 082 451 8801

National Route	R511
Section	Brits to North West/Limpopo
Distance	75.4 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Rehabilitation and reconstruction between Bethanie intersection (km 10.6) to Beestekraal intersection (km 36.4) commenced on 1 February 2019. Stop / Go operations and deviations will be encountered and may add ±0.5 hour to travelling time. Routine road maintenance teams may also be encountered on the sections excluded from the reconstruction project.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R511
Section	North West / Limpopo border to Thabazimbi
Distance	62km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good. Poor road markings on some sections
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R511
Section	Gauteng /north West Border to Broedestroom
Distance	7.49 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R512
Section	R104 to Brits
Distance	10.06 km
Description	Two-lane single carriageway with gravel shoulders. The N4 bridge allowing access to the R104 is closed for a period of 10 months March 2020 for the upgrade of the N4 and the bridge to allow for a double carriageway (access only from the N4 Rustenburg). The interchange on the R511 Section 2 (Hartbeespoort to Brits) will be utilized to access Brits and the N4 until construction of the R512 bridge is completed.
Expected Road Condition	Fair to good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R516
Section	Koedoeskop to Bela Bela – R101
Distance	82.0km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Andre Van Der Merwe 071 643 1004

National Route	R518
Section	Lephalale to Marken
Distance	70km
Description	Two-lane single carriageway with unpaved shoulders. Slope in the mountain area full of falling rocks
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

National Route	R518/24
Section	Mahwelereng N11 to Marken
Distance	101.70 km
Description	Two-lane single carriageway with unpaved shoulders. Paved shoulders in the mountain area (Kloof Pass) Slope in the mountain area full of falling rocks.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Stop and Go road closures will be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

National Route	R518
Section	Mokopane to Zebediela
Distance	47.281km
Description	Two lane single carriageway.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R518
Section	Zebediela to Lebowakgomo
Distance	25.8km
Description	Two lane single carriageway.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R520
Section	R510/3 Junction to Vaalwater
Distance	54km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	R521
Section	Polokwane to Dendron
Distance	62.3 km
Description	Two-lane single carriageway.
Expected Road Condition	Fair. Gravel shoulders.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Trish Ngobeni 082 5558493

National Route	R521
Section	Dendron to Vivo
Distance	8km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Trish Ngobeni 082 686 5667

National Route	R521
Section	Vivo to R23/1 Intersection
Distance	6.5km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Stop/Go controls may occur.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Trish Ngobeni 082 686 5667

National Route	R523
Section	Vivo to Masekwaspoot
Distance	67km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Trish Ngobeni 082 686 5667

National Route	R524
Section	Louis Trichardt to Punda Maria Gate
Distance	130.3km
Description	Two lane single carriageway with no paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Johan de Vries 073 308 2356

National Route	R526
Section	Mica to Gravelotte
Distance	33.03km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R529
Section	Giyani to Letsitele
Distance	77.6km
Description	Two lane single carriageway with no paved shoulders.
	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Beware of pedestrians
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R531
Section	Klaserie junction with R40 to Orpen Gate at Kruger National Park
Distance	3km
Description	Single carriageway with paved shoulders.
	Surfacing Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Beware of stray animals
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wessel Schalkwyk 082 371 3285

National Route	R532
Section	Junction with R36 to Mpumalanga border towards Graskop
Distance	11.4km
Description	Single carriageway with gravel shoulders.
	Surfacing Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R555
Section	Witbank to Middelburg
Distance	21 km
Description	A two-lane single carriageway road with wide shoulders
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Timothy Masalesa 076 349 4168

National Route	R555
Section	Limpopo / Mpumalanga border at Stoffberg to Kokwaneng
Distance	72.86
Description	Single carriageway with gravel and paved shoulders.
Expected Road Condition	First 30km in poor condition. Rest is fair to good. Line markings in poor condition.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Nathanael Pillay 074 309 0937

National Route	R555
Section	Kokwaneng to Burgersfort
Distance	37.705km
Description	Single carriageway with gravel and paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Nathanael Pillay 074 309 0937

National Route	R556
Section	Tsitsing to Ledig (Sun City) to R510 intersection
Distance	29.6km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Good. Be aware of stray animals.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R565
Section	Rustenburg to Ledig (Sun City)
Distance	34.9km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R567
Section	N11/13 to Seshego (Kompane Street)
Distance	63.7km
Description	Two lane single carriageway with no paved shoulders.
Expected Road Condition	Good. Speed humps between Moletji and Seshego
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Domestic animals from Ga-Matlala to Moletjie in the road reserve
Duration of work	Ongoing
Contact for Routine Road Maintenance	Hannelie Swanepoel 082 380 5264

National Route	R570
Section	N4 Interchange to Malelane Kruger Park Gate
Distance	3.648 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered. Sugar canes along the road.
Duration of Work	Ongoing
Contact for Routine Maintenance	Hannelie Swanepoel 084 516 3330

National Route	R570
Section	N4 Interchange to Jeppe's Reef Border Post
Distance	40.89 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819
National Route	R571
Section	N4 Interchange to Managa Border Post

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Distance	60.469 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	First 30km is good. Rest fair to good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	R572/2
Section	Monte Christo to Tom Bourke
Distance	47.95km
Description	Two-lane single carriageway with unpaved shoulders.
Expected Road Condition	Fair/Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

National Route	R573
Section	Section 2-Moloto to Moteti
Distance	48.652 km
Description	Two-lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good 4 New circles constructed and completed
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks with lane deviations
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wim Prinsloo 076 972 3185 (082 494 8947)

National Route	R573
Section	Section 3 - Moteti to Marble Hall
Distance	43.741 km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Section 3 from Km 19.2 up to Km 43.8 under construction though Construction is temporarily on HOLD
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wim Prinsloo 076 972 3185 (082 494 8947)

National Route	R578
Section	Louis Trichardt to Giyani
Distance	90.76
Description	Two lane single carriageway with no paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Johan de Vries 073 308 2356

National Route	R579
Section	Hlogotlou to Phokwane
Distance	26km
Description	Two-lane single carriageway with no paved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	R579
Section	Phokwane to Chuniespoort
Distance	78.9km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gert Swanepoel 084 516 3330

National Route	S27
Section	Villiers to Mpumalanga / Gauteng Border
Distance	50.2km
Description	Single carriageway with gravel shoulders from km 0 to km 43 and short gravel road portion from km 35 to km 43
Expected Road Condition	Good (Gravel road in good condition).
Expected Travel Condition	Emergency Teams and routine route maintenance team may be encountered on the road.
Duration of Work	Ongoing (Contract ends Feb 2020)
Contact for Routine Road Maintenance	Solomon Mathabe 071 159 6123

NATIONAL BORDER CONTROL POSTS

Botswana Border

Border Post	Location	Description	Condition	Opening Times
Twee Rivieren	Situated in the Kgalagadi Cross Border National Park	Single carriageway gravelled road.	Fair	08h00 to 16h30
Gemsbok	Between Upington and Botswana	Single carriageway gravelled road.	Fair	08h00 to 16h30
Middelputs	Between Van Zylsrus and Botswana	Single carriageway gravelled road.	Fair	08h30 to 16h30
McCarthy's Rest	Route R380 between Kathu and Thshabon (Botswana)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Makopong	Route R379 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Bray	Route R378 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Boshoek	Route R375 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Magobistad	Between Mafikeng & Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h30
Ramatlabama	Between Mafikeng & Botswana	Single carriageway paved road.	Good	07h00 to 20h00
Skilpadshok	N4 Platinum – Lobatse	Single carriageway paved road.	Good	07h00 to 19h30
Swartkopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 19h00
Kopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 22h00
Derdepoort	Between Rustenburg & Botswana	Single carriageway gravelled road.	Poor	07h00 to 19h00
Stockpoort	From Ellisras to Botswana	Single carriageway paved road.	Good	08h00 to 16h00
Groblers Bridge	From Potgietersrus on N11 to Botswana	Single carriageway paved road.	Good	08h00 to 18h00
Zanzibar	Between Alldays & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Platjan	Between Alldays & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Pondrifi	From Alldays on R521 to Botswana	Single carriageway paved road.	Good	08h00 to 16h00

Namibia Border

Border Post	Location	Description	Condition	Opening Times
Alexander Bay	Between Alexander Bay and Oranjemund (Namibia)	Single carriageway paved road.	Good	06h00 to 22h00
Violsdrift	Route N7/B1 between Springbok and Keetmanshoop (Namibia)	Single carriageway paved road.	Good	24 hours
Onseepkans	Route R358/C10 between Pofadder and Karasburg	Single gravelled road with single traffic lane bridge over Orange River Bridge	Fair	08h00 to 16h30
Nakop	Route N10/B3 between Upington and Karasburg (Namibia)	Single carriageway paved road with gravelled shoulders. New Border Control Post situated 1 km from actual border with Namibia.	Good	24 hours
Noenieput	Between Upington and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Rietfontein	Route R31/C16 between Askam and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30

Zimbabwe Border

Border Post	Location	Description	Condition	Opening Times
Beitbridge	On N1 between RSA and Zimbabwe	Single carriageway paved road.	Fair	Passengers: 24hrs Commercial: 24hrs

Mozambique Border

Border Post	Location	Description	Condition	Opening Times
Pafuri	In Kruger National Park, nearest route is R525, east/west direction ± 25 km adrift)	Single carriageway paved road under construction.	Fair	08h00 to 16h00
Lebombo	On N4 between Nelspruit and Maputo	Single carriageway paved road.	Good	06h00 to 22h00
Kosibay (Farazela)	On R22 between RSA and Mozambique	Single carriageway paved road with narrow paved shoulders.	Good	06h00 to 18h00

Swaziland Border

Border Post	Location	Description	Expected Condition
Mananga	On R571 between Komatipoort and Swaziland	Single carriageway paved road.	Fair
Jeppe's Reef	On R570 between Malelane and Swaziland	Single carriageway paved road.	Good
Josefsdal	On R40 between Barberton and Piggs Peak	Single carriageway gravelled road	Poor
Oshoek	On N17 between Ermelo and Manzini	Single carriageway paved road.	Good
Waverley	Off R33 between RSA and Swaziland	Single carriageway paved road.	Good
Nerston	On R65 between RSA and Swaziland	Single carriageway paved road.	Fair
Emhlalatinhi	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Bothashoop	Between Piet Retief and Swaziland	Single carriageway gravelled road.	Fair
Mahamba	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Onverwacht	D1936 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good
Golela/Lavumisa	P 720 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good

Lesotho Border

Border Post	Location	Description	Expected Condition
Monantsapas	R 57/S1579 (Free State)	Single carriageway paved road	Fair to good
Caledonspoort	P 92/1 (Free State)	Single carriageway paved road	Fair to poor
Ficksburg Bridge	R 26 / P75/1 (Free State)	Single carriageway paved road	Fair
Peka Bridge	S 388 / S 306 (Free State)	Single carriageway gravel road	Poor
Maseru Bridge	N8 (Free State)	Single carriageway paved road.	Fair
Van Rooyen's Gate	P66/1 (Free State)	Single carriageway paved road	Fair
Sepapu's Gate	S4 (Free State)	Single carriageway gravel road	Poor
Makhaleng Bridge	S2 (Free State)	Single carriageway gravel road	Very Poor
Telle Bridge	R 392 (from Sterkspruit in the Eastern Cape)	Single carriageway paved road.	Good
Ongeluksnek	Eastern Cape: Off R 56. Closest towns are Mount Fletcher and Matatiele	Gravel approach road.	Poor to very poor. Only suitable to 4x4 vehicles beyond the border post.

Qacha's Nek	Eastern Cape: Closest town Matatiele	Gravel approach road.	Poor
Ramaselitso Gate	Eastern Cape: Closest from Matatiele	Gravel approach road.	Poor
Sani Pass	P 318 (KwaZulu-Natal)	Gravel approach road	Fair but often only accessible to 4X4 vehicles beyond the border post.

THE SOUTH AFRICAN NATIONAL ROADS AGENCY SOC LTD

Contact Details

Head Office

48 Tambotie Avenue
Val de Grace
Pretoria, 0184
Tel. 012 844 8000
Fax 012 362 2117

Northern Region

38 Ida Street
Menlo Park
Pretoria, 0081
Tel. 012 426 6200
Fax 012 348 1680

Eastern Region

58 Van Eck Place
Mkondeni
Pietermaritzburg
Tel. 033 392 8100
Fax 033 386 6284 / 3365

Southern Region

20 Shoreward Drive
Baywest
Port Elizabeth
6025
Tel. 041 398 3200
Fax 041 492 0201

Western Region

1 Havenga Street
Oakdale, Bellville
7530
Tel. 021 957 4600
Fax 021 910 1699

Website: www.sanral.co.za
E-mail: info@nra.co.za
Fraud Hot Line: 0800204558