



The South African National Roads Agency SOC Limited

Road Condition Advisory Report

April 2021

Northern Region

38 Ida Street

Menlo Pak

Pretoria

0081

Western Region
1 Havenga Street
Oakdale, Bellville
7530

N1

National Route	N1
Section	Old Oak Interchange to Rawsonville
Distance	64 km
Description	Two-lane dual carriageway with paved shoulders.
Expected Travel Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Chris Roux 083 440 7553

National Route	N1
Section	Polokwane (Meropa Casino) to Doornbult
Distance	22.300 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Emergency Standby Teams may be encountered Major Roadworks upgrades from Meropa N1 to R71 interchange resume with their normal operation as from the 01 May 2020, during Covid-19 Alert Level 4. Speed limit throughout the construction zone (for the first 15km) has been lowered to 40 – 60km/h. Essential Road Users are warned to adhere to the temporary signage and speed limits .
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Thabo Malete 073 418 5228

National Route	N1
Section	28X Doornbult to Louis Trichardt (N1-28X)
Distance	98.750 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Emergency Standby Teams may be encountered Essential Motorists should be alert of stray animals around Matoks area
Duration of Work	Ongoing

Contact for Routine Road Maintenance	Thabo Malete 073 418 5228

National Route	N1
Section	Bloemfontein to Kroonstad
Distance	189 km
Description	Around Bloemfontein and extending northwards for some 15km, the road is a four-lane dual carriageway with wide paved shoulders. Thereafter it reduces to a four-lane single carriageway for the next 20kms, otherwise it is a two-lane single carriageway with paved shoulders and passing lanes on steep gradients. The last 10 km, known as the Kroonstad Bypass, is a four-lane dual carriageway.
Expected Road Condition	Generally good except for the section between Ventersburg and Kroonstad, where the road surfacing is being rehabilitated.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A contract for the upgrade between Ventersburg and Holfontein is in progress. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. A contract for the upgrade between Holfontein and Kroonstad is in progress. Traffic is free flowing. Motorists are advised to obey the posted traffic signs. 3. A contract for the upgrade of the Kroonstad Traffic Control Centre is in progress.. Traffic is free flowing. Motorists are advised to obey posted traffic signs.
Duration of Work	<ol style="list-style-type: none"> 1. Until February 2019 2. Until January 2019 3. Until March 2019
Contact for Routine Road Maintenance	Abel Majorobela 079 896 3377

National Route	N1
Section	23 (12.71km), 24 (25km) 25 (89km) (Bela Bela to Ysterberg)
Distance	126.71 km
Description	Four-lane dual divided carriageway freeway from the Bela Bela/Settlers interchange to the Kranskop toll plaza. Four-lane single undivided carriageway freeway from the Kranskop Toll Plaza to Ysterberg.
Expected Travel Condition	Road surface is in a good condition. Pedestrians crossing the road at Mookgophong. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing until February 2024
Contact for Routine Road Maintenance	Stephan du Plessis / Dirk Hofmann 0844911165 / 0829276203

National Route	N1-29X
Section	Makhado to Beitbridge
Distance	107 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Fair to Good (KM 0 To 29) Fair to bad (KM 29 To 70) Good (KM 70 To 107)
Expected Travel Condition	Routine road maintenance teams may be encountered. Beware of stationary vehicles on the Mountain Pass and along the rest of the route. Very sharp curves and slow-moving vehicles along the mountain pass. Short stop/go control may occur. Permanent pothole teams may be encountered too
Duration of Work	Ongoing
Contact for Routine Maintenance	Pius Ngassa 0711731194

National Route	N1 25 NRA N.001 – 250 – 2018/1
Section	From km. 0.0 (north of Middelfontein to Nyl Plaza) (Great North Toll Road)
Distance	57.70 km
Description	Four-lane single undivided carriageway freeway from km. 0. (North of Middelfontein to the Kranskop Toll Plaza.
Expected Travel Condition	1.Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	KBK Engineers Gustav Fouche 082 780 2391 (N1 25)

National Route	N1: R101: N1 24X NRA X.002 – 051 _ 2015/1
Section	Middelfontein to Mookgopong Municipal Border (N1/24X: R101)
Distance	4.78 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	N1: R101: N1 25X NRA X.002 – 051 – 2015/1
Section	Mookgopong Municipal Border to Mokopane (N1/25X: (R101)
Distance	67.13 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	N1: R101 N1 25Y NRA X.002 – 051 2015/1
Section	Mookgopong I/C to N1/25X Intersection (N1/25Y: R101)
Distance	2.570 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance Teams may be encountered

Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

N2

National Route	N2
Section	Empangeni to Pongola
Distance	250 km
Description	A 2-lane single carriageway with paved shoulders. South bound N2 Section 30, Km47 – reduced shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Sanele Dlamini (Route Manager) 065 884 9884

National Route	N2
Section	Pongola to KwaZulu-Natal / Mpumalanga Border
Distance	38 km
Description	A 2-lane single carriageway road with passing lanes on the steeper gradients.
Expected Road Condition	Fair
Expected Travel Condition	Routine road maintenance may be encountered
Duration of work	On going
Contact for Routine Road Maintenance	Sanele Dlamini 065 884 9884

National Route	N2
Section	KwaZulu Natal / Mpumalanga border north of Pongola Border to Piet Retief
Distance	57km
Description	A Two-lane single carriageway narrow gravel shoulder.
Expected Road Condition	Bad
Expected Travel Condition	Routine Road Maintenance teams may be encountered. There are many potholes that are developing rapidly Route patrol may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 071 638 9828

National Route	N2
Section	Piet Retief to Ermelo
Distance	98.20 km
Description	A Two-lane single Carriageway narrow gravel shoulder. First 7km is 4 lanes undivided
Expected Road Condition	Bad
Expected Travel Condition	Route patrol may be encountered. There is a large number of potholes that are developing rapidly thus road users are encouraged to drive with caution. Routine Road Maintenance teams may be encountered. .
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 071 638 9828

National Route	N2
Section	34-Piet Retief to Ermelo
Distance	From 48.80 to 98.60 km(49.80)
Description	A two- lane Single carriageway narrow gravel shoulder.
Expected Road Condition	Bad but RRM team are busy with surface and potholes repairs. Road markings need to be done on KM 74.0
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Motorist should expect compulsory stop and go because of surface repair.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N2
Section	Brookes Nek (provincial boundary) to Port Shepstone (Sections 21X & 22X)
Distance	135 km
Description	This section of the N2 in KZN is a two-lane single carriageway with narrow paved shoulders. Passing lanes are provided on all the severe grades with the exception of a short 6 km section, 26 km north of Kokstad.
Expected Road Condition	Good.
Expected Travel Condition	
Duration of Work	
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	N2
Section	Durban to Empangeni
Distance	162 km
Description	For 71 km, up to Stanger, the road is a four-lane dual carriageway. For the next 52 km, up to the Mtunzini Toll Plaza, the road is a four-lane undivided carriageway with paved shoulders. The remaining portion is a single carriageway with alternating passing opportunities.
Expected Road Condition	Good.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A closure of the N2 at Umhlali River Bridge and at Umvoti River Bridge are in progress. No Stop/Go controls will be in place, but a single lane and speed restrictions are in place on the northbound carriageway. 2. A contract for the upgrade of the N2 to a dual carriageway freeway between Mtunzini Toll Plaza and Empangeni T-junction is in progress. No Stop/Go controls will be in place. Cross over to a portion of the new constructed carriageway is expected in December 2018.
Duration of work	<ol style="list-style-type: none"> 1. Until August 2019. 2. Until June 2019.
Contact for Routine Road Maintenance	Emeka Mgbemere 083 641 9056 (Route Manager – Durban to eMdloti) Mikhail Ramlukan 074 325 8752 (Assistant Route Manager – Durban to eMdloti) Stollie van Wyk 072 283 6669 (eMdloti to Empangeni)

National Route	N2
Section	33 – From Mpumalanga / Kwazulu Natal Provincial boundary to Mkhondo town Centre
Distance	From 0.00 to 63,0 (63,0)
Description	Mostly Single carriageway two lane road with occasional passing lanes and paved and gravel shoulders

Expected Road Condition	Very poor and require large areas of pavement reconstruction. Very rough and bumpy road surface due to many patching and repairs. Grass cutting and shoulder construction as well as guardrail repairs
Expected Travel Condition	Routine Road Maintenance teams executing road pavement repairs may be encountered Motorist should be alert to the vast quantity of timber and coal trucks on the route Section through town is highly trafficked and road condition is very poor. The section between Km 27 and 31 is very rough and bumpy with many pavement failures. The section between km 43.0 and km 44.5 is very slippery and considered as a high accident zone and it is advised to not exceed speeds of 80km/h
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Schalk v Wyk 0780691808

National Route	N2
Section	34 – From Mkhondo town Centre to Mkhondo municipal boundary at Sheepmoor intersection
Distance	From 0,0 to 48,8 (48,8)
Description	Mostly Single carriageway two lane road and gravel shoulders. Short section with four lanes.
Expected Road Condition	Very poor and require large areas of pavement reconstruction, several pavement failures occur along the route, grass cutting and shoulder repairs are on-going
Expected Travel Condition	Routine Road Maintenance teams executing road pavement repairs may be encountered Motorist should be alert to the vast quantity of timber and coal trucks on the route
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Schalk v Wyk 0780691808

N3

National Route	N3
Section	Durban to Cedara (Hilton)
Distance	85 km
Description	This entire section is a multi-lane dual carriageway. The first 4km out of Durban carries heavy traffic with up to 5 lanes in each direction. The next 40 km, up to Cato Ridge, has 3 lanes in each direction with wide paved shoulders. The section between Cato Ridge and the end of the Pietermaritzburg Bypass (33 km) has a two-lane plus paved shoulder configuration, except on steep gradients to the east of Pietermaritzburg where passing lanes are provided. The final 14 km to Howick incorporates the steeply graded Town Hill, which has 3 lanes with paved shoulders in each direction.
Expected Road Condition	Good. Damaged concrete truck lane at Townhill. Proceed with caution.
Expected Travel Condition	1. A contract for the upgrade of the Hammarsdale Interchange is ongoing. There is minimal disruption to traffic on the N3, however there will be disruption to local traffic. The posted speed limit through the site is 80km/hr. There will be temporary lane closures in the coming months to complete the aspects of the bridge and short term full closures of the N3 can be expected. Disruptions to traffic should be minimal. There will be a full road closure towards the end of the project for demolition of the existing bridge structure and blasting, however details will be made available closer to the time. 2. Routine road maintenance teams may be encountered, including road marking. Expect reduced lanes.
Duration of Work	1. Until August 2019. 2. Until December 2018.
Contact for Routine Road Maintenance	Emeka Mgbemere 083 641 9056 (Route Manager) Mikhail Ramlukan 074 325 8752 (Assistant Route Manager)

National Route	N3 (The N3 Toll Route operated by N3 Toll Concession (RF) Proprietary Limited
----------------	---

Section	Cedara to Heidelberg
Distance	415 km
Description	This section of road is a public private partnership between SANRAL and the N3Toll Concession (Pty) Ltd. This toll route is a four-lane dual carriageway road between Cedara and the Tugela Toll Plaza. From the Tugela Toll Plaza to the Wilge Toll Plaza (Villiers) the road is a four-lane single carriageway with shoulders of varying width. The section between the Tugela Toll Plaza and Warden has at-grade intersections and access roads with reduced speed limits signposted. The remainder of the road between Villiers and Heidelberg is a four-lane dual carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	<p>Current planned construction works include:</p> <ol style="list-style-type: none"> 1. Rehabilitation between Cedara and Mooi River. Work commenced in April 2017 and is programmed for completion in June 2020. 2. Rehabilitation of Van Reenens Pass. Work will commence in November 2018 and is programmed for completion in September 2020. 3. Rehabilitation between the Vaal River and the De Hoek Toll Plaza. Work commenced in March 2018 and is programmed for completion in February 2019. 4. Ongoing routine road maintenance, grass cutting and litter collection. <p>Traffic may be restricted through the construction zones to one lane in each direction under reduced speed.</p> <p>During the period 14 December 2018 to 8 January 2019, there will be no long term construction in operation and there will be two lanes open to traffic in both directions.</p> <p>Road users are urged to obey the posted speed limits, maintain safe following distances and refrain from littering.</p>
Duration of Work	Please see above. Maintenance personnel will be on standby to deal with any emergency repairs.
Contact for Routine Road Maintenance	N3TC Customer Care Line 0800 634 357 0800 N3 HELP

N4

National Route	N4
Section	Nelspruit: Valencia Road to N4
Distance	8.6km
Description	Single carriageway with gravel shoulders.
Expected Road Condition Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	N4
Section	12, R512 to N4
Distance	11,6 km
Description	Two lane double carriageway with paved shoulders between the R560 and R512 interchanges. The remainder of the route is a two-lane single carriageway with paved shoulders.

Expected Road Condition Expected Road Condition	Very Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

N11

National Route	N11
Section	Middelburg to Loskop
Distance	29.240 km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair Good High accident zone (Kranspoort mountain pass) km 36
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane / Trish Ngobeni 076 389 7688/ 082 686 5667

National Route	N11
Section	Loskop to Mookgopong Municipal Border
Distance	44.300km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane / Trish Ngobeni 076 389 7688/ 082 686 5667

National Route	N11
Section	Mookgopong Municipal Border to Mokopane Weigh Bridge / N1/25X Intersection
Distance	89.040km
Description	Single carriageway with gravel shoulders
Expected Road Condition	Good to excellent
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane / Trish Ngobeni 076 389 7688/ 082 686 5667

National Route	N11
Section	7 - Msukaligwa Municipal border / Vaal River to Ermelo
Distance	From 0.00 to 29.79 km(29.85)
Description	Single carriageway road with passing lanes and paved shoulders.

Expected Road Condition	Fair but needs road marking in some areas especial from Ermelo town towards KM 22.2
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Vaal River to Ermelo
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

National Route	N11
Section	8 - Ermelo to Hendrina
Distance	From 0.00km to 42.54 km (42.54)
Description	Single carriageway road with passing lanes and paved shoulders.
Expected Road Condition	Good, Road Markings need to be done from KM 1.0 to KM 7.0
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of coal trucks from Hendrina to Ermelo
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Faith Mogano and Ayanda Mkhize 0716389828 and 0714727372

N12

National Route	N12
Section	Lekwa-Teemane Border to Wolmaransstad
Distance	38.50 km
Description	Two-lane single carriageway with paved shoulders
Expected Road Condition	Generally good condition
Expected Travel Condition	Minor maintenance work from time to time on this section. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12
Section	Wolmaransstad to Matlosana Municipal Border
Distance	37.20 km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	1. Poor through Wolmaransstad town from km 0.00 at Fells Street to km 2.1 East of Makwassie Spruit 2. Generally good condition from km 2.1 to km 10.6 and from Km 16 to km and from Km 16 to km 7.2 3. Routine road maintenance teams will be active with occasional localised Stop/Go controls for pavement repairs between km 10.6 and km 15.2.
Expected Travel Condition	1. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12
----------------	-----

Section	Maquassi Hills/ Matlosana Municipal border to Klerksdorp
Distance	39.14 km
Description	Two-lane single carriageway with wide paved shoulders on most of the section, except closer to Klerksdorp.
Expected Road Condition	Good to very good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorists should be alert of traffic circle as you enter and exit Klerksdorp.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 0829349153

National Route	N12
Section	Klerksdorp to Matlosana / JB Marks Municipal border
Distance	15.73 km
Description	Two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Road partially closed between Klerksdorp and Stilfontein due to a sink hole within the road reserve. Expect lane reductions.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 0829349153

National Route	N12
Section	Klerksdorp to Matlosana / JB Marks Municipal border
Distance	12.78 km
Description	Two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Road partially closed between Klerksdorp and Stilfontein due to a sink hole within the road reserve. Expect lane reductions.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 0829349153

National Route	N12/12
Section	Christiana - Bloemhof
Distance	0.0 – 55.4
Description	No existing fence on both sides of the road at Christiana and Bloemhof straining animals and pedestrians could be a problem. Speed limit on both sections are 80 Km/h. Rest of the section is safe and the surface is in a good driving condition. Surfaced shoulders 2.5 m wide
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phumza Baqwa 083 384 8081

National Route	N12/16
Section	Merafong to Potchefstroom Industrial
Distance	15.7 to 43
Description	Extending northwards for some 27.30km, road reserve with dual carriage way
Expected Road Condition	Generally good condition
Expected Travel Condition	<ol style="list-style-type: none"> 1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Grass cutting in process
Duration of Work	<ol style="list-style-type: none"> 1. Until November 2023 2. Ongoing
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

National Route	N12/17
Section	Potchefstroom to Gauteng border
Distance	4.50 to 18.90
Description	Extending northwards for some 14.4km, road reserve with dual carriage way
Expected Road Condition	Generally good condition
Expected Travel Condition	Traffic is free flowing. Motorists are advised to obey the posted traffic signs
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

N14

National Route	N14
Section	9 - Vryburg to Delareyville
Distance	35.59 km (km 48.2- km 83.79)
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	1 November 2020 – 31 October 2023
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	10 - Delareyville to Sannieshof
Distance	39.82 km (km 39.82 – km 0.0)
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	1 November 2020 – 31 October 2023
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	11 - Sannieshof to Biesiesvlei
Distance	16.8 km (km 16.8 – km 0.0)
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	1 November 2020 – 31 October 2023
Contact for Routine Road Maintenance	Willem – Erik Jacobson 076 148 0321

National Route	N14
Section	Coligny to Ventersdorp
Distance	68.8 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	

National Route	N14
Section	Ventersdorp to North West / Gauteng Border
Distance	49.7km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair. Isolated potholes
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	

National Route	N14/8
Section	Vryburg to Northern Cape Border East of Kuruman
Distance	87.00 km (km 141.50 to 54.50)
Description	Around Vryburg and extending Westwards towards the Northern Cape Border for some 84.80km, the road is two-lane single carriageway with wide gravel shoulders.
Expected Road Condition	Generally good condition with minor surface failures
Expected Travel Condition	<ol style="list-style-type: none"> 4. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 5. Minor maintenance work from time to time on this section 6. Routine road maintenance teams will be active with occasional localised Stop/Go controls for pavement repairs. 7. Road sections closures in market street Vryburg CBD Grass cutting on both sides of the road
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Moeketsi Moko 065 916 1749 / 078 833 2785

National Route	N14/9
Section	VRYBURG TO TSWAING MUNICIPAL BORDER
Distance	48.2 km
Description	Around Vryburg and extending towards the Tswaing Municipal Border for some 48.2km, the road is two-lane single carriageway with wide gravel shoulders.
Expected Road Condition	Generally good condition
Expected Travel Condition	<ol style="list-style-type: none"> 1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs. 2. Stop and Go where patches are done on market street. 3. Minor maintenance work from time to time on this section
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 7452

National Route	N14/11
Section	Municipal Border to Coligny (km 16.8 to km 62.38)
Distance	45.58km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	N14/12
Section	Coligny to Municipal border towards Ventersdorp (km 0.0 to km 29.0)
Distance	29.0 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good. Uneven riding surface. Re-occurring potholes
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Stop and Go's at pavement repair work.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

N17

National Route	N17
Section	4 – Govan Mbeki Municipal Boarder to Ermelo
Distance	38.02Kms (From KM17.70 to KM55.72)
Description	Single carriageway road with passing lanes, 8 intersections and paved shoulders.
Expected Road Condition	The condition of the section is satisfactory except a backlog of W401s on both east and west bounds need an urgent attention.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	36 Months

Contact for Routine Road Maintenance	Portia Mashashane (RM), Chwayita Maponyane (ARM1) and Nkonzo Mvelase (ARM2) 0660518080, 0718806260 and 0792732386
--------------------------------------	---

National Route	N17
Section	5 - Ermelo to Chief Albert Luthuli Municipal Boarder
Distance	74.65Kms (From KM0.00 to KM74.65)
Description	Single carriageway road with passing lanes, Railway Intersection, 17 intersections and paved shoulders.
Expected Road Condition	Routine Road Maintenance teams may be encountered. Expect stop and go on the first 2 kilometers of the section as well as from KM 60 to KM 74.56 (Warburton)
Expected Travel Condition	Motorist should be alert to the vast quantity of wood trucks from Warburton to Chief Albert Luthuli Municipal Boarder
Duration of Work	36 Months
Contact for Routine Road Maintenance	Portia Mashashane (RM), Chwayita Maponyane (ARM1) and Nkonzo Mvelase (ARM2) 0660518080, 0718806260 and 0792732386

N18

National Route	N18/2
Section	Pudimoe to Northern Cape Border South of Taung
Distance	27.5 km (km 0 to 27.50)
Description	From Pudimoe Southwards for 19.6km to Taung where a traffic circle is encountered. The road continues Southwards towards the Northern Cape border for 8.2km as two-lane single carriageway with gravel shoulders
Expected Road Condition	Generally good condition
Expected Travel Condition	<ol style="list-style-type: none"> 1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs 2. Minor maintenance work from time to time on this section 3. Missing fencing and stray animals is a problem 4. Grass cutting on both sides of the road 5. Operational Stop and Go's on Shoulder repairs
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Moeketsi Moko 065 916 1749 / 078 833 2785

National Route	N18/3
Section	Vryburg to Pudimoe
Distance	49.00 km (km 0 to 49.00)
Description	Around Vryburg and extending Southwards for some 49.00km to Pudimoe, the road is two-lane single carriageway with wide gravel shoulders
Expected Road Condition	Generally good condition
Expected Travel Condition	<ol style="list-style-type: none"> 1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Minor maintenance work from time to time on this section 3. Missing fencing and stray animals is a problem 4. Grass cutting on both sides of the road 5. Operational Stop and Go's on Shoulder repairs

Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Moeketsi Moko 065 916 1749 / 078 833 2785

National Route	N18/4
Section	VRYBURG TO STELLA
Distance	46.60km
Description	Around Vryburg and extending for some 46.10km to Stella, the road is two-lane single carriageway with wide gravel shoulders
Expected Road Condition	Generally good condition
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs, 2. Minor maintenance work from time to time on this section
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 7452

National Route	N18/5
Section	STELLA TO RATLOU MUNICIPAL BORDER
Distance	20.20
Description	From Stella for 20.20km to the Ratlou Border, the road is two-lane single carriageway with wide gravel shoulders
Expected Road Condition	Generally good condition
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs. 2. Minor maintenance work from time to time on this section.
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 7452

R22

National Route	R22
Section	Hluhluwe to Farazela (RSA/Mozambique border)
Distance	175 km
Description	A 2-lane single carriageway road with narrow paved shoulders throughout.
Expected Road Condition	Fair. Traffic congestion through the Town of Manguzi (ongoing issue) due to traders and high volume of pedestrian activity.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	On going
Contact for Routine Road Maintenance	Sanele Dlamini 065 884 9884

R24

National Route	R24
Section	Rustenburg to Gauteng Border

Distance	44.8 km (km 00.0 – km 44.8)
Description	Two lane double carriageway with paved shoulders between Buiten Street and Oorsak Road. The remaining section is a two-lane carriageway with passing lanes through Olifantsnek Pass with unpaved shoulders
Expected Road Condition	Road Condition: Fair to Good Isolated bumps can be expected on the road
Expected Travel Condition	Routine Road Maintenance Teams will be encountered, Route Patrol services. Stop/Go's will be encountered from time to time.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Heinrich Scheepers Tel: 060 492 8600

R30

National Route	R30
Section	Klerksdorp to Matlosana / JB Marks Municipal border
Distance	37.6 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Expected Road Condition	Bad with uneven riding surface and isolated pothole areas.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Short stop/go's may occur from time to time.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

National Route	R30
Section	JB Marks to Olifantsnek
Distance	44.38 km (km 32.2 – km 76.5)
Description	Two lane single carriageway with unpaved shoulders
Expected Road Condition	Road Condition: Fair to Good Bumps can be expected due to unevenness of the road
Expected Travel Condition	Routine Road Maintenance Teams will be encountered on the road, Route Patrol services, Stop/Go's will be encountered from time to time
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Heinrich Scheepers Tel: 060 492 8600

National Route	R30
Section	Free State / North West Border to Klerksdorp
Distance	14.5 km
Description	Two-lane narrow single carriageway with gravel-shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

R33

National Route	R33
Section	Piet Retief to Amsterdam
Distance	35.9 km
Description	A Two-lane Single Carriageway narrow gravel shoulder.
Expected Road Condition	Good
Expected Travel Condition	Normal maintenance on this section. Route patrol may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 0716389828

National Route	R33
Section	Amsterdam to Warburton
Distance	88.54 km
Description	A Two-lane single carriageway with narrow gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Gabions are in bad conditions and an -inspection was done. Patches are completed. Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Faith Mogano 0716389828

National Route	R33
Section	Warburton (from N17/5) to Carolina
Distance	38km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R33
Section	Carolina to Belfast (N4)
Distance	49.2km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered, construction of Access at km 40.173 Northern Coal Weltevreden Mine
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

National Route	R33
Section	N11 – Marble Hall to Modimolle R101
Distance	85.900 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	From Km 0.0 to 78.0 Good –and from Km 78.0 –to 86.0 Poor
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	On Ongoing
Contact for Routine Road Maintenance	Wandile Jiyane/ Trish Ngobeni 076 886 9997/ 082 686 5667

National Route	R33 Section 13 & 14 NRA X.002 – 051 – 2015/1
Section	Modimolle over Vaalwater to Lephalale – (R510)
Distance	63.05 & 85.3 km
Description	Single carriageway with limited paved shoulders otherwise gravel shoulders.
Expected Road Condition	R 33/13km 0.0 63.05.: Fair - Good & R33/14: km 0.0 – 85.49 Condition is poor. Potholes to be expected Km 0.0 – 85.3 poor road markings
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	R33
Section	8- Warburton to Chief Albert Luthuli Municipal Boarder
Distance	8.42Kms (From KM62.94 to KM71.36)
Description	Single carriageway.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	36 Months
Contact for Routine Road Maintenance	Portia Mashashane (RM), Chwayita Maponyane (ARM1) and Nkonzo Mvelase (ARM2) 0660518080, 0718806260 and 0792732386

National Route	R33
Section	7- Mkhondo Municipal Boarder to Warburton
Distance	37.95kms – (From KM14.60 to KM52.54)
Description	Single carriageway narrow gravel shoulder.
Expected Road Condition	Reseal project commenced on the 7th of April 2021, so motorists should be alert of delays to be caused by road works during the upcoming 18 months.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	36 Months
Contact for Routine Road Maintenance	Portia Mashashane (RM), Chwayita Maponyane (ARM1) and Nkonzo Mvelase (ARM2) 0660518080, 0718806260 and 0792732386

National Route	R33
Section	5 – From Mpumalanga / Kwazulu Natal Provincial boundary to N2 intersection
Distance	From 16,1 to 48,3 (32,2)
Description	Single carriageway two lane road with paved shoulders
Expected Road Condition	Fair but needs isolated road pavement repairs and general surface treatment. Grass cutting and shoulder construction
Expected Travel Condition	Routine Road Maintenance teams patrolling or working on the pavement may be encountered Motorist should be alert to the vast quantity of timber and coal trucks using the route
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Schalk v Wyk - 0780691808

National Route	R33
Section	6 – From N2 intersection to Amsterdam town Centre
Distance	From 0,00 to 35,98 (35,98)
Description	Single carriageway two lane road with occasional passing lanes and paved shoulders
Expected Road Condition	Poor and in need of road pavement repairs and surface treatment in most areas. Regular pavement failures occur. Grass cutting and shoulder construction required
Expected Travel Condition	Routine Road Maintenance teams working on the pavement may be encountered Motorist should be alert to the vast quantity of timber and coal trucks using the route Steep downhill sections and high river bridge crossings.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Schalk v Wyk – 0780691808

National Route	R33
Section	7 – From Amsterdam town Centre to Mkhondo municipal boundary
Distance	From 0,00 to 14,6 (14,6)
Description	Single carriageway two lane road and paved shoulders.
Expected Road Condition	Fair but needs some road pavement repairs and general surface treatment required. Occasional pavement failures occur. Grass cutting and repairs to guardrails on-going
Expected Travel Condition	Routine Road Maintenance teams working on the pavement may be encountered Motorist should be alert to the vast quantity of timber and coal trucks using the route
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Schalk v Wyk – 0780691808; Zandile Khoza - 0736093311

R34

National Route	R34/1
Section	VRYBURG TO MAMUSA MUNICIPAL BORDER
Distance	40.70
Description	Around Vryburg and extending for some 40.70km to the Mamusa Municipal border, the road is two lane single carriageway with wide gravel shoulders
Expected Road Condition	Generally good condition
Expected Travel Condition	1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs. 2. Minor maintenance work from time to time on this section.

Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 745

National Route	R34/2
Section	Scweizer-Reneke - Bloemhof
Distance	0.0 – 57.7 km
Description	Construction work (installing pipeline) outside Schweizer-Reneke. Speed limit 60 Km/h. Rest of the section in a safe driving condition, except for deformation on the positive side in the left wheel lane. Gravel shoulders exists. Road markings are faded, but still visible.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	André van der Merwe 071 643 1004

National Route	R34/3
Section	Bloemhof – Free State Border
Distance	0.0 – 6.7 km
Description	Surface in safe driving condition. Gravel shoulders exists. Road markings are faded, but still visible. A Stop/Go sections occurs on the bridge over Bloemhof Dam. Stopping periods are short due to a low traffic volume, and do not interfere with the normal traffic flow . The speed limit on the stop/go section is 40 Km/h.
Expected Road Condition	Fair to Poor
Expected Travel Condition	Good. Bridge joints needs repairs
Duration of Work	Ongoing
Contact for Routine Road Maintenance	André van der Merwe 071 643 1004

R37

National Route	R37
Section	Burgersfort to Lydenburg
Distance	64 km
Description	Single carriageway road with paved shoulders.
Expected Road Condition	First 5-48 km fair condition. Rest fair to good
Expected Travel Condition	Routine Road Maintenance teams may be encountered as well as STOP/GO controls on some sections Beware of stray animals Rehabilitation (Construction) with control STOP/GO 10 km before Lydenburg Potholes can be expected
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R37
Section	Lydenburg to Sabie

Distance	43.94Km
Description	Single carriageway road with mostly paved shoulders.
Expected Road Condition	Fair to good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Potholes can be expected
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R37
Section	Sabie to Nelspruit
Distance	49.20km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Potholes can be expected
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

R38

National Route	R38
Section	Hendrina to Carolina
Distance	42.9km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Christoph Botha 079 882 1193

R40

National Route	R40
Section	Barberton to Nelspruit
Distance	32.77km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered Protest action may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R40
Section	White River to Hazyview
Distance	48.7
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Shoulder closure 25 km before Hazyview at Swartfontein Beware of stray animals Potholes can be expected
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

National Route	R40
Section	Hazyview to Klaserie
Distance	67
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Surfacing Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Beware of stray animals and pedestrians Potholes can be expected Protest action may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Adrie Van Niekerk 076 481 5276

R52

National Route	R52
Section	Koster to N4 Rustenburg
Distance	38.7 km (km 00.0 – km 38.7)
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Section close to Koster from km 0 up to km 5 is bumpy with isolated potholes and cracking. Overall road is in very good condition from Km 5 onwards to the N4 intersection at Km 38.7.
Expected Travel Condition	Routine Road Maintenance Teams will be encountered, Route Patrol services.
Duration of Work	Ongoing
Contact for Routine Maintenance	Heinrich Scheepers Tel: 060 492 8600

National Route	R52/1
Section	Biesiesvlei to Lichtenburg (km 0.0 to km36.6)
Distance	36.6km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Uneven riding surfaces. Shoulder edge drops. Re-occurring potholes.
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Shoulder repair work on road reserve.
Duration of Work	Ongoing

Contact for Routine Maintenance	Marius Nel 073 538 5019
---------------------------------	----------------------------

R53

National Route	R53
Section	Parys to Potchefstroom
Distance	44.7 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

National Route	R53
Section	Potchefstroom to Ventersdorp
Distance	58.5km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

National Route	R53/1
Section	Free State Border to Potchefstroom
Distance	0.30 to 44.70
Description	Extending Southwards for some 44.40km, the road is a two-lane single carriageway with gravel shoulders.
Expected Road Condition	Generally fair condition
Expected Travel Condition	Traffic is free flowing. Motorists are advised to obey the posted traffic signs
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

R54

National Route	R54
Section	Potchefstroom to Emfuleni Local Municipality Border
Distance	42.60 km
Description	Two-lane single carriageway with gravel shoulders.

Expected Road Condition	Fair to bad with isolated pothole areas
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

National Route	R54 /1
Section	N12 to Gauteng Border
Distance	00 to 22.30 km
Description	Extending Southwards for some 22.30km, the road is a two-lane single carriageway with gravel shoulders.
Expected Road Condition	Generally Fair condition
Expected Travel Condition	Traffic is free flowing. Motorists are advised to obey the posted traffic signs.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

National Route	R54 /1
Section	Free State Border (Parys) to Gauteng North Border
Distance	00 to 29.20 km
Description	Extending Southwards for some 29.20km, the road is a two-lane single carriageway with gravel shoulders.
Expected Road Condition	Generally Fair condition
Expected Travel Condition	Traffic is free flowing. Motorists are advised to obey the posted traffic signs, Grass cutting in process
Duration of Work	Until August 2020 Until December 2020
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

R56

National Route	R56
Section	Middleburg and Elliot
Distance	310km
Description	Two lane single carriage way with gravel shoulders.
Expected Road Condition	Middelburg to Steynsburg is in fair condition. Steynsburg to Molteno is poor. Molteno to N6 is fair. N6 to Dordrecht is very poor. Dordrecht to Indwe is poor. Indwe to Elliot is in a bad state. Routine road maintenance busy installing road signs.
Expected Travel Condition	Routine road-maintenance teams may be encountered. Construction teams and stop-go controls will be encountered from Indwe to Elliot.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

R101

National Route	R101 Section 9 NRA X.002 – 051 – 2015/1
Section	Modimolle to Middelfontein
Distance	16.4 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Poor road condition. Potholes can be expected
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Gustav Fouche 082 780 2391

R500

National Route	R500
Section	Parys to Carletonville
Distance	55.4 km
Description	Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

National Route	R500/1
Section	Parys to Gauteng border (Fochville)
Distance	0.00 to 29.20
Description	Extending northwards for some 29.20km, road reserve with single carriage way
Expected Road Condition	Generally fair condition
Expected Travel Condition	<ol style="list-style-type: none"> 1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs 2. Pavement Repair 3. Grass cutting
Duration of Work	<ol style="list-style-type: none"> 1. Until November 2023 2. Until 30 April 2021 3. 30 April 2021
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

R501

National Route	R501
Section	Potchefstroom to Westonaria Municipal Border
Distance	64.3 km
Description	Two-lane narrow single carriageway with gravel shoulders leading into a two-lane narrow double carriageway with gravel shoulders.

Expected Road Condition	Road is closed from Carletonville up to entrance Doornfontein (+- 5km) with detour road recommended. The single carriageway is bad to poor with isolated potholes. The condition of the dual carriageway is good.
Expected Travel Condition	Delays should be expected on the section road that is closed and detour road that is being utilized. Alternative road is recommended Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

National Route	R501
Section	Free State Border to Potchefstroom
Distance	21.2 km
Description	Two-lane narrow single carriageway with gravel shoulders
Expected Road Condition	Fair
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Meyer Odendaal 082 934 9153

National Route	R501/2
Section	Free State Border to Potchefstroom
Distance	0.00 to 21.20
Description	Extending Southwards for some 24.20km, road reserve with single carriage way and gravel shoulders
Expected Road Condition	Bad condition
Expected Travel Condition	Traffic is free flowing. Motorists are advised to obey the posted traffic signs,
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

National Route	R501/3
Section	Potchefstroom to Gauteng border
Distance	3.90 to 33.70
Description	Extending northwards for some 29.80km, road reserve with dual carriage way
Expected Road Condition	Generally good condition
Expected Travel Condition	<ol style="list-style-type: none"> 1. Traffic is free flowing. Motorists are advised to obey the posted traffic signs 2. Pavement Repair 3. Culvert Cleaning
Duration of work	<ol style="list-style-type: none"> 1. Until November 2023 2. Until 23 April 2021 3. End April 2021
Contact for Routine Road Maintenance	Manie du Preez 083 262 0242

R503

National Route	R503
Section	Klerksdorp to Matlosana/ Ditsobotla Municipal border
Distance	48.70 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Fair to Good. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Meyer Odendaal 082 934 9153

National Route	R503/1
Section	Klerksdorp to Coligny (km 47.93 to km 74.6)
Distance	26.67km km
Description	Two-lane single carriageway with gravel shoulders
Expected Travel Condition	Good.
Duration of Work	Ongoing
Contact for Routine Maintenance	Marius Nel 073 538 5019

National Route	R503/2
Section	Coligny to Lichtenburg (km 0.0 to km 21.9)
Distance	21.9 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Marius Nel 073 538 5019

R504

National Route	R504
Section	Wolmaranstad to Leeudoringstad
Distance	28.90 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Poor. Isolated potholes
Expected Travel Condition	1. Routine road maintenance teams may be encountered. 2. Routine road maintenance teams will be active with occasional localised Stop/Go controls for pavement repairs from km 15.8- km 28.9.
Duration of Work	Ongoing
Contact for Routine Maintenance	Phumza Baqwa 083 384 8081

National Route	R504
Section	Leeudoringstad to Free State Border
Distance	24.10 km

Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Poor.
Expected Travel Condition	1. Routine road maintenance teams may be encountered on this section.
Duration of Work	Ongoing
Contact for Routine Maintenance	Phumza Baqwa 083 384 8081

R505/4

National Route	R505
Section	4 – Maquassi Hill Municipality Border to Ditsobotla Municipal Border
Distance	49.5 km (km 37.8 – km 87.3)
Description	Two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Good. Rehabilitation completed in 2019
Expected Road Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Willem-Erik Jacobson 076 148 0321

National Route	R505/4
Section	Wolmaranstad to N14/11 (km 87.3 to km 93.5)
Distance	6.2 km
Description	Two-lane single carriageway with surfaced shoulders.
Expected Travel Condition	Good.
Expected Road Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Marius Nel 073 538 5019

National Route	R505/4
Section	Wolmaransstad to Tswaing Border
Distance	37.82 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Good.
Expected Travel Condition	1. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Phumza Baqwa 083 384 8081

National Route	R505/5
Section	N14/11 to Lichtenburg (km 0.0 to km 27.0)
Distance	27.0 km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair. Edge breaks and edge drops at various positions. Potholes re-occurring

Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

National Route	R505/6
Section	Lichtenburg to Ottoshoop (km 0.0 to km 37.1)
Distance	37.1 km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Fair to good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Marius Nel 073 538 5019

R510

National Route	R510/3
Section	Hermanusdoring to Lephalale
Distance	56km
Description	Two-lane single carriageway with unpaved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing (July 2021)
Contact for Routine Road Maintenance	Russell Odendaal – 081 254 5488 Glen Mmako – 082 451 8801

R511

National Route	R511
Section	NW/GP Border to Brits
Distance	25.6 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Kobus Vermeulen 082 850 7361
National Route	R511
Section	Brits to North West/Limpopo

Distance	75.4 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Rehabilitation and reconstruction between Bethanie intersection (km 10.6) to Beestekraal intersection (km 36.4) commenced on 1 February 2019. Stop / Go operations and deviations will be encountered and may add ± 0.5 hour to your travelling time. Expected completion date: 31 May 2021. Routine road maintenance teams may also be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

R512

National Route	R512
Section	Gauteng /north West Border to R104 (Broedestroom)
Distance	7.49 km
Description	Two-lane single carriageway with gravel shoulders.
Expected Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

National Route	R512
Section	R104 to Brits
Distance	10.06 km
Description	Two-lane single carriageway with paved shoulders.
Expected Road Condition	Fair to good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 850 7361

R518

National Route	R518/1
Section	Lephalale to Marken
Distance	23.9km (Km46.500 to 70.400)
Description	Two-lane single carriageway with unpaved shoulders.
Expected Road Condition	Fair to Good

Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing (July 2021)
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

National Route	R518/2
Section	Mahwelereng N11 to Marken
Distance	101.70 km
Description	Two-lane single carriageway with unpaved shoulders. Paved shoulders in the mountain area (Kloof Pass) Slope in the mountain area full of falling rocks.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Stop and Go road closures will be encountered
Duration of Work	Ongoing (July 2021)
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

National Route	R518
Section	Lephalale to Marken
Distance	70km
Description	Two-lane single carriageway with unpaved shoulders. Slope in the mountain area full of falling rocks
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing (January 2021)
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

National Route	R518/2
Section	Mahwelereng N11 to Marken
Distance	101.70 km
Description	Two-lane single carriageway with unpaved shoulders. Paved shoulders in the mountain area (Kloof Pass) Slope in the mountain area full of falling rocks.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Stop and Go road closures will be encountered
Duration of Work	Ongoing(January 2021)
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

R520

National Route	R520 Section 1 NRA X.002 – 051 – 2015/1
Section	R510/3 Junction to Vaalwater
Distance	54km

Description	Single carriageway with gravel shoulders.
Expected Road Condition	Fair to Good.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

R524

National Route	R524
Section	Louis Trichardt to Punda Maria Gate
Distance	130.3km
Description	Two lane single carriageway with no paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Short stop/go control may occur. Beware of pedestrians and cattle in the Rural Areas. Workmen may be encountered removing edge build-up (slitting) in low lying areas.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Pius Ngassa 0711731194

R556

National Route	R556
Section	Tsitsing to Ledig (Sun City) to R510 intersection
Distance	29.6km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Good.
Expected Travel Condition	Routine Road Maintenance.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Manthathi Masinga 073 200 143

R565

National Route	R565
Section	Rustenburg to Ledig (Sun City)
Distance	34.9km
Description	Two lane single carriageway with paved shoulders.
Expected Road Condition	Bad
Expected Travel Condition	Routine Road Maintenance.
Duration of work	Ongoing

Contact for Routine Road Maintenance	Manthati Masinga 073 200 143
--------------------------------------	---------------------------------

R570

National Route	R570-1
Section	Jeppe's Reef Border Post & Matsamo Border Post – Eswatini (Swaziland) to N4 Interchange.
Distance	40.89 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Road condition is good however road markings need to be done. Access wash-aways & edge build-up and drop-offs in Schoemansdal & Jeppe's Reef area Also expect stray animals – cattle in these areas.
Expected Travel Condition	Routine road maintenance teams may be encountered. Speed humps were instated in Schoemansdal & Jeppe's Reef area. High accident zone at intersection R581 & R570 - One Tree Hill and another high accident zone for the last six kilometers of this route. (Compost farm area, weighbridge access, suger factory intersection and the N4 interchange.)
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	R570-2
Section	N4 Interchange to Malelane Kruger Park Gate
Distance	3.648 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	Road condition is good however road markings need to be done.
Expected Travel Condition	Routine road maintenance teams may be encountered. Sugar canes along the road. (Edge build-up)
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

R571

National Route	R571-1
Section	Mananga Border Post - Eswatini (Swaziland) to N4 Intersection
Distance	60.469 km
Description	Single carriageway with paved shoulders.
Expected Road Condition	First 30km is fair to good. Rest is good. Edge build-up at accesses. Faded road markings. Access wash-aways & edge build-up and drop-offs
Expected Travel Condition	Speed humps were instated in the Masibekela and Kamaqhekeza (Naas) areas. Also expect stray animals – cattle in these areas. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	R571-2
Section	Commencing from the Northern Municipal boundary of the town Komatipoort up to Crocodile River Bridge / Kruger Park Gate

Distance	8.94 km (km 4.2 to km 13.14)
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Road condition is good however road markings need to be done.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

R572

National Route	R572/2
Section	Monte Christo to Tom Bourke
Distance	47.95km
Description	Two-lane single carriageway with unpaved shoulders.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of work	Ongoing(January 2021)
Contact for Routine Road Maintenance	Russell Odendaal Glen Mmako 081 254 5488 082 451 8801

R573

National Route	R573
Section	Section 1 – Zambezi / N1 to Moloto i
Distance	Approx. 45 km
Description	Two-lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good Taken over by SANRAL 16 TH June 2020
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks with lane deviations
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wim Prinsloo 076 972 3185 (082 494 8947)

National Route	R573
Section	Section 2 - Moloto to Moteti
Distance	48.652 km
Description	Two-lane single carriageway with paved shoulders
Expected Road Condition	Fair to Good 4 New circles constructed (completed)
Expected Travel Condition	Routine Road Maintenance teams may be encountered Roadworks with lane deviations
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wim Prinsloo 076 972 3185 (082 494 8947)

Maintenance	
-------------	--

National Route	R573
Section	Section 3 - Moteti to Marble Hall
Distance	43.741 km
Description	Two-lane single carriageway with gravel shoulders
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered Section 3 from Km 19.2 up to Km 43.8 under construction / Contractor resumed work on 5 th of October
Duration of work	Ongoing
Contact for Routine Road Maintenance	Wim Prinsloo 076 972 3185 (082 494 8947)

R578

R581

National Route	R578
Section	Louis Trichardt to Giyani
Distance	90.76
Description	Two lane single carriageway with no paved shoulders and passing lanes on sustained grades.
Expected Road Condition	Fair to Good
Expected Travel Condition	Routine Road Maintenance teams may be encountered. Short stop/go control may occur. Beware of pedestrians and stray cattle. Workmen may be encountered removing edge build-up (slitting) in low lying areas.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Pius Ngassa 0711731194
National Route	R581-2
Section	Tonga up to R571 Intersection in Mangweni.
Distance	10.19 km
Description	Single carriageway with paved and gravel shoulders.
Expected Road Condition	Road condition is good however road markings need to be done. Urban areas Tonga and Mangweni. Access wash-aways & edge build-up.
Expected Travel Condition	Routine road maintenance teams may be encountered. Speed humps were instated in the Tonga and Mangweni areas. Also expect stray animals – cattle in these areas.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

R582

National Route	R582-1
Section	N4 Intersection to Coopersdal / R571 Intersection
Distance	21.06 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Road condition is good however road markings need to be done. High Accident Zone at single lane Julius Furley bridge.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

National Route	R581-1
----------------	--------

Section	One Tree Hill / R570 Intersection up to Tonga.
Distance	26.74 km
Description	Single carriageway with paved and gravel shoulders.
Expected Road Condition	WARNING : Caution to be taken at km 25 road surface repairs in progress Good. Edge build-up at accesses. Faded road markings. Fist 12 km rural area, followed by urban areas Kamhlushwa, Mzinti and Tonga. Also expect stray animals – cattle in these areas.
Expected Travel Condition	Routine road maintenance teams may be encountered. Access wash-aways & edge build-up and drop-offs Speed humps were instated in the Kamhluswa, Mzinti and Tonga areas.
Duration of Work	Ongoing
Contact for Routine Maintenance	Johan Van Niekerk 082 882 9819

N7

National Route	N7
Section	Klipvlei to Melkboom
Distance	213 km
Description	Dual carriageway with paved shoulders
Road Condition	Very Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Jerome Buys 082 328 9422

National Route	N7
Section	Melkboom to Kerboschfontein
Distance	252 km
Description	Single carriageway with paved and / or gravel shoulders
Road Condition	Fair
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Barry Andrews

	083 654 1920
National Route	N7 Section 7-8
Section	Kerboschfontein to Vioolsdrift
Distance	164 km
Description	Single carriageway with paved / gravel shoulders and no passing lanes. Rest areas at regular intervals
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Driaan Koegelenberg 072 347 4969

N8

National Route	N8
Section	Groblershoop to Rooisand (Section 6)
Distance	8 km
Description	Single carriageway with gravel shoulders. Stopping places are provided at regular intervals.
Road Condition	Fair.
Expected Travel Condition	Motorists should be alert to stray animals. The route is prone to Kudu buck in the roadway between dusk and dawn. Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Reginald Januarie 074 736 5019

National Route	N8
Section	Groblershoop to Vaal River
Distance	210 km
Description	Single carriageway with gravel shoulders.
Expected Road Condition	Routine road maintenance Teams may be encountered
Road Condition	Good
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Milton van Heerden 078 460 6552

National Route	N8
Section	Vaal River to NC/FS Border
Distance	231 km
Description	The first five km section from Bloemfontein is a four-lane dual carriageway with wide paved shoulders.
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered,
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Marco Du Plessis

	082 323 3696
--	---------------------

N9

National Route	N9 Section 7
Section	Twefontein to Colesberg
Distance	168 km
Description	Single carriage way with paved and / or gravel shoulders
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Nande Kayise 072 289 0663

N10

National Route	N10
Section	Kopieskraal to Elandsheuwel
Distance	168 km
Description	Single carriageway with paved and/ or gravel shoulders.
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Nande Kayise 072 289 0663

National Route	N10
Section	Kopieskraal to Omdraai Vlei
Distance	204 km
Description	Single carriageway with paved and / or gravel shoulders.
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Belinda Jooste 082 423 1152

N10

National Route	N10
Section	Omdraai Vlei to Boegoeberg
Distance	253 km
Description	Single carriageway with gravel shoulders.
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Reginald Januarie 074 736 5019

National Route	N10
Section	Boegoeberg to Nakop Border
Distance	187 km
Description	Single carriageway with paved and / or gravel shoulders.
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Charl Muishond 079 017 9353

National Route	N12
Section	Riet River to NC/NW Border
Distance	231 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Routine road maintenance teams may also be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Marco Du Plessis 082 323 3696

N14

National Route	N14/9
Section	VRYBURG TO TSWAING MUNICIPAL BORDER
Distance	48.2 km
Description	Around Vryburg and extending towards the Tswaing Municipal Border for some 48.2km, the road is two-lane single carriageway with wide gravel shoulders.
Expected Road Condition	Generally good condition
Expected Travel Condition	Traffic is free flowing. Motorists are advised to obey the posted traffic signs. Minor maintenance work from time to time on this section
Duration of Work	Until November 2023
Contact for Routine Road Maintenance	Matlou Tumelo 076 569 745
National Route	N14
Section	Springbok to Holte/Hunites
Distance	81 km
Description	Single carriageway with paved / gravel shoulders. Rest areas at regular intervals.
Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Driaan Koegelenberg 072 347 4969
National Route	N14
Section	Holte/Hunites to Keimoes
Distance	252 km
Description	Single carriageway with paved shoulders.
Road Condition	Good.

Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Claudia Jannetjies 078 675 8971
National Route	N14
Section	Olyvenhoutsdrift to Zonderhuis
Distance	66 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Charl Muishond 079 017 9353
National Route	N14
Section	Zonderhuis to NC/NW Border
Distance	256 km
Description	Single carriageway with paved shoulders.
Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Mzoxolo Ntebe 072 746 9827
National Route	N14
Section	Keimoes to Olyvenhoutsdrift Border
Distance	23 km
Description	Single carriageway with paved shoulders.
Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Thabang Sesele 083 877 9057

N17

National Route	N17
Section	4 – Govan Mbeki Municipal Boarder to Ermelo
NDistance	38.02Kms (From KM17.70 to KM55.72)
Description	Single carriageway road with passing lanes, 8 intersections and paved shoulders.
Expected Road Condition	The condition of the section is satisfactory except a backlog of W401s on both east and west bounds need an urgent attention.
Expected Travel Condition	Routine Road Maintenance teams may be encountered.
Duration of Work	36 Months
Contact for Routine Road Maintenance	Portia Mashashane (RM), Chwayita Maponyane (ARM1) and Nkonzo Mvelase (ARM2) 0660518080, 0718806260 and 0792732386

National Route	N17
Section	5 - Ermelo to Chief Albert Luthuli Municipal Boarder
NDistance	74.65Kms (From KM0.00 to KM74.65)
Description	Single carriageway road with passing lanes, Railway Intersection, 17 intersections and paved shoulders.
Expected Road Condition	Roughly 80% of the section is Good, between chainage 0.0 to 2.0, there is a lot of potholes on both bounds, crocodile cracks as well as on the last 10 kilometers of the section is looking very bad because of the trucks
Expected Travel Condition	Routine Road Maintenance teams may be encountered Motorist should be alert to the vast quantity of wood trucks from Warburton to Chief Albert Luthuli Municipal Boarder
Duration of Work	36 Months
Contact for Routine Road Maintenance	Portia Mashashane (RM), Chwayita Maponyane (ARM1) and Nkonzo Mvelase (ARM2) 0660518080, 0718806260 and 0792732386
National Route	N18 (R49)
Section	Warrenton to NC / NW Border

Distance	231 km
Description	Single carriageway with gravel shoulders
Road Condition	Good
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Marco Du Plessis 082 323 3696

N18

R24

National Route	R24
Section	Rustenburg to Gauteng Border
Distance	44.8 km (km 00.0 – km 44.8)
Description	Two lane double carriageway with paved shoulders between Buiten Street and Oorsak Road. The remaining section is a two-lane carriageway with passing lanes through Olifantsnek Pass with unpaved shoulders
Expected Road Condition	Road Condition: Fair to Good Isolated bumps can be expected on the road
Expected Travel Condition	Routine Road Maintenance Teams will be encountered, Route Patrol services. Stop/Go's will be encountered from time to time.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Heinrich Scheepers Tel: 060 492 8600
National Route	
Section	NC/ WC border to Groot Lemoenkop West Section 7-10
Distance	286 km
Description	Single carriageway road with 1 metre surfaced shoulders.
Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Jacques Wentzel 060 504 7161
National Route	R27
Section	Groot Lemoenkop West to Keimoes Section 10-11

Distance	155 km
Description	Single carriageway road with paved shoulders.
Road Condition	Good.
Expected Travel Condition	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Route Manager: Thabang Sesele 083 877 9057

Southern Region

20 Shoreward drive

Baywest

Port Elizabeth

6025

National Route	N2
Section	Natures Valley to Storms River
Distance	40 km
Description	A two-lane single carriageway with surfaced shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Toll Road
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	N2
Section	Storms River Town to Elands River
Distance	14 km
Description	A two-lane single carriageway with shoulders.
Expected Travel Condition	Good

Expected Travel Condition	Toll Road
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	N2
Section	Elands River to Gamtoos
Distance	98 km
Description	A two-lane single carriageway with shoulders.
Expected Travel Condition	Good
Contact for Construction	Michelle van Rooyen 072 777 7232

National Route	N2
Section	Gamtoos River to Van Stadens River
Distance	19 km
Description	14, 7 km of 2-lane single carriageway and 4.3 km of dual carriageway with surfaced shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Undulations occur on sections of this road. At Thornhill, pedestrians could be encountered.
Duration of Work	
Contact for Routine Road Maintenance	Henry Steins 082 312 7343

National Route	N2
Section	Van Stadens River to Port Elizabeth (Coega IDZ)
Distance	57 km
Description	Dual carriageway with 2 lanes per direction.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Henry Steins 082 312 7343

National Route	N2
Section	Port Elizabeth (Coega IDZ) to Colchester
Distance	14Km
Description	Dual carriageway with 2 lanes per direction
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Henry Steins 082 312 7343

National Route	N2
Section	Colchester to Nanaga
Distance	13Km
Description	13km single carriageway
Expected Travel Condition	Good.
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2 section 12 & 13
Section	Nanaga to Komgha River
Distance	30km
Description	2 - Lane single carriageway, narrow road width.
Expected Travel Condition	Good, but no paved shoulders in place.
Duration of Work	
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2 section 13
Section	Komgha River to Grahamstown
Distance	42km
Description	2 - lane single carriageway
Expected Travel Condition	Construction is complete and the road conditions are good.
Duration of Work	Project completed
Contact for construction	
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539

National Route	N2 section 13
Section	Komgha River to Grahamstown
Distance	42km
Description	2 - lane single carriageway
Expected Travel Condition	Construction is complete and the road conditions are good.
Duration of Work	Project completed

Contact for construction	
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539

National Route	N2
Section	Grahamstown to Fish River
Distance	47km
Description	A 2-lane single carriageway is being upgraded
Expected Travel Condition	Construction commenced in April 2015 on phase 1. 62 km to 78.7 km and is now complete. The Fish river bridge: km 103, is also complete. Construction of phase 2 commenced in June 2017, 78.7 km to 92.6km. Completion is scheduled for April 2019.
Expected Travel Condition	Speed restrictions will be in place. Construction traffic will be encountered. Speed humps have been installed for safety of road users. Stop/Go controls are in place to reduce traffic speed. The stop/go controls will be removed during the holidays. However, traffic calming and speed restrictions will be in place due to work taking place alongside the road. Animals at R67 intersection east of Grahamstown. Livestock in vicinity of R67 intersection.
Duration of Work	April 2015 to June 2019 (Phase 2) Jan 2019 – April 2021 (Phase 3)
Contact for Routine Road Maintenance	Bathandwa Mankayi 072 774 6539
Contact for Construction project	Steve Beckerling – Engineer's representative on site 083 554 3605

National Route	N2
Section	Fish river to Keiskamma Pass
Distance	27 km
Description	A 2-lane single carriageway.
Expected Travel Condition	Good
Expected Travel Condition	Isolated repairs being undertaken.
Duration of Work	
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2
Section	Keiskamma River to Green River
Distance	23 km
Description	A 2-lane single carriageway

Expected Travel Condition	Good
Expected Travel Condition	Recently upgraded
Duration of Work	
Contact for Routine Road Maintenance	Shami Eksteen 072 774 6539

National Route	N2
Section	Green River to Breidbach - Section 14 & 15
Distance	13km
Description	Upgrading from Green River to Breidbach Interchange. Rehabilitation of section of route through King Williams Town from Buffalo River to Zwelitsha has been completed. Work from Green River to Buffalo river and at Breidbach interchange is planned for future implementation.
Expected Travel Condition	Typical traffic signals in King Williams Town.
Duration of Work	Not applicable at this stage.
Contact for construction	Nick Kitsopoulos 082 576 4667

National Route	N2
Section	Gonubie to Kei River
Distance	60 km
Description	The first 2km is a 4-lane dual carriageway. Thereafter it becomes a 2-lane single carriageway with wide paved shoulders. Passing lanes are provided on some steep grades.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Mike De Lange 082 779 2993

National Route	N2
Section	Kei River to Dutywa
Distance	68 km
Description	Single carriageway road with paved shoulders and passing lanes.
Expected Travel Condition	The condition is fair.
Expected Travel Condition	Roaming animals in some areas near villages. N2 Toleni to Ibeka – expect up to 2hr delays due to road works.

Contact for Routine Road Maintenance	Mike De Lange 082 779 2993
--------------------------------------	-------------------------------

National Route	N2
Section	Dutywa to Mthatha
Distance	85 km
Description	Single carriageway road with paved shoulders and passing lanes.
Expected Travel Condition	Fair
Expected Travel Condition	Roaming animals in some areas near villages
Contact for Routine Road Maintenance	Mike De Lange (RRM queries only) 082 779 2993

National Route	N2
Section	Tetyana to Sithebe Komkulu
Distance	17 km
Description	Upgrading of N2 from Tetyana (km 24) to Sitebe Komkulu (Km 41.0)
Expected Travel Condition	Under construction.
Expected Travel Condition	Mostly 2-way at a maximum speed of 60km/h. Expect stop/go controls for short durations. You may contact the Resident Engineer, MR. Joe van Dyk on the number below, to confirm the blasting times.
Duration of work	October 2016 – May 2019
Contact for Construction project	Joe van Dyk 083 283 6507

National Route	N2
Section	Mthatha to Brookes Nek
Distance	168 km
Description	A 2-lane single carriageway with passing lanes and paved shoulders.
Expected Travel Condition	The Expected Road Condition between km 54 to km 70 is fair however routine maintenance teams may be encountered. Animals may be encountered in some areas near villages.
Contact for Routine Road Maintenance	Ernest Zellhuber 072 789 5046

N6

National Route	N6
Section	East London to Stutterheim
Distance	70 km
Description	A two-lane single carriageway with paved shoulders and passing lanes in places
Expected Travel Condition	Fair to good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Stutterheim to Cathcart
Distance	49 km
Description	Construction completed, road is open.
Expected Travel Condition	Good.
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

National Route	N6
Section	Cathcart to Queenstown
Distance	59 km
Description	A two-lane single carriageway with paved shoulders and passing lanes in places.
Expected Travel Condition	Completed project. Road condition is fair to good.
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

National Route	N6
Section	Queenstown to Jamestown
Distance	107km
Description	A two-lane single carriage way with paved shoulders
Expected Travel Condition	Good
Duration of Work	
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

National Route	N6
Section	Jamestown to Aliwal North
Distance	58 km
Description	A two-lane single carriageway with paved shoulders.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Aphelele Ndandani 078 680 4351

N9

National Route	N9
Section	Western Cape and Eastern Cape Boundary to Aberdeen (3+4)
Distance	138 km
Description	A two-lane single carriageway with gravel shoulders.
Expected Travel Condition	Good
Expected Travel Condition	Motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Danre Gerber 071 679 1349

National Route	N9
Section	Aberdeen to Graaff Reinet (SECTION 5)
Distance	54 km
Description	A two-lane single carriageway with paved shoulders.
Expected Travel Condition	Good.
Duration of Work	
Contact for Routine Road Maintenance	Danre Gerber 071 679 1349

National Route	N9
Section	Graaff-Reinet to Middelburg (SECTION 6)
Distance	105 km
Description	A Two-Lane single carriageway with paved shoulders
Expected Travel Condition	Good.
Contact for construction work	Danre Gerber 071 679 1349

National Route	N9
Section	Middelburg to the intersection of the N10 and N9 between Middelburg and Noupoort (Carlton Heights) (SECTION 7)
Distance	24 km
Description	
Expected Travel Condition	Good.
Expected Travel Condition	Routine road maintenance. Travel condition is good.
Duration of work	
Contact for Routine Road Maintenance	Danre Gerber 071 679 1349

N10

National Route	N10
Section	Nanaga-Paterson
Distance	24 km
Description	Two lane single carriageway road. Some passing lanes
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Solethu Kela 076 963 0897

National Route	N10
Section	Paterson – Olifantskop Pass
Distance	23 km
Description	Two lane single carriageway road. Some passing lanes in pass
Expected Travel Condition	Good
Duration of work	
Contact for Routine Road Maintenance	Solethu Kela 076 963 0897

National Route	N10
Section	Jaskraal to Baviaans River
Distance	43 km
Description	Two lane single carriageway road with paved shoulders
Duration of work	Complete
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Solethu Kela 076 963 0897

National Route	N10
Section	Olifantskop Pass to Baviaans River north of Cookhouse
Distance	134 km
Description	Two lane single carriageway.
Expected Travel Condition	Good
Contact for routine Road Maintenance	Solethu Kela 076 963 0897

National Route	N10
Section	Baviaans River to Riet River
Distance	25 km
Description	Two-lane single carriageway.
Expected Travel Condition	Good
Contact for Routine Road Maintenance	Solethu Kela 076 963 0897

National Route	N10
Section	Riet River to Tarka River
Distance	37 km
Description	Single carriageway with paved shoulders.
Expected Travel Condition	
Resident Engineer	
Contact for Routine Road Maintenance	Solethu Kela 076 963 0897

National Route	N10
Section	Cradock to Middelburg
Distance	95 km
Description	The first 43 km is a two-lane single carriageway road with wide paved shoulders. The last 30 km is a two-lane single carriageway road with gravel shoulders.
Expected Travel Condition	Fair.
Contact for Routine Road Maintenance	Solethu Kela 076 963 0897

R56

National Route	R56
Section	1, N9 Middleburg to Steynsburg
Distance	85km
Description	One lane single carriage way
Expected Road Condition	First 16km is in fair condition. Further, the condition is newly surfaced and good.
Expected Travel Condition	
Duration of work	
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

National Route	R56
Section	2, Steynsburg to Molteno
Distance	57km
Description	One lane single carriage way
Expected Road Condition	Fair to good with pavement repairs recently completed.
Contact for Routine Road Maintenance	Daniela Bosman 082 395 0875

National Route	R56
Section	3, Molteno to N6
Distance	35km
Description	One lane carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	4, N6 to Dordrecht
Distance	35km
Description	One lane single carriage way
Expected Road Condition	Poor.
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	5, Dordrecht to Indwe
Distance	38km
Description	One lane single carriage way
Expected Road Condition	Poor.
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56
Section	6, Indwe to Elliot
Distance	56km
Description	Two lane single carriage way
Expected Road Condition	Special maintenance project between Indwe via Elliot to Maclear for a period of 30 months as from February 2016 to October 2018.
Expected Travel Condition	Expect Stop/Go conditions with 20-minute delays.
Duration of work	32 months, from Feb 2016 to October 2018. Not complete.
Resident Engineer	Ian Posset 084 585 5895
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R56 Section 7
Section	Eliot to Maclear
Distance	68km
Description	Two lane single carriage way with alternate passing and gravel shoulders
Expected Road Condition	Under construction and up to RRM standards.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A contract for the refurbishment of the road to Maclear has stopped, Routine road maintenance in progress 2. Traffic is being accommodated on the newly-constructed road sections but with speed restrictions in place. 3. Special maintenance project between Indwe via Elliot to Maclear for a period of 32 months as from February 2016 to October 2018. Contract stopped. Routine road maintenance busy with emergency pavement repairs and road signs. 4. Stop/go controls are in place.
Duration of work	32 months, from Feb 2016 to October 2018.
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R56 Section 8
Section	Maclear to KZN Border
Distance	168km
Description	Two lane single carriage way with gravel shoulders
Expected Road Condition	Good and up to RRM standards.
Expected Travel Condition	<ol style="list-style-type: none"> 1. A contract for the reseal of the R56 section 8, from Maclear to Mount Fletcher (km 0.0 – km 64.4) was completed in November 2016. 2. A contract for the refurbishment of the road from Matatiele to KZN border is being planned for 2019. 3. Routine road-maintenance teams may be encountered.
Duration of work	Completed. No road works. In a good condition.
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R56
Section	8, Matatiele to Eastern Cape Border
Distance	37km
Description	Two lane single carriage way
Expected Road Condition	Fair to poor. All potholes fixed on this route.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R58
Section	Section 12 from Km 33 – 58 Venterstad to Burgersdorp
Distance	22km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	Good.
Duration of work	
Contact for Routine Road Maintenance	Happy Maduna 083 282 5256

National Route	R58
Section	3, Burgersdorp to Aliwal North N6
Distance	55km
Description	Two lane single carriage way

Expected Road Condition	Good
Expected Travel Condition	
Duration of work	
Contact for Routine road maintenance	Happy Maduna 083 282 5256

National Route	R58
Section	4, Aliwal North N6 to Lady Grey
Distance	49km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	
Duration of work	
Contact for construction	Happy Maduna 083 282 5256

National Route	R58
Section	5, Lady Grey to Barkley East
Distance	66km
Description	Two lane single carriage way
Expected Road Condition	Fair
Expected Travel Condition	Motorists to drive with care due to potential rock falls.
Duration of work	
Contact for construction	Happy Maduna 083 282 5256

National Route	R58
Section	6, Barkly East to Elliot
Distance	62km
Description	Two lane single carriage way
Expected Road Condition	Fair
Duration of work	
Contact for construction	Happy Maduna 083 282 5256

National Route	R58
Section	7, R56 to R410
Distance	4,55km
Description	Two lane single carriage way
Expected Road Condition	Fair

Duration of work	
Contact for construction	Happy Maduna 083 282 5256

National Route	R61
Section	1 (East Cape/West Cape Border to Aberdeen)
Distance	74.5 km
Description	Narrow, single carriageway road with 2 lanes
Expected Travel Condition	Fair
Expected Travel Condition	No construction, but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Danie Gerber 071 679 1349

National Route	R61
Section	Bethesda (N9 Intersection) to Cradock (N10 Intersection) (section 2)
Distance	85.8 km
Description	A narrow 2-lane single carriageway with gravel shoulders over most of the length.
Expected Travel Condition	Fair but Good where repair work is complete.
Duration of work	Phase 2: Completed
Expected Travel Condition	A reseal project from the N9 to the Wapadsberg Pass (Km 0.0 to Km 14.0) will commence in the latter half of 2019.
Contact for Routine Road Maintenance	Meran Arnolds 074 450 8935

National Route	R61
Section	Cradock (N10 Intersection) to Tarkastad (section 3)
Distance	74.5 km
Description	A narrow 2-lane single carriageway with gravel shoulders
Expected Travel Condition	0-24km Fair.
Expected Travel Condition	Construction- over 27km, in the middle of this section, km 24 to 51, is now complete. Km 24-51 in good condition. Km 51-75 in a fair to poor condition. Motorists to be aware of wild animals in rural areas and pedestrians in urban areas at Cradock and Tarkastad.
Duration of work	
Contact for Routine Road Maintenance	Meran Arnolds 074 450 8935

National Route	R61
Section	Section 3. Cradock to Tarkastad
Distance	
Description	
Expected Travel Condition	Special maintenance project underway from May 2019 for an 18-month period.
Duration of work	
Contact for Resident Engineer	Christo Miller 083 556 5535

National Route	R61
Section	Tarkastad to Queenstown (section 4)
Distance	63.1km
Description	A 2-lane single carriageway with surfaced shoulders.
Expected Travel Condition	Road in good condition. Beware of livestock in places.
Contact for Routine Road Maintenance	Meran Arnolds 074 450 8935
Contact for Construction Work	

National Route	R61
Section	Queenstown (N6) to Cofimvaba (Section 5)
Distance	60km
Description	A 2 Lane single carriageway with paved shoulders.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Motorists may encounter occasional short-terms closures on sections in this area due to maintenance repairs. Stop/go controls at KM 54.3. Waiting time will be approximately 10 minutes.
Expected Travel Condition	Route back to RRM for maintenance.
Contact for Construction works	No construction.
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Cofimvaba to Engcobo (Section 6)
Distance	92 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Expected Travel Condition	Fair to good.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Motorists may encounter occasional short-term closures on short section in this area.
Duration of Work	No construction.
Contact for Routine Road Maintenance	Riaan Graaf (RRM) 082 821 0175

National Route	R61
Section	Engcobo to Mthatha (Section 7)
Distance	49 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Expected Travel Condition	Fair to good
Expected Travel Condition	Motorists to be aware of pedestrian and stray animals. Construction works are in progress from the Baziya km12 to Mthatha Airport km39. Reduced speed as gravel detours can be expected. There are also limited road markings. Motorists may encounter occasional short-term closures on short section in this area. Road may also be closed for short durations.
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	R61 Mthatha to Ngqeleni (Section 8)
Distance	5.7km
Description	A two (2) lane single carriageway with paved shoulders.
Expected Travel Condition	Motorists to be aware of pedestrians and stray animals. Travel condition is good.
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Mthatha to Port St Johns (Section 8)
Distance	74 km
Description	A 2-lane single carriageway, with surfaced shoulders.
Expected Travel Condition	Fair.

Expected Travel Condition	Libode to Mngazi Upgrading of nine intersections. Reduced speed and localised bypasses/detours
Duration of work	Libode to Mngazi – completion date July 2019.
Contact for Routine Road Maintenance	Riaan Graaf (Routine road maintenance) 082 821 0175
Contact for Construction works	Nick North-Coombs 082 411 2890 (Libode to Mngazi)

National Route	R61 (Wild Coast)
Section	Ntafufu River to Lusikisiki (Section 9)
Distance	18 Km
Description	Two-lane Single carriageway with Passing lanes
Expected Travel Condition	Good
Expected Travel Condition	Motorist to be aware of pedestrians and animals. The road is winding, and motorists may encounter occasional short-term closures on a short section for routine maintenance.
Duration	
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175
Contact for Construction	

National Route	R62
Section	East Cape borders to N2
Distance	117km
Description	Single carriage road
Expected Travel Condition	Fair but narrow width
Contact for Routine Road Maintenance	Michelle van Rooyen 072 777 7232

National Route	R63
Section	East Cape border to Graaff Reinet
Distance	50km
Description	Single carriageway with gravel shoulders
Expected Travel Condition	Good but narrow over most of the section. In wet weather, occasionally dislodged rocks can be found in the Oudeberg pass. Please drive with caution.
Expected Travel Condition	A section of this route runs through a National Park so watch out for game. .
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R63
Section	Graaff Reinet to R75 junction (to Pearston)
Distance	23km
Description	Single carriageway with paved shoulders
Expected Travel Condition	Good

Expected Travel Condition	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R63
Section	R75 to Pearston , Somerset East to N10
Distance	123km
Description	Two-way single carriage way with gravel shoulders
Expected Travel Condition	Good but narrow.
Contact for Routine Road Maintenance	Johannes Nel 083 295 0606

National Route	R63
Section	Pearston to Bruintjies Hoogte (Section 9 km 43 to Section 10 km 24.7)
Distance	32.35km
Description	Two-way single carriage way with gravel shoulders
Expected Travel Condition	Road is in a good condition but narrow at places. Improved rest areas can be found along the route with beautiful scenery of the Karoo landscape.
Contact for Routine Road Maintenance	Albert Meyburgh – 082 896 3128

National Route	R63
Section	N10 to Bedford
Distance	78km
Description	Two-way single carriage way with gravel shoulders. 4km section before Bedford in poor condition, reduce speed at km 16.9 – km 20.9
Expected Travel Condition	Fairly good, except the 4km section before Bedford which is poor.
Contact for Routine Road Maintenance	Albert Meyburgh – 082 896 3128

National Route	R63
Section	Adelaide to Komga
Distance	189km

Expected Travel Condition	Poor condition between Fort Beaufort and Alice and between Bhisho and Komga. Upgrade due soon.
Expected Travel Condition	Two-way single carriage way. Motorists may encounter occasional short closures by maintenance team, between Fort Beaufort and Alice, and between Bhisho and Komga. Beware of roaming animals near settlement areas.
Contact for Routine Road Maintenance	Odwa Ndlwana – 071 045 8203

National Route	R67
Section	Grahamstown to Fort Beaufort
Distance	70.65km
Description	
Expected Travel Condition	The road is winding, observe speed limit through ECCA Pass and beware of wild animals after dusk. Two-lane single carriageways. Motorists may encounter occasional short-term closures by maintenance teams.
Contact for Routine Road Maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849

National Route	R67
Section	Fort Beaufort to Seymour
Distance	42km
Description	Two-lane carriageway
Expected Travel Condition	Project complete. Road now open.
Contact for routine road maintenance	Gerhard Bester 083 679 1849

National Route	R67
Section	Seymour to Whittlesea
Distance	54,45km
Description	Two-lane single carriage with passing lane
Expected Travel Condition	Fair
Expected Travel Condition	Beware of pedestrian and animals - observe speed limit through to Nico Malan Pass. Stop/go controls in operation on this section. Currently doing line markings.
Contact for Routine road maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849

National Route	R67/5
Section	Whittlesea to Swart Kei
Distance	15,4km
Description	

Expected Travel Condition	Project is in completion stage. Road opened.
Expected Travel Condition	Beware of pedestrians and animals crossing.
Contact for Routine Road Maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849

National Route	R67/5
Section	Swart Kei to Queenstown
Distance	18,3km
Description	Two-way lane single carriageway with gravel shoulders
Expected Travel Condition	Fair to poor. Narrow road.
Expected Travel Condition	Fair to poor. Narrow roads.
Contact for Routine Road Maintenance	Conrad Bezuidenhout / Gerhard Bester 083 679 1849

National Route	R72
Section	Nanaga to Alexandria
Distance	50 km
Description	Two lane single carriageway with paved shoulders
Expected Road Condition	Good
Duration of work	
Contact for Routine Road Maintenance	Ian Smith 084 415 2002
National Route	R72
Section	Alexandra – Peddie turnoff. New Keiskamma rivers
Distance	117km
Description	Two lane single carriageway with grave shoulders
Expected Road Condition	Fair but narrow width
Expected Travel Condition	Construction has commenced between Port Alfred and Fish River, where reduced speeds and stop/go controls will apply. Construction of Bihra River to Open Shaw, where reduced speeds and stop/go controls will apply.
Contact for Construction	Hendrik Pretorius 082 772 1335 (Port Alfred to Fish River) Rian Groenewald 082 837 0500 (Bihra to Open Shaw)
Duration of work	Till August 2018
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R72
Section	Peddie turn off to East London Airport
Distance	62km
Description	Two lane single carriageway with paved shoulder

Expected Road Condition	Good
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R75
Section	Port Elizabeth to Uitenhage North
Distance	28km
Description	Dual carriageway with 2 lanes per direction for the first 14 km. Not a freeway and a lot of level accesses exist, also a lot of pedestrian movements
Expected Road Condition	Good
Expected Travel Condition	Please take special care for first 13 km and normal RRM work. Reconstruction from km 1,0 to km 13 has commenced. Expect delays.
Duration of work	To be completed in May 2019.
Contact for construction	Andre Roodt 082 490 0199.
Contact for Routine Road Maintenance	Lauren Adams 073 311 1818

National Route	R75
Section	Uitenhage North to Jansenville
Distance	136km
Description	A two-lane narrow, single carriageway with gravel shoulders.
Expected Road Condition	Fair
Expected Travel Condition	Fair, no construction currently underway, but routine maintenance is ongoing. Look out for warthogs.
Duration of work	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R75
Section	Jansenville to R63 junction (Pearston)
Distance	59km
Description	A two-lane, narrow single carriageway with gravel shoulders. The last 23km with paved shoulders.
Expected Road Condition	Fair
Expected Travel Condition	No construction but motorists may encounter occasional short closures for routine maintenance. Very narrow sections from Jansenville for +- 50km.
Duration of work	
Contact for Routine Road Maintenance	Babalwa Mbandazayo 072 327 4045

National Route	R390
----------------	------

Section	1 – Cradock to Hofmeyr
Distance	67.9km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good, up to RRM standards.
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Marco Du Plessis 079 893 6256

National Route	R390
Section	2 - Hofmeyr to R56 Steynsburg
Distance	34.20km
Description	Two lane single carriageway with gravel shoulders
Expected Road Condition	Good, recently resealed
Expected Travel Condition	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Daniela Bosman 082 935 0875

National Route	R391
Section	Section 2
Distance	37.49km
Description	Reseal project underway until December 2019. Expect stop/go sections.
Expected Road Condition	
Duration of Work	Ongoing
Resident Engineer	Mike Miller 083 974 2072

National Route	R410 Section 1
Section	R392 Intersection to Lady Frere
Distance	Km 0.0 to Km 38.8
Description	Two lane single carriageways with gravel shoulders for 38.8 km, up to Lady Frere.
Expected Road and travel condition	Poor to fair. Routine road maintenance teams may be encountered.
Duration of Work	RRM Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R410 Section 2
Section	Lady Frere to Cala
Distance	Km 0.0 to Km 58.0
Description	Two lane single carriageways with alternating passing and gravel shoulders.
Expected Road Condition	Good and Up to RRM Standards
Expected Travel Condition	A contract for the Reseal of the R410 Section 2 was completed July 2017. Routine Road Maintenance teams may be encountered

Duration of Work	RRM Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

National Route	R410 Section 3
Section	Cala to R58 Intersection
Distance	Km 0.0 to Km 16.8
Description	Two lane single carriageways with alternating passing and gravel shoulders.
Expected Road Condition	Good and Up to RRM Standards
Expected Travel Condition	A contract for the Reseal of the R410 Section 2 was completed July 2017. Routine Road Maintenance teams may be encountered
Duration of Work	RRM Ongoing
Contact for Routine Road Maintenance	Vincent Gouws 082 300 7409

THE SOUTH AFRICAN NATIONAL ROADS AGENCY SOC LTD

Contact Details

Head Office

48 Tambotie Avenue
Val de Grace
Pretoria, 0184
Tel. 012 844 8000
Fax 012 362 2117

Northern Region

38 Ida Street
Menlo Park
Pretoria, 0081
Tel. 012 426 6200
Fax 012 348 1680

Eastern Region

58 Van Eck Place
Mkondeni
Pietermaritzburg
Tel. 033 392 8100
Fax 033 386 6284 / 3365

Southern Region

20 Shoreward Drive
Baywest
Port Elizabeth
6025
Tel. 041 398 3200
Fax 041 492 0201

Western Region

1 Havenga Street
Oakdale, Bellville

7530
Tel. 021 957 4600
Fax 021 910 1699

Website: www.sanral.co.za
E-mail: info@nra.co.za
Fraud Hot Line: 0800204558



